

620 Shuttle Hill Road

August 26th, 2022

Inspected by Bradley W. Koser Prepared for Jason

Buyer's Agent



Bowen Agency Realtors

Seller's Agent



Real Broker LLC

620 Shuttle Hill Road Page 1 of 33

≡ SITE DETAILS

APPROXIMATE HUMIDITY

☑ 76%

ESTIMATED SQUARE FEET

☑ 1918

INSPECTION FEE

S \$325

NUMBER OF STORIES

☑ One

STYLE

☑ Ranch

WEATHER CONDITIONS

☑ Partly cloudy throughout the day.

YEAR BUILT

☑ 1984

APPROXIMATE TEMPERATURE

☑ 75° F

IN ATTENDANCE

☑ Client

B Safe Home Inspections LLC

NUMBER OF BEDROOMS

OCCUPANCY

TYPE OF BUILDING

WEATHER CONDITIONS

620 Shuttle Hill Road Page 2 of 33

1 · ROOFING

5.1 The inspector shall: A. inspect: 1. roofing materials. 2. roof drainage systems. 3. flashing. 4. skylights, chimneys, and roof penetrations. B. describe: 1. roofing materials. 2. methods used to inspect the roofing. 5.2 The inspector is NOT required to inspect: A. antennas. B. interiors of vent systems, uses, and chimneys that are not readily accessible. C. other installed accessories.

GENERAL / ROOF TYPE / INSPECTION METHOD **(i)** INSPECTION METHOD ☑ Roof **© ROOF TYPE/STYLE COVERINGS** ① MATERIAL **OSHINGLES MISSING © EXPOSED NAILS** Shed and House Roof ① DAMAGED COVERINGS

1.1 · SHINGLES MISSING

Observations

620 Shuttle Hill Road Page 3 of 33




Observed areas that appeared to be missing sufficient coverings. Recommend further evaluation by a qualified contractor.

1.2 · EXPOSED NAILS

Informational

620 Shuttle Hill Road Page 4 of 33



Under-driven or exposed nails were found in one or more roof coverings. Recommend further evaluation by a qualified contractor.

1.3 · DAMAGED COVERINGS

Observations

620 Shuttle Hill Road Page 5 of 33



Roof coverings exhibited general damage that could affect performance. Recommend a qualified roofer evaluate and repair.

FLASHINGS

• MATERIAL

☑ Aluminum

ROOF DRAINAGE SYSTEMS

GUTTER MATERIAL

☑ Aluminum

① DOWNSPOUTS DRAIN NEAR HOUSE

1.4 · DEBRIS

Observations

620 Shuttle Hill Road Page 6 of 33



Debris has accumulated in the gutters. Recommend cleaning to facilitate water flow.

Here is a DIY resource http://www.lowes.com/projects/repair-and-maintain/gutter-cleaning-and-repair/project for cleaning your gutters.

1.5 · DOWNSPOUTS DRAIN NEAR HOUSE

Recommend Action



One or more downspouts drain too close to the homes foundation. This can result in excessive moisture in the soil at the foundation, which can lead to foundation/structural movement. Recommend further evaluation by a qualified contractor to have drain at least 6 feet from the foundation.

Here is a helpful DIY link https://www.thisoldhouse.com/how-to/how-to-drain-downspout-water-flow-away-house and video on draining water flow away from your house.

SKYLIGHTS, CHIMNEYS & ROOF PENETRATIONS

620 Shuttle Hill Road Page 7 of 33

1.6 · LOOSE BRICKS/MISSING MORTAR

Observations



Minor cracks in mortar. Recommend further evaluation by a qualified Masonary contractor.

2 · EXTERIOR

4.1 The inspector shall: A. inspect: 1. wall coverings, flashing, and trim. 2. exterior doors. 3. attached and adjacent decks, balconies, stoops, steps, porches, and their associated railings. 4. eaves, soffits, and fascias where accessible from the ground level. 5. vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building. 6. adjacent and entryway walkways, patios, and driveways. B. describe wall coverings. 4.2 The inspector is NOT required to inspect: A. screening, shutters, awnings, and similar seasonal accessories. B. fences, boundary walls, and similar structures. C. geological and soil conditions. D. recreational facilities. E. outbuildings other than garages and carports. F. seawalls, break-walls, and docks. G. erosion control and earth stabilization measures.

GENERAL INSPECTION METHOD

(i) INSPECTION METHOD

Attic Access

☑ Visual

DECKS, BALCONIES, PORCHES & STEPS

620 Shuttle Hill Road Page 8 of 33

① APPURTENANCE-EXTRAS/ADDITIONS

- Patio
- Shed
- ① MATERIAL

2.1 · MATERIAL

Informational



No issues at the time of inspection.

EAVES, SOFFITS & FASCIA

2.2 · NO ISSUES FOUND AT THE TIME OF INSPECTION.

Informational

620 Shuttle Hill Road Page 9 of 33









No issues found at the time of inspection

SIDING, FLASHING & TRIM

① SIDING/FLASHING/TRIM MATERIAL

- ☑ Brick
- ☑ Vinyl

① SIDING STYLE

620 Shuttle Hill Road Page 10 of 33

① CRACKING - MINOR

2.3 · CRACKING - MINOR

Observations



Small crack in siding on West side of house. Recommend monitoring. Repair as needed.

WALKWAYS, PATIOS & DRIVEWAYS

① DRIVEWAY AND WALKWAY MATERIALS

☑ Asphalt

Concrete

2.4 · DRIVEWAY AND WALKWAY MATERIALS

Informational

620 Shuttle Hill Road Page 11 of 33



Asphalt

2.5 · DRIVEWAY CRACKING - MINOR

Observations



Minor cosmetic cracks observed, which may indicate movement in the soil. Recommend monitor and/or have driveway contractor patch/seal.

EXTERIOR DOORS

① EXTERIOR ENTRY DOOR MATERIAL

☑ Wood

620 Shuttle Hill Road Page 12 of 33

2.6 · NO ISSUES FOUND AT THE TIME OF INSPECTION.

Informational

No issues found at the time of inspection

3 · AIR CONDITIONING

9.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. central and permanently installed cooling equipment. 2. distribution systems. C. describe: 1. energy source(s). 2. cooling systems. 9.2 The inspector is NOT required to: A. inspect electric air cleaning and sanitizing devices. B. determine cooling supply adequacy and distribution balance. C. inspect cooling units that are not permanently installed or that are installed in windows. D. inspect cooling systems using ground source, water source, solar, and renewable energy technologies.

GENERAL(TYPE)	
① TYPE	
☑ Air Conditioner	
☑ Heat Pump	
COOLING EQUIPMENT	
① LOCATION	
☑ Exterior West	
① BRAND	
☑ Unknown	
① ENERGY SOURCE/TYPE	
☑ Electric	
3.1 · BRAND	
Recommend Action	

620 Shuttle Hill Road Page 13 of 33



No information tag on unit. Looks to be at or near end of life. Recommend further evaluation by a qualified heating and cooling contractor.

4 · INTERIORS

10.1 The inspector shall inspect: A. walls, ceilings, and floors. B. steps, stairways, and railings. C. countertops and a representative number of installed cabinets. D. a representative number of doors and windows. E. garage vehicle doors and garage vehicle door operators. F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: A. paint, wallpaper, and other finish treatments. B. floor coverings. C. window treatments. D. coatings on and the hermetic seals between panes of window glass. E. central vacuum systems. F. recreational facilities. G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or confirm the operation of every control and feature of an inspected appliance.

CEILINGS

① CEILING MATERIAL

WALLS

620 Shuttle Hill Road Page 14 of 33

① WALL MATERIAL

- ☑ Drywall

WINDOWS

- **WINDOW MANUFACTURER**
- **(i) WINDOW TYPE**

4.1 · DAMAGED

Observations



One or more windows appears to have general damage, but are operational. Recommend a handyman or contractor paint, lubricate & adjust as necessary.

FLOORS

620 Shuttle Hill Road Page 15 of 33

① FLOOR COVERINGS

- Engineered Wood
- Laminate
- ☑ Vinyl


5 · FIREPLACES AND FUEL-BURNING APPLIANCES

12.1 The inspector shall: A. inspect: 1. fuel-burning replaces, stoves, and replace inserts. 2. fuel-burning accessories installed in fireplaces. 3. chimneys and vent systems. B. describe systems and components listed in 12.1.A.1 and .2. 12.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. fire screens and doors. 3. seals and gaskets. 4. automatic fuel feed devices. 5. mantles and replace surrounds. 6. combustion air components and to determine their adequacy. 7. heat distribution assists (gravity fed and fan assisted). 8. fuel-burning replaces and appliances located outside the inspected structures. B. determine draft characteristics. C. move fireplace inserts and stoves or firebox contents.

CHIMNEY & VENT SYSTEMS

5.1 · CHIMNEY LINER DIRTY

Recommend Action



Chimney liner had layer of creosote dust, so underlying structure couldnt be inspected for cracks. Recommend qualified chimney sweep company inspect and/or clean.

GENERAL TYPE

620 Shuttle Hill Road Page 16 of 33

① FIREPLACE TYPE

☑ Wood

5.2 · FIREPLACE TYPE

Informational

Everything looked operational at time of inspection. Blower fan was operational at the time of inspection.

6 · APPLIANCES

10.1 The inspector shall inspect: F. installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders by using normal operating controls to activate the primary function. 10.2 The inspector is NOT required to inspect: G. installed and free-standing kitchen and laundry appliances not listed in Section 10.1.F. H. appliance thermostats including their calibration, adequacy of heating elements, self cleaning oven cycles, indicator lights, door seals, timers, clocks, timed features, and other specialized features of the appliance. I. operate, or con rm the operation of every control and feature of an inspected appliance.

DISHWASHER

(i) BRAND

☑ GE

6.1 · OPERATIONAL

Operational



Operational at time of inspection.

620 Shuttle Hill Road Page 17 of 33

RANGE/OVEN/COOKTOP

① RANGE/OVEN BRAND

① EXHAUST HOOD TYPE

☑ Re-circulate

6.2 · OPERATIONAL AT TIME OF INSPECTION

Operational



Range/Oven/Cooktop were Operational at time of inspection.

REFRIGERATOR

(i) BRAND

☑ Whirlpool

6.3 · OPERATIONAL

Operational

620 Shuttle Hill Road Page 18 of 33



Refrigerator operational at time of inspection.

7 · PLUMBING

6.1 The inspector shall: A. inspect: 1. interior water supply and distribution systems including fixtures and faucets.

2. interior drain, waste, and vent systems including fixtures. 3. water heating equipment and hot water supply systems. 4. vent systems, flues, and chimneys. 5. fuel storage and fuel distribution systems. 6. sewage ejectors, sump pumps, and related piping. B. describe: 1. interior water supply, drain, waste, and vent piping materials. 2. water heating equipment including energy source(s). 3. location of main water and fuel shut-off valves. 6.2 The inspector is NOT required to: A. inspect: 1. clothes washing machine connections. 2. interiors of vent systems, flues, and chimneys that are not readily accessible. 3. wells, well pumps, and water storage related equipment. 4. water conditioning systems. 5. solar, geothermal, and other renewable energy water heating systems. 6. manual and automatic re-extinguishing and sprinkler systems and landscape irrigation systems. 7. septic and other sewage disposal systems. B. determine: 1. whether water supply and sewage disposal are public or private. 2. water quality. 3. the adequacy of combustion air components. C. measure water supply low and pressure, and well water quantity. D. fill shower pans and fixtures to test for leaks.

DRAIN, WASTE, & VENT SYSTEMS

① MATERIAL

☑ PVC

ODRAIN SIZE

1 1/2"

7.1 · DRAIN SIZE









Operational at time of inspection.

GENERAL

① MAIN WATER SHUT-OFF DEVICE (LOCATION)

- ☑ Basement

$7.2 \cdot \text{MAIN WATER SHUT-OFF DEVICE (LOCATION)}$

Informational

620 Shuttle Hill Road Page 20 of 33



Main water shut off

WATER HEATER

(i) LOCATION

• MANUFACTURER

☑ Rheem

OPOWER SOURCE

© CAPACITY

7.3 · ANNUAL MAINTENANCE FLUSH NEEDED

Observations

Water heaters should be flushed annually to prevent sediment buildup and maintain efficiency. Recommend a qualified plumber service and flush.

Here is a DIY link to help http://www.familyhandyman.com/plumbing/water-heater/how-to-flush-a-water-heater/view-all.

620 Shuttle Hill Road Page 21 of 33

7.4 · MANUFACTURER

Operational

Operational at time of inspection.

7.5 · CAPACITY

Informational



Manufactured in 2019

7.6 · IMPROPER INSTALLATION

Recommend Action



Recommend adding a drip pan under water heating. A drip pan will prevent unexpected leaks in the home.

8 · ELECTRICAL

620 Shuttle Hill Road Page 22 of 33

7.1 The inspector shall: A. inspect:

- 1. service drop.
- 2. service entrance conductors, cables, and raceways.
- 3. service equipment and main disconnects.
- 4. service grounding.
- 5. interior components of service panels and subpanels.
- 6. conductors.
- 7. overcurrent protection devices.
- 8. a representative number of installed lighting fixtures, switches, and receptacles.
- 9. ground fault circuit interrupters and arc fault circuit interrupters. B. describe:
- 10. amperage rating of the service.
- 11. location of main disconnect(s) and subpanels.
- 12. presence or absence of smoke alarms and carbon monoxide alarms.
- 13. the predominant branch circuit wiring method. 7.2 The inspector is NOT required to: A. inspect:
- 14. remote control devices.
- 15. or test smoke and carbon monoxide alarms, security systems, and other signaling and warning devices.
- 16. low voltage wiring systems and components.
- 17. ancillary wiring systems and components not a part of the primary electrical power distribution system.
- 18. solar, geothermal, wind, and other renewable energy systems. B. measure amperage, voltage, and impedance. C. determine the age and type of smoke alarms and carbon monoxide alarms.

SERVICE ENTRANCE CONDUCTORS

① ELECTRICAL	SERVICE	INSTALLA	ATION A	ND C	CONDU	CTORS
--------------	---------	----------	---------	------	-------	-------

- 220 Volts
- ☑ Aluminum

8.1 · OPERATIONAL

Operational

Operational at time of inspection

8.2 · ELECTRICAL SERVICE INSTALLATION AND CONDUCTORS

Informational

620 Shuttle Hill Road Page 23 of 33



Operational at time of inspection.

PANEL-SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS

① PANEL MANUFACTURER

① PANEL TYPE

① PANEL CAPACITY

8.3 · PANEL TYPE

Informational

620 Shuttle Hill Road Page 24 of 33



No issues at the time of inspection.

8.4 · PANEL CAPACITY

Operational



200 amp service

DEFECTIVE-CONNECTED DEVICES AND FIXTURES

① COVER PLATES DAMAGED

☑ In garage

8.5 · INOPERABLE SWITCH

Informational

620 Shuttle Hill Road Page 25 of 33



Could not operate switch at time of inspection. Recommend further evaluation by a qualified electrical contractor.

8.6 · COVER PLATES DAMAGED

Recommend Action



Receptacle has a damaged cover plate. Recommend replacement by a handyman or contractor.

9 · HEATING

620 Shuttle Hill Road Page 26 of 33

8.1 The inspector shall: A. open readily openable access panels. B. inspect: 1. installed heating equipment. 2. vent systems, uses, and chimneys. 3. distribution systems. C. describe: 1. energy source(s). 2. heating systems. 8.2 The inspector is NOT required to: A. inspect: 1. interiors of vent systems, uses, and chimneys that are not readily accessible. 2. heat exchangers. 3. humidifiers and dehumidifiers. 4. electric air cleaning and sanitizing devices. 5. heating systems using ground-source, water-source, solar, and renewable energy technologies. 6. heat-recovery and similar whole-house mechanical ventilation systems. B. determine: 1. heat supply adequacy and distribution balance. 2. the adequacy of combustion air components.

HEATING EQUIPMENT

① HEAT TYPE
☑ Forced Air
① BRAND
① ENERGY SOURCE
☑ Electric
① FILTER TYPE
9.1 · HEAT TYPE Informational
All operational at time of inspection.
9.2 · BRAND Recommend Action

620 Shuttle Hill Road Page 27 of 33



Manufactured in 1996. Past life expectancy. Recommend further evaluation by a qualified heating and cooling contractor.

9.3 · FILTER TYPE

Informational



In return duct at furnace.

9.4 · FILTER SIZE

Informational

620 Shuttle Hill Road Page 28 of 33



16 X 20

9.5 · SERVICING/CLEANING

Informational

Furnace should be cleaned and serviced annually. Recommend a qualified Heating and cooling contractor clean, service and certify furnace.

Here is a resource https://www.directenergy.com/learning-center/home-improvement/importance-of-furnace-maintenance on the importance of furnace maintenance.

10 · INSULATION AND VENTILATION

11.1 The inspector shall: A. inspect: 1. insulation and vapor retarders in unfinished spaces. 2. ventilation of attics and foundation areas. 3. kitchen, bathroom, laundry, and similar exhaust systems. 4. clothes dryer exhaust systems. B. describe: 1. insulation and vapor retarders in unfinished spaces. 2. absence of insulation in unfinished spaces at conditioned surfaces. 11.2 The inspector is NOT required to disturb insulation.

ATTIC INSULATION

(1) INSULATION TYPE

☑ Batt

10.1 · INSULATION TYPE

Informational

620 Shuttle Hill Road Page 29 of 33



See photos

10.2 · RECOMMENDED R-VALUE

Informational

Recommended attic insulation R-value in Pennsylvania is between R-39 and R-60

ATTIC VENTILATION

① ATTIC VENTILATION TYPE

Ridge Vents

EXHAUST SYSTEMS

10.3 · OPERATIONAL AT TIME OF INSPECTION

Informational

All in good working condition at the time of inspection.

11 · STRUCTURAL COMPONENTS

620 Shuttle Hill Road Page 30 of 33


- 3. STRUCTURAL COMPONENTS 3.1 The inspector shall: A. inspect structural components including the foundation and framing. B. describe:
- 4. the methods used to inspect under floor crawlspaces and attics.
- 5. the foundation.
- 6. the floor structure.
- 7. the wall structure.
- 8. the ceiling structure.
- 9. the roof structure. 3.2 The inspector is NOT required to: A. provide engineering or architectural services or analysis. B. offer an opinion about the adequacy of structural systems and components. C. enter under floor crawlspace areas that have less than 24 inches of vertical clearance between components and the ground or that have an access opening smaller than 16 inches by 24 inches. D. traverse attic load-bearing components that are concealed by insulation or by other materials.

CEILING STRUCTURE

① MATERIAL

11.1 · MATERIAL

Informational



No issues at the time of inspection


FLOOR STRUCTURE

620 Shuttle Hill Road Page 31 of 33

① MATERIAL
☑ Wood joists
© SUB-FLOOR MATERIALS
☑ OSB
☑ Plywood
FOUNDATION, BASEMENT & CRAWLSPACES
⊙ MATERIAL
☑ Concrete
☑ Masonry Block
① BASEMENT/CRAWLSPACE FLOOR
☑ Concrete
ROOF STRUCTURE & ATTIC
① MATERIAL
☑ Plywood
☑ Wood
① TYPE
☑ Gable
11.2 · MATERIAL

620 Shuttle Hill Road Page 32 of 33

Informational



No issues found at time of inspection.

WALL STRUCTURE

① MATERIAL

GENERAL-INSPECTION METHODS

© INSPECTION METHOD

Attic Access

620 Shuttle Hill Road Page 33 of 33