

-	
Access	The site can be accessed directly from Cranfield
	Road or from the north via a potentially
	improved Manor Farm access.
Landscape	The site lies on the edge of the village although
	views into/out of the site are screened by
	vegetation and buildings at Manor Farm. It
	could be developed without any significant
	landscape harm.
Flooding/drainage	There are no known flooding or drainage issues
	associated with the site.
Heritage	Development of the site would not adversely
	affect any designated heritage assets.
Ecology	There are no known ecological constraints
	affecting the site, although it is noted there are
	ponds to the immediate west and north of the
	site, which would need to be surveyed for
	newts or any application subject to the District
	Licensing Scheme.
Conclusion	The site is well related to the existing village, is
	unconstrained, and benefits from good access.
	However, it would establish development to
	the west of Cranfield Road.
	It should nevertheless be considered further for
	allocation, which should be in a form restricted
	to the portion of site with road frontage – see
	map below.



Area within dotted line suitable for further consideration