

Illustration 16.0 Reverse Turnaround Combination Service

```

TIE UP SCREEN
PST507B
TRAIN:( 114-01 - TC ) OF: 111005 - 0400 JOB TYPE: 04 ROUTE: COND-ONLY: Y
METHOD OF PAY: TCS FIXED
TRAIN ORIGIN STN: 04370 TURN OR WRK>DH STN: 04370 TIEUP STN : 04335

DOMTS : A HELD OUT: AOMTS DATE-TIME B
WRK BEGAN: HELDAWAY: RELVD RESP DATE-TIME: C

D TRAIN E > 3000 F WORK G FINAL ACTUAL START RL RETURN RL SWTCH F-125
LENGTH HRSPWR UNITS INSPC MILES RM RM RM RM ENRTE FAXED
( 10064 ) ( Y ) ( 02 ) ( N ) ( 150 ) ( ) ( ) ( ) ( ) ( ) ( )
START OMTS2 DEPT ARR TURN DEPT TURN OMTS2 ARR
RETRN OMTS2 DEPT ARR TURN DEPT TURN OMTS2 ARR TAXI ARR

X EMPLOYEE NAME CC R ORDR OFFD REST H ST? MLS H/A ROOM CALL NG?
SHEWCHUK, LJ (LACEY) ESB EN 0400 I N
SYKES, D. (DAVE) CD 0400 N

ENTER=INQUIRE/PROCESS PF1=HELP PF3=EXIT PF4=RTE PF5=TIEUP
PF10=DELAYS PF11=CLAIMS PF12=AFHT LODGING UPDATE
    
```

A	DOMTS	Time at which the engine passed the outer main track switch at the train origin station.
B	AOMTS Date-Time	Date and time at which the train passed the outer main track switch at the objective terminal.
C	Relvd Resp Date-Time	Date and time at which the train stopped.
D	Train Length	Length of the train in feet
E	> 3000 Hrspwr	If the combined horsepower is more than 3000, place a 'Y', if not, place an 'N'.
F	Work Units	Number of units working the train
G	Final Inspc	If final inspection was completed enter a 'Y', otherwise enter an 'N'
H	X	Place an 'X' next to each employee reporting off duty.
I	OFFD	Time the employees are reporting off duty.
J	Ensure all information is correct prior to submitting. Press PF5 to submit your Tie-up.	