



Exporting Face Scans to STL/PLY/OBJ Files

You can export face scans to third-party STL, PLY, and OBJ files.

To export a face scan to a STL, PLY, or OBJ file:

1. Right-click the face scan object. The context menu is displayed.
2. Select **Export to STL**, **Export to PLY**, or **Export to OBJ**. The **Export** window is displayed.
3. Click the **ellipsis** to select a folder for the exported file and type a name for the exported file.

Note: We recommended exporting the file to an empty folder to prevent any mix-up of the exported data.

4. Click **OK**. A message is displayed that the file has been successfully exported to the selected file path.

Note: Be sure to send all exported files to your vendor.

Related Topics

[Accessing 3D Tools](#)

[Using the Auto Detect Landmarks Feature](#)

[Importing STL/PLY Files](#)

[Working with Images and Documents](#)