AR	olbase sectors	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be er	ndorsed with Name, Rati	, Repairs and Alterations ing and Certificate Number of ages for other specific entries.)			
	Date Tail#		25 Hours	: TTAF: TTE	ENG: TTP:					
	Engil 1. Per #1 7 2. Re Ran I her	7/80 #2 78/80 emoved spar engine and a eby certify the ditional Inspermined to be	9288-51E. I cylinder c 0 #3 78/80 k plugs, insall ops chec at this aircection in the	ompressions #4 77/80. spected and cks were goo raft & engine e scope and	rotated them. od, no leaks noted at the was inspected in accepted of 14 CFR Part					
	Ak	ALC AV	D LAU CAN	MARENA	Cert: Sign:	A&P 3727664 IA Man La				

		Total Paris							
YEAR 20 23 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20 23 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
IS Mar	1.2		E Fi	I have installed Lycoming EL-39288-51E Model# 110-360-EXP286 IAW with the manufacturer's installation procedures and 14 CFR Part 43 Appendix D and it is ina condition for safe operation. I have ran the engine and it performs within manufacturer's specifications.  Removed cowling, tarqued the throttle serve arm nut and installed new cetter pin pla: M824665-208.  Leinstalled cowling. Ops check okay.  Leinstalled cowling and drained engine oil. Removed oil liter pla: AA48110-2. Installed and tarqued new all filter pla: AA48110-2 to 18ft 165. Reinstalled drain plug and installed safety wire. Added 8 quarts of Aeroshell of mineral oil. Ops check okay, no leaks noted.	27 Ma	40.2			Removed cowling and drained engine sit. Lemoved sit filter pln: AA48110-2. Installed and torqued new sit filter pln: AA48110-2 to 18ft lbs. Reinstalled drain plug and installed safety wire. Added 8 quarts of Phillips 20x-50. Ops check okay, no leaks noted Reinstalled cowling."
				412					The state of the s