

PROPELLER MAINTENANCE RECORD

PROPELLER MODEL 740M6-0-60

PROPELLER SERIAL NUMBER A56727

TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE

Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

PROPELLER SERIES**	BOLT DIA. (Inches)	RECOMMENDED WRENCH TORQUE		
		in.-lb.	ft.-lb.	n.-m.
69CK, M69CK (6 bolts) 72CK (6 bolts) 74CK, M74CK (6 bolts) 76AK, M76AK (6 bolts) 76AM6, M76AM (6 bolts) 74DM6, M74DM (6 bolts) *74DR, M74DR (8 bolts)	3/8 (0.375)	280-300	23-25	32-34
74DM7 (6 bolts)	7/16 (0.4375)	480-540	40-45	54-61
72CC (6 bolts) 74DC, M74DC (6 bolts) 76EM8, M76EMM (6 bolts) *80BM8, M80BMM (6 bolts)	1/2 (0.500)	720-780	60-65	81-88

*Not in production

**These are the basic propeller models. Spacer addition does not affect recommended wrench torque.

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
22 APRIL 97	3825.10	INSTALLED NEW PROPELLER ON PIPER PA 28-140 N5714U, S/N 28-26514	I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION. DATE 4-22-97 TOTAL TIME 0.0 <i>Donald F. Minnell</i> A & P # 516726276 IA
5-15-98	3888.92	TACH: R&R PROP TO REMOVE COWL-REWORKED AND SAFETIED	I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AIRWORTHY CONDITION. DATE 5-15-98 TOTAL TIME 63.82 <i>Donald F. Minnell</i> A & P # 536726276 IA

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-1-00	4005.2	(TT:180.1) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
6-17-01	4114.7	(TT:289.6) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
6-8-02	4325.5	(TT:500.4) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
8-17-03	4452.9	(TT:527.8) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
12-28-05	4542.5	(TT:638.2) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
3-15-08	4657.6	(TT:753.3) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
5-2-09	4735.9	(TT:831.6) ANNUAL INSPN & FOUND TO BE AIRWORTHY.	Donald M. Burt IA539525456
7-8-18	4967.0	REMOVED PROPELLER FOR OVERHAUL	James H. Bergman A401820200
11/1/18	4968.0	INSTALLED OVERHAULED PROPELLER	James H. Bergman A401820200 IA
2-8-2020	5060.5	PT-1235.4 - Annual Inspn + found to be airworthy.	IA3575997
3-12-2021	5481.3	PT-1656.2 - Annual Inspn found to be airworthy.	IA3575997
4-1-2022	5812.35	PT-1987.25 - Annual Inspn found to be airworthy.	IA3575997
6-14-2024	2135.9	Annual Inspn complete	Jim 2704250 IA

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]