## Capital Fund Program - Five-Year Action Plan

Status: Submitted Approval Date: Approved By: 02/28/2022

Part I: Summary						
PHA Name: Housing Authority of the City of Sedalia, MO		Locality (City/County & State)  X Original 5-Year Plan		Revised 5-Year Plan (Revision No:		)
PHA Number: MO074						
A.	Development Number and Name	Work Statement for Year 1 2025	Work Statement for Year 2 2026	Work Statement for Year 3 2027	Work Statement for Year 4 2028	Work Statement for Year 5 2029
	CASA LOMA & ANTHONY BUCKNER (MO074000001)	\$731,125.00	\$731,125.00	\$731,125.00	\$731,125.00	\$731,125.00

paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Signage)

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)						
Work State	Work Statement for Year 1 2025						
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost			
	CASA LOMA & ANTHONY BUCKNER (MO074000001)	<u>.</u>		\$731,125.00			
ID0000077	Operations(Operations (1406))	PHA operating expenses		\$200,000.00			
ID0000078	Dwelling Structures(Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Tuck-Pointing,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Interior (1480)-Bathroom Flooring (non routine),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Housing Related Hazards (1480)-Hazard Controls-Carbon Monoxide,Housing Related Hazards (1480)-Hazard Controls-Fire Hazard(s),Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Eucrib Ontit-Site Work (1480)-Ence Painting,Dwelling Unit-Site Work (1480)-	1480 Unit Exterior stairwells, Unit Interior remodel to include flooring, cabinetry, fixtures, bathrooms, doors, HVAC, and painting. Site Work, update Carbon Monoxide detectors, and smoke alarms to meet NSPIRE standards		\$431,125.00			

Work Statement for Year 1

			ī	I
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000079	Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	Salary increases, Sundry, and other		\$75,000.00
ID0000092	Management Improvement(Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other, Management Improvement (1408)-Security Improvements (not police or guard-non-physical), Management Improvement (1408)-Staff Training, Management Improvement (1408)-System Improvements, Management Improvement (1408)-Empowerment Activities)	1408 - Management Improvement		\$25,000.00
	Subtotal of Estimated Cost			\$731,125.00

Part II: Supporting Pages - Physical Needs Work Statement
---

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	<b>Estimated Cost</b>
	CASA LOMA & ANTHONY BUCKNER (MO074000001)			\$731,125.00
ID0000080	Operations(Operations (1406))	PHA operating expenses		\$200,000.00
ID0000093	Management Improvement (Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other, Management Improvement (1408)-Security Improvements (not police or guard-non-physical), Management Improvement (1408)-Staff Training, Management Improvement (1408)-System Improvements)	1408 - Management Improvement		\$25,000.00
ID0000097	Dwelling Structures (Housing Related Hazards (1480)-Hazard Controls-Carbon Monoxide, Housing Related Hazards (1480)-Hazard Controls-Fire Hazard(s), Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Carports -Surface Garage, Dwelling Unit-Exterior (1480)-Columns and Porches, Dwelling Unit-Exterior (1480)-Decks and Patios, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Exterior Lighting, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking, Dwelling Unit-Exterior (1480)-Exterior (1480)-Landings and Railings, Dwelling Unit-Exterior (1480)-Goditers - Downspouts, Dwelling Unit-Exterior (1480)-Landings and Railings, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Windows, Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Commodes, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Curb and Gutter, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Pedestrian paving, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Pedestrian paving, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Sit	1480 Unit Exterior stairwells, Unit Interior remodel to include flooring, cabinetry, fixtures, bathrooms, doors, HVAC, and painting. Site Work, update Carbon Monoxide detectors, and smoke alarms to meet NSPIRE standards		\$431,125.00

Part II: Supporting Pages - Physical Needs Work Statements (s)  Work Statement for Year 2 2026					
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost	
	(1480)-Water Lines/Mains,Dwelling Unit-Exterior (1480)-Foundations)		<u> </u>		
ID0000101	Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	Salary increases, Sundry, and other		\$75,000.00	
	Subtotal of Estimated Cost			\$731,125.00	

Part II: Supporting Pages	- Physical Needs Work Statements (s)
---------------------------	--------------------------------------

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	<b>Estimated Cost</b>
	CASA LOMA & ANTHONY BUCKNER (MO074000001)			\$731,125.00
ID0000083	Operations(Operations (1406))	PHA operating expenses		\$200,000.00
ID0000094	Management Improvement (Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other, Management Improvement (1408)-Security Improvements (not police or guard-non-physical), Management Improvement (1408)-Staff Training, Management Improvement (1408)-System Improvements)	1408 - Management Improvement		\$25,000.00
ID0000100	Dwelling Structures(Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Signage, Dwelling Unit-Site Work (1480)-Storm Drainage, Dwelling Unit-Site Work (1480)-Siding, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes, Dwelling Unit-Exterior (1480)-Tuck-Pointing, Dwelling Unit-Exterior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Hazard Controls-Carbon Monoxide, Housing Related Hazards (1480)-Hazard Controls-Fire Hazard(s), Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Exterior (1480)-E	1480 Unit Exterior stairwells, Unit Interior remodel to include flooring, cabinetry, fixtures, bathrooms, doors, HVAC, and painting. Site Work, update Carbon Monoxide detectors, and smoke alarms to meet NSPIRE standards		\$431,125.00

Part II: Sup	Part II: Supporting Pages - Physical Needs Work Statements (s)					
Work Statement for Year 3 2027						
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost		
	Landings and Railings, Dwelling Unit-Exterior (1480)-Roofs)					
ID0000102	Administration(Administration (1410)-Salaries,Administration (1410)-Other,Administration (1410)-Sundry)	Salary increases, Sundry, and other		\$75,000.00		
	Subtotal of Estimated Cost			\$731,125.00		

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	<b>Estimated Cost</b>
	CASA LOMA & ANTHONY BUCKNER (MO074000001)			\$731,125.00
ID0000088	Operations(Operations (1406))	PHA operating expenses		\$200,000.00
ID0000095	Management Improvement(Management Improvement (1408)-Empowerment Activities, Management Improvement (1408)-Equal Opportunity, Management Improvement (1408)-Other, Management Improvement (1408)-Security Improvements (not police or guard-non-physical), Management Improvement (1408)-System Improvements)	1408 - Management Improvement		\$25,000.00
ID0000098	Dwelling Structures(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Dearking,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Housing Related Hazards (1480)-Hazard Controls-Carbon Monoxide,Housing Related Hazards (1480)-Hazard Controls-Fire Hazard(s),Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior (1480)-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-I	1480 Unit Exterior stairwells, Unit Interior remodel to include flooring, cabinetry, fixtures, bathrooms, doors, HVAC, and painting. Site Work, update Carbon Monoxide detectors, and smoke alarms to meet NSPIRE standards		\$431,125.00

Work Stater	ment for Year 4 2028			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	(1480)-Balconies-Porches-Railings-etc)	•	•	!
100000102	Administrative (Administrative (1410) Other Administrative (1410) Selector Administrative (1410)	Colonia and the salation		1 675 000 00
ID0000103	Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-Sundry)	Salary increases, Sundry, and other		\$75,000.00
ID0000103		Salary increases, Sundry, and other		\$75,000.00
ID0000103	Sundry)	Salary increases, Sundry, and other		
ID0000103		Salary increases, Sundry, and other		\$75,000.00 \$731,125.00

Part II: Supporting Pages	- Physical Needs	Work Statements	(s)
I alt II. Duppol ting I ages	- I Hysicai i iccus	William Statements	(3)

Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	<b>Estimated Cost</b>
	CASA LOMA & ANTHONY BUCKNER (MO074000001)			\$731,125.00
ID0000091	Operations(Operations (1406))	PHA operating expenses		\$200,000.00
ID0000096	Management Improvement(Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements,Management Improvement (1408)-Empowerment Activities,Management Improvement (1408)-Equal Opportunity,Management Improvement (1408)-Other,Management Improvement (1408)-Security Improvements (not police or guard-non-physical))	1408 - Management Improvement		\$25,000.00
ID0000099	Dwelling Structures(Dwelling Unit-Site Work (1480)-Curb and Gutter, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Fencing, Dwelling Unit-Site Work (1480)-Landscape, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Pedestrian paving, Dwelling Unit-Site Work (1480)-Palayground Areas - Equipment, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Signage, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Water Lines/Mains, Housing Related Hazards (1480)-Hazard Controls-Carbon Monoxide, Housing Related Hazards (1480)-Hazard Controls-Fire Hazard(s), Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc, Dwelling Unit-Exterior (1480)-Building Slab, Dwelling Unit-Exterior (1480)-Carports - Surface Garage, Dwelling Unit-Exterior (1480)-Columns and Porches, Dwelling Unit-Exterior (1480)-Decks and Patios, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Exterior Doors, Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape, Dwelling Unit-Exterior (1480)-Foundations, Dwelling Unit-Exterior (1480)-Gutters - Downspouts, Dwelling Unit-Exterior (1480)-Siding, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes, Dwelling Unit-Exterior (1480)-Soffits, Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes, Dwelling Unit-Interior (1480)-Appliances, Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks, Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical), Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Hinterior Cobinets, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Flooring, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Flooring, Dwelling Unit-Interior	1480 Unit Exterior stairwells, Unit Interior remodel to include flooring, cabinetry, fixtures, bathrooms, doors, HVAC, and painting. Site Work, update Carbon Monoxide detectors, and smoke alarms to meet NSPIRE standards		\$431,125.00

Work State	ment for Year 5 2029			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving)			-
	Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving)			
ID0000104	Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-	Salary increases, Sundry, and other	1	\$75,000.00
ID0000104		Salary increases, Sundry, and other		\$75,000.00
ID0000104	Administration(Administration (1410)-Other, Administration (1410)-Salaries, Administration (1410)-	Salary increases, Sundry, and other		\$75,000.00 \$731,125.00