

# ATTN: WOODWIND REPAIR

## HURK'S PLACE

553 VALLEY VIEW DRIVE

FONTANA, WI 53125

(262) 374-1688 Call or Text

PRICES ARE GOOD THROUGH DECEMBER 31, 2025

## FREE USA RETURN SHIPPING INCLUDED\*

<b>Tenon Replacement -</b>	Clarinet or Oboe	\$137.00	includes return UPS Ground shipping
<b>Tenon Replacement -</b>	Alto or Bass Clarinet	\$198.00	includes return UPS Ground shipping
<b>Tenon Replacement -</b>	Bassoon Wing Joint	\$198.00	includes return UPS Ground shipping
<b>Tenon Replacement -</b>	Bassoon Maple Bass Joint	\$264.00	includes return UPS Ground shipping
<b>Receiver Replacement -</b>	Clarinet or Oboe	\$274.00	includes return UPS Ground shipping
<b>Receiver Replacement -</b>	Alto or Bass Clarinet	\$349.00	includes return UPS Ground shipping
<b>Tone Hole Replacement -</b>		\$79.00	includes return UPS Ground shipping

**SHIPPING INSTRUCTIONS** – Include a letter stating the needed repair, the ship to address, and requested insurance amount. Free shipping includes \$100.00 insurance only. **We will not be responsible for uninsured packages.** Free shipping is **UPS ground** only.

\*Businesses in Hawaii will receive a \$9.00 repair discount, as shipping charges will apply even for UPS ground.

**It is not necessary to send the complete instrument in the case as long as you include the mating joint.**

**INSURANCE** - \$100.00 of insurance on your package is included. The following are some of the current UPS insurance rates during 2025 only:

300 - \$3.15	500 - \$5.25	700 - \$7.35	1,000 - \$10.50
1,500 - \$15.75	2,000 - \$21.00	2,500 - \$26.25	3,000 - \$31.50

**TO PREPAY** – Simply add the repair cost plus insurance and include a check or money order. We DO NOT ACCEPT CREDIT CARDS.

**CREDIT** – Approved Credit Application required for open account. Accounts are net 30 days, 1&1/2% per month.

**FIRST ORDER** – First order must be prepaid or C.O.D. The C.O.D. fee for 2025 is \$21.00.

**TAX WISCONSIN DEALERS** – A Wisconsin Sales and Use Tax Exemption Certificate must be completed to avoid any sales tax and will be kept on file.

**MATERIALS** – Receivers are made from ABS plastic. All tenons are made from ABS plastic except bassoon bass joint tenons which are made from solid maple.

WE HAVE BEEN PROVIDING TENON, RECEIVER, AND TONE HOLE REPLACEMENTS FOR OVER 37 YEARS. HAVING PRODUCED THOUSANDS OF REPAIRS, YOU CAN BE ASSURED IN THE QUALITY OF OUR WORKMANSHIP.

AT HURK'S PLACE, PRIDE IS TAKEN IN THE CUSTOM MACHINING DONE TO PRODUCE THE ACCURATE PLACEMENT OF RECEIVER POSTS AND THE EXACT FIT OF TENONS. EVERY REPAIR IS MACHINED FROM RAW MATERIAL TO CLOSE TOLERANCES TO MATCH THE MATING TENON OR RECEIVER. NO PRE-MADE TENON REPLACEMENTS ARE USED. TENONS ARE CORKED AND PRECISION MACHINE GROUND TO SIZE.

**WE THANK YOU FOR YOUR BUSINESS!**  
**THE HURKMAN FAMILY**