



W [CLT:1] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
PR1	1	6	6
PR2	1	1	1
PR3	1	1	1
PR4	1	4	4
PR5	1	1	1
PR6	1	1	1
GRAND TOTAL:			14



IPE180

14 NO.REQUIRED AS DRAWN MARKED- CLT1


W [CLT.2] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
PR1	1	6	6
PR2	1	1	1
PR3	1	1	1
PR4	1	4	4
PR5	1	1	1
PR6	1	1	1
GRAND TOTAL:			14



IPE180

14 NO.REQUIRED AS DRAWN MARKED- CLT2


W [CLT.26] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
PR1	3	6	18
PR2	3	1	3
PR3	3	1	3
PR4	3	4	12
PR5	3	1	3
PR6	3	1	3
GRAND TOTAL:			42



135X30X4-CFA


42 NO.REQUIRED AS DRAWN MARKED- CLT26

W [PLT.7] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
PR1	1	6	6
PR2	1	1	1
PR3	1	1	1
PR4	1	4	4
PR5	1	1	1
PR6	1	1	1
GRAND TOTAL:			14



PLT10X130

14 NO.REQUIRED AS DRAWN MARKED- PLT7




PLT12X300

14 NO.REQUIRED AS DRAWN MARKED- PLT8

W [PLT.8] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
C1	1	1	1
C2	1	1	1
C3	1	1	1
C4	1	1	1
C5	1	1	1
C6	1	2	2
C7	1	2	2
C8	1	1	1
C9	1	1	1
C10	1	2	2
C11	1	1	1
GRAND TOTAL:			14


W [PLT.9] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
GC1	1	1	1
GC2	1	1	1
GRAND TOTAL:			2



PLT12X300

2 NO.REQUIRED AS DRAWN MARKED- PLT9

W [PLT.21] ALLOCATION TO ASSEMBLIES			
ASSEMBLY MARK	NO. IN ONE ASSEMBLY	NO. OF. ASSEMBLIES	TOTAL REQ'D
PR1	1	6	6
PR2	1	1	1
PR3	1	1	1
PR4	1	4	4
PR5	1	1	1
PR6	1	1	1
GRAND TOTAL:			14



PLT10X130

14 NO.REQUIRED AS DRAWN MARKED- PLT21