Inspection Report

Provided by:

Home Inspectors Pro (424) 281-6940

sample report

Property Address:

767 Fairmont Ave. Glendale, CA 91203



Table Of Contents:

Section name.	Section number.
Report Information	
Exterior	4
Foundation - Crawl Space	5
Grounds	6
Heating & Cooling	7
Plumbing	8
Electrical	9
Kitchen	10
Interior - Living Room	11
Interior - Dinning Room	12
Interior - Bedroom 1	13
	14
Garage - Laundry	17

1 Report Information

Client Information

Client Name

Client Phone

Client Email n

Agent Information

Agent Name

Agent Phone

Property Information

Property Type

Stories

Approximate Year

Built

Approximate Square

Footage

Number of Bedroom

Number of Bath

Direction House Faces

Furnished

Occupied

Utilites on During

Inspection

People Present

Inspection Information

Inspection Date

Inspection Time

Weather Conditions

Outside Temperature

Price for Inspection

WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

Exterior:

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water

penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible) (as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

OUTSIDE THE SCOPE OF THE INSPECTION

- -Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection.
- -The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;
- Building code or zoning ordinance violations Thermostatic or time clock controls or Low Voltage wiring systems Geological stability or soils conditions Water softener or water purifier systems or solar heating systems Structural stability or engineering analysis Saunas, steam baths, or fixtures and equipment Building value appraisal or cost estimates Pools or spa bodies or sprinkler systems and underground piping Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters Furnace heat exchanger, freestanding appliances, security alarms or personal property Specific components noted as being excluded on the individual system inspection form Adequacy or efficiency of any system or component Prediction of life expectancy of any item.
- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

Definition of conditions:

- AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.
- R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.
- S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

		2 Report Summary Page		
This is only a summary of the inspection report and is not a complete list of discrepancies.				
Section	Condition#	Comment		
Roofing	1	The roof covering showed signs of cracking, curling, and loss of granules. This condition generally indicates that the roofing materials are approaching or close to the end of their useful life. Although immediate replacement may not appear necessary at this time, we recommend maintenance be performed on a regular basis with annual inspection by a qualified roofing contractor. The inspector cannot offer an opinion as to whether the roof leaks today unless it is moderately raining at the time of inspection.		
Roofing	2	The gutters were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis.		
Exterior	8	The paint / finish of the Stucco was deteriorated and is in need of repair, replacement and / or maintenance.		
Exterior	9	A few of the window Stools had dry rot damage. It is suggested that a "Licensed General Contractor" be contacted for further evaluation and repair.		
Foundation - Crawl Space	14	Evidence of rodents were observed. While this observation may exist now, the occurrence may have been some time ago. Client should contact a pest control company for further evaluation.		
Grounds	19	The Vegitation on the property needs to be trimmed to prevent damage to the house. It is suggested that a "Licensed Landscaping Contractor" be contacted for further evaluation and repair.		
Heating & Cooling	21	The heating system was operational at time of inspection. This is not an indication of future operation or condition. The air filter was dirty. Suggest replacing as soon as possible. To increase the efficiency of your heating system, we recommend changing your systems fir filter(s) regularly (every 2-3 months).		
Electrical	36	A few of the outlets externally were loose. Recommend have it replaced or repaired. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.		
Kitchen	42	Loose / damaged outlet was observed at kitchen. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.		
Kitchen	45	The kitchen Cabinet door hinges were loose. Recommend to have		

		them repaired or replaced.
		Cabinet drawers and or drawer guides need adjustment or repair.
		It is suggested that a "Licensed General Contractor" be contacted for
	+	further evaluation and repair.
Interior - Dinning Room	66	1 out of the 4 lights in the bedroom was out. Recommend having it replaced by a licensed Electrician.
Interior - Bedroom 1	73	Loose / damaged outlet was observed at bedroom. Three pronged outlets did not test for proper ground at bedroom. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.
Interior - Bedroom 1	75	A smoke detector was missing or removed at the Bedroom. Recommend having one installed.
Interior - Bedroom 2	81	Missing receptacle or switch covers were observed at. Recommend covers be installed for safety.
Interior - Bedroom 2	82	1 out of the 4 lights in the bedroom was out. Recommend having it replaced by a licensed Electrician.
Interior - Bedroom 2	83	A smoke detector was missing or removed at the bedroom. Recommend to have one installed.
Bathroom 1	91	The exhaust fan made an unusual noise / vibration in bath
Bathroom 1	94	There were multiple tiles that were damaged on the shower wall. Recommend having them replaced.
Bathroom 2	106	When the water was diverted from the tub spout to the shower head, some water was still running from the spout in bath. Adjustment or repair may be needed to the diverter faucet or tub spout. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.
Garage - Laundry	108	The paint / finish of the Stucco was deteriorated and is in need of repair, replacement and / or maintenance.
Garage - Laundry	109	The roof covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection. The gutters were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis.
Garage - Laundry	114	The hinge on the door was loose. recommend having it repaired.
Garage - Laundry	115	The vehicle door motor chain was disconnected.

3 Roofing

Roof Covering

Method of Inspection The roof was inspected by walking the safe and accessible areas.

Roof Style Gable and Flat

Roof Covering

Material


Number of Layers

1) Roof Covering Condition

Asphalt composition shingles. and Rolled roofing

Not Inspected

The roof covering showed signs of cracking, curling, and loss of granules. This condition generally indicates that the roofing materials are approaching or close to the end of their useful life. Although immediate replacement may not appear necessary at this time, we recommend maintenance be performed on a regular basis with annual inspection by a qualified roofing contractor. The inspector cannot offer an opinion as to whether the roof leaks today unless it is moderately raining at the time of inspection.









water stain, rolled roof has cracks.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected





Shingles are curling



2) Gutter & Downspout Conditions



The gutters were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis.



Debris in the gutters

3) Vent Stacks



The Vent Stacks appeared to be in serviceable condition at the time of

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

inspection.









Attic Area

Attic Access Master Bedroom closet

Method of Inspection The attic was inspected by partially entering due to blocked access small attic

space.

Roof Frame Type The roof framing is constructed with truss framing.

4) Attic Conditions

The visible and accessible portions of the attic appeared to be in serviceable condition at the time of the inspection.



Attic Ventilation Type

Gable Vents

Attic Ventilation Conditions

The Attic Ventilation appeared to be in serviceable condition at the time of inspection.

Attic Insulation Type

Batt Insulation

5) Attic Insulation Conditions

AS

The attic has fiberglass batt insulation. The approximate depth of the insulation is 8 to 10 inches. This appears adequate.



4 Exterior

Front - Back Entrance

Front Entrance Type

Covered Porch

6) Front Entrance Conditions



Common settlement type cracks were observed to the porch.





Cracks.

Back Entrance Type

Patio

7) Back Entrance Conditions

AS

The visible portions of the patio appeared to be in serviceable condition at the time of the inspection.



Exterior Walls

Structure Type

Wood frame

Exterior Wall Covering

The visible and accessible areas of the exterior siding material are stucco.

8) Exterior Wall Conditions




The paint / finish of the Stucco was deteriorated and is in need of repair, replacement and / or maintenance.


AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected















Exterior Windows - Doors


Window Type Double Hung

Window Material Vinyl

9) Window Conditions




A few of the window Stools had dry rot damage. It is suggested that a "Licensed General Contractor" be contacted for further evaluation and repair.





dry rot damage

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



10) Exterior Door Conditions



The door(s) appeared to be in serviceable condition at the time of the inspection.



Exterior Water Faucet(s)

Faucet Location

exterior


11) Faucet Conditions



The hose faucets appeared to be in serviceable condition at the time of the inspection. These should be drained prior to freezing temperatures.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected





5 Foundation - Crawl Space

Foundation

Crawl Space **Foundation Type**

Foundation Material Concrete

12) Foundation **Conditions**



The Foundation appeared to be in serviceable condition at the time of inspection.





Flooring Structure

Flooring Support Type

The wood framing floor system was constructed of 2 X 8 floor joists.

13) Flooring Support **Conditions**



The visible and accessible areas of the wood framing system appeared to be in serviceable condition at the time of the inspection.



Crawl Space

Inspection Method

Entered Crawl Space

14) Description



Evidence of rodents were observed. While this observation may exist now, the occurrence may have been some time ago. Client should

contact a pest control company for further evaluation.







6 Grounds

Grading

Grading Slope The site is moderately sloped.

15) Grading Conditions

AS

Grading of the soil near the foundation appears to be in serviceable

Driveways - Sidewalks - Walkways


Driveway Material

Concrete

16) Driveway Conditions



Common cracks were observed in the driveway.





common cracks

Sidewalk Material

Concrete

17) Sidewalk Conditions

AS

The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection.



Retaining Wall

Retaining Wall Material Block

18) Retaining Wall Conditions



The visible and accessible portions of the retaining walls appeared to be in serviceable condition at the time of the inspection.



Vegetation

19) Description



The Vegitation on the property needs to be trimmed to prevent damage to the house. It is suggested that a "Licensed Landscaping Contractor" be contacted for further evaluation and repair.







Fencing - Gates

20) Fencing - Gate Condition



The Fencing and or Gates on the property appeared to be in serviceable condition at the time of inspection.



7 Heating & Cooling

Heating

Location of Unit Attic

Heating Type Not Inspected

Energy Source Not Inspected

Approximate BTU

Rating

Not Inspected

21) Unit Conditions

The heating system was operational at time of inspection. This is not an indication of future operation or condition.

The air filter was dirty. Suggest replacing as soon as possible. To increase the efficiency of your heating system, we recommend changing your systems fir filter(s) regularly (every 2-3 months).





Dirty Filter

Distribution Type

The visible areas of the heat distribution system is piping with radiators.

22) Distribution Conditions

AS

The visible and accessible areas of the distribution system appeared to be in serviceable condition at the time of inspection.

23) Ventilation Conditions

AS

The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.

24) Thermostat Condition

AS

The normal operating controls appeared to be serviceable at the time of the inspection.

Air Condition - Cooling

Type of Cooling System

Split system

AC Unit Power

240V

25) AC Unit Conditions

AS

The A/C unit appeared to be in serviceable condition at the time of inspection. This is not an indication of future operation or condition.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected







8 Plumbing

Water Main Line

Main Shutoff Location

exterior

Main Line Material

Not Inspected

26) Main Line & Valve Conditions

AS

The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.

Water Supply Lines

Supply Line Material

The visible material used for the supply lines is copper.

27) Supply Line Conditions



The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection. All of the supply lines were not fully visible or accessible at the time of the inspection.





Drain - Waste Lines

Drain Line Material

The visible portions of the waste lines are cast iron. and The visible portions of the waste lines are plastic.

28) Drain Line Conditions



The visible portions of the waste lines appeared to be in serviceable condition at the time of inspection. All of the waste lines were not fully visible or accessible at the time of the inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected







Water Heater(s)

Water Heater Type Natural Gas

Water Heater Location exterior

Water Heater Capacity 38 Gallon

29) Water Heater

Conditions



The water heater was operable at the time of inspection. This does not however guarantee future performance, operation, or condition.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected






Gas Main Line

30) Gas Meter Condition



The Gas Meter appeared to be in serviceable condition at the time of inspection.



9 Electrical

Service Drop - Weatherhead

Electrical Service Type The electrical service is overhead.

Electrical Service

Not Inspected


Material

Number of Conductors Three

31) Electrical Service Conditions

AS

The main service entry appeared to be in serviceable condition at the time of inspection.



Main Electrical Panel

Main Disconnect At Main Panel

Location

Electric Panel Location The main electric panel is located at the exterior.

Panel Amperage Rating The electrical capacity of main breaker was listed / labeled as 200 amps.

Circuit Protection Type Breakers

32) Wiring Methods

The main power cable and branch circuit wire types could be determined. See also main panel comments.

33) Electrical Panel
Conditions

The main panel appeared to be in serviceable condition at the time of the inspection.





Electrical Subpanel

Subpanel Location n/a

34) Subpanel NI n/a Conditions

Carbon Monoxide Detectors

35) Carbon Monoxide Detectors Condition

AS

The Carbon Monoxide Detector in the living room appeared to be in serviceable condition at the time of inspection.



Exterior Electrical

36) Exterior Electrical Condition



A few of the outlets externally were loose. Recommend have it replaced or repaired. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.







Loose

10 Kitchen

Walls - Ceilings - Floors

37) Wall Conditions




The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



38) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



39) Floor Conditions




The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

AS



Windows - Doors

40) Kitchen Window Conditions





41) Kitchen Door Conditions

AS

The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

42) Electrical Conditions



Loose / damaged outlet was observed at kitchen. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected






Loose,

43) Lighting Conditions

The Lighting in the Kitchen appeared to be in serviceable condition at the time of inspection.



AS

AS

Kitchen Sink - Counter tops - Cabinets

44) Counter Conditions

The visible portion kitchen counters appeared to be in serviceable condition at the time of the inspection.



45) Cabinet Conditions

The kitchen Cabinet door hinges were loose. Recommend to have them repaired or replaced.

Cabinet drawers and or drawer guides need adjustment or repair. It is suggested that a "Licensed General Contractor" be contacted for further evaluation and repair.



Hinge was loose











Hinge was loose.

The kitchen sink appeared to be in serviceable condition at the time of the inspection. The faucet appeared to be in serviceable condition at the time of the inspection. The visible areas of the plumbing under the kitchen sink appeared to be in serviceable condition at the time of the inspection.



47) Garbage Disposal Condition



AS

The sink disposal was operable at the time of the inspection. Client should consult a licensed plumber, manufacturer, or disposal supply company for information on proper usage and safety related concerns.



Appliances

48) Stove - Range Condition



Not Inspected



49) Hood Fan Conditions

NI

n/a

50) Dishwasher Conditions

AS

Not Inspected

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



51) Refrigerator Condition



Not Inspected



11 Interior - Living Room

Walls - Ceilings - Floors

52) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



53) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



54) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



Windows - Doors

55) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.





56) Interior Door Conditions

AS

The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

57) Electrical Conditions

AS

- The Electrical in the Living Room appeared to be in serviceable condition at the time of inspection.
- 58) Lighting Conditions
- The Lighting in the Living Room appeared to be in serviceable condition at the time of inspection.




59) Smoke Detector Conditions

Not Inspected

12 Interior - Dinning Room

Walls - Ceilings - Floors

60) Wall Conditions





61) Ceiling Conditions

The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



AS

62) Floor Conditions

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. Furnishings and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk-through, including, but not limited to, any staining, floor sloping, squeaking / movement or adverse conditions that may not have been visible or accessible during the time of original inspection. Such conditions should be brought to the attention of your Realtor (if applicable) or Attorney prior to closing of this property.



Windows - Doors

- 63) Interior Window Conditions
- AS The sample of windows tested were operational at the time of the inspection.
- **64) Interior Door Conditions**
- The interior doors appeared to be in serviceable condition at the time of the inspection.



Electrical Conditions

- 65) Electrical Conditions
- The Electrical in the Dinning Room appeared to be in serviceable condition at the time of inspection.
- **66) Lighting Conditions**
- 1 out of the 4 lights in the bedroom was out. Recommend having it replaced by a licensed Electrician.



light was out.

67) Smoke Detector Conditions

Not Inspected

NI

13 Interior - Bedroom 1

Walls - Ceilings - Floors

68) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.

Furnishings, pictures, wall coverings, and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk through. Client is advised to note any staining or conditions that may not have been visible during the time of inspection. Such conditions should be brought to your Realtor (if applicable) or Attorney's attention prior to closing of this property.



69) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



70) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

Furnishings and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk-through, including, but not limited to, any staining, floor sloping, squeaking / movement or adverse conditions that may not have been visible or accessible during the time of original inspection. Such conditions should be brought to the attention of your Realtor (if applicable) or Attorney prior to closing of this property.



Windows - Doors

71) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.



72) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

73) Electrical **Conditions**

Loose / damaged outlet was observed at bedroom. Three pronged outlets did not test for proper ground at bedroom. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.



Loose outlet.

Open Ground.

74) Lighting Conditions

The Lighting in the Bedroom appeared to be in serviceable condition at AS the time of inspection.



75) Smoke Detector **Conditions**

A smoke detector was missing or removed at the Bedroom. Recommend having one installed.

14 Interior - Bedroom 2

Walls - Ceilings - Floors

76) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.


Furnishings, pictures, wall coverings, and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk through. Client is advised to note any staining or conditions that may not have been visible during the time of inspection. Such conditions should be brought to your Realtor (if applicable) or Attorney's attention prior to closing of this property.



77) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.




78) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

Furnishings and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk-through, including, but not limited to, any staining, floor sloping, squeaking / movement or adverse conditions that may not have been visible or accessible during the time of original inspection. Such conditions should be brought to the attention of your Realtor (if applicable) or Attorney prior to closing of this property.



Windows - Doors

79) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.






80) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

- 81) Electrical Conditions
- Missing receptacle or switch covers were observed at. Recommend covers be installed for safety.



Needs cover

- 82) Lighting Conditions
- 1 out of the 4 lights in the bedroom was out. Recommend having it replaced by a licensed Electrician.



Light was out.

- 83) Smoke Detector Conditions
- A smoke detector was missing or removed at the bedroom. Recommend to have one installed.

15 Bathroom 1

Walls - Ceilings - Floors

84) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



85) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



86) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



Windows - Doors

87) Bathroom Window Conditions



The sample of windows tested were operational at the time of the inspection.



- 88) Bathroom Door Conditions
- AS
- The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions


- 89) Electrical Conditions
- AS
- The Electrical in the Bathroom appeared to be in serviceable condition at the time of inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



90) Lighting Conditions

The Lighting in the Bathroom appeared to be in serviceable condition at the time of inspection.



91) Vent Fan Conditions

The exhaust fan made an unusual noise / vibration in bath



Vent was loud

Bathroom Sink

92) Counter - Cabinet Conditions



The Counter / Cabinet in the Bathroom appeared to be in serviceable condition at the time of inspection.



93) Sink Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath



Shower - Tub - Toilet

94) Shower - Tub Conditions



There were multiple tiles that were damaged on the shower wall. Recommend having them replaced.





Tile Damaged.

95) Toilet Conditions




The toilet appeared to be in serviceable condition at the time of inspection in bath



16 Bathroom 2

Walls - Ceilings - Floors

96) Wall Conditions





97) Ceiling Conditions

AS The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



AS


98) Floor Conditions

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.



Windows - Doors

99) Bathroom Window Conditions





100) Bathroom Door Conditions

AS

The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

101) Electrical Conditions



The Electrical in the Bathroom appeared to be in serviceable condition at the time of inspection.



102) Lighting Conditions

The Lighting in the Bathroom appeared to be in serviceable condition at the time of inspection.



AS

103) Vent Fan Conditions

The Vent Fan in the Bathroom appeared to be in serviceable condition at the time of inspection.




Bathroom Sink

104) Counter - Cabinet Conditions



The Counter / Cabinet in the Bathroom appeared to be in serviceable condition at the time of inspection.



105) Sink Conditions




The sink appeared to be in serviceable condition at the time of inspection in bath



Shower - Tub - Toilet

106) Shower - Tub Conditions







Diverter valve leaking.

107) Toilet Conditions

The toilet appeared to be in serviceable condition at the time of inspection in bath



17 Garage - Laundry

Walls - Ceilings - Floors

Garage Type

The garage has been converted to living space. Client is advised to obtain permit information from township.

108) Siding Conditions (if detached)



The paint / finish of the Stucco was deteriorated and is in need of repair, replacement and / or maintenance.



109) Roof Conditions (if detached)



The roof covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection.

The gutters were filled with leaves and debris at the time of the inspection. Suggest cleaning and removal of debris on a regular basis.





Gutter filled with debris.

110) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.

Personal belongings and / or shelving prevented a full inspection of the entire wall. Moving or disturbing homeowner personal property is outside the scope of our inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



111) Ceiling Conditions

The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



AS

AS

112) Floor Conditions

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection. Furnishings and personal item storage prevented a full visual inspection of all areas. Conditions can change between the time of inspection and closing. Client is advised to perform a careful check of all areas during final walk-through, including, but not limited to, any staining, floor sloping, squeaking / movement or adverse conditions that may not have been visible or accessible during the time of original inspection. Such conditions should be brought to the attention of your Realtor (if applicable) or Attorney prior to closing of this property.

113) Window Conditions

The sample of windows tested were operational at the time of the inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



114) Door Conditions

R The hinge on the door was loose. recommend having it repaired.






Hinge is loose.

115) Vehicle Door Conditions

R The vehicle door motor chain was disconnected.





Disconnected

Mechanical Opener

yes

116) Electrical Conditions


AS

The Electrical in the Garage appeared to be in serviceable condition at the time of inspection.

117) Lighting Conditions

AS

The Lighting in the Garage appeared to be in serviceable condition at the time of inspection.



Laundry Room

Location

Hallway

118) Laundry Room Conditions



The visible and accessible portions of the laundry plumbing components appeared to be in serviceable condition at the time of inspection.

One Stop Home Inspections

