

mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MT-Propeller Warranty Policy

Dear Customer,

Congratulations on the purchase of your new MT-Propeller. Engineered with the customer in mind, it is designed to provide years of reliable and trouble-free service.

Scheduled maintenance or servicing of your MT-propeller should be accomplished at your nearest **MT-Propeller Approved Service Station**.

For location of the MT-Propeller Approved Service Station nearest you, please call us and ask for Produkt Support.

NOTE

Having work performed at a facility other than a MT-Propeller Approved Service Station may void your warranty.

USE OF LOGBOOK

Owner Name _____

Address _____

Propeller Model MTV-12-B

Blade Model 183-59B

Hub Serial No. 230309

Blade Serial No. 1 A0B-98255

2 A0B-98256

3 A0B-98257

4 ~~_____~~

5 ~~_____~~

6 ~~_____~~

Propeller Diameter: 183 cm ± 0.5 cm

Low Pitch: 10 ° ± 0.2 ° TCI: 72 Month


High Pitch: 35 ° ± 1 ° TBO: 1800 Hrs.

Feathering: / ° ± / °



Reverse: / ° ± / °

at radius station: 68.5 cm

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
May 11 2023	00:00	/	Manufactured	
<p>MT-Propeller USA, Inc. 1180 Airport Terminal Drive, DeLand, FL 32724 FAA Approved Repair Station Q4MR908Y Phone: (386) 736-7762 Fax: (386) 736-7696 E-mail: info@mt-propellerusa.com</p>				
<p>Propeller Model: MTV-12-B/183-59b S/N: 230309</p>				
<p>Propeller TSN: 0.0 hrs. Propeller is NEW</p>				
<p>Assembled propeller in accordance with W/O: 23-362MT and overhaul manual E-220, Revision 69, dated April 14, 2023.</p>				
<p>Blade S/N: 1) AOB-98255 2) AOB-98256 3) AOB-98257</p>				
<p>Year of manufacture: 2023</p>				
<p>I certify this propeller has been assembled and inspected, and determined to be in airworthy condition at this time. Return to service this date, July 13, 2023</p>				
<p>Juergen Zahner, Inspector, Q4MR908Y <u>Zahner</u></p>				
N				11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Time since Overhaul			
Model MTV-12-B		Date: 11/20/2023		
Registration N405ST		Tach: 365.48		
S/N 230309		TSN: -0-		
1. INSTALLED NEW PROPELLER ON AIRCRAFT N405ST AS PER A/C M/M. OPS CHECK AND LEAK CHECK NORMAL.				
				
DANIEL ESTEBAN POSADA AP3775575IA				

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY



Authorized Signatures
ation
ers

Model MTV-12-B

Date: 02/08/2024

Registration N405ST

Tach: 371.96

S/N 230309

TSN: 6.48

1. PERFORMED ANNUAL INSPECTION AS PER FAR 43 APPENDIX D CHECKLIST.
2. VERIFIED AD'S AS PER TRITON AVIATION DATA ON FEBRUARY 8TH, 2024.

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION CHECKLIST AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION

DANIEL ESTEBAN POSADA

A handwritten signature in black ink, appearing to read "D. Posada", written over a grid background.

AP3775575IA

NOTE: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11 & 12

MT-Propeller Entwicklung GmbH

Flugplatzstraße 1

D-94348 Atting, Germany

Tel.: +49-(0)9429-9409-0

Fax: +49-(0)9429-8432

E-mail: sales@mt-propeller.com

Internet: www.mt-propeller.com

MT-Propeller USA, Inc.

1180 Airport Terminal Drive

DeLand, FL 32724

USA

Tel.: (386) 736-7762

Fax: (386) 736-7696

E-mail: info@mt-propellerusa.com

Internet: www.mt-propellerusa.com