

Gulfstream American Corp. Model: AA-5B N4554E S/N: AA5B1209 Page 1 of 5

SB	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
MSB505	12/1/1997	Inspection of Crankshaft ID for corrosion.	N	N/A by Engine Model (O-360-A4K)	N/A
SB-194	8/1/2011	Dry Control Column Bearings	N	N/A by Model. (AG-5B)	N/A
SB-193	11/5/2010	Aft Wing Spar Inspection	N	N/A by Model. (AG-5B)	N/A
SB-192	8/20/2009	Aft Fuselage (Bulkhead) Inspection	Y	C/W by inspection IAW the procedures outlined in CSB. (SAIB CE-09-37)	1/8/2021
SB-191	4/1/2005	Rear Seat Belt Attach Bracket	N	N/A by Model. (AG-5B)	N/A
SB-190	3/1/2005	Throttle Cables	N	N/A by Model. (AG-5B)	N/A
SB-189	9/16/2002	Missing Rivets	N	N/A by Model. (AG-5B)	N/A
SB-188	12/15/1999	Ruptured Instrument Pressure Lines	Y	CW by inspection of oil and fuel pressure lines from under the instrument panel. No corrosion observed.	1/8/2021
SB-187	11/6/1997	Engine Oil Breather Blockage	Y	CW by inspection. N/A by affected hose type not installed onto breather system.	1/8/2021
SB-186	5/10/1995	Interior Parts Corrosion	N	N/A by Model. (AG-5B)	N/A
SB-185	7/6/1994	Wing Attach Shoulder Bolts	Y	C/W by compliance with AD 95-19-15.	6/14/1997
SB-184	7/10/1993	Aileron Control Interference	N	N/A by Model. (AG-5B)	N/A
SB-183	6/29/1993	Parker Wheel Brake Master Cylinders	N	N/A by Model. (AG-5B)	N/A
SB-182	3/10/1993	ARTEX ELT	N	N/A by Model. (AG-5B)	N/A
SB-181	11/18/1992	Fuel System Contamination	N	N/A by Model. (AG-5B)	N/A
SB-180	11/28/1992	Fuel System Inspection	N	N/A by Model. (AG-5B)	N/A
SB-179	9/25/1992	Flap Torque Tube Bearing Inspection	Y	Inspected IAW the inspection criteria. Correct installation of torque tube bearings observed.	1/8/2021
SB-178A	7/30/1993	Inspection of Nose Landing Gear Tubes	N	N/A by Model. (AG-5B)	N/A

Gulfstream American Corp. Model: AA-5B N4554E S/N: AA5B1209 Page 2 of 5

SB	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
SB-177	9/11/1991	Inspection of Aileron Torque Tubes	Y	C/W by inspection of aileron torque tubes IAW inspection criteria & work performed during compliance with AD 79-22-04.	1/8/2021
SB-176	4/5/1991	Alternator Light Circuit Modification	N	N/A by Model. (AG-5B)	N/A
GA SB176	7/26/1989	Integral Fuel Tanks Inspect for deterioration	Y	Aircraft not equipped with SK140A	N/A
SB-175	6/26/1987	Inspection of Carburetor Inlet Duct	N	N/A by Model. (AA-5, AA-5A)	N/A
SB-174	6/26/1987	Inspection of Carburetor Butterfly Valve	N	N/A by Model. (AA-1 Series)	N/A
SB-173	3/11/1985	Seat Belt Attachment Bracket Replacement	N	N/A by Model. (AA-1 Series)	N/A
SB-171	6/3/1981	Voltage Regulator Replacement	Y	N/A by affected VR not currently installed.	1/8/2021
SB-170	7/23/1981	Air Filter Retention Screen	N	N/A By Model (AA-5, AA-5A)	N/A
SB-169	3/18/1980	Outboard Elevator Drain Holes	Y	C/W by addition of drain holes.	7/8/1981
SB-168	1/29/1980	Aileron Torque Tube Joint Inspection	Y	N/A. Service Kit 150 Not currently installed.	N/A
SB-167C	5/12/1983	McCauley Propeller Hub Inspection	Y	Applicable under AD 82-27-01. C/W By compliance with AD @ 1489.0 Next Due 1689.0	10-1-2012
SB-166	10/1/1979	Seat Belt Replacement	N	N/A by Serial Number. (AD 79-16-02)	N/A
SB-165A	11/9/1979	Aileron Inspection or Modification	N	N?A by Serial Number. Aircraft not modified with SK150.	N/A
SB-164	6/1/1979	Rockwell Collins Audio Panels	N	N/A. Aircraft not equipped with Rockwell Collins AMR-350 Audio Panel	N/A
SB-163	None	Aileron Torque Tube Inspection and Modification	N	N/A B Serial Number.	N/A

Gulfstream American Corp. Model: AA-5B N4554E S/N: AA5B1209 Page 3 of 5

SB	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
SB-162	2/28/1979	Removal of Canopy Cable System	N	N/A By Model (AA-1B/C)	N/A
SB-161	5/24/1977	Narco ELT-10	Y	Inspected IAW AD 77-02-08. No corrosion found. Tested IAW FAR 91.207.	1/8/2021
SB-160	3/21/1977	Alternate Static Valve Inspection	N	N/A by Serial Number	N/A
SB-156	10/11/1976	Oil Cooler Replacement	N	N/A by aircraft S/N. N/A by Oil Cooler S/N.	N/A
SB-155A	7/30/1976	Bond-line Protection	N	N/A By Serial Number.	N/A
SB-154	4/9/1976	Fuel Line Inspection	N	N/A by Serial Number	N/A
SB-153	2/2/1976	Spar/Skin Spacer Removal	N	N/A by Serial Number	N/A
SB-152A	1/22/1976	Upper Cowling Hinge Replacement	N	N/A by Serial Number	N/A
SB-151	10/23/1975	Center Spar Console Inspection	N	N/A by Serial Number	N/A
SB-150A	1/12/1976	Carburetor Mixture Control	N	N/A by Serial Number.	N/A
SB-149	3/3/1975	Nose Gear Strut Inspection	N	N/A by Serial Number	N/A
SB-147	2/8/1975	Rudder Control Bar Inspection	N	N/A by delivery date. (AD75-07-04)	N/A
SB-148	2/25/1975	Air Filter	N	N/A by Serial Number	N/A
SB-146	2/5/1975	Firewall Rivet Installation	N	N/A by Model.	N/A
SB-145	1/29/1975	Upper Engine Mount Bolt Insp.	N	N/A by Serial Number.	N/A
SB-144A	3/12/1975	Mixture Control	N	N/A by Model (AA-1)	N/A
SB-143	12/5/1974	United Altimeter	N	N/A by Model. (AA1 &AA-5)	N/A
SB-142	6/20/1974	Throttle Cable	N	N/A by Model (AA-1 & AA-5)	N/A
SB-141	1/15/1974	Left Magneto P Lead	N	N/A by Model (AA1B & AA5)	N/A
SB-140	12/14/1973	ELT Antenna Rivet Change	N	N/A by Model. (AA-1A, AA1B, AA5)	N/A
SB139	12/5/1973	Master Cylinder Inspection	N	N/A By Model. (AA1 &AA5)	N/A
SB-138	6/7/1973	Placard Installations	N	N/A by Model (AA1, AA1A, AA1B)	N/A

Gulfstream American Corp. Model: AA-5B N4554E S/N: AA5B1209 Page 4 of 5

SB	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
SB-137A	6/22/1973	Engine Mount Inspection	N	N/A by Serial Number.	N/A
SB-136	2/20/1973	Elevator Trim Tab Inspection	N	N/A by Serial Number	N/A
SB-135	2/20/1973	Carburetor Air Box	N	N/A by Serial Number	N/A
SB-134	12/21/1972	Headliner Inspection	N	N/A by Serial Number	N/A
SB-133	10/16/1972	Fuel Pressure Lines Inspection	N	N/A by Model.	N/A
SB-132	9/19/1972	Additional Aileron Drain Holes	N	N/A by Model	N/A
SB-131	5/3/1972	Rudder System Spring Replacement	N	N/A by Model.	N/A
SB-130	3/8/1972	Flap Motor / Right Rudder Cable Clearance Inspection	N	N/A by Model.	N/A
SB-129	3/29/1972	Front Seat Improvement	N	N/A by Model.	N/A
SB-128	2/23/1972	Fuel Tank Vent Line Inspection	N	N/A by Model.	N/A
SB-127A	7/19/1974	Control Cable Inspection	N	N/A by Model.	N/A
SB-126	1/18/1972	Control Surface Bearing Support	N	N/A by Model (AA-1A)	N/A
SB-125	11/9/1971	Weight & Balance Data Sheet Correction	N	N/A by Model. (AA1A)	N/A
SB-124	9/3/1971	Modification of Radio Support	N	N/A by Model.	N/A
SB-123	2/24/1971	Carburetor Inspection	N	N/A by Model.	N/A
SB-121	1/4/1971	Nose Gear Strut Inspection	N	N/A by Model.	N/A
SB-120	10/7/1970	Throttle Cable Inspection	N	N/A by Model.	N/A
SB-119	9/18/1970	Spinner Back Plate Inspection	N	N/A by Model.	N/A
SB-118	7/28/1970	Oil Pressure Line Inspection	N	N/A by Model.	N/A
SB-117	5/11/1970	Paint Removers	N	N/A by Model.	N/A

Gulfstream American Corp. Model: AA-5B N4554E S/N: AA5B1209 Page 5 of 5

SB	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
SB-116	1/9/1970	Exhaust System Inspection	N	N/A by Model.	N/A
SB-115	12/15/1969	Main Landing Gear Bracket Inspection	N	N/A by Model. (AA1)	N/A
SB-114A	11/17/1969	Marvel Drain Plugs	N	N/A by Model. (AA1)	N/A
SB-113	5/28/1969	Engine Cooling Improvements	N	N/A by Model. (AA1)	N/A
SB-106	1/7/1969	Ground Strap Installation	N	N/A by Model. (AA1)	N/A
SL89-1	7/28/1989	Auto Fuel in GA aircraft	Y	Auto Fuel is NOT approved for use in this aircraft REGARDLESS of engine fuel system STC.	1/8/2021

Parker Cleveland Wheels & Brakes Model: 40-77A, 40-88C

PRM	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
PRM 78	10/22/2002	Preferred Bearing Grease	Y	Complied with by use of Mobil HSC100 Grease in wheel bearings.	1/8/2021
PRM 94	5/12/2009	40-77A,B,F Wheel Assembly Tie Bolts	Y	Complied with by installation of new AN4-22A tie bolts and MS21042-4 nut.	1/8/2021

OTHER COMPONENTS

Number	Effective Date	Subject	Applicable Y/N	Compliance	Compliance Date
SB-18	10/14/2010	Marvel-Schebler HA-6 Carburetor Models with Machined from Billet housings.	N	N/A. Carburetor body is Die-Cast and not "Machined from Billet" IAW Marvel-Schebler Emergency Service Bulletin (SB) No. SB-18, dated October 14, 2010, or Revision A, dated March 15, 2011. (See AD 2012-03-07)	1/8/2021