


# SERVICE



# BULLETIN



DATE 9-4-70 NO. 1898

SUBJECT: WHEELS AND TIRES  
SUJET: HUB CAP REMOVAL

MODELS: 1970 CHALLENGER "T/A"  
MODÈLES:

The Challenger "T/A" model uses a combination of hub cap and trim ring as standard equipment. The trim ring can be easily distorted by the hub cap removal tool if due care is not taken.

In order to prevent this distortion, the trim ring should either be removed or some adequate cushion provided between the ring and the tool during hub cap removal.

A handwritten signature in cursive script, reading "W. F. Chisholm".

W. F. Chisholm  
Service Manager

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)

(CE BULLETIN VOUS EST FOURNI À TITRE DE RENSEIGNEMENT TECHNIQUE SEULEMENT; IL N'AUTORISE AUCUNE RÉPARATION)

