

Lady Chapel Roof

The orange buckets are packed away, no longer collecting raindrops or donations for the leaking roof above the Lady Chapel.

After nearly a year of fundraising and receipt of a grant from Valencia Communities Fund work was able to commence February this year and is all complete, keeping the Lady Chapel dry and the building structure protected from water damage.



The lead roof coverings had deteriorated over the years allowing water to seep underneath as well as well as pointing to flashing areas along the castellations.



With the lead removed, any damage from water ingress was able to be addressed as part of the works.



Lady Chapel Roof



Replacement timbers and aluminium rainwater systems installed.



New stainless steel roof coverings and flashings installed in line with other areas of the church roofs.



Thank you to all our fundraisers, donors and Valencia Communities Fund for making this happen and helping maintain our beautiful church building for future generations.