



price guide

General Maintenance rate \$75

Anything done under the home is a minimum \$250

Anything done in the attic is a minimum \$125

Tasks that are not priced are done at general maintenance rate.

Prices listed are for labor charge only. Material charge = Material cost + 30%

Cabinets

kitchen \$ 2X cost of cabinets, before markup

medicine \$50 bath wall mount \$50

vanity cabinet only \$200 24" \$250 30" \$300 36"

Caulking

remove caulk from tub and apply new. Caulk counter tops and sink tops caulk exterior windows 1 story caulk exterior windows 2 story

\$75 \$50 lot \$50 per \$75 per *All service calls have a minimum charge.
Include travel time, fuel expense and tolls if applicable.
\$75 - \$100

Countertops laminate

\$ 2X cost of countertops after mark up includes demo

Decks replacement

1 board	\$85
2 boards	\$150
3 boards	\$200
4-5 boards	\$225
6-8 boards	\$275
each additional	\$35 per
seal deck	\$200
stain deck	\$ hourly





price guide

Doors

install single exterior entry door	\$400
install split jamb door	\$175
hinge and install slab door	\$125
install slider door	\$600
install sliding screen door	\$100
replace doorknob	\$ 25
•	
replace lockset (knob/deadbolt)	\$ 50
replace weatherstripping	\$ 50
replace sweep (bottom side)	\$115
replace sweep (face screwed)	\$ 50
install bifold door	\$125
\$250 set	Ψ120
install slider closet door	\$140
\$280 set	ψ1 4 0
replace storm door	\$175
replace door closer	\$50

Drywall and repair

apply patch and skim	\$100
skimcoat small	\$75
skimcoat large	\$125
replace small drywall approx -2x2	\$125
replace large drywall area 4x4	\$225

Drywall ceilings

repair half sheet repair full sheet	\$250 \$400
Install luan access panel	\$35

Build and install new access panel

\$85

General Maintenance rate \$75

Anything done under the home is a minimum \$250


\$125 Anything done in the attic is a minimum

Tasks that are not priced are done at general maintenance rate.

Prices listed are for labor charge only. Material charge = Material cost + 30%

Electric

replace light fixtures	\$55
replace ceiling fan	\$125
replace chandelier	\$60
replace 2 story light	\$100
replace bath exhaust fan	\$150
replace range hood	\$150
replace outlet or switch	\$35
replace GFCI	\$50
replace ballast	\$75
Replace doorbell kit	\$75
replace doorbell button	\$25
replace garage door opener	\$250
Install over range microwave	\$150
install waterproof outlet cover	\$25
Install stove/dryer cord	\$50
replace stove/dryer outlet	\$75
, or ourse	





price guide

Fencing

Install panel	\$75
install post	\$100
install and build gate	\$150
demo per panel/post	\$ 30
replace fence pickets	\$ hourly
replace gate hardware	\$25

complete fence job post and panel \$125.00

Flooring

sheet vinyl floor	
approx. 5x6	\$250
approx. 8x8	\$400
install laminate	\$ 3 / ft
install vinyl plank	\$ 3 /ft
floor demo	\$.075 / ft
tile removed	\$1.25 / ft
tile installed	\$ 5 /ft
backer board instal	led \$25 /sheet
luan installed	\$25 /sheet

General Repairs

replace ceiling or floor register	s \$15
install towel bar/ tp holder	\$25
hang mirror	\$50
install window mini blind	\$30
Install vertical blind slider	\$75
replace furnace filter	\$25
replace pipe wrap on condens	er \$50
replace coil stove burner	\$35

General Maintenance rate \$75

Anything done under the home is a minimum \$250

Anything done in the attic is a minimum \$125

Tasks that are not priced are done at general maintenance rate.

Prices listed are for labor charge only. Material charge = Material cost + 30%

Gutters


1 story gutter cleaning	\$150
2 story gutter cleaning	\$250
securing 1 story	\$ 85
securing 2 story	\$125
Installing downspout 1 story	\$100
installing downspout 2 story	\$125
Installing gutters 1 story	\$75/hr
Installing gutters 2 story	\$100/hr

Full gutter install \$4.50/ft

* linear footage includes downspouts

Handrails

build exterior handrail	\$ 75/hr
replace interior spindle	\$45.00
Secure handrail	\$ 75/hr
Install handrail arm	\$ 25.00





price guide

s that are not priced are done at general tenance rate

Insulation

large area \$2 sq ft small area \$50 minimum

When bidding to remove ceilings with attic above, typically all insulation needs replacing. Insulation should always be thick enough to fill wall or come to joist height

Mailboxes

replace wall mount mailbox \$25 replace mailbox post \$65 replace mailbox, post, bracket \$125

Mortar and Chimney

tuck pointing \$85 /hr chimney crown re-coat \$250 Install Chimney cap (vent \$165 diverter)

Moulding/trim

*all moulding has vinyl equivalent if needed.

baseboard and casing	\$1.50 /lf
crown	\$3 /lf
shoe moulding	\$1.50 /lf
Install new casing 3 pc	\$ 75
Install new casing 1 pc	\$ 50

Painting

exterior painting	\$ 75/hr
interior painting	\$2.05 sq ft

Does not include ceilings. Total sq/ft of property. 2 colors (includes paint)

Paint ceiling only	\$1.50 sq ft
Large room 10x15 walls, trim	\$400
small room 10x10 walls, trim	\$250

Plumbing

replace kitchen faucet	\$150
Install new kitchen sink	\$150
replace bathroom faucet,	\$125
replace bath sink drain assembly	\$75
replace vanity cabinet 18" 36" 48"	\$250-\$450
replace basket strainer	\$85
replace trap assembly	\$85
Replace supply lines	\$10
replace garbage disposal	\$175
unstick garbage disposal	\$85
replace sprayer and hose	\$35
Install new toilet	\$200
replace wax ring	\$65
install super ring (broken flange)	\$50
replace toilet seat	\$25





Name Mender

price guide

General Maintenance rate

Anything done under the home is a minimum

Anything done in the attic is a minimum

Tasks that are not priced are done at general

Prices listed are for labor charge only. Material charge = Material cost + 30%

Plumbing (cont.)

rebuild exterior faucet	\$85
replace interior cut off	\$80
rebuild shower stem	\$65
replace shower stem	\$85
replace stem in faucet	\$85
replace flapper in toilet	\$25
replace fill valve	\$100
replace tank kit (all parts)	\$150
install dishwasher	\$125
unstop drain	\$90
replace tub diverter	\$50
replace shower head	\$25
Install new tub surround	\$450
remove tile tub surround	\$500
(replace drywall as needed)	\$150
(may require painting bathroom)	

Roofing

roof inspection	\$150
replace shingle tabs -5	\$165
replace shingle tabs -15	\$250
replace 1 pipe collar	\$175
replace 2 pipe collars	\$275
replace 3 pipe collars	\$350
replace attic power vent fan	\$300
replace attic power vent fan	\$200
replace basic attic vent	\$75
Replace sheathing	
small 2x2	\$400
large 4x4	\$750

Pressure washing

one story	\$225
two story	\$325
attach a shed	\$50
walkway	\$ hourly
driveway	\$ hourly
deck (small) 10x10	\$150
deck (large)	\$ 225
fence	\$ hourly

Rotted Wood Replacement

Exterior wood replaced needs to be caulked and painted to be complete. Price includes painting. Repalcemenr wood on second floor + 50%

2' of door jamb & brick mould 7'	\$225
1 pc brick mould 7'	\$110
garage door jamb with brick mould	\$145
porch post colonial	\$200
window sill and nose	\$150
fascia/soffit (exterior trim) per board	\$100
Sub floor re-placement 2x2	\$300
4x4	\$450
4x8	\$600



price guide

General Maintenance rate

thing done under the home is a minimum \$250.

Anything done in the attic is a minimum

Tasks that are not priced are done at general maintenance rate.

Prices listed are for labor charge only. Material charge = Material cost + 30%

Screens includes material

build and install new screen	\$85
re-screen	\$65
re-screen slider door l	\$90

Shutters

* shutters usually run 60 per pair to purchase. Replacing is preferred over painting.

replace shutters 1 story	\$50
replace shutters 2 story	\$75
reinstall fallen shutter 1 story	\$85
reinstall allen shutter 2 story	\$100

Siding

*if more than one or two pieces, add hourly rate.

Add \$50 per piece if on second floor.

replace 1 pc up to 12'	\$160
replace 2 pc	\$185
replace siding corner	\$150
repair/replace soffit	\$125
replace dryer vent	\$75
add bird guard	\$25
replace j channel	\$50.00
Topiace j charifier	

Smoke Detectors

Battery operated	\$15
wired	\$25

Stairs

Replace exterior stairs

* stringers and treads

3 tread	\$ 200
4 tread	\$ 250
5 tread	\$ 300
Replace attic stairs	\$ 550

Water Heaters

replace electric WH	\$500
replace gas WH	\$600
reroute TPR line	\$75
install pan under exisiting	\$250

All service calls have a minimum charge. Include travel time, fuel expense and tolls if applicable. \$75 - \$100

