

The Toyo Guy - Mobile Onsite Pricing

Onsite Full Service Package Pricing:

Laser 30	Best Case	Worst Case
Onsite Mobile Shop Fee	\$ 100.00	\$ 100.00
Overhaul Rebuild (Labor)	\$ 150.00	\$ 150.00
PARTS:		
Gasket Kit	\$ 127.00	\$ 127.00
Burner Gasket	included in kit	included in kit
Heat Chamber Gasket	included in kit	included in kit
Lower Gasket	included in kit	included in kit
Upper Gasket	included in kit	included in kit
Joint Gasket	included in kit	included in kit
Peep Window Gasket	included in kit	included in kit
Mica Peep Window	included in kit	included in kit
Igniter Guide Gasket	included in kit	included in kit
Fuel Nozzle Gasket	included in kit	included in kit
Relief Gasket	included in kit	included in kit
Air Joint Gasket	included in kit	included in kit
Flame Rod Gasket	included in kit	included in kit
Burner Assembly (*)	\$ -	\$ 236.00
Burner Ring	\$ -	\$ 34.00
Igniter	\$ -	\$ 125.00
Water Block Filter	\$ 25.00	\$ 25.00
	\$ 402.00	\$ 797.00
(*) typically this is a necessary part that needs to be replaced.		
Any parts not listed above will be an additional cost.		

Laser 53 / 300	Best Case	Worst Case
Onsite Mobile Shop Fee	\$ 100.00	\$ 100.00
Overhaul Rebuild (Labor)	\$ 150.00	\$ 150.00
PARTS:		
Gasket Kit	\$ 106.00	\$ 106.00
Burner Gasket	included in kit	included in kit
Heat Chamber Gasket	included in kit	included in kit
Peep Window Gasket	included in kit	included in kit
Mica Peep Window	included in kit	included in kit
Relief Gasket	included in kit	included in kit
Air Joint Gasket	included in kit	included in kit
Igniter Guide Gasket	included in kit	included in kit
Flame Rod Gasket	included in kit	included in kit
Fuel Nozzel Gasket	included in kit	included in kit
Burner Assembly (*)	\$ -	\$ 370.00
Burner Ring	\$ -	\$ 52.00
Igniter	\$ -	\$ 136.00
Water Block Filter	\$ 25.00	\$ 25.00
	\$ 381.00	\$ 939.00
(*) typically this is a necessary part that needs to be replaced.		
Any parts not listed above will be an additional cost.		

The Toyo Guy - Mobile Onsite Pricing

Onsite Full Service Package Pricing:

Laser 56 / 560	Best Case	Worst Case
Onsite Mobile Shop Fee	\$ 100.00	\$ 100.00
Overhaul Rebuild (Labor)	\$ 150.00	\$ 150.00
PARTS:		
Gasket Kit	\$ 108.00	\$ 108.00
<i>Burner Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Heat Chamber Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Igniter Guide Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Flame Rod Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Peep Window Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Mica Peep Window</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Joint Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Fuel Nozzel Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
Burner Assembly (*)	\$ -	\$ 216.00
Burner Ring	\$ -	\$ 52.00
Igniter	\$ -	\$ 142.00
Water Block Filter	\$ 25.00	\$ 25.00
	\$ 383.00	\$ 793.00
(*) typically this is a necessary part that needs to be replaced.		
Any parts not listed above will be an additional cost.		

Laser 73 / 730	Best Case	Worst Case
Onsite Mobile Shop Fee	\$ 100.00	\$ 100.00
Overhaul Rebuild (Labor)	\$ 150.00	\$ 150.00
PARTS:		
Gasket Kit	\$ 187.00	\$ 187.00
<i>Burner Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Blower Motor Case Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Heat Chamber Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Burner Insulating Pad</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Igniter Guide Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Flame Rod Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Peep Window Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Mica Peep Window</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Fuel Nozzle</i>	<i>included in kit</i>	<i>included in kit</i>
<i>Joint Gasket</i>	<i>included in kit</i>	<i>included in kit</i>
Burner Assembly (*)	\$ -	\$ 253.00
Burner Ring	\$ -	\$ 81.00
Igniter	\$ -	\$ 142.00
Water Block Filter	\$ 25.00	\$ 25.00
	\$ 462.00	\$ 938.00
(*) typically this is a necessary part that needs to be replaced.		
Any parts not listed above will be an additional cost.		

The Toyo Guy - Mobile Onsite Pricing

Onsite Full Service Package Pricing:

Pre-Season Inspection:

All Models	Price:
Visual Inspect / Light Clean	\$ 175.00
New Peep Window	included
New Peep Gasket	included
Flame Rod Cleaned/Reinstall	included
New Flame Rod Gasket	included
Water Block Filter	included
	\$ 175.00
Valid ONLY June 1st - Sept 30th.	
*This is a inplace service only. No removal.	

Repairs & Other Services:

\$200 Service Call + Parts

Other Services: New oil tank installs, fuel lines run, new/replacement stove installs, etc.
Fees will vary depding on parts needed for task.

Standard Service Call:

\$200 Call out fee

Normal business hours 9-5 Mon - Fri

Deposits:

Varies

Will be assessed on a case by case basis
Trapper Creek/Talkeetna clients will be charged \$100 deposit at time of booking service. This fee will be credited on bill.

Trapper Creek/Talkeetna Trip:

\$100 Trip Charge

Any location past Sheet Creek Lodge MP 88 on Parks Hwy
Trip charge fee will be waived on any full service packages performed

Emergency Service Call:

\$200 Emergency Call Fee
\$200 Standard Service Call Fee
+ Parts

After normal business hours/holidays