



## ***Product Overview***

### ***SCRUBrite AP-580***

#### **Acid Activated Pumice**

#### ***Product Description***

---

SCRUBrite AP-580 is an acid activated, 3F pumice that chemically removes copper oxidation and imparts anti-tarnish properties on the copper surface during the pumice scrubbing process. AP-580 can be used dry or mixed with water to form a slurry. AP-580 is designed specifically for automatic scrubbing operations but can be used in hand applications as well.

#### ***Physical Properties***

---

Specific gravity:	2.2
pH (1% slurry):	<5
Appearance:	white to gray free flowing powder

#### ***General Operation***

---

AP-580 can be applied using hand scrubbing, mechanical scrubbing or mechanized spraying. A mixture of one pound of AP-580 per one gallon of water is recommended for use with IS scrubbers.

#### ***Storage***

---

Store in original containers above 40 °F.

#### ***Safety***

---

CAUTION! AP-580 contains acidic components. Avoid contact with eyes, skin and clothing. Wear chemical handler's gloves, goggles and protective clothing when handling. Read and understand Material Safety Data Sheet before using this product.

#### ***Notice***

---

The information and recommendations, contained herein, regarding this product are, to the best of our knowledge, true and accurate. We make no guarantee of results because the conditions of actual use are beyond our control. We assume no liability for damages or penalties resulting from the use of this product or following our recommendations. Our recommendations and suggestions for use of this product are not intended to grant license to operate under or infringe any patent.