

CTI Replacement Model Numbers For Siemens® Products

| Siemens® Model # | CTI Replace- ment Model # | Siemens® Model # | CTI Replace- ment Model # |
|---------------------|------------------------------|-------------------------|------------------------------|
| 505-CP2572 | 2572-B | 505-4716 | 2596/2597 |
| 505-2555 | 2555-A | 505-4732 | 2597 |
| 505-2556 | 2556-A | 505-4808 | 2598/2598-8/2599 |
| 505-2557 | 2557-A | 505-4816 | 2598/2599 |
| 505-2571 | 2573-MOD | 505-4832 | 2599 |
| 505-2580 | 2580 | 505-4908 | 2534 |
| 505-2590-A | 2590-A | 505-4916-A | 2532 |
| 505-4008-A | 2588-8 / 2589-B | 505-4932-A | 2531 |
| 505-4016-A | 2589-B | 505-6108-A/B | 2558 |
| 505-4032-A | 2589-B | 505-6208-A/B | 2562 |
| 505-4208-A | 2588-8 / 2589-B | 505-6504 | 2500P-R4 |
| 505-4216-A | 2589-B | 505-6508 | 2500P-R8 |
| 505-4232-A | 2589-B | 505-6516 | 2500P-R16 |
| 505-4308 | 2588-8 / 2589-B | 505-6511 | 2500-R11-A |
| 505-4316, 4316-A | 2589-B | 505-6660 | 2512/2512A/2515A |
| 505-4332 | 2589-B | 505-6660-A ¹ | 2512/2512A/2515A |
| 505-4408-A | 2588-8 / 2589-B | 505-6660-B ¹ | 2512/2512A/2515A |
| 505-4416-A | 2589-B | 505-6663 | 2513 |
| 505-4432-A | 2589-B | 505-6663-A | 2513-A |
| 505-4508 | 2596/2596-8/2597 | 505-6851-A/B | 2500-RIO-A/B |
| 505-4516 | 2596/2597 | 505-6870 | 2500-RBC |
| 505-4532 | 2597 | 505-7002 | 2502 |
| 505-4608 | 2598/2598-8/2599 | 505-7003 | N/A |
| 505-4616 | 2598/2599 | 505-7012 | 2501 |
| 505-4632 | 2599 | 505-7016 | 2501 |
| 505-4708 | 2596, 2596-8, 2597 | 505-7028, 7028-A | 2559-TC |

CTI Replacement Model Numbers For Siemens® Products

| Siemens® Model # | CTI Replace- ment Model # | Siemens® Model # | CTI Replace- ment Model # |
|-----------------------|------------------------------|---------------------|------------------------------|
| 505-7038 | 2559-RTD | | |
| 545-1101 ² | 2500-C200 | | |
| 545-1102 | 2500-C200 | | |
| 545-1103 ³ | 2500-C100 | | |
| 545-1104 | 2500-C200 | | |
| 545-1105 ³ | 2500-C100 | | |
| 545-1106 | 2500-C200 | | |
| 555-1101 | 2500-C300 | | |
| 555-1102 | 2500-C400 | | |
| 555-1103 | 2500-C300 | | |
| 555-1104 | 2500-C400 | | |
| 555-1105 | 2500-C300 | | |
| 555-1106 | 2500-C400 | | |

NOTES

¹ if 505-6660-A/B is used in redundant mode, CTI 2512-A or 2515-A must be used for replacement

² if memory extension card is used with 545-1101, then 2500-C300 must be used for replacement

³ if a Profibus-DP annex card is installed, 2500-C200 must be used for replacement

CTI Replacement Model Numbers For Siemens® Products

| Siemens® Model # | CTI Replacement Model # | Siemens® Model # | CTI Replace- ment Model # |
|---------------------|----------------------------|---------------------|---|
| 500-5001 | 2588-8, 2589-B | 500-5056 | 2599 |
| 500-5002 | 2588-8, 2589-B | 500-5061 | 2534, 2530 |
| 500-5005 | 2588-8, 2589-B | 500-5062 | 2534, 2530 |
| 500-5006 | 2588-8, 2589-B | 500-5187 | 2589-B |
| 500-5007 | 2585 | 500-5192 | 2589-B |
| 500-5008 | 2588-8, 2589-B | 500-5194 | 2585 |
| 500-5009 | 2558, 2550-A | | |
| 500-5010 | 2598-8, 2599 | | |
| 500-5011 | 2598-8, 2599 | | |
| 500-5012 | 2598-8, 2599 | | |
| 500-5013 | 2596-8, 2597 | | We offer very similar fully compatible solutions for Series 500 CPU's like 520, 525, 530, 535, 560, 575. If you need replacements for these products, please refer to our Replacement Guide at http://www.controltechnology.com or contact us. |
| 500-5016 | 2562, 2560-A | | |
| 500-5018 | 2585 | | |
| 500-5019 | 2595 | | |
| 500-5030 | 2589-B | | |
| 500-5031 | 2597 | | |
| 500-5032 | 2580 | | |
| 500-5033 | 2590-A | | |
| 500-5037A | 2558, 2550-A | | |
| 500-5047A | 2562, 2560-A | | |
| 500-5048 | 2581 | | |
| 500-5049 | 2591-A | | |
| 500-5051 | 2559-TC | | |
| 500-5052 | 2557-A | | |
| 500-5055 | 2589-B | | |