## TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

WDI Sample Report Way	Dallas	75000
Inspected Address	City	Zip Code
	SCOPE OF INSPECTION	

## SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- Β. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). **Inspection does not cover** any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment, has rendered the pest(s) inactive.
- If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed D. that some degree of damage is present.
- Ε. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.


## THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD F. **DESTROYING INSECTS.**

- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- Ι. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

WDI Sample Report Way	<u>Dallas</u> City			7500 Zip Cod	
A House Inspection Services, PLLC. Name of Inspection Company		#9986	, SPCS #5! SPCS Business Lic	59963	
1C. PO Box 117773 Carrollton	TX		75011	(214)2	43-5676
Address of Inspection Company City	State		Zip	Tele	phone No.
1D. <u>Greg House</u>		1E.	Certified Applicator	$\checkmark$	(check one )
Name of Inspector (Please Print)			Technician		
1F. <u>Tuesday, February 16, 2021</u> Inspection Date					
2. WDI Sample Report		Seller 🛛	Agent 🛛 Buver 🗹	Management Co. 🗆	Other
Name of Person Purchasing Inspection			0 ,	U U	
3. Unknown Owner/Seller					
4. REPORT FORWARDED TO: Title Company or Mortgagee (Under the Structural Pest Control regulations only the purcha	Purchaser of Ser ser of the service is		Seller receive a copy)	Agent 🗹	Buyer 🗹
The structure(s) listed below were inspected in accordance with the officia to the conditions listed under the Scope of Inspection. A diagram must be 5A. <u>Single Story, Slab, Occupied, Single Family Re</u>	attached including sidence, Encl	all structure: osed Ga	s inspected. I <b>rage</b>		ce. This report is made subject
List structure(s) inspected that may include residence, detached garages a	and other structure	s on the prop	perty. (Refer to Part	A, Scope of Inspection)	
5B. Type of Construction: Foundation: Slab ☑ Pier and Beam □ Pier Type:	Basamant	<b>D</b> Other			
Siding: Wood 🗹 Hardie Plank 🗆 Brick 🗹 Stone 🗆 Stucco 🖵					
Roof: Composition ☑ Wood Shingle □ Metal □ Tile □ Othe					
6A. This company has treated or is treating the structure for the following w	_	-	-		
<b>3</b>	rtial 📙	Spot L		U Other	
If treating for drywood termites or related insets, the treatment was: Ful					
6В. <u>N/A N/A</u>			_ <u>N/A</u>		
Date of Treatment by Inspecting Company C This company has a contract or warranty in effect for control of the following	Common Name of In ng wood destroying		Nam	ne of Pesticide, Bait or C	ther Method
Yes No M List Insects: <u>N/A</u> If "Yes", copy(ies) of warranty and treatment diagram mus					
Neither I nor the company for which I am acting have had, presently have, nor the company for which I am acting is associate in any way with any pa Signatures:				of sale of this property.	I do further state that neither I
7A. <u>Greg House, Certified Applicator #559963</u> Inspector (Technician or Certified Applicator Name and License Num	ber)				
Others Present: 7B. <u>N/A</u> Apprentices, Technicians, or Certified Applicators (Names) and Regis					
Apprentices, Technicians, or Certified Applicators (Names) and Regist	tration/License Nur	nber(s)			
Notice of Inspection Was Posted At or Near:					
8A. Electric Breaker Box BB. Date Posted: Tuesday,	February 16,	2021	_		
Water Heater Closet					
Beneath the Kitchen Sink	Yes 🗹	No E	-		
9A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B.		NO L			
9B. The obstructed or inaccessible areas include but are not limited to the					
	_	ng Areas		ter box abutting structure	
	Slab Jo	ints		vl Space pholes	
Soil Grade Too High ⊻ Heavy Foliage Other □ Specify: <u>Furniture &amp; St</u>				pholes	
10A. Conditions conducive to wood destroying insect infestation? (Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.	Yes 🗹	No [			
10B. Conducive Conditions include but are not limited to:					
Wood to Ground Contact (	G) 🗌	Formboard	ls left in place (I)	Excessive Moisture	(J)
Debris under or around structure (K) D Footing too low or soil line	· –	Wood Rot			
Planter box abutting structure (O) Wood Pile in Contact with S			ence in Contact with		Í
		mulch, C	7-Wood posts	8	

WDI Sample Report Way	Dallas				<u>7500(</u>	)	
Inspected Address 11. Inspection Reveals Visible Evidence in or on the structure:	City Active I	nfestation	Previous	nfestation	Zip Code Previous T		
11A. Subterranean Termites	Yes 🗆	No 🗹	Yes 🗆	No 🗹	Yes 🗹	No 🗆	
11B. Drywood Termites	Yes 🛛	No 🗹	Yes 🗆	No 🗹	Yes 🛛	No 🗹	
11C. Formosan Termites	Yes 🗖	No 🗹	Yes 🗆	No 🗹	Yes 🗆	No 🗹	
11D. Carpenter Ants	Yes 🗆	No 🗹	Yes 🗆	No 🗹	Yes 🗖	No 🗹	
11E. Other Wood Destroying Insects Specify:	Yes 🗆	No 🗹	Yes 🗖	No 🗹	Yes 🗌	No 🗹	
11F. Explanation of signs of previous treatment (including pesticides, baits, ex Apparent drill holes.	xisting treatmer	nt stickers or ot	her methods) i	dentified:			
11G. Visible evidence of: <u>N/A</u> has been observe	ed in the followi	ing areas: <u>N/</u>	Α				
If there is visible evidence of active or previous infestation, it must be noted. inspected must be noted in the second blank. (Refer to Part D, E & F, Scope 12A. Corrective treatment recommended for active infestation or evidence of	of Inspection)			st blank and all ic	lentified infe	sted areas of the pr	roperty
as identified in Section 11. (Refer to Part G, H and I, Scope of Inspection	on)			Yes 🗖		No 🗹	
12B. A preventive treatment and/or correction of conducive conditions as ider Specify reason: <u>M- Wood Rot, L- High Soil Line</u> Refer to Scope of Inspection Part J	ntified in 10A &	10B is recomm	nended as follo	ws: Yes 🗹		No 🗆	
· · ·							_

Diagram of Structure(s) Inspected The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E-Evidence of infestation; A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; F-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H-Carpenter Ants; Other(s) - Specify <u>M- Wood rot, L- High soil line, R- Wood fence, N- Heavy foilage, C1- Wood mulch, C7- Wood posts, PST-</u> Previous treatment



\*\*\*DRAWING NOT TO SCALE\*\*\*

See sections 12A & 12B for any treatment and/or correction of conducive conditions recommended. All other conducive conditions appear to be by design of the property.

Additional Comments No active WDI infestation of any type observed at accessible areas at this date and time. No mud tubes, frass, powder, exit holes, or swarmers. See Sections 12A & 12B for any treatment and/or correction of conducive conditions.

WDI Sample Report Way	Dallas	75000
Inspected Address	City	Zip Code
5	Statement of Purchaser	
I have received the original or a legible copy of this form. I have read and un understand that my inspector may provide additional information as an adder If additional information is attached, list number of pages:	,	understand the "Scope of Inspection." I
Signature of Purchaser of Property or their Designee	Date	
Customer or Designee not Present     Buyers Initials		

## WDI Photos

High soil lines present at property.





Wood rot at back soffit.

