

All Around Home Inspection



This Home Inspection Is Exclusively Prepared for:

*AB Sample
102 Any Street
Your Town , TX*



Darron Bunch

TREC # 22645

☎ *817-917-2327*

✉ *darronbunch@gmail.com*

PROPERTY INSPECTION REPORT

Prepared For: AB Sample
(Name of Client)

Concerning: 102 Any Street, Your Town , TX
(Address or Other Identification of Inspected Property)

By: Darron Bunch, Lic #TREC # 22645 05/09/2018
(Name and License Number of Inspector) (Date)

(Name, License Number of Sponsoring Inspector)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules (“Rules”) of the Texas Real Estate Commission (“TREC”), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer’s installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller’s disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector’s responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous

or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathroom, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Present at Inspection:

- Buyer Seller Selling Agent Listing Agent
 Occupant

Building Status:

- Vacant Owner Occupied Tenant Occupied Other

Weather Conditions:

- Fair/Sunny Cloudy Rain Temp:83 °F

Utilities On: Yes No Water No Electricity No Gas

- New Construction Existing/ Resale

Notice

The term, "not to today's standards", is referring to the (SOP) Standards Of Practice set by (TREC) Texas Real Estate Commission.

The term, "appears to be as intended", is referring to the intent of the user/homeowner of the product, appliance, system, and/or systems normally used in everyday living and not the intent of any Engineer, Designer, or Builder.

SCOPE OF INSPECTION

These standards of practice define the minimum levels of inspection required for substantially completed residential improvements to real property up to four dwelling units. A real estate inspection is a non-technically exhaustive, limited visual survey and basic performance evaluation of the systems and components of a building using normal controls and does not require the use of specialized equipment or procedures. The purpose of the inspection is to provide the client with information regarding the general condition of the residence at the time of inspection. The inspector may provide a higher level of inspection performance than required by these standards of practice and may inspect components and systems in addition to those described by the standards of practice.

GENERAL LIMITATIONS

The inspector is not required to:

- (A) inspect:
(i) items other than those listed within these standards of practice;

- (ii) elevators;
- (iii) detached buildings, decks, docks, fences, or waterfront structures or equipment;
- (iv) anything buried, hidden, latent, or concealed
- (v) sub-surface drainage systems;
- (vi) automated or programmable control systems, automatic shut-off, photoelectric sensors, timers, clocks, metering devices, signal lights, lightning arrestor system, remote controls, security or data distribution systems, solar panels or smart home automation components; or
- (vii) concrete flatwork such as; driveways, sidewalks, walkways, paving stones or patios;

(B) report:

- (i) past repairs that appear to be effective and workmanlike except as specifically required by these standards;
- (ii) cosmetic or aesthetic conditions; or
- (iii) wear and tear from ordinary use;

(C) determine:

- (i) insurability, warrant ability, suitability, adequacy, compatibility, capacity, reliability, marketability, operating costs, recalls, counterfeit products, product lawsuits, life expectancy, age, energy efficiency, vapor barriers, thermostatic performance, compliance with any code, listing, testing or protocol authority, utility sources, or manufacturer or regulatory requirements except as specifically required by these standards;
- (ii) the presence or absence of pests, termites, or other wood-destroying insects or organisms;
- (iii) the presence, absence, or risk of asbestos, lead-based paint, mold, mildew, corrosive or contaminated drywall "Chinese Drywall" or any other environmental hazard, environmental pathogen, carcinogen, toxin, mycotoxins, pollutant, fungal presence or activity, or poison;
- (iv) types of wood or preservative treatment and fastener compatibility; or (v) the cause or source of a conditions;

(D) anticipate future events or conditions, including but not limited to:

- (i) decay, deterioration, or damage that may occur after the inspection;
- (ii) deficiencies from abuse, misuse or lack of use;
- (iii) changes in performance of any component or system due to changes in use or occupancy;
- (iv) the consequences of the inspection or its effects on current or future buyers and sellers;
- (v) common household accidents, personal injury, or death;
- (vi) the presence of water penetrations; or
- (vii) future performance of any item;

(E) operate shut-off, safety, stop, pressure or pressure-regulating valves or items requiring the use of codes, keys, combinations, or similar devices;

(F) designate conditions as safe;

(G) recommend or provide engineering, architectural, appraisal, mitigation, physical surveying, realty, or other specialist services;

(H) review historical records, installation instructions, repair plans, cost estimates, disclosure documents, or other reports;

(I) verify sizing, efficiency, or adequacy of the ground surface drainage system;

(J) verify sizing, efficiency, or adequacy of the gutter and downspout system;

- (K) operate recirculation or sump pumps;
- (L) remedy conditions preventing inspection of any item;
- (M) apply open flame or light a pilot to operate any appliance;
- (N) turn on decommissioned equipment, systems or utility services; or
- (O) provide repair cost estimates, recommendations, or re-inspection services.



Darron Bunch
TREC # 22645

817-917-2327

darronbunch@gmail.com

This is an Agreement between you, the undersigned AB Sample, and All Around Home Inspection, the Inspector, pertaining to our inspection of the Property at: 102 Any StreetYour Town , TX

The terms below govern this Agreement.

1. The fee for our inspection is **\$275.00** payable in full at a time of the inspection and must be paid prior to release of the report.
2. We will perform a **visual inspection** of the home and buildings requested by the Client and provide you with a written report identifying the defects that is observed and deemed material. The report is only supplementary to the seller's disclosure provided by the seller or seller's agent.
3. Unless otherwise noted here in this Agreement; Or not possible to complete, we will perform the inspection in accordance with the current Standards of Practice (SOP) of the Texas Real Estate Commission (TREC) www.trec.texas.gov . You understand that TREC SOP contains limitations, exceptions, and exclusions. You understand that TREC is not a party to this Agreement, has no control over us, and does not employ or supervise us. You understand the inspector performing the inspection may have limitations in attic spaces and crawl spaces. The inspector reserves the right to exclude or make exception in accordance to TREC SOP for the safety of the inspector.
4. We **will NOT** test for the presence of radon, a harmful gas, or mold. We **will NOT** test for compliance with applicable building codes or for the presence of or for any potential dangers arising from the presence of asbestos, lead paint, soil contamination, or other environmental hazards or violations. If any structure you want us to

inspect is a log structure or includes log construction, you understand that such structures have unique characteristics that may make it impossible for us to inspect and evaluate them. Therefore, the scope of our inspection will not include decay of the interior of logs in log walls, log foundations or roofs, or similar defects.

5. Our inspection and report are for your use only. You give us permission to discuss our observations with real estate agents, owners, repair persons, or other interested parties. **You understand it is your responsibility having repairs or findings of the inspection remedied prior to closing.** You will be the sole owner of the report and all rights to it. We are not responsible for use or misinterpretation by third parties, and third parties who rely on it in any way do so at their own risk and release us (including employees and business entities) from any liability whatsoever. If you or any person acting on your behalf provide the report to a third party who then sues you and/or us, you release us from any liability and agree to pay our costs and legal fees in defending any action naming us. Our inspection and report are in no way a guarantee or warranty, express or implied, regarding the future use, operability, habitability or suitability of the home and buildings or its components. We disclaim all warranties, express or implied, to the fullest extent allowed by law.

6. We assume no liability for the cost of repair or replacement of unreported defects, either current or arising in the future. In all cases, our liability is limited to liquidated damages in an amount not greater than the fee you paid us. You waive any claim for consequential, exemplary, special or incidental damages or for the loss of the use of the home or buildings. You acknowledge that this liquidated damages is not a penalty, but that we intend it to: (1) reflect the fact that actual damages may be difficult or impractical to ascertain; (2) allocate risk between us; and (3) enable us to perform the inspection for the agreed-upon fee.

7. We do not perform engineering, architectural, plumbing, or any other job function requiring an occupational license.

8. If you believe you have a claim against us, you agree to provide us with the following: (1) written notification of your claim within seven days of discovery in sufficient detail and with sufficient supporting documents that we can evaluate it; and (2) immediate access to the premises. Failure to comply with these conditions releases us from liability.

9. You agree that the exclusive venue for any litigation arising out of this Agreement shall be in the county where we have our principal place of business. If you fail to prove any claim against us, you agree to pay all our legal costs, expenses and attorney's fees incurred in defending that claim.

10. If a court declares any provision of this Agreement invalid, the remaining provisions remain in effect. This Agreement represents our entire agreement; there are no terms other than those set forth herein. All prior discussions are merged into this Agreement. No statement or promise by us shall be binding unless reduced to writing and signed by one of our authorized officers. Any modification of this Agreement must be in writing and signed by you and by one of our authorized officers. This Agreement shall be binding upon and enforceable by the parties and their heirs, executors, administrators, successors and assignees. You will have no cause of action against us after one year from the date of the inspection.

11. Past-due fees for your inspection shall result in non-release of your report until payment is made. All past-due fees will be requested prior closing transaction with your title company. You agree to pay all costs and attorney's fees we incur in collecting the fees owed to us. If the Client is a corporation, LLC, or similar entity, you personally guarantee payment of the fee.

12. If you request a re-inspection, the re-inspection is subject to the terms of this Agreement.

13. You may not assign this Agreement.

14. If a court finds any term of this Agreement ambiguous or requiring judicial interpretation, the court shall not

Report Identification: 0509Sample, 102 Any Street, Your Town, TX

construe that term against us by reason of the rule that any ambiguity in a document is construed against the party drafting it. You had the opportunity to consult qualified counsel before signing this.

15. If there is more than one Client, you are signing on behalf of all of them, and you represent that you are authorized to do so.

I HAVE CAREFULLY READ THIS AGREEMENT. I AGREE TO IT AND ACKNOWLEDGE RECEIVING A COPY OF IT BY EMAIL WITH THIS REPORT. THE UNDERSIGNED CLIENT OR REPRESENTATIVE AGREE AND ACCEPT ELECTRONIC SIGNATURE AS ORIGINAL TO THIS AGREEMENT.

Client or Representative

Date:05/09/2018

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): Slab

Comments:

Note: This is a limited visual inspection of the foundation and includes only visual indicators of foundation performance. No specialized tools or procedures were used. The opinion exposed are of apparent conditions of accessible and unobstructed areas of the structure and not of absolute fact and are only good for the date and time of inspection. The inspector is not a structural engineer and the inspection is not an engineering report and should not be considered one.

Note: Weather conditions, drainage, leakage and other adverse factors are able to effect structures, and differential movements are likely to occur. The inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. Future performance of the structure cannot be predicted or warranted.

Viewed from: Viewed from multiple locations at perimeter.

Corner spalling/popping or cracking observed.

Evidence of air pockets during the form and pour process observed in multiple locations.

Finished floor is the foundation surface. Surface cracking observed. Commonly found when concrete dry's and sets.



B. Grading and Drainage

Comments:

Note: Any area where the ground or grade does not slope away from the structure is to be considered an area of improper drainage. Six inches per 10 feet.

Drainage needs to be corrected.

Grade slopes towards foundation

Side walk may trap water runoff

Recommend further evaluation to improve drainage.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



-
-
-
-

C. Roof Covering Materials

Type(s) of Roof Covering: Composition Asphalt Shingles

Viewed From: Ground view

Comments:

Note: Not all views of the roof cover can be seen at once. Some views of the cover maybe obstructed by other parts or systems of the structure. Due diligence and good judgment will be used in viewing and or accessing the roof depending on the conditions determined at the time of inspection.

Notice: ground conditions in multiple locations were soft, unlevel, or void spaces under the added sod created unsafe conditions for use of a ladder.

Roof cover appears to be in first stages of life.

Appears to be as intended at the time of inspection.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



D. Roof Structures and Attics

Viewed From: Entered the Attic

Approximate Average Depth of Insulation: 6"-8"

Comments:

Rafter ties of minimum 2 x 4 between every rafter pair is recommended.

Under periling minimum 2 x 4 to are also recommended to prevent rafter movement and bowing.

Recommend further evaluation by structural engineer.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

E. Walls (Interior and Exterior)

Comments:

Interior walls made of : Drywall

Exterior walls made of : Stone, Hardie Board

Appears to be as intended at time of inspection.

-

F. Ceilings and Floors

Comments:

Floor Covering: Stained Slab

Ceiling Material: Drywall

Slab cracking observed in finish floor. Commonly found issue.



-

G. Doors (Interior and Exterior)

Comments:

Conflict of pantry doors. Both should closed beside the other and not forced.
Master bedroom door frame and door touch. Damage observed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



-
-
-
-

H. Windows

Comments:

Note: Signs of lost seals in the thermal pane windows may appear and disappears as temperatures and humidity changes. Some windows with lost seals may not be evident at the time of inspection. The windows are only checked for obvious fogging. If some seals were noted, recommend all windows be checked by specialist for further lost seals.

Windows are: Double Hung

Window screens are not installed. Found in the attic.

-
-
-
-

I. Stairways (Interior and Exterior)

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

J. Fireplaces and Chimneys

Comments:

Note: Recommend fireplaces be checked and cleaned yearly before use to insure proper draft and ventilation.

Type of Fireplace: N/A

-

K. Porches, Balconies, Decks, and Carports

Comments:

Appear to be as intended at the time of inspection

-

L. Other

Comments:

II. ELECTRICAL SYSTEMS

-

A. Service Entrance and Panels

Comments:

Note: Work area around service panel 30"x 36" at a height of 6'-6" above finished floor minimum. Only 1 wire per over current device, breaker, or service lug as listed or labeled by today's standards.


Panel Location: Garage

Service: Under ground

Wire Type: Copper

Service Amps: 200

Appear to be as intended at the time of inspection



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper

Comments:

Note: Recommend replacing the smoke detector batteries every six months.

Ground/ARC Fault Circuit Interrupt Safety Protection Note: GFCI protection is recommended at outlets in the kitchen, bathrooms, garage, exterior, or any outlet within 6 feet of water sources.

GFCI tested


GFCI is not used as recommended by today's standards.

GFCI protection is not used in all locations within 6 feet of a water source.

Notice: Outlets behind the washing machine can be difficult to reset if tripped.

Outlet behind the refrigerator can trip and food be spoiled. Thus GFCI are not used as these locations that are also commonly within 6 foot of a water source.

Damage under counter observed.



III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

-

A. Heating Equipment

Type of System: Central Heat

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

Energy Source: Electric


Comments:

Note: Recommend the central heat unit system be serviced each year to achieve proper performance.

Primary drain is to have a trap and uncapped vent.

Door stop is no recommended. Access should not be blocked 30 x 30 min.

Recommend further evaluation buy licensed professional in HVAC.



-
-
-
-

B. Cooling Equipment

Type of System: Central

Comments:

Note: Recommend the central heat/cooling unit system be serviced each year to achieve proper performance. Inspector cannot determine the amount of coolant in the unit or if the unit has a coolant leak present at the time of inspection.

A/C Size: 3.0 ton

Appear to be as intended at the time of inspection

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



-
-
-
-

C. Duct Systems, Chases, and Vents

Comments:

Type of Duct: Flex Duct

Appear to be as intended at the time of inspection



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

IV. PLUMBING SYSTEMS

A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Out front, at the street

Location of main water supply valve: Out front, North

Static water pressure reading: 40-50 psi

Comments:

Note: Water pressure is considered normal between 40 psi and 80 psi.

Shower Diverter. Did not properly control water flow to the shower head.

Mixing valve control improperly installed.

Anti syphon, back flow devices are recommended by today's standards.

Recommend further examination by licensed professional plumber.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



-

B. Drains, Wastes, and Vents

Comments:

Appear to be as intended at the time of inspection

-

C. Water Heating Equipment

Energy Source: Electric

Capacity: 50 gallon

Comments:

Note: Water heating equipment in a location that a leak in the tank may cause damage, A secondary drain pain should be installed by today's standards.

PEX piping is to be increased one nominal pipe size when used as a drain line.

Drain pains are recommended to piped be outside or approved drain.

Improper wiring observed.

Recommend further evaluation by licensed plumbing professional.


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



-
-
-
-

D. Hydro-Massage Therapy Equipment

Comments:

-
-
-
-

E. Other

Comments:

V. APPLIANCES

-
-
-
-

A. Dishwashers

Comments:

Note: The dishwasher lower panel is not removed during inspection. Back flow prevention may not be visible on some units.

Appear to be as intended at the time of inspection

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

B. Food Waste Disposers

Comments:

C. Range Hood and Exhaust Systems

Comments:

Appears to be working as intended at time of inspection.

D. Ranges, Cooktops, and Ovens

Comments:

Appear to be as intended at the time of inspection.

E. Microwave Ovens

Comments:

Appear to be as intended at the time of inspection

F. Mechanical Exhaust Vents and Bathroom Heaters

Comments:

Appear to be as intended at the time of inspection

G. Garage Door Operators

Comments:

Appear to be as intended at the time of inspection

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

-

H. Dryer Exhaust Systems

Comments:

Note: Recommend the dryer vent system be checked and cleaned periodically for lint buildup.

Lint collection or dryer exhaust system is to be vented to the exterior.



-

I. Other

Comments:

VI. OPTIONAL SYSTEMS

-

A. Landscape Irrigation (Sprinkler) Systems

Comments:

-

B. Swimming Pools, Spas, Hot Tubs, and Equipment

Type of Construction:

Comments:

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---

C. Outbuildings

Comments:

D. Private Water Wells (A coliform analysis is recommended)

Type of Pump:

Type of Storage Equipment:

Comments:

E. Private Sewage Disposal (Septic) Systems

Type of System: Aerobic

Location of Drain Field: Out back, South

Comments:

Breaker was off stopping the proper function.
System in alarm at the time of inspection.
Clean out uncapped. Recommend threaded clean out cap.
Tank level full
Septic aerator system is not setting level.
Functional flow tested.
Recommend farther evaluation by professional septic service provider.

Note: System seemed to run until proper water levels were reached and the alarm stopped by the end of the inspection.



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



-
-
-
-

F. Other

Comments: