PROPELLER MAINTENANCE RECORDS

Page No				
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	GENTION			TOTALS brought forward from previous page
8.3.05			4978.0	I worked propelly IAW on annual
0,0				Injectur and won found
				a wal of Design
				Con the state of t
11-3-05			5074·D	Quested propelly tow an
				June Insputio and war
				found to be auworthy
				Exerce me fal splins
				with TCB composition por
				TCB14422-00 Composite
				spinin Form 337 & WHB
				+ Post updated this date
				Zustrustion for Continuel
				De worthinen gustall w
				POA.
				Tufact
				2672876/71
uhalad			10.7	
11/20/06			5/25.01	ANNUAL INSPECTION COMPLIFED This ATZ and That Time Juny 1/2/2/2/2
				A12 and Tact Time my lensy
		•		Ported FRW. Bulk HSAD With New.
7/24/1			7/12 >	1
4-1100			742-3	Cw annal Que for and
			7	Februies xo he giverty
				26125761In
				ZUR TOTAL CASI
				SUB-TOTALS this page OTALS—Carry forward to pays some
				OTALS—Carry forward to next page

				Page No
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
2009	5242.5	_	5242.5	TOTALS brought forward from previous page
1 AUG	5242.5	_	5242.5	PROP INSPECTION 1/19/W # 100 HR MSP
				AND FOUND TO BE IN MERWORFY CONDITION.
				Jams & Don't AF 1917057.
1400	5242.5	_		ANNUAL INSPECTION COMPLETIED THIS
				DATE AND FOUND TO 1312 IN MIRWORTH
				Condion.
				Ham Bays
				ASP15061841A
icion	05350.08		5330.0	1 / /
DEFEN	000000		3370.02	PROP INSPECTISO 1/A/W A 100 HR INSP
				MAN FOUND to BIZ IN AIRWORTHY CONDITION
		 		Lama & Don't Afrigi7057.
1500700	25330.09		52200	PROP HANNUR INSPECTION COMPLIEBED THIS
1 SCF ZUIC	10.00	•	00.00	DAGE AND FOUND to BE IN ARWORTHY CONDUCTION
				HALLOGO -
				AF 15065 9AB
6 oct 201	1 5411.86	/	5411.86	PROP ANNUAL INSPECTION COMPLETED THIS
				DATE AND FOUND TO BE IN HIRWORTHY CONDITION.
				Mark Makes
				#5P 150619#IA.
				NO FURTHER ENTRIES THIS PAGE
				D. R. Cheun #3422310
				SUB-TOTALS this page
				TOTALS-Carry forward to next page

irecti Repo

Page No				
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
2012	5479.18	9	5479.18	TOTALS brought forward from previous page
				October 26, 2012. HUB: 74DM6-0-58. SN: K41400. TT: .6470.3
				TSO: 0.00. Overhauled propeller, painted and statically balanced in accordance with Sensenich Manual: SPRM590. All other current service
		b,		NOTICE: An Airworthiness Directives complied with as of this date. NOTICE: An Airworthiness Directive may apply to the installation of the
				propeller described hereon. The installer is responsible for ensuring complete compliance with any applicable installation Airworthiness Directive.
	*			Maintenance Release (Complete Overhaul)
		*		The aircraft propeller, or appliance identified above was overhauled and Inspected in accordance with Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at this
				repair station under Work Order Number 12-7447.
				Signed , for AIR PROP SPECIALISTS, INC. Certificate Number 1X4R274M, 3671 Industrial Park Drive,
a1 L	T-2/ 157			Marianna, FL 32446
26001.	5479.18	0	5479.18	
				ON 14c. PROP MOUNT BOLTS TORQUE
				MND SAFEFIED,
				Jams & Dont 1817057
10/19/14	5605.41	126.23	5605.41	INSP. PLOP AND FOUND TO BE IN
				AIRWORTHY COND. Shall florell -
,				003493697 A+PIA
S/N K4:	1400			
I certify	y that I hav that this p	e perform propeller is	ned an ann s servicable	ual inspection of this propeller using Sensenich service manual
			1	
	Mis 3	7		
Jonatha	n E Dent			3503172 A&P IA
				SUB-TOTALS this page
				TOTALS-Carry forward to next page

DATE	TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
2016				TOTALS brought forward from previous page
13 APR	5697.8		5697.8	PROP REMOULED, STRIPED,
			HOMS	REFINISHED AND ALDDINED.
	23.	N DNA HOT)	-3211 120 r	REPAINTED BLUCK AND GREY. REINSTALLED ON AIRCRAIT AND
		POT 01	DD VHTS , WE.	Bolts FORQUE to 25 FT 205.
	331	1 1 3 A 11 11 11 11 11 11 11 11 11 11 11 11 1	.127	186 WORK DONE 1/4/W AC 43.13.
				Lames E. Dont Atligitos 7
25007 20	16		5728.78	
Date: 10-2	25-2016	TSMO:		
Jopathan E	Dent			A&P 3503172 IA
280CT 17			5790.05	MODEL <u>74 DM6-0-58</u> SN <u>A 40406</u> TACH <u>5790.05</u> TTIS <u>5790.05</u> SMOH <u>UNK</u>
				I CERTIFY THAT THIS <u>PROPEULER</u> HAS BEEN INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.
				SIGNATURE CERTIFICATE # / TYPE
23 JAN 19	5844.9	365.72	5844.9	MODEL 24 PM6-0-58 SN A40406 TACH 5844.9 TTIS 5844.9 SMOH 365.72 I CERTIFY THAT THIS PROPERTY HAS BEEN INSPECTED I/A/W AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.
				SIGNATURE CERTIFICATE # / TYPE
				TOTALS-Carry forward to next page

age No				
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
7 - 1 - 1 - 1 - 1 - 1 - 1				TOTALS brought forward from previous page
IFEB 2	0 5 905.8	426.62	5905.8	11 12 11 17 N V // 2 N V N // 1/ (/
				TABLE # PARTIE 1905 8 SMOH # 10 101
	` .			I CERTIFY THAT THIS PROPERTY HAS BEEN INSPECTED I/A/W AN ANNUAL INSPECTION AND WAS
			~	DETERMINED TO BE IN AN AIRWORTHY CONDITION.
	1			003493897 A&P-IA
				SIGNATURE CERTIFICATE # / TYPE
	,			
x 20 0 1	5940.6	461.47	5940.6	NOT SENSENICH CHEELTHEB21
120 21	3770.0	7011/2	Q , / D (C	MODEL 2 + 10/16-10-58 SN 4 40406 TACH 5940.6 TTIS 5940.6 SMOH 461.42
				CERTIFY THAT THIS PROPERTY HAS BEEN
			٠.	INSPECTED I/A/W AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.
				un 1 1 N W
				IGNATURE O03493897 A&P IA CERTIFICATE # / TYPE
				WIGHT ONL VITTE
	Con	inspected A	2 Inchection I	AW FAR 43 appendix D. I certify that this propeller spection and is found airworthy at this time. 467
		with S	cted and dres Sensenich Ma	: 74DM6-0-58 SN: K41400 TT: 7028.82 TSO: 0 sed nick in leading edge of propeller in accordance nuals: SPRM590. All other current service worthiness Directives complied with as of this date.
		the pr ensur	opeller descr	orthiness Directive may apply to the installation of ibed hereon. The installer is responsible for compliance with any applicable installation ctive.
		The air	Pegulations of th	or appliance identified above was serviced in accordance he Federal Aviation Agency and is approved for return to
		servic Work	e. Pertinent deta Order Number	ails of the inspection are on file at this repair station under 21-1047.
		Signe Certifi 32446	icate Number 1	, for AIR PROP SPECIALISTS, INC. X4R274M, 3671 Industrial Park Drive, Marianna, FL
		1		

N33532 TACH: 6045.0 TTAF: 6045.0 SMOH: 0 DATE: 10/19/2021
Sensenich 74DM6-0-56 SN: K41400
Installed this overhauled propeller on this ACFT. Installed using new hardware Referencing Piper SM 2130 # 21-1047
Jeb Ragsdale A&P 2732467

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WO	ORK PERFORMED— F PERSON PERFORMING WORK
				TOTALS brought forward from previous	page
	Se Co W	ensenich 74DN ompleted 100	16-0-56 SN: HRJnspection	IAW FAR 43 appendix D. I certify that this proinspection and is found airworthy at this time.	peller
	Sen Con I cei	senich 74DM6 npieted 100HF	6-0-56 SN: K4 R inspection IA propeller was	6236.0 SMOH: 191.0 DATE: 3/31/2022 41400 AW FAR 43 appendix D. Cleaned and dressed prinspected IAW a 100HR inspection and is found Jeb Ragsdale A&P 2732467	
	Sense Comp I certif	nich 74DM6-0 leted 100HR li	-56 SN: K414 nspection IAW opelier was in:	36.0 SMOH; 291.0 DATE: 7/6/2022 400 / FAR 43 appendix Date: 7/6/2022 spected IAW a 1001/B inspection and is found leb Ragsdale A&P 2732467	
		Sensenich Complete I certify th	74DM6-0-56 S d 100HR Inspecti	TAF: 6435.3 SMOH: 390.3 DATE: 9/29/2022 iN: K41400 ion IAW FAR 43 appendix D. was inspected IAW a 100 IB inspection and is found Jeb Ragsdale A&P 2732467	
		Sense: Compl	nich 74DM6-0 leted 100HR I t this propelle	o.0 TTAF: 6534.0 DATE: 11/26/2022 0-56 SN: K41400 SMOH: 489.0 Inspection IAW FAR 43 appendix D. It was inspected IAW a 100HR inspection and airworthy at this time. In ale A&P 2732467	

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
3				TOTALS brought forward from previous page
			rt this PROPLI	O2 FEBUARY 2023 TTAF 6606.7 LER has been inspected in accoradance with an ANNUAL en found to be in airworthy condition as of this 14th day approved return to service as of this day.
		Casey Paul	Patterson	
		Casey Paul A&P 27863		
		A&P 27863	55 IA	
				•
L				SUB-TOTALS this page
			0 0.00 0.00	TOTALS-Carry forward to next page