

MultiPerson Thermal Screening Setup Guide

STEP 1 - ASSEMBLY

ThermaVis Camera Mount and Tripod



Assemble ThermaVis Camera Mount with the Camera Hole on the Left-Hand Side and the USB-C connection on the right hand side.

Assemble Tripod and fix the T-bar to the top of the Tripod.



Fix the ThermaVis Camera Mount to the Right-Hand-Side of the T-Bar with the USBC Port facing inwards. Fix the Tablet holder to the Left-Hand-Side of the T-Bar.

STEP 2 - SETUP

Connections & software



Connect the Tablet (USB) and Thermal Camera (USB-C) via the USB to USB-C Cable provided.

Run ThermaVis - Thermal Screening Software on the Tablet. Located on the desktop.

Need Help?
Please contact [ThermaVis Support](#)