

Annual Inspection and Maintenance Reports for Stormwater Control Measures (SCMs)

COVER SHEET

Section 5.4.8 (c) of the Chapel Hill Land Use Management Ordinance requires that "All stormwater management facilities must be inspected by the responsible party, in accordance with the approved schedule in the stormwater operation and maintenance plan, to identify maintenance and repair needs, and to ensure compliance with the requirement of the recorded operation and maintenance plan."

GENERAL INFORMATION

Please use one Cover Sheet per site and one Inspection Report Form for each SCM on the site. Please include captioned color photographs of each main component of the SCM at the end of the Inspection Report Form.

	SITE	INSPECTOR	
Site / Owner Name:	Chandler Woods	Inspector Name:	Timothy P. Grady
Site Street Address:	Abbot Place	Company Name:	G2 Design, P.A
Site PIN:	9870617474	Mailing	PO Box 297
Owner Mailing Address:	4112 BLUE RIDGE RD STE 100 Raleigh, NC 27612	Address:	Apex, NC 27502
Phone Number:	(919) 233-7660	Phone Number:	919-321-0638
Owner Email Address:	susanlindelof@elite-mgmt.com	Email Address:	tgrady@g2designpa.com

INSPECTION REPORT FORMS

Indicate the quantity of each SCM on the site in the table below. Please use one form for each SCM and submit all forms together with photographs as a single PDF report with this Cover Sheet as the first page.

SCM	QUANTITY	SCM	QUANTITY
Bioretention Cell	1	Permeable Pavement	
Constructed Wetlands		Sand Filter	
Dry Pond		StormFilter	
Grassed Swale		Underground Detention	
Hydrodynamic Separator		Wet Pond	2
Level Spreader		Other (Describe)	


COVER SHEET PAGE 1 OF 2 REVISED: 2.12.2025

INSPECTION RESULTS

Please note all required maintenance or repairs on the individual inspection forms. A re-inspection and certification must be completed within 60 days of failed report date. It is highly recommended that the inspector be part of the repair process in order to ensure that repairs are being performed promptly and properly.



The certifying professional must sign and seal below.



MAINTENANCE RECORDS

Please attach records of routine SCM maintenance since the last inspection and maintenance report submittal to the Town. Routine maintenance is required for each SCM per Town ordinance and per the recorded maintenance covenants.

Are records available?



PROFESSIONAL CERTIFICATION

Certification shall be provided by a registered North Carolina Professional Engineer or Landscape Architect with qualified professional Stormwater Control Management (SCM) Inspection and Maintenance training.

I, <u>Timothy P. Grady</u>, as a duly registered <u>RLA</u> in the State of North Carolina, attest that I have performed a thorough inspection for all SCMs associated with this site. I further attest that all SCMs (please circle appropriate response) <u>are or are not</u> performing as designed and in compliance with the Town of Chapel Hill ordinances and the terms and conditions of the recorded maintenance agreement.



Date: 4/28/2025

Signature:

NCSU BMP Certification Number or list similar training credential:

__023



CHANDLER WOODS – CHAPEL HILL, NC

Stormwater Control Measure (SCM) Location Map

10.19.2022





Annual Inspection and Maintenance Reports for Stormwater Control Measures (SCMs)

BIORETENTION

Important: Please note that this inspection checklist is not an exhaustive list of inspection items for any particular SCM. It is the responsibility of the professional inspecting the facility to perform a comprehensive inspection and to note additional items as necessary.

GENERAL INFORMATION

Site Name:	Chandler Woods	Date:	04/24/2025
SCM Location:	Abbot Place	SCM ID Number: (if applicable, per approved plans)	

CODE KEY

N/A = Not Applicable	M = Monitor; Minor Maintenance Needed (SCM is Functioning as Designed)
PASS = No Maintenance Needed; Functioning as Designed	FAIL = Maintenance Required; SCM <i>not</i> Functioning as Designed

INLET DEVICES

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Velocity Dissipator Pad Condition	PASS	
Structural Condition	PASS	
Erosion or Undercutting	PASS	
Other (describe)		

BIORETENTION PAGE 1 OF 3 REVISION: 10.5.2017

BIORETENTION CELL

ASSESSMENT	CODE	COMMENTS
Overgrown Vegetation	PASS	
Standing Water for > 12 Hours Post Rain Event	PASS	
Plants are Dead, Diseased or Dying	PASS	
Soils and/or Mulch Clogged with Sediment	PASS	
Invasive Vegetation (Estimate %)	PASS	
Mulch Depth and Condition	PASS	Mulch remove/replace likely due 2026 pending conditions
Erosion or Gullies Present	PASS	
Underdrain System	PASS	
	PASS	
Ponding Depth		
		Design Ponding Depth: 12"
		Existing Ponding Depth: 12"
Other (describe)		

OUTLET DEVICE

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Structural Condition	PASS	
Velocity Dissipator Pad Condition	М	Nuisance trees present; see photographic journal
Pipe Condition	PASS	
Erosion or Undercutting	PASS	
High-flow Bypass	PASS	Turf emergency spillway stable with established vegetation
Other (Describe)		

MISCELLANEOUS

ASSESSMENT	CODE	COMMENTS
Trash or Debris	PASS	
Access	М	Portion of outlet easement overgrown; see Photo Journal
Vandalism	PASS	
Signage	N/A	
Other (Describe)		
Other (Describe)		
Other (Describe)		

PHOTOGRAPHS

Please attach digital photographs of the site and each main component of the SCM with descriptive captions.



Annual Inspection and Maintenance Reports for Stormwater Control Measures (SCMs)

WET POND

Important: Please note that this inspection checklist is not an exhaustive list of inspection items for any particular SCM. It is the responsibility of the professional inspecting the facility to perform a comprehensive inspection and to note additional items as necessary.

GENERAL INFORMATION

Site Name:	Chandler Woods	Date:	04/24/2025
SCM Location:	Abbot Place	SCM ID Number: (if applicable, per approved plans)	WP #1

CODE KEY

N/A = Not Applicable	M = Monitor; Minor Maintenance Needed (SCM is Functioning as Designed)
PASS = No Maintenance Needed; Functioning as Designed	FAIL = Maintenance Required; SCM <i>not</i> Functioning as Designed

INFLOW POINTS

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Velocity Dissipator Condition	PASS	
Pipe Condition	PASS	Partially submerged at normal pool per design
Erosion or Undercutting	PASS	
Other (describe)		

WET POND PAGE 1 OF 4 REVISED: 11.17.2021

FOREBAY

ASSESSMENT	CODE	COMMENTS
Sediment and Debris Accumulation	PASS	
Side Slope Erosion	PASS	
Invasive Vegetation	PASS	Algae actively managed by SCM maintenance company
Other (describe)		

VEGETATED SHELF / MAIN TREATMENT AREA

ASSESSMENT	CODE	COMMENTS
Sediment and Debris Accumulation	PASS	
Visible Pollution or High Turbidity	PASS	
Plants are Dead, Diseased or Dying	М	See photographic journal
Vegetation Height and Density	PASS	
Bare Soils or Erosive Gullies	PASS	
Invasive Vegetation (Estimate %)	PASS	
Algae or Aquatic Weed Cover (Estimate %)	PASS	
Other (describe)		

EMBANKMENT

ASSESSMENT	CODE	COMMENTS
Erosion or Loss of Dam Material	PASS	
Shrubs or Trees Present	PASS	
Animal Burrows	PASS	
Soft or Boggy Areas	PASS	
Other (Describe)	М	Bare/sparse areas at downslope; see photographic journal

OUTLET DEVICE

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Structural Condition	PASS	
Velocity Dissipator Pad Condition	PASS	
Pipe Condition	PASS	
Orifice Condition	PASS	
Erosion or Undercutting	PASS	
High-flow Bypass	PASS	
Other (describe)	М	Seepage at riser outlet structure; see photographic journal

MISCELLANEOUS

ASSESSMENT	CODE	COMMENTS
Trash or Debris	PASS	
Access	PASS	
Vandalism	PASS	
Fish or Wildlife Observations	PASS	
Fence Condition	N/A	
Signage	N/A	
Other (describe)		
Other (describe)		
Other (describe)		

PHOTOGRAPHS

Please attach digital photographs of the site and each main component of the SCM with descriptive captions.



Annual Inspection and Maintenance Reports for Stormwater Control Measures (SCMs)

WET POND

Important: Please note that this inspection checklist is not an exhaustive list of inspection items for any particular SCM. It is the responsibility of the professional inspecting the facility to perform a comprehensive inspection and to note additional items as necessary.

GENERAL INFORMATION

Site Name:	Chandler Woods	Date:	04/24/2025
SCM Location:	Abbot Place	SCM ID Number: (if applicable, per approved plans)	WP #2

CODE KEY

N/A = Not Applicable	M = Monitor; Minor Maintenance Needed (SCM is Functioning as Designed)
PASS = No Maintenance Needed; Functioning as Designed	FAIL = Maintenance Required; SCM <i>not</i> Functioning as Designed

INFLOW POINTS

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Velocity Dissipator Condition	PASS	
Pipe Condition	PASS	
Erosion or Undercutting	PASS	
Other (describe)		

WET POND PAGE 1 OF 4 REVISED: 11.17.2021

FOREBAY

ASSESSMENT	CODE	COMMENTS
Sediment and Debris Accumulation	PASS	
Side Slope Erosion	PASS	
Invasive Vegetation	PASS	
Other (describe)	PASS	Non-vegetated earthen berm w/ top at normal pool per design

VEGETATED SHELF / MAIN TREATMENT AREA

ASSESSMENT	CODE	COMMENTS
Sediment and Debris Accumulation	PASS	
Visible Pollution or High Turbidity	PASS	
Plants are Dead, Diseased or Dying	М	See photographic journal
Vegetation Height and Density	PASS	
Bare Soils or Erosive Gullies	PASS	
Invasive Vegetation (Estimate %)	PASS	
Algae or Aquatic Weed Cover (Estimate %)	PASS	
Other (describe)	М	Overgrowth at retaining walls; see photographic journal

EMBANKMENT

ASSESSMENT	CODE	COMMENTS
Erosion or Loss of Dam Material	PASS	
Shrubs or Trees Present	М	Remove overgrowth/debris along toe of dam; see photographic
Animal Burrows	PASS	
Soft or Boggy Areas	PASS	
Other (Describe)	М	Maintenance required at landscaped portions; see photo journal

OUTLET DEVICE

ASSESSMENT	CODE	COMMENTS
Obstruction: Vegetation, Debris, Sediment, Other	PASS	
Structural Condition	PASS	
Velocity Dissipator Pad Condition	PASS	
Pipe Condition	PASS	
Orifice Condition	PASS	
Erosion or Undercutting	PASS	
High-flow Bypass	PASS	
Other (describe)	М	Seepage at riser outlet structure; see photographic journal

MISCELLANEOUS

ASSESSMENT	CODE	COMMENTS
Trash or Debris	PASS	
Access	PASS	
Vandalism	PASS	
Fish or Wildlife Observations	PASS	
Fence Condition	PASS	
Signage	N/A	
Other (describe)		
Other (describe)		
Other (describe)		

PHOTOGRAPHS

Please attach digital photographs of the site and each main component of the SCM with descriptive captions.



P: 919.321.0638 F: 919.321.8311 PO BOX 297 APEX, NC 27502

PHOTOGRAPHIC JOURNAL

SCM #1 – WET DETENTION POND #1 (WEST)



A: VIEW OF WET DETENTION POND





B: VIEW OF FOREBAY AND INLET



C: VIEW OF DAM EMBANKMENT





D: VIEW OF SIDE SLOPES





E: VIEW OF RISER EXTERIOR AND INTERIOR



F: VIEW OF OUTLET DISCHARGE AREA

SCM #2 – WET DETENTION POND #2 (NORTH)



A: VIEW OF WET DETENTION POND





B: VIEWS OF FOREBAY AND INLET



C: VIEW OF DAM EMBANKMENT



D: VIEW OF SIDE SLOPES AND RETAINING WALLS





E: VIEW OF RISER EXTERIOR AND INTERIOR



SCM #3 - BIORETENTION (EAST)



A: VIEW OF BIORETENTION



B: VIEW OF NORTH END OF CELL WITH INLET/FOREBAY





C: VIEWS OF SIDE SLOPES





<u>D: VIEW OF RISER OUTLET STRUCTURE EXTERIOR AND INTERIOR</u>

(FUNCTIONAL INTERNAL WATER STORAGE CONFIRMED)





E: VIEWS OF OUTLET CONDUIT DISCHARGE

SUMMARY OF MISC. REMEDIATION REQUIRED OVER COMING YEAR

INSPECTION WAS IMPLEMENTED WITH HOA AND MAINTENANCE CONTRACTOR; HOA CURRENTLY CONTRACTING FOR IMPLEMENTATION OF ALL TASKS

SCM #1 – WET DETENTION POND #1 (WEST)





A: APPLY HEAVY APPLICATION OF PINE STRAW TO DAM DOWNSLOPE WHERE THERE IS NO VEGETATION (IF PREFERRED, CONCERTEDLY/PROPERLY REMEDIATE TO ESTABLISH TURFGRASS COVER)





B: COMPARE PLANT ESTABLISHMENT AT LITTORAL SHELF WITH PERMIT PLANTING PLAN;

DETERMINE SHORTFALLS AND PERFORM SUPPLEMENTAL PLANTING ACCORDINGLY

2024 PLANTING INEFFECTIVE DUE TO LACK OF POOL: VALVE OPENED BY APPARENT MISCREANTS





C: REMEDIATE LOW POOL LEVEL RESULTING FROM OUTLET STRUCTURE LEAKS: PUMP TO REMOVE STANDING WATER; THOROUGHLY CLEAN ORGANICS FROM ALL SEEPAGE POINTS & SEAL WITH NON-SHRINK HYDRAULIC CEMENT

SCM #2 - WET DETENTION POND #2 (NORTH)





A: COMPARE PLANT ESTABLISHMENT AT LITTORAL SHELF WITH PLANTING PLAN;

DETERMINE SHORTFALLS & PERFORM SUPPLEMENTAL PLANTING ACCORDINGLY

IMPROVEMENT NOTED SINCE 2024 ESPECIALLY AT SHALLOW WATER ZONE





B: CUT/REMOVE IMMATURE WOODY VEGETATION TO DAM TOE & REMOVE LARGE DEBRIS; STRING-TRIM REMAINING HERBACEOUS GROWTH





C: REMEDIATE LOW POOL LEVEL RESULTING FROM OUTLET STRUCTURE LEAKS: THOROUGHLY CLEAN ORGANICS FROM ALL SEEPAGE POINTS & SEAL W/ NON-SHRINK HYDRAULIC GROUT



D: CUT VOLUNTEER VEGETATION AND ON BOTH SIDES OF RETAINING WALL FENCE






E: REMOVE WEEDS AND REPLENISH MULCH AT LANDSCAPE BED AND AROUND NURSERY TREES ALONG DAM DOWNSLOPE AT WESTERN END

SCM #3 - BIORETENTION (EAST)





A: CUT/REMOVE TWO NUISANCE TREES FROM OUTLET DISCHARGE AREA;
TREAT STUMPS WITH HERBICIDE TO PREVENT RE-GROWTH





B: CUT & REMOVE TREES & SHRUBS AT REMAINING PORTION OF OUTLET DISCHARGE EASEMENT CORRIDOR (AREA IN RED ABOVE); MAINTAIN ENTIRE EASEMENT (OUTLINED IN GREEN) AS MOWED AT A MAXIMUM HEIGHT OF 18"





ADVISORY: ADEQUATE MULCH COVERAGE OVERALL CONFIRMED; HOA IS
ADVISED TO BUDGET FOR COMPREHENSIVE MULCH REMOVEREPLACE
TASK THAT MAY BE REQUIRED IN 2026 (BASED ON CONDITION)

- End of Report -



Stormwater Operations and Maintenance

Log Sheet

Facility Name: Chandler Woods	Permit Number:		
Address: 214 Abbot Place Chapel Hill, NC 27516			
Owner: Chandler Woods MOA PO Box 20969 Raleigh, NC 27619	E-mail: Tom@tracmanagement.com	Phone: (919) 612-5296	
Qualified Professional: Triangle Pond Management	E-mail: aquatics@trianglepondmanagement.com	Phone: 919-398-3221	
Begin Date: April 2024	End Date: March 2025	Signature: Charles Robertson	

Date	BMP Type and ID#	Inspected By:	Cause for Inspection	Conditions Requiring Correction	Comments and Actions Taken
4/22/24	All	Justin T.	Maintenance	Trash/Debris/Algae/Woody vegetation	Removed/Controlled
5/29/24	All	Anthony M.	Maintenance/Mowing	Trash/Algae/Woody Vegetation	Removed/Controlled
6/20/24	All	Justin T.	Maintenance	Trash/Debris/Unwanted Vegetation	Removed/Controlled
7/30/24	All	Dylan C.	Maintenance/Mowing	Trash/Unwanted Vegetation	Removed/Controlled
8/26/24	All	Christian A.	Maintenance	Trash/Debris/Unwanted Vegetation	Removed/Controlled
9/24/24	All	Anthony M.	Maintenance/Mowing	Trash/Debris/Unwanted Vegetation	Removed

Date	BMP Type and ID#	Inspected By:	Cause for Inspection	Conditions Requiring Correction	Comments and Actions Taken
10/18/24	All	Andrew D.	Maintenance	Trash/Debris/Unwanted Vegetation	Removed/Controlled
11/7/24	All	Connor D.	Maintenance/Mowing	Trash/Debris/Sediment	Removed
12/30/24	All	Dylan C.	Maintenance	Trash/Debris/Unwanted Vegetation	Removed/Controlled
1/27/25	All	Matt J.	Maintenance	Trash/Debris/Sediment	Removed
2/28/25	All	Greg V.	Maintenance	Trash/Debris/Sediment/Unwanted Vegetation	Removed/Controlled
3/28/25	All	Colin R.	Maintenance	Trash/Debris/Sediment/Unwanted Vegetation	Removed/Controlled

Instructions: Record all inspections and maintenance activities for all SCMs at the facility on this form. Use additional log sheets and/or attach extended comments or documentation as necessary. Submit a copy of this completed Stormwater Operations and Maintenance Log Sheet in the Annual Inspection Report. Start a new log at the time of submission. More instructions about SCM inspection submittal guidelines can be found at this <u>website</u>. The following notes provide guidance for completing the Stormwater Operations and Maintenance Log Sheet.

- BMP ID# If applicable, use ID# from the approved site plan.
- Inspected by Note all inspections and maintenance activities on this form, including the required independent annual inspection.
- Cause for inspection Note if the inspection is routine, pre-rainy-season, post-storm, annual, or in response to a noted problem or complaint.
- Conditions Requiring Correction Note any condition that requires correction or indicates a need for maintenance.
- Comments and Actions Taken Describe any maintenance performed or will need to be performed in the future.