

PARTS BULLETIN

DATE 2018

EEPB1801

SUBJECT: BUSH HOG 98371 TURF CHAMP BLADE SPINDLE REPLACEMENTS

ENCORE 362044

Bush Hog Models TC-180, TC-200, TC-220 with 52" & 61" Decks

Bush Hog Spindle assembly part number 98371 and Encore part number 362044 are no longer available and will need to be replaced with the current style spindle part number 583106.

When replacing an old style spindle assembly with the current style, you will have to replace the other spindles on the deck along with the pulleys and accompanying hardware.

For Spindle Replacement on 52" & 61" Decks order the following:

- 3 of 583106 Spindle
- 3 of 583107 Pulley
- 3 of 583110 Pulley Spacer
- 3 of 105269 Pulley Washer
- 3 of 105010 Pulley Lock Washer
- 3 of 104511 Pulley Nut
- 3 of 583109 Blade Spacer
- 3 of 583108 Blade Spring Disc Washer
- 3 of 100347 Blade Bolt

