

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 06 September 2021
Australia – Victoria

No. 268 - 2021

Local Port of Port Phillip

Portsea

Port Phillip Heads Marine National Park – Portsea Hole Southern Buoy Reinstated

Date: **Immediate**

Previous Notice: 151(T)-21 is referred and cancelled

Details: Mariners are advised that the lit special mark buoy, with characteristics Fl.Y.5s, marking the southern boundary of Portsea Hole at approximate location: 38°18.817'S, 144°42.750'E (WGS84), has been reinstated.

Mariners are advised to navigate with caution and within the speed limit within the vicinity of Portsea Hole.

Charts & Publications

Affected: AUS 144, 158

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

A/Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.