

- 1 Make sure USB cord is plugged in the back of the computer
- 2 Make sure Power cord is connected (you will see a red light in the scanning slot for few seconds after connecting the power)
- 3 Go to "start" (Circle/window at bottom left corner of the screen)
- 4 Go to "control panel" (if you are in "category view" change to "small icons" or "Classic view")
- 5 Click on system
- 6 Click on "device manager"
- 7 If you see "KeyScan KS810-P USB2.0 Scanner" under Imaging Devices - our driver is already installed.
- 8 See if you have a yellow exclamation mark or question mark by "USB 2.0 Scanner" (it might be under "imaging devices" or under "other devices")
- 8 Right click on the "USB2.0 Scanner" and click on "update driver"
- 9 Click on browse my computer for driver software
- 10 At "search for driver at this location" go to:
 - For 64 Bit: C:\Program Files (x86)\KeyScan\KS810-P\Control\Driver\64bit
 - For 32 Bit: C:\Program Files\KeyScan\KS810-P\Control\Driver\32
- 11 Click next and follow the wizard directions

At any stage Vista, Win 7, 8, or 10 might ask for permission to continue the driver installation – please allow

After driver install please calibrate your scanner

- Go to "KeyScan imaging"
- Click on "file"
- Click on "Calibrate Scanner"
- Follow on screen directions

Thank you