













	4500	CSX Number	Tie Plugger (TPM)	
FMC	4501	Not Assigned	Main Frame Assy.	
FMC	4501-500	090.4501500.1	TPM Brake Pivot Arm Weldment for Rear Pivot Axle	
FMC	4502	Not Assigned	Bolt on Cab assembly	
FMC	4503	Not Assigned		
FMC	4504	Not Assigned		

FMC	4505	Not Assigned		
FMC	4506	Not Assigned		
FMC	4507	Not Assigned		
FMC	4508	Not Assigned		
FMC	4509	090.0004509.1	Tap Block	

FMC	4510	093.0004510.1	TPM Cab Corner Shelf	
FMC	4511	090.0004511.1	TPM Replacement Side Rubber Step Upgrade	
FMC	4512	090.4512000.1	TPM Side Hanging Step	