



DESTACADO

BOTADORES PCIO INDIV. SE VDE X CAJA

11-34150873 what's app.

[hobras@gmail.com](mailto:hobras@gmail.com)

LISTA ACTUALIZADA AL 03 DE MARZO 2021

REPUESTOS FORD Y VOLKSWAGEN

HB	OEM	DESCRIPCION	OR	P/LISTA	
10007	<b>T71953513A</b>	PLANCA GIRO F100 92/98	ARG.	838	
10040	<b>D4TZ 13341 A</b>	PLAQUETA GIRO F100 74/77	ARG.	1234	
10046	<b>D3DZ 13341 A</b>	PLAQUETA GIRO FALCON 73/77 CON BALIZA	ARG	2971	
10047	<b>D8DZ 13341 A</b>	PLAQUETA GIRO FALCON 78/80	ARG	3331	
10048	<b>D9TZ 13341 A</b>	PLAQUETA GIRO F10081/83 -FACL 80/82	ARG	3003	
10049	<b>D8TZ 13341 A</b>	PLAQUETA GIRO F100 79/81	ARG.	3331	
10052	<b>E7TZ13305A</b>	PLAQUETA/PAL. GRO/BNA F100 82/	ARG.	3900	
10053	<b>D4TZ11572A</b>	CONT. ARR. FALC/F100 ( SW 992)	ARG	1544	
10065	<b>86AU 11572 A</b>	CONT.ARRANQUE ESCORT 88/	ARG	1011	
10066	<b>547 905 865</b>	CONTACTOR ARRANQUE ESCORT 92/ORION	ARG	1245	
10067	<b>95AB11572AB</b>	CONTACTOR ARRANQUE ESCRT 97/	ARG	1245	
10068	<b>89FB 11572AB</b>	CONTCTOR FIE/KA MV	ARG	1245	
10069	<b>2S6511572AA</b>	CONT.ARRANQUE FIE-ECO-*KA 02/08	ARG	1227	
10073	<b>D4DZ13305A06</b>	PALANCA GUIÑO FALCON 74/78	ARG	750	
10074	<b>D3DZ13305A</b>	PALANCA GUIÑO FALCON 73/77	ARG	750	
10075	<b>D8DZ13305B</b>	PALANCA GUIÑO FALCON 78/80	ARG	750	
10077	<b>D8TZ 13305 A</b>	PALANCA GUIÑO F100 78/80	ARG	750	
10078	<b>D9DZ13305A</b>	PALANCA GUIÑO FALC.80/82-F10081/83	ARG	750	
10079	<b>E2TZ13305AP</b>	PAL.GIRO/BOC.FALC 82/F10082	ARG.	976	
10088	<b>7E0905865</b>	CONTACTOR ARRANQUE AMAROK	CHINA	1267	
10092	<b>7S65 14529 AA</b>	TECLA ALZ CRIST ECOSP/RANGER CUADRUPLE	CHINA	2106	OF.
10093	<b>7S65 14529 BA</b>	TECLA ALZ CRIST ECOSP/RANGER DOBLE	CHINA	1201	
10097	<b>95AG 14K147 CA</b>	CONMUTADOR LUCES ESCORT 97/	ARG.,	4810	OF.
10098	<b>97KG14K147 CB</b>	COMANDO LUCES KA 97/99 S/BALIZA	ARG.,	4621	OF.
10100	<b>97KG014K147 BB</b>	COMANDO LUCES FIE/KA/ECOSPORT	ARG.,	4810	OF.
10103	<b>89FB3B734A2D</b>	MOVIMIENTO DIRECCION FTA 89/96-K 96/ 00	CHINA	2167	
10390	<b>70993658</b>	KIT DISTRIBUCIÓN RANGER 2,0	CHINA	17667	
10393	<b>2S4 415501</b>	MOV.DIR. F100 92/98 IMP.	CHINA	4775	
10398	<b>1L542450X</b>	EJE PED RANGER COMPLETA CON BUJES 98/12	ARG	698	
10908	<b>928F-12K073-A</b>	SENSOR ROT.CIG. ECOSPORT , FOCUS 1.6/MON 2TER THOMSON		6553	
10401	<b>BF7T4635A</b>	CRUCETA RANGER. 97/ ARB	INDIA	1680	
10409	<b>LTK829998</b>	KIT BULON Y TCA RAP. CAJA CARGA F100 92/	ARG.	560	
10410	<b>89AG3W007AA</b>	TRICETA SIE 1.6-FIE MV 30MMX 22E	IMP.	1824	
10414	<b>XS4C 3W007AA</b>	TRICETA FOC.KA.FTA 00/ 30.5MM X 21	IMP	1824	
10415	<b>96FG 3W007 AC</b>	TRICETA KA 30.5MM X22	IMP	2612	
10416	<b>XS4C 3W007DA</b>	TRICETA OSCILANTE ECO/FOC 41.5MM X 24E	IMP	4056	
10417	<b>XS4C 3W007CA</b>	TRICETA FOCUS OSCIL. 33.9MM X 23E	IMP	3379	

10419	<b>3W007</b>	TRICETA OSCIL. ECO/FTA KINETIC 40MMX22E	IMP	<b>4333</b>
10440	<b>EITZ11654A</b>	LLAVE DE LUZ F100 82/91	CHINA	<b>2195</b>
10479	<b>2H0857500C</b>	REP. COMPL ESP. AMAROK	ARGENT	<b>1460</b>
10601	<b>2S6Q 8A586 AD</b>	CARCAZA TERM COMPL.FIE/ECOSP 1.4 DIESEL	CHINA	<b>4657</b>
10615	<b>9M5Q 8A586 BA</b>	CAJA TERMOSTATO ECOSPORT 2013/ 1.5 DIESEL	CHINA	<b>6257</b>
10626	<b>6S6511572AA</b>	COLLAR IGNIC.C/CONT. FIE,KA,ECO 02/12	CHINO	<b>2522</b>
10635	<b>2M5T 14529 DB</b>	TECLA ALZ CRIST FOCUS CUADRUPLE	CHINA	<b>2871</b>
10639	<b>98AB11572 BC</b>	CONTACTOR ARRAN ECO/FTA/FOC/TRANS	CHINO	<b>1970</b>
10643	<b>86VB 11572 BC</b>	CONTACTOR ARRANQUE TRANSIT MV	CHINO	<b>1535</b>
10789	<b>YS4Z 14529 C</b>	TECLA ALZ CRIST FOCUS ONE SIMPLE	CHINA	<b>704</b>
10845	<b>3M5H 18B647 N</b>	RESISTENCIA AA CAL. FIE/ECO/FOCUS 07/	CHINA	<b>1780</b>
10846	<b>940002904</b>	RESIST AIRE ACOND. FOCUS L/NVA	IMP	<b>8347</b>
10847	<b>325959263-1</b>	RESISTENCIA AA CALEF GALAXY 1.8 2.0	CHINA	<b>1899</b>
10857	<b>91AB 9A819 AC</b>	RESIST.ELEC.ESC 96/8 KA MV C/AA	IMP	<b>1970</b>
10858	<b>547-959493</b>	RESIST.ELECT.GALAXY-ORION -2 SALIDAS	IMP	<b>788</b>
10898	<b>83MU 17K692 A</b>	BOMBA LAV. FALC/F100/SIERRA/ESC	CHINA	<b>711</b>
10901	<b>1S71 17K624 FE</b>	BOMBA LAVP FOCUS C/ LAV.LTA TRAS.	CHINA	<b>1067</b>
10908	<b>928F 12K073 A</b>	SENS CIG FOC 1,6 2 TERM. -MONDEO	THOMSON	<b>6553</b>
10910	<b>4M5X 12K073AA</b>	SENS.LEVA ECO SIGMA 1,6 DRAGON 1,5	CHINA	<b>3300</b>
10915	<b>XS6F97479AB</b>	SENSOR MAP FIE,FOC,ECO 1.6 ROCAM -KA 1.0/1.6 4T	MTE THOM	<b>3879</b>
10918	<b>F2TZ-9B989-A</b>	SENSOR MARIPOSA F100 4.9 95/98 SENT.HORA.	MTE.THOM	<b>10193</b>
10920	<b>F5RZ-9B989-A</b>	SENSOR MARIP MOND.2.5 95/ SENT.ANTI-HORA	MTE THOM	<b>2635</b>
10925	<b>98AB 9E731 AGH</b>	SENSOR VEL.FIE.,FOCUS SIGMA MN	CHINA	<b>2810.7</b>
10968	<b>3L5Z 11654 BA</b>	LLAVE LUZ TABLERO RANGER 97/2012	CHINA	<b>2670</b>
10969	<b>F81Z 11654 BC</b>	LLAVE DE LUCES F100 99/05 USA	USA	<b>AGOTADO</b>
10970	<b>1450955</b>	TAPA TERM CONEX.AGUA ECO/FOC/MOND 2.0	CHINA	<b>3263</b>
10978	<b>94FG11667A1A</b>	BOTON BALIZA ESCORT,KA,FIESTA,ECOSP.	ARG	<b>191</b>
10982	<b>076906051B</b>	SENS. GASS AMAROK 2.0 MET THOMSON	BRASIL	<b>5690</b>
11010	<b>8N15 14529 BB</b>	TECLA ALZA CRIST ECOSP 08/12 CUADR	CHINA	<b>4086</b>
11032	<b>1143426</b>	RELAY BUJIPRECAL FIESTA 2002-2014 1.4 DIESE	CHINA	<b>6060</b>
11059	<b>C1B1 9A819 CE</b>	RESISTENCIA ELECT.ECOSP SIGMA 1.6	ORIGINAL	<b>3682</b>
11070	<b>8N1514529AA</b>	TECLA ALZA CRIST ECOSP/FTA 08/12 SPL	CHINA	<b>1205</b>
11073	<b>97KG 13A350 AC</b>	TECLA BALIZA FORD KA MV/ TRANSIT 2000	CHINA	<b>1989</b>
11096	<b>2S65 14529 AA</b>	TECLA LEV CRIST ECOSP /FITA 2003/6 PIN *-RANGE	CHINA	<b>612</b>
11099	<b>1K4959857B</b>	TECLA CUAD. AMAROK 10 TERM.	CHINA	<b>2003</b>
11168	<b>96FG 14528 BC1</b>	TECLA ALZ CRIST S/MCO DOBLE KA 97/08	CHINA	<b>1483</b>
11171	<b>96FG 3W007 AA</b>	TRICETA FIESTA/COURRIER 32MM X 22E	IMP.	<b>1332</b>
11194	<b>1151</b>	TRICETA RANGER / EXPLORER 327MM X 34 E	IMP	<b>2479</b>
11199	<b>F2DZ 11666A</b>	PERILLA LLAVE DE LUCES RANG 98/12	TURKEY	<b>824</b>
11212	<b>AV11 18B647 AB</b>	RESISTENCIA AA CALEF. ECOSP 2012/TRANS	CHINA	<b>1936</b>
11217	<b>93BG 14A132 AB</b>	TECLA ALZ CRIST. ESCORT 97 CUADRUPLE	CHINA	<b>3300</b>
11218	<b>96FG 14529 AC</b>	TECLA ALZA CRIST FIE 96/02 MONDEO SIMP 7 PINES	CHINA	<b>587</b>
11219	<b>95BG 14529 AB</b>	TECLA ALZA CRIST ESC 97/MOND.TRANS. SIMP 6 PIN	CHINA	<b>587</b>
11220	<b>98AG 14529 AC</b>	TECLA ALZ CRIST FOCUS 99/08 DOBLE	CHINA	<b>1622</b>
11221	<b>96FG 14529 AD</b>	TECLA ALZ CRIST SIMP C/MCO KA H/2012	CHINA	<b>853</b>

11226	<b>95AG 14529 BA</b>	TECLA ALZA CRIST FOCUS 97/ DOBLE	CHINA	<b>2502</b>
11227	<b>96FG 14529 AD</b>	TECLA A.CRIST PTA DER. FIESTA 2/4 PTAS. SIMPLE	CHINA	<b>704</b>
11228	<b>98FG14529 BC</b>	TECLA A.CRIST DBLE C/MCO DOBLE KA 2012/	CHINA	<b>1483</b>
11230	<b>D4TZ 13305 A</b>	PALANCA GUIÑO F10074/78	ARG	<b>750</b>
11231	<b>D9TZ13305A</b>	PALANCA GUIÑO FALCON HASTA 82	ARG	<b>772</b>
11234	<b>7S5519A860AA</b>	RESISTENCIA AA CALF.FOCUS/MONDEO	CHINA	<b>1535</b>
11235	<b>F7UH 19A706 AA</b>	RESIST. AA/CALE. EXPL.F100 99/12	CHINA	<b>1295</b>
11236	<b>4C2Z 19A706 BA</b>	RESIST. F250/350 -F4000	IMP	<b>1298</b>
11237	<b>AB39 19A706 AA</b>	RESISTENCIA AA CALEF. RANGER 2012	CHINA	<b>1810</b>
11244	<b>93BB 17H624 AA</b>	BOMBA LAVAPARAB ESCORT/FTA/FOC/KA C/L.LTA	CHINA	<b>949</b>
11248	<b>6M2T 14529 DA</b>	TECLA ALZ CRIST FOC.II 1.6/2.0 06/10 SIMPLE	CHINA	<b>771</b>
11249	<b>AS6515K218AA</b>	TECLA ANTINEBLA FORD KA 2010/14	CHINA	<b>1260</b>
11260	<b>97FG3C083B1A</b>	SOPORTE CON RULEMAN SEMI EJE FIESTA 30MM	ARG	<b>2980</b>
11261	<b>XS6E6268AAKIT</b>	KIT DISTRIBUCION ROCAM 1.6	CHINO	<b>3727</b>
11266	<b>BF8T 4800C</b>	SOP. CARDAN RANGER 98/ 2.5	IMP	<b>3197</b>
11268	<b>1764875</b>	SENSOR MULTIF. RANGER 2012 2.2/3.2 TRANSIT	CHINA	<b>8 530.00</b>
11271	<b>97AG3C083A</b>	RUL.SEMI EJE COUR,FTA,ECO,FOC,KA	CHINO	<b>1574</b>
11283	<b>059-109417-G</b>	BALAN DE VALVULAS AMAROK TDI MELLING USA	usa	<b>1610</b>
11284	<b>70992868X</b>	COJINETE EJE VENTI RANGER/F100 MAXION 2.5	CHINA	<b>1507</b>
11288	<b>03L 109243 KIT</b>	KIT DIST. AMAROK 2.0 DIE VKMA001148/0126	EWA	<b>15959.2</b>
11290	<b>2H0501171</b>	RUL.RDA TRAS. AMAROK	CHINA	<b>5770</b>
11310	<b>BGTIT 4800 A</b>	SOPORTE CARDAN RANGER 3.0	ARG	<b>3507</b>
11311	<b>2H0598351</b>	SOP.CARDAN AMAROK	CHINO	<b>4477</b>
11318	<b>06C141671D</b>	CRAP.EMBRAGUE AMAROK 2.0	CHINA	<b>10778</b>
11319	<b>98FP9H307DB</b>	BOMBA DE NAF COMPLFIESTA - KA 1.0/1.3/1.6	CHINA	<b>12631</b>
11320	<b>5L55 9H307 CA</b>	BOMBA COMB RANG 3.0	CHINA	<b>16883</b>
11322	<b>98AP 9H307 AC</b>	BOMBAE NAFT SOLA FOCUS 1.8 2.0 ZETEC 1.6	CHINA	<b>4862</b>
11324	<b>5L55 9H307CA</b>	BOMBA DIES SOLA FORD RANGER 3.0	CHINA	<b>5671</b>
11325	<b>XS6E6C501ACX</b>	BOT HIDR Flta KA FOCUS ECOSPORT ROCAM 1.6 8V	USA	<b>1013</b>
11328	<b>C8AZ 6500 A</b>	BOT.HID. FALC/F100 7 BANC. Cja x 4 unid.	USA	<b>821</b>
11343	<b>B52Q 6500 BA</b>	BOT.HID. MOT.PUMA 2.2/3.2 RANG-TRANSIT(4)	USA	<b>2208</b>
11344	<b>6C1Q 6K551</b>	BAL DE VALV. C/ MIC.BOT. Puma 2.2/3.2 x cja 4u	USA	<b>1928</b>
11346	<b>2H0407615B</b>	MAZA DEL RDA AMAROK S/RUL	CHINA	<b>9547</b>
11373	<b>5M5Q10D310AAX</b>	MANCHON TENSOR ALT. FOCUS TDCI H/2008	CHINO	<b>3343</b>
11415	<b>XS6E 6K255 KIT</b>	GUIAS ROCAM 1.6 JUEGO	CHINA	<b>2442</b>
11424	<b>2S6G 8A586 B1A</b>	CARCAZA C/TERM. ALUM.ROCAM COMP	CHINA	<b>4035 OF.</b>
11426	<b>2S6G 8A586 B1A</b>	CARCAZA C/TER, PLAST. ROCAM COMP	CHINA	<b>3441 OF.</b>
11431	<b>97FG3C083A1A</b>	SOPORTE C/ RULEMAN S/EJE FTA,COURR 0.45MM	ARG	<b>3528</b>
11443	<b>7L5Z 13K359 AA</b>	CONMUT.MULT. RANG 05/12 19 pines	TAIWAN	<b>3817</b>
11444	<b>2S65 9A819 BB</b>	RESISTENCIA ELECT. ECOSPORT/FTA /KA	CHINO	<b>1749</b>
11448	<b>F57Z 14529 AB</b>	TECLA ALZ CRISTAL RANGER DBLE 95/03	CHINA	<b>2782</b>
11449	<b>F57Z14529 A</b>	TECLA ALZ CRISTAL RANGER SIMP 95/03	CHINA	<b>1855</b>
11495	<b>96FF10C382 BH</b>	TENS.ALT. GATE FOCUS 2 AG.99/2000	CANADA	<b>33647</b>
11513	<b>1445915</b>	TENSOR ALT. TRANSIT 2.4 2011	CHINO	<b>7757</b>
11525	<b>CN153W007AA</b>	TRICETA ECOSPORT D.OSC. 38.2MM X 22	IMP	<b>3740</b>

11568	<b>6M5G 9K478 AB</b>	CJA TERM.MONDEO/KUGA 2.5 DURATEC,	TURKEY	<b>6608</b>
11575	<b>EB39-8C617-CA</b>	ENB.VISCOSO RANG.2.12/TRANSIT PUMA 2.2-3.2	AUSTRIA	<b>AGOTADO</b>
11580	<b>BBBQ 8A586 AB</b>	CARC.TERM. ALUM. RANG. 2012/S/BBO	ARG.	<b>3957</b>
11671	<b>XL5Z 14B166 BA</b>	INTERRUP.TRACC.4X4 EXPL.RANG 97/12	USA	<b>7555</b>
11673	<b>FIEZ 13350 A</b>	TECLA BALIZA FOCUS 2015	MEXICO	<b>2117</b>
11678	<b>8N15 11666 AA</b>	TECLA ACCION-TRACC.4X4 ECOSP 07/12	ORIGINAL	<b>3175</b>
11692	<b>BM5T 14529 AB</b>	TECLA ALZ CRIST FIE 2014/15 4 PINES	ORIGINAL	<b>826</b>
11694	<b>FIEZ 14529 A</b>	TECLA ALZ CRIST TRAS. FIE 2015/	ORIGINAL	<b>927</b>
11718	<b>96FG 3W007AB</b>	TRICETA FIESTA/KA/COURR. 32MM X 20E	IMP.	<b>1802</b>
11724	<b>1185</b>	TRICETA MOND. D.OSCIL. 38X33E	IMP	<b>4380</b>
11726	<b>XS4C 3W007BA</b>	TRICETA FOCUS/ESCORT TD 37MM X 30 E	IMP	<b>2760</b>
11741	<b>1373385</b>	CAJA TERM MONDEO 07/14 DURATORQ DIES.	TURKEY	<b>7138</b>
11751	<b>1731782</b>	CAJA TERMOSTATO TRANSIT 2012-2014 2.2	TURKEY	<b>5246</b>
11752	<b>1717589</b>	TAPA DISTRIB RANGER 12/-17 2.2 PUMA DIESEL	TUERKEY	<b>5909</b>
11753	<b>1477409</b>	SENSOR NIV.ACEITE TRANSIT 2.2 MOT PUMA	ESPAÑA	<b>8804</b>
11755	<b>FIDZ 6500 A</b>	BOT HID. F100 4.9 Caja x 4 unid.	USA	<b>1465</b>
11756	<b>03L109521A</b>	BOT HID. AMAROK 2.0/3.0 Melling -USA	USA	<b>1083</b>
11767	<b>938M6500B2A</b>	BOT.HID. ESCORT,MOND. 16V MOT ZET. BLI X8U	USA	<b>1007</b>
11781	<b>1473714</b>	BASE FILTRO ACEITE DURATEC 2.0 NAFTA	CHINA	<b>2560</b>
11784	<b>2H0407627A</b>	RUL.RDA DEL AMAROK	CHINA	<b>4650</b>
11805	<b>1053644</b>	ACTUADOR PERILLA ESC MOND T 99/02	BRASIL	<b>821</b>
11806	<b>5S43 2B384 AA</b>	ANILLLO SENSOR ABS TRAS.ECO.FTA.FO	BRASIL	<b>1920</b>
11807	<b>1145964</b>	BASE FILTRO ACEITE ECOSPORT 2003/ 1.4 DSL	CHINA	<b>1080</b>
11808	<b>1203004</b>	BASE FILTRO ACEITE MONDEO /TRANSIT	CHINA	<b>1576</b>
11809	<b>1303477</b>	BASE FILTRO ACEITE TRANS 10/14 2.2-2.4 MON 07/	TURKEY	<b>1111</b>
11810	<b>93BB 17K624 AA</b>	BOMBA LAVP. COURR/KA/FOC 1 SALIDA	CHINA	<b>895</b>
11816	<b>2-1036</b>	TRICETA RANGER 4X4 98/04 39.7MM X 34E	IMP	<b>3283</b>
11819	<b>7L55 3W007 A</b>	TRICETA RANGER /KUGA D.OSC. 46.77MM X 27E	IMP	<b>8832</b>
11823	<b>XS6E 6L266 AH</b>	SENSOR HID.CADENA ROCAM 1.6	CHINA	<b>2551</b>
11825	<b>ERR 1471 C</b>	VAL.GASES MAXION INTERNATION	BRASIL	<b>1445</b>
11829	<b>1372333</b>	TERMOST.REF.ACEITE TRANSIT 10/14 2.2-2.4	TURKEY	<b>1574</b>
11833	<b>BK2Q 6K261 AA</b>	SENSOR CADENA TRANS 10/12 2.2	ORIGINAL	<b>8447</b>
11857	<b>XS6H 9A819 CA</b>	RESISTENCIA ELECT. COURRIER 1.8 DIESEL	CHINO	<b>1836</b>
11858	<b>3F2Z 18591 AA</b>	RESISTENCIA AA CALEF. FIESTA 2010/2013	CHINA	<b>3839</b>
11859	<b>7E0959263C</b>	RESIST.AIR/CALEF. AMAROK	CHINO	<b>2437</b>
11862	<b>7S4Z 14529 C</b>	TECLA ALZ CRIST FOCUS 00 S/CIERRE CENT 1 TOQL	TURKEY	<b>2030</b>
11864	<b>1C3Z 11654 AB</b>	LLAVE DE LUCES F100 05/12 USA	USA	<b>15759</b>
11865	<b>4C3Z 13K359AAA</b>	CONMUT. MULT.F100 02/12 19PIN	TAIWAN	<b>11134</b>
11866	<b>F57Z 11A152 A</b>	INTERR. EMB. RANG 94/F100 99/ 14000 - EXPL	USA	<b>1910</b>
11866	<b>F57 11A152 A</b>	INTERRUP EMBRAGUE RANG H/99 F100 99/ EXPL.	USA	<b>1910</b>
11867	<b>1420678</b>	ENFRIADOR COMP FOCUS 1.8 DIESEL	CHINA	<b>14842</b>
11872	<b>73194</b>	SENSOR AGUA GASOIL RANG 3.0	CHINA	<b>3574</b>
11877	<b>YL5Z 9F775 BA</b>	VAL.PRES.COMB RANG/EXPL.NAFTA	BRASIL	<b>AGOTADO</b>
11915	<b>8S4Z6G004A</b>	SENSOR TEM. FOCUS,ECO 2.0 DURATEC.	MTE THOM	<b>1205</b>
11924	<b>E5TZ 9J306 BA</b>	FILTRO MED.COMB. F100 99/RANG	USA	<b>2592</b>

11925	<b>BK2Q 6K780 A</b>	RETEN T/VAL. Puma 2.2 -3.2 Rang/Tra	BRASIL	<b>1451</b>
11928	<b>93BG17B676BA</b>	COMANDO ESP. ECOSP. 03/12	CHINA	<b>1661</b>
11929	<b>CN15 17B676 AA</b>	COMANDO ESP. ECOSPORT 12/17 ORG	CHINA	<b>1986</b>
11930	<b>325 959 565 105</b>	COMANDO ESP ELE F100 92/98	CHINA	<b>1986</b>
11931	<b>BG5T6500AA</b>	BOT HID. RANGER 3.0 CJA 4 UNID.	USA	<b>1591</b>
11932	<b>1057328</b>	GUIA SOP.LAT. PORTON TRANSIT 97/99	TURKEY	<b>5358</b>
11933	<b>1052396</b>	CERRADURA PORTON TRANS 97/99	TURKEY	<b>8248</b>
11934	<b>86VB V266A62AI</b>	MANIJA INT. PORTON TRANS C/CBLE 97	CHINA	<b>1677</b>
11935	<b>1770524</b>	SENS.TEMP FOC 08/13 1.8 DS. THOMS	THOMSON	<b>1412</b>
11938	<b>8V2Z12B579A</b>	SENSOR FLUJO AIRE MAF 2.ECO/FIE/RANG 2.2/3.2	IMP	<b>11176</b>
11939	<b>1355231</b>	BRAZO/PEST. CAPOT FOC/KUGA 08/12	CHINA	<b>2150</b>
11940	<b>1145941</b>	ENFRIADOR ECO/FTA 1.4 Diesel	CHINA	<b>6856</b>
11941	<b>7S7Z 8B856 B</b>	ENFRIADOR ACEITE mot.SIGMA 1.6 2015/	CHINA	<b>9222</b>
11943	<b>1229499</b>	TUBO INTERC.FOCUS 99/08 1.8 D	ARG.,	<b>1879</b>
11944	<b>1102636</b>	TERMOSTATO REFRIG.ACEI TRANSIT 2000/01	UCRAN	<b>1619</b>
11949	<b>1746832</b>	TECLA ALZ CRIST FOCUS 2013/ 6 PINES	GERMAY	<b>3181</b>
11955	<b>YL5Z19W616AA</b>	MOTOR ACT.A/A CALF.RANG H/2011	CHINA	<b>8742</b>
11956	<b>3C3Z19E616BA</b>	MOTOR ACT.AA/CALE.F100 99/	CHINA	<b>9625</b>
11963	<b>928M9K478AFC</b>	CJA TERM. ESC. 1.8 COMPLETA	CHINA	<b>8899</b>
11964	<b>928M 6K478AF</b>	CJA TERM. ESCORT 1.8 ZETEC	CHINA	<b>5654</b>
11965	<b>1119869/1227801</b>	JGO GUIAS DIST. ECO/FOC/MOND 2.0 DURATEC	TURKEY	AGOTADO
11968	<b>CN1Z 14A626 A</b>	MODULO ACT.CERR. PORT. ECOSP 2012/	ORIGINAL	AGOTADO
11969	<b>6M8Z6B288C</b>	SENSOR POS A/ DE LEVAS ECOSP08/17 - FOC-MOND	CHINO	<b>7047</b>
11973	<b>1087980</b>	GUIA SOP.LAT.PORTON INF. TRA 97/99	TURKEY	AGOTAD
11975	<b>4800-V6</b>	SOPORTE CARDAN EXPLORER, RAGER V6 30MM	IMP	<b>2414</b>
11987	<b>974F6A785BA</b>	TAPA ACEITE TRANSIT 97/ 1018555	TURKEY	<b>1152</b>
11988	<b>1781598</b>	DIAFRAG REC.ACEITE MOND/KUG 2.5	BRASIL	AGOTADO
12001	<b>059109417F</b>	BALANC AMAROK PASS VENTO A3 A4 2.0 3.0 TDI	usa	<b>1610</b>
12013	<b>1211772</b>	ENFRIADOR ACEITE TRANSIT 2000-2001	CHINA	<b>8994</b>
12017	<b>1108931</b>	SENS.TEMP.FOCUS 99/05 2.0/MOND	THOMSON	<b>3264</b>
12035	<b>1405017</b>	ENFRIADOR ACEITE FOCUS 1.8 00/08 DIESEL	CHINA	<b>6745</b>
12036	<b>X67E 6A228 CC</b>	TENS.ALT.,MONDEO DURATORQ DIE	ITALIA	<b>13443</b>
12069	<b>1531004</b>	CONEX.AGUA FIE,KA,FOC 1.6 SIGMA 7M5G 8K556AG	TURKEY	<b>3570</b>
12076	<b>5Z0919149</b>	SENS.CIG. FIE/ECO 1.4 TDCI	PKW	<b>2698</b>
12084	<b>928M9K478AG</b>	CJA TERM .ESCORT 1.6 ZETEC ROSC GDE	CHINA	<b>8899</b>
12081	<b>1676580</b>	CARTER ACEI TRANS 2010-2012 / PUMA 2.4 DIESEL	SPAIN	<b>11745</b>
12099	<b>1748942</b>	POLEA DE CIG. TRANSIT 2.2/2.4 PUMA DIES.	ESPAÑA	<b>21211</b>
12110	<b>1126980</b>	CONECTOR BBA AGUA RANG 2012/ TRANS 2010/	TURKEY	<b>1424</b>
12111	<b>1494057</b>	MANIJA PORTON TRANSIT 00/01-10/14	CHINA	<b>3184</b>
12117	<b>XS6E 6K255 JGO</b>	KIT GUIAS MAS TENSOR HID.ROCAM	CHINA	<b>4908</b>
12137	<b>XS6G 6M293 A1B</b>	TAPA VALV ZET/ROC C/JTA 99/04	BRASIL	<b>8105</b>
12138	<b>2S6G6M293A1B</b>	TAPA VALV ZET/ROC C/JTA 04/08	BRASIL	<b>8105</b>
12139	<b>AB39 4W602 AA</b>	SOOP.CARDAN RANGER 2012/	NAC	<b>6030</b>
12143	<b>F57Z 17B676 A</b>	COMANDO ESPEJO EL RANGER 98/	ORIGINAL	<b>2230</b>
12144	<b>03L957147</b>	SENSOR DE FASE. A/L AMAROK 2010 2.0 TDI	CHINO	<b>4416</b>

12145	<b>BV61 18K179 YD</b>	MANG.CALEF.FOCUS 13/19 DURATEC	HUTCHINS	<b>AGOTAD</b>
12148	<b>AB39 19E619 BA</b>	MOTOR ACT. CALEF. RANGER 2012	CHINA	<b>AGOTAD</b>
12150	<b>AB39 19E619 AA</b>	MOTOR ACT. CALEF. RANGER 2012	CHINA	<b>3764</b>
12156	<b>XS6E6268AA</b>	CADENA DIST. ROCAM	CHINA	<b>1180</b>
12158	<b>5ND959855</b>	TECLA SIMPLE ALZA CRIST. BDE CROM AMAROK	CHINA	<b>1038</b>
12161	<b>1751001</b>	SOPORTE CAJA VELOCIDAD FOCUS 2008/KUGA	original	<b>4715</b>
12163	<b>DS7T 14C376 AA</b>	BOTON INTERRUPT IGNICION FOCUS 08/13	ORIGINAL	<b>2884</b>
12166	<b>7S4Z 14529 B</b>	TECLA ALZ CRIST FOCUS 00/09 6 PINES	CHINA	<b>2225</b>
12172	<b>1405758</b>	SENSOR AGUA ECO/FTA 1.4 ORIG.	ORIGINAL	<b>6642</b>
12175	<b>1633900</b>	CJA TERM.MONDEO 02/07 2.0-2.0 PUMA	TURKEY	<b>4217</b>
12178	<b>1367589</b>	CONEX.MANG.CAL. MOND 07/14 DURAT. DSL	TURKEY	<b>1918</b>
12182	<b>1477141</b>	ENFRIADOR ACEITE MOND. 04/07 DURAT.DSL	CHINA	<b>10044</b>
12185	<b>AB39 13A350 AB</b>	TECLA BALIZA RANGER 12/17 VERS.XL	CHINA	<b>1409</b>
12191	<b>BF8T 12A648 AA</b>	SENSOR TEMP. F100 98/6 CUMM	MTE THOM	<b>1412</b>
12199	<b>BH1T3A003AA</b>	FILTRO COMB.RANGER 3.0 ORIGINAL	ORIGINAL	<b>2980</b>
12201	<b>F65Z14529 AAA</b>	TECLA ALZA CRIST F100 99/2008 SIMP	CHINA	<b>3171</b>
12202	<b>F65Z14529 AAB</b>	TECLA ALZA CRIST F100 99/2008 DBLE	CHINA	<b>3660</b>
12205	<b>1371567</b>	VALV.CALEF. RANGER/TRANSIT	CHINA	<b>1050</b>
12215	<b>1145941C</b>	CARCAZA C/ENF. ECO/FTA 1.4 Diesel	CHINA	<b>15706</b>
12218	<b>1355231</b>	CILINDRO CAPOT FOCUS/KUGA 08/12	CHINA	<b>4451</b>
12223	<b>BE8Z 14529 BA</b>	TECLA ALZ CRISTAL FIE 2010/2013 SIMPLE 6 PINES	CHINA	<b>2498</b>
12224	<b>BE8Z 14529 AA</b>	TECLA ALZ CRISTAL FIE 2010/2013 4+8+7 PINES CUA	CHINA	<b>11597</b>
12228	<b>1S7Z6C315AAA</b>	SENSOR POS.CIGUEÑAL MOT.DURATEC 2.0 ECO, F	CHINA	<b>2823</b>
12240	<b>73193</b>	SENSOR POSC.CIG. RANG 3.0 Aleman	SIEMENS	<b>8885</b>
12241	<b>1102434</b>	REPAR PALANCA CAMBIOS TRANSIT 2000-2009	TURKEY	<b>575</b>
12243	<b>96FF6M091AD</b>	CABLE BUJIA INCAND. ESC.FIE,MOND	ARG.,	<b>1123</b>
12245	<b>E2DZ 18495 A</b>	GrRIFO CALF. FALCON 82 A/A	ARG	<b>2217</b>
12254	<b>AB39 70G298 AA</b>	RESISTENCIA AA RANGER 2012/	CHINA	<b>4114</b>
12260	<b>70420026</b>	GUIA DIST. RANG 3.0	IMP	<b>2069</b>
12269	<b>1737879</b>	SOPE MOT TRANSIT 12-24 2.2 PUMA/DUR DEL	SPAIN	<b>12203</b>
12272	<b>5164985</b>	INTERRUPTOR ARRANQUE ECOSP 06/12 CJA AUTOM.	ORIGINAL	<b>3969</b>
12273	<b>1476110</b>	TERM. FOCUS/MONDEO 2009/ 2.0 DURATEC 16V	CHINA	<b>3759</b>
12275	<b>1494924</b>	SOPORTE CAJA VEL.TRANS 10/14	TURKEY	<b>9966</b>
12277	<b>1746665</b>	ENFRIADOR RANGER 2012/	CHINA	<b>AGOTADO</b>
12278	<b>1746665-C</b>	CARCAZA C/ENFRIADOR RANG 2012 2.2-3.2	CHINA	<b>23665</b>
12280	<b>70420025/26</b>	JGO GUIAS DIST.RANGER 3.0 (2+2	IMP	<b>5601</b>
12281	<b>7040025</b>	GUIA DIST. RANGER 3.0	IMP	<b>1629</b>
12282	<b>F2GZ 1A189G</b>	SENSOR PRES.NEUMATIC. ECO 2017/	ORIG	<b>4002</b>
12283	<b>BK3Q 6C887 NB</b>	SENSOR COMPRESOR TURBO RANG 12/	ORIGINAL	<b>9871</b>
12288	<b>F4FZ 11572 B</b>	INTERRUPTOR IGN. RANGER 97/05	BRASIL	<b>7905</b>
12289	<b>96BM 6K614 AB</b>	TAPA ACEITE FIE 96/99 1.3 ENDURA	BRASIL	<b>1174</b>
12292	<b>1811604</b>	SENSOR POS A/DE LEVAS DURATDIES. RANG/MOND TRA		<b>7308</b>
12295	<b>BK3Z 6881 D</b>	ENFRIADOR ACEITE TRANSIT 10/014 2.2-2.4 PUMA	CHINA	<b>8097</b>
12298	<b>1L5ZEZ 6C315 AA</b>	SENSOR CIG RANGER 2.3 4 CIL.	CHINA	<b>8968</b>
12306	<b>E9TZ9278A</b>	BULBO ACEITE F100 1995-1998 4.9 F5TF9278AA	USA	<b>agotado</b>

12315	<b>1720609</b>	TAPA BASE FILT ACE RANG 12/ 2.2/3.2 PUMA DIES	TUERKEY	<b>AGOTADO</b>
12318	<b>XS6F9F479AB</b>	SENSOR MAP ECOSPORT 2003/ 1.6 ZETEC ROCAM	THOMSON	<b>3879</b>
12319	<b>2SB121405B</b>	DEPOS.FI00 96/98 MWM TD	ORIG	<b>AGOTAD</b>
12320	<b>1440539</b>	MANGUERA FILTRO AIRE TRANSIT 2010-2012 2.4	CHINA	<b>3487</b>
12323	<b>8L5Z 11572 A</b>	INTERRUPTOR IGN. RANG 08/12	USA-ORIG	<b>8355</b>
12324	<b>E9TZ 12A112A</b>	PLACA CAPT. DIST F100 95/98 4.9 USA	USA	<b>10767</b>
12325	<b>1320555</b>	SENSOR TEMP. TRANSIT 00/01 -2010/12	TURKEY	<b>AGOTADO</b>
12327	<b>1733253</b>	CARC.TERM. PLAST.. RANG. 2012/C/BBO	TURKEY	<b>5246</b>
12328	<b>1731782</b>	CJA TERM. TRANSIT 10/12	TURKEY	<b>5246</b>
12329	<b>1148056</b>	SENSOR POS ARB LEVAS ECOSP 2003-10 1.4 DIE	CHINA	<b>3345</b>
12330	<b>7282774</b>	PERILLA COMANDO AA ESCORT 96/2002	TURKEY	<b>823</b>
12331	<b>A2C0000704</b>	VALV.REG.PRESION RANGER 3.0	CHINA	<b>8535</b>
12332	<b>XC45 10884AA</b>	BULBO TEMP.CARGO 81/2006 CUMM	MTE THON	<b>2510</b>
12331	<b>BG5T9350AA</b>	VALVULA REGULADORA PRESION RANGER 3.0	CHINA	<b>8535</b>
12333	<b>1037465</b>	SENS.ARB/LEV ROCAM 1.6 MTE	THOMSON	<b>4336</b>
12335	<b>03L121111AB</b>	CARC TERMOST.AMAROK 2.0 TDI	CHINA	<b>2670</b>
12344	<b>1038298</b>	REPAR PALANCA CAMBIOS TRANSIT 1997-1999	TURKEY	<b>536</b>
12347	<b>1202487</b>	TUBO SAL-AGUA FIE 1.4 (2S6Q 8K512 AA)	CHINA	<b>9670</b>
12348	<b>1685830</b>	TUBO SALIDA AGUA CAL.ECOSP. 13/18 1.5 DIES.	TURKEY	<b>6701</b>
12349	<b>3049449</b>	CONEX.AGUA TUB.MOND V6 2.5 DURATEC	TURKEY	<b>4602</b>
12350	<b>1319480</b>	CARCAZA TERM.COMPL. FOC 1.8/2.0 05/09	TURKEY	<b>3650</b>
12352	<b>4443555</b>	ENFRIADOR ACE. MOND 01/07 3.0 V6 NAFTA	HOLLA	<b>13897</b>
12353	<b>1385380</b>	ENFRIADOR ACEITE FOCUS 1.8 DSL 2008/13	CHINA	<b>7520</b>
12354	<b>AN15 7K387 AA</b>	SELECTORA FIE,KA,FOC,ECO 2010/14	CHINO	<b>AGOTADO</b>
12361	<b>1301461</b>	TRABA MED.COMB ECO 12/FIE 13/FOC 99/20/KUGA	BRASIL	<b>2287</b>
12362	<b>F75Z9A307 AB</b>	TRABA MED.COMB.FI00 99/12 CON JTA.	BRASIL	<b>AGOTADO</b>
12366	<b>1858445</b>	TAPA VALVUL RANG 012/ 2.2 PUMA-TRANS 2.2	TURKEY	<b>AGOTAD</b>
12368	<b>AN15 7K387 AR</b>	REPARACION SELECTORA CBIO ECO 10/14	ARG.	<b>1489</b>
12369	<b>3S4H 9A819 AA</b>	RESIT.ELECT FOC 03/08 ROCAM/ ZET/DUR 2.0	ARG.	<b>3226</b>
12370	<b>056121012A</b>	BBA AGUA ELEC ADIC AMAROK 2.0 TDI BI	CHINA	<b>12921</b>
12383	<b>BG5T9H544CA</b>	SENS.ARB.LEV RANGER 3.0 05/12	TAIWAN	<b>10765</b>
12378	<b>YL5Z13K359BAA</b>	CONMUT MULTIP RANGER 95/98 16 PINES	CHINA	<b>5342</b>
12379	<b>AG9Z9F479B</b>	SENSOR MAP RANGER 2.2/3.2 KUGA, 14/ MOND 11/	THOMSON	<b>3916</b>
12385	<b>E77Z11654B</b>	LLAVE LUCES EXPLORER 92/95-F100 4.9	USA	<b>7398</b>
12388	<b>BC1Q6K2371AA</b>	TAPA VALV TRANS 010-12 2.4 PUMA/DURATORQ	TURKEY	<b>14684</b>
12389	<b>7h0965561</b>	BBA AGUA ELEC ADIC AMAROK 2.0 TDI BI	china	<b>13052</b>
12391	<b>CP9Z-8K556-B</b>	CONEXI AGUA ECOSP/ 17/ 2.0- FOCUS 2.0 2013/ DUF	TURKEY	<b>6753</b>
12392	<b>26105255</b>	POLEA CIUG.ESCORT,GALXY,ORION	ARG	<b>1151</b>
12393	<b>26 103 547</b>	DEFLECT T/ VALV GALAXY/ESCORT/ORION M/AUDI	ARG	<b>393</b>
12394	<b>2S6Q-6L070-JGO</b>	TAPAS DISTRIB FIESTA ,ECOS 1.4 TDCI JUEGO	CHINA	<b>5170</b>
12396	<b>2S61-9S468-AD</b>	ELEC/VULA CANISTER FOCUS/ECOSPORT/C-MAX 2.0 TDCI		<b>9972</b>
12397	<b>1S7Z9J559AA</b>	VALV CTRL AIRE ADMI IMRC RANGER 2001-2012 2.3 DOHC		<b>2144</b>
12398	<b>6142793</b>	CARTER ACEITE FIES 1.3 BL 95/99 86BM-6675-BA	CHINA	<b>9760</b>
12399	<b>1342630</b>	CARTER DE ACEITE FIESTA/ECOSPORT 1.4 TDCI	CHINA	<b>6191</b>
12400	<b>1053869</b>	CARTER DE ACEITE FOCUS ZETEC 1.8/2.0	CHINA	<b>4558</b>

12402	<b>2H0857500R</b>	REPARACION PIVOT ESP. AMAROK	ARGENT	<b>605</b>
12404	<b>73192</b>	BULBO ACEI RANGER h/-2012 3.0 DIESEL BF7T9278A	MEXICO	<b>1179</b>
12406	<b>1385683</b>	VARILLA NIV ACEITE TRANSIT 2010-2012 2.4 PUMA/	TURKEY	<b>1855</b>
12410	<b>5C3Z11572AA</b>	INTERR IGNICION F100 2002-2012 -RANGER 2005/12 ORIG		<b>agotado</b>
12434	<b>6C2Z13713AA</b>	INTERR PTA F100 92/98 - -RANG 94/97-EXPLORER	usa	<b>3324</b>
12447	<b>5243591</b>	VALV C/ AIRE ADM IMRC -ECO/FOCVMOND07-14 2.0 DUR		<b>2820</b>
12451	<b>83DT7A377C1B</b>	VALV CJA AUTOMA/FALCON/TAUNUS/SIERRA	USA	<b>3255</b>
12456	<b>1444973</b>	TUBO COLECT COMBLE FIESTA-ECO 2002-2012 1.4	TURKEY	<b>3337</b>
12460	<b>1521487</b>	CAÑO RET DE INYECT FOCUS/MONDEO/S-MAX 06/ 1.8 DIESEL		<b>AGOTADO</b>
12462	<b>988F9B989BB</b>	SENSOR MARIP. TPS ROCAM 1.6 DURAT 2.0	THOMSON	<b>2395</b>
12463	<b>7173046</b>	SENS.TPS FTA- ESC - ZETEC - ROCAM 1.0 1.6 END 1.3	THOMSON	<b>2848</b>
12466	<b>1128018</b>	TERMOST REFR. ACEITE MOND 2001-2007 2.0 PUMA	TURKEY	<b>1962</b>
12471	<b>028907319B</b>	SENSOR CIG.POLO 1.9	PKW	<b>3418</b>
12475	<b>YS6A6C315AB</b>	SENSOR POSI CIGUE RPM ECOSPT 04-2012 1.6 ZE/R	PKW	<b>1865</b>
12477	<b>89FB 6C315</b>	SENSOR LEVA FIE 94/94 ESP. 1,3		<b>3781</b>
12487	<b>7H0927803/4</b>	KIT SENS.ABS I/D DEL. AMAROK 2.0 TDI	CHINA	<b>3836</b>
12490	<b>6740816</b>	SENSOR CIG F FIESTA KA 1.3I FOCUS 1.6 16V ROCAM	CHINO	<b>AGOTAD</b>
12499	<b>1543842</b>	VALV.PRES. BBA INY 1.4 D . 1.8 D X3980030005Z		<b>8051</b>
12493	<b>1439900</b>	Sens. MAP ROCAM 1.6/DURATEC 2.0	THOMSON	<b>4558</b>
12495	<b>03C906433A</b>	SENS.RPM CIG. AMAROK, FOX,SURAN,GOL 1.6	CHINA	<b>2430</b>
12496	<b>03C906051</b>	SENS.MAP AMAROK, KOX,SURAN,GOL 1.6	CHINA	<b>4623</b>
12503	<b>AV6Z19E616A</b>	MOTOR CONTR AI ACONDIC TRANSIT 2014/	USA	<b>2881</b>
12505	<b>1089959</b>	RESIST MOTOR CALEF TRANSIT 1997-1999 -2001-10/1	CHINA	<b>1889</b>
12506	<b>AV6Z19E616A</b>	MOT.CONT.A/A FOC/MOND/KUTA /TRANS. 08/	USA	<b>7730</b>
12510	<b>96FP3N824BA</b>	BULBO DIR.HID. ECO,FTA,KA,FOC, RANG	CRIFA	<b>1830</b>
12511	<b>1807897</b>	ENFRIADOR GASES EGR RANG 2014/ 2.2 -3.2 PUMA	CHINA	<b>AGOTADO</b>
12531	<b>BG5T9H544AA</b>	SENSOR POS CIG RPM RANGER 2005-2012 3.0	TAIWAN	<b>5410</b>
12532	<b>73191</b>	SENSOR PRESI ABS MAP RANGER 2005-2012 3.0 IN ORIGINAL		<b>6974</b>
12533	<b>03Ñ130235M</b>	CAÑO RET.INYECT.AMAROK 2.0 TDI	CHINA	<b>6565</b>
12534	<b>03L109145/...</b>	KIT DIST TAPAS CORREAS AMAROK 2.0	CHINA	<b>9092</b>
12535	<b>03Ñ103469F</b>	TAPA VALV. AMAROK 2.0	CHINA	<b>21454</b>
12536	<b>03L103623A</b>	DEFLEC DE CARTER AMAROCK 2.0 TDI	CHINA	<b>3683</b>
12537	<b>03L 115433</b>	TAPA SOPOR FILTRO ACEITE AMAROK 2.0 TDI	CHINO	<b>2763</b>
12543	<b>4F0422371E</b>	DEPOSITO DIR.HID. AMAROK	CHINO	<b>5019</b>
12551	<b>1S5Q8509AA</b>	POLEA BBA AGUA ROCAM 1.6	ITALIA	<b>3033</b>
12552	<b>2-1022</b>	TRICETA FOCUS 32X23E	IMP	<b>2420</b>
12558	<b>3F2Z9G756AC</b>	VALV.PRES.COMB FOCUS 05/09 DURAT. C/AUTOM	IMP	<b>4904</b>
12569	<b>7173046</b>	SENSOR POSIC.MARIP TPS FIE 96/06 1.6 ZET/ROCAM	THOMS.	<b>2848</b>
12580	<b>T12919075</b>	BULBO ACEITE F100 1992-1998 MWM/MAXION SIAP	ARG.	<b>2637</b>
12583	<b>027/127177/3</b>	SEPARAD VAPOR COMBUST ESCORT 90/ AUDI	CHINO	<b>2314</b>
12592	<b>1S7Z8597AK</b>	CDO BBA AGUA DURATEC 2.0 ECO,FOC,MOND	BRASIL	<b>604</b>
12609	<b>9S6G12K073BA</b>	SENSOR A/LEV. ROCAM 1.6 08/13	TAIWAN	<b>3482</b>
12611	<b>1111037</b>	SENSOR POSICION ARBOL DE LEVAS 1.6 SIGMA	TAIWAN	<b>1957</b>
12614	<b>1021992</b>	SENSOR VELOC. TRANSIT 9+7/99	TURKEY	<b>7885</b>
12616	<b>1491949</b>	CIL.MAEST.EMB.MOND. DURATEC 07/14 2.0	CHINO	<b>6685</b>

12619	<b>FITZ9C968A</b>	VALV PRES COMB RANGER 1994-2001 4.0 V6 OHV +	BRASIL	<b>7045</b>
12621	<b>CN157K387AB</b>	REP.PAL CAMBIO CAJA IB5 FIE,ECO, KA	ARGENT	<b>1677</b>
11331/2	<b>70993784/85</b>	JGO BALANCILES 2+2 RANG.3.0 C/ BOTADOR	USA	<b>22559</b>
12622	<b>1483819</b>	<b>SENS TURBO MONDEO 07-14 2.0 DSI</b>	TAILAND	<b>8080</b>
12624	<b>1496238</b>	<b>TUBO COND A/ INTERC FOCUS 08-13 1.8 DIES</b>		<b>7084</b>
12625	<b>XS4Q6K683FA</b>	<b>MANG A/INTERC FOCUS 99-09 CURV</b>	ARG.	AGOTADO
12634	<b>BE8Z 8K556 A</b>	<b>CONEX.AGUA SIGMA 1.6 S/SENS</b>	TURKEY	<b>2867</b>
12636	<b>5N0965561A</b>	<b>BBA AGUA.ADIC.ELE PASSAT 3P</b>	PKW	<b>13508</b>
12637	<b>1K0965561F</b>	<b>BBA AGUA ELEC. VENTO 2 PIN</b>	PKW	<b>12886</b>
12638	<b>059121012A</b>	<b>BBA AGUA ELECA AMAROK 3 P</b>	PKW	<b>13508</b>
12639	<b>078121599C/F/E</b>	<b>BBA AGUA ELECT PASSAT 2.8 2P</b>	PKW	<b>13569</b>
12640	<b>1K0965561J</b>	<b>BBA AGUA ELECT VENTO 2.0</b>	PKW	<b>13508</b>
12641	<b>1516726</b>	<b>DIAF.T/VALV. TRANS 2.4 10/12</b>	BRASIL	<b>3528</b>
12645	<b>030906433K</b>	<b>SENS.CIG. GOL III 1.6</b>	PKW	<b>2973</b>
12649	<b>XS6E6268AA</b>	<b>CADENA DIST.ROCAM Y TENS HIDR</b>	CHINO	<b>3384</b>
12651	<b>YS4G6A642AA</b>	<b>ENFRIAD ACE FOC 02-05 2.0 ZETEC</b>	ESPAÑA	<b>6080</b>
12653	<b>XS6E-12648BA</b>	<b>SENS.TEMP. ROCAM 1.6 ECO/FTA/KA</b>	THOMSON	<b>1450</b>
12660	<b>XL2Z2C204AA</b>	<b>SENS ABS FORD RANG 2.5 3.0 TDCI 4X4</b>		<b>4433</b>
12662	<b>TACO 6118</b>	<b>TACO CAB DEL. (RAD)f100 67.73</b>	ARG	<b>474</b>
12663	<b>TACO 6117</b>	<b>TACO CAB DEL/TRAS. F100 67/73</b>	ARG	<b>533.05</b>
12664	<b>TACO C 6773</b>	<b>JGO TACOS C/ BUL F10067/73</b>	ARG	<b>3980</b>
12665	<b>TACO 6134</b>	<b>TACO DEL CAB F100 74/80</b>	ARG	<b>538</b>
12666	<b>TACO 6135</b>	<b>TACO CABINA MEDIA F10074/80</b>	ARG	<b>772</b>
12667	<b>TACO 6136</b>	<b>TACO CABINA TRAS. F100 74/80</b>	ARG	<b>786.68</b>
12668	<b>TACO C 74/80</b>	<b>JGO TACOS C/BUL. F100 74/80</b>	ARG	<b>5119.4</b>
12669	<b>TACO 6149</b>	<b>TACO DEL CAB F100 81/98</b>	ARG	<b>546</b>
12671	<b>TACO 6150</b>	<b>TACO TRAS F100 81/98</b>	ARG	<b>1185</b>
12672	<b>TACO C 81/98</b>	<b>JGO TACOS C/BUL. F100 81/98</b>	ARG	<b>6065.43</b>
12673	<b>CITB 8100272A</b>	<b>TACO CAJA F100 67</b>	ARG	<b>135.92</b>
12674	<b>BULON 1</b>	<b>BULON P/6117/18/35/36/49</b>	ARG	<b>151.1</b>
12675	<b>BULON 2</b>	<b>BULON P/6135/6136</b>	ARG	<b>163.2</b>
12676	<b>BULON 3</b>	<b>BULON P/6150</b>	ARG	<b>223.38</b>
12677	<b>TACO 1070</b>	<b>TACO CAB DEL RANG 97/ CAB SIM</b>	ARG	<b>1978</b>
12678	<b>TACO 1071</b>	<b>TACO CAB. INT. RANG 97/ CAB SIM</b>	ARG	<b>1780</b>
12679	<b>TACO 1072</b>	<b>TACO CAB TRAS.RANG 97 " "</b>	ARG	<b>2070.9</b>
12680	<b>TACO RANG 97</b>	<b>JGO TACOS RANG 97 C.SIM C/BUL</b>	ARG	<b>13376</b>
12687	<b>5M5Q10D310AA/</b>	<b>SENSOR ALT.FOCUS 1.8 TDCI INA</b>	CANADA	<b>30534</b>
12690	<b>AB39 9H307 EC</b>	<b>BBA DIESEL COMPL.RANG.PUMA</b>	CHINA	<b>23151</b>
12693	<b>89BF6766AB</b>	<b>TAPA ACEITE FIE 94/95 1.3 ESP.</b>	ARG	<b>1130</b>

**Valoe 0 - sin stock - RECUADRO, Destacado.**

PRECIOS DE LISTA.

Son precios del dia. Se factura con los precios vigentes a la fecha de despacho

