

G-GGGR - Modifications and Repairs

Manufacturer	Description	Manufacturer Approval	EASA/CAA Approval	FAA Approval	Embodied on (date)	Embodied on (hours)	Work Pack	Weight & Balance Amendment Record
Airbus Helicopters Canada Limited	Installed ECL aft battery relocation kit (Access Door and Mounting Tray only)		EASA STC 10016747	FAA STC SR00422NY	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters Canada Limited	Installed ECL aft baggage door (fwd hinged)		EASA STC EASA.IM.R.S.01321	FAA STC SR00676NY	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters Canada Limited	Installed Electrical Power Supply for optional 50 Amp / Longline / Carousel System		EASA STC 10051182 R1		23-Jan-20	7703.3	HP15239	Aircraft Weighed: 17-Dec-2019 (Aircraft Weighed with modification installed)
Airbus Helicopters, Inc	Installed heavy-duty cargo tie-down		EASA STC 10072001	FAA STC SH7693SW-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed R/H half instrument panel		EASA STC 10072006	FAA STC SR09279RC-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed controllable landing searchlight		EASA STC 10072004	FAA STC SH8154SW-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed tail rotor guard		EASA STC 10071973	FAA STC SH4636SW-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed AIM505 attitude gyro		EASA STC 10071970	FAA STC SH2917SW-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed hourmeter (Hobbs hourmeter installed)	350A73-9305	EASA STC 10064912	FAA STC SH4016SW-D	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Tech-Tool Plastics Inc	Installed Tech-Tool co-pilot solid door window without slider (3501-2025-1)		EASA STC 10042997	FAA STC SR09000RC	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Tech-Tool Plastics Inc	Installed Tech-Tool pilot solid door window with slider (3501-2030-2)		CAA AAN 25066 Iss 6	FAA STC SR09003RC	12-Feb-20	7703.3	HP15849	Negligible
Onbaord Systems International	Installed OnBoard cargo swing		EASA STC 10016937	FAA STC SR01164SE	23-Jan-20	7703.3	HP15239	Aircraft Weighed: 17-Dec-2019 (Aircraft Weighed with modification installed)
Onbaord Systems International	Fuel Drain Guard Kit		EASA STC EASA.IM.R.S.01164		23-Jan-20	7703.3	HP15239	Aircraft Weighed: 17-Dec-2019 (Aircraft Weighed with modification installed)

G-GGGR - Modifications and Repairs

Eagle Copters USA	Installed Geneva Aviation avionics console (P132) with electrical system upgrade		EASA STC 10016948	FAA STC SH4747NM	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Dart Aerospace Limited	Installed Dart boarding steps (D350-291-213/214)		CAA AAN 27937	FAA STC SH967NE	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Dart Aerospace Limited	Installed aft maintenance steps		CAA AAN 27937	FAA STC SH967NE	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Dart Aerospace Limited	Installed Dart cargo mirror		EASA STC 10017074	FAA STC SH856NE	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Dart Aerospace Limited	OEM Skidtube Training Wearplate Kit		EASA STC 10060926		02-Feb-18	7496		Aircraft Weighed: 17-Dec-2019
Dart Aerospace Limited	Vertical Reference Window Installation		EASA STC EASA.IM.R.S.01560		23-Jan-20	7703.3	HP15239	Aircraft Weighed: 17-Dec-2019 (Aircraft Weighed with modification installed)
RSG Products Inc (Integrated Flight Systems Inc)	Installed IFS air conditioner systems (R134)		EASA STC EASA.IM.R.S.01243	FAA STC SH3509SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Aerometals	Installed FDC/aerofilter (1350IN1-7)		EASA STC 10040685	FAA STC SR00811SE	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installation Ryan 9900BX TCAD System	S358250 350A73-1603	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	22-Aug-06	11.5	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed the KCS55A Compass System	S358250 350A73-9305 SK350-0494	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installed Honeywell Radar Altimeter System	S358250 350A73-9305 350A73-1684 SL350-0495	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installation - Glide Slope antenna	350A73-1519	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019

G-GGGR - Modifications and Repairs

Airbus Helicopters, Inc	Conductive paint, AS350 cabin roof	350A73-1556	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installation - Com antenna, cabin roof	350A73-1623	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Installation - FDC Barrier Filter Control	SK350-0493	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Relocated instrument lighting potentiometer	350A73-9305	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.2	FAA Form: DERY-710242-SW DERY-710121-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Repaired air intake	EASA.21J.700 MG11142005-1	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.5.3	FAA Form: DERY-710242-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Repaired contoured sliding door correctly	EASA.21J.700 AE2006-117	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.5.3	FAA Form: DERY-710242-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Airbus Helicopters, Inc	Repaired an existing antenna hole in the poy carbonate canopy roof	SK350-0413	Accepted under the FAA-EASA TIP Rev 6 and Amendment 1 and 2 Para 3.3.5.3	FAA Form: DERY-710242-SW	16-Aug-06	7.9	S358250	Aircraft Weighed: 17-Dec-2019
Aerospace Design Facilities Ltd	Avionics Upgrade & Preparation for UK C of A	EASA.21J.125 ADF2019-227	EASA STC 10053621 R2 EASA STC 10060527		23-Jan-20	7703.3	HP15209	Aircraft Weighed: 17-Dec-2019 (Aircraft Weighed with modification installed)