This photo shows how Liscott attempted to hide the fact that the modules weren't properly mated. Liscott simply had the drywall crew cut out and reframe this one small stub wall. The large gap indicates how far apart the modules still remain. KO CO

行

and the same of the

CHT CHT Die

PREMIUM PREMIUM PREMIU

HU.F