

Liscott didn't install the house wrap with the proper fasteners nor did Liscott cover all exposed wood. They simply covered this defective work with siding. Also note the sloppy construction and gaps in the soffit and fascia.





EVERBIT

CC-ESR-201

THE HOME DEPOT

EVERBIT

CC-315R-2955

THE HOME DEPOT


EVERBIT

EVERBIT

EVERBIT

EVERBIT

EVERBIT



EVERBITLTM

ICC-ES ESR-2955

EVERBITLTM

EVERBITLTM
ICC-ES ESR-2955

Protecto Wrap
1-800-758-8127
www.protectowrap.com
Made in USA
ASTM 2112



No electrical boxes on
any of the exterior lighting.