



PROPELLER MAINTENANCE RECORDS

Aircraft Registration N6731Z
Propeller Position LEFT
Propeller Serial No. ED6342B



PROPELLER MAINTENANCE RECORDS

Log No. 1

Aircraft Registration No. N6731Z

Propeller Manufacturer Hartzell

Hub Model PHC-J3YF-2UF/FC7663DRB

Blade Design No. _____

Hub Serial No. ED6342B

Blade Serial No's.

1. L56107
2. L56110
3. L56111
4. _____

Pitch Range:

High 20.8 Low 15.3

Feather 84.0 Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft 2.18.2016

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- | | |
|--|--------------------------------|
| <input checked="" type="checkbox"/> Left | <input type="checkbox"/> Right |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |

(All applicable information must be filled in)

254/752-8381

Waco Regional Airport • P.O. Box 5219 • Waco, Texas 76708
FAX 254-752-3307

1-800-445-9713

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				
				<div style="display: flex; justify-content: space-between;"> <div data-bbox="359 595 510 649">  </div> <div data-bbox="518 595 949 649"> <p>Loyd's AIRCRAFT MAINTENANCE, INC. (661) 393-1588 Fax (661) 393-2502 SO# 19053</p> </div> <div data-bbox="1077 563 1220 670"> <p>N 6731Z AFTT: 3459.50 Hobbs: 334.30 Prop. TT: 288.20 Prop. S/N ED6342E Date: 3/1/2017</p> </div> </div> <p>Work Accomplished</p> <p>Left Propeller -</p> <p>Discrepancy: Annual inspection due. Resolution: Completed an annual inspection this date in accordance with F.A.R. 43 Appendix D, Textron/ Beechcraft Baron 58P, Annual/100 Inspection Guide 102-590000-5, A25, 01 JUN 2002.</p> <p>I certify that a Annual 100 HR Inspection was performed on the above propeller, in accordance with FAR 43, Appendix D, and Textron/ Beechcraft Baron 58P, Annual/100 Inspection Guide 102-590000-5, A25, 01 JUN 2002.</p> <p>This propeller is approved for return to service with respect to the work performed.</p> <p><i>Mark W Wiebe</i> Mark W Wiebe AP561868073IA</p>
				<div style="display: flex; justify-content: space-between;"> <div data-bbox="454 1074 582 1117">  </div> <div data-bbox="590 1074 949 1117"> <p>Loyd's AIRCRAFT MAINTENANCE, INC. (661) 393-1588 Fax (661) 393-2502 SO# 19706</p> </div> <div data-bbox="981 1053 1109 1138"> <p>N 6731Z AFTT: 3595.80 Hobbs: 470.60 Prop. TT: 424.50 Prop. S/N ED6342B Date: 6/3/2019</p> </div> </div> <p>Work Accomplished</p> <p>Left Propeller -</p> <p>Discrepancy: Annual inspection due. Resolution: Completed an annual inspection this date in accordance with F.A.R. 43 Appendix D, Textron/ Beechcraft Baron 58P, Annual/100 Inspection Guide 102-590000-5, A25, 01 JUN 2002.</p> <p>I certify that a Annual 100 HR Inspection was performed on the above propeller, in accordance with FAR 43, Appendix D, and Textron/ Beechcraft Baron 58P, Annual/100 Inspection Guide 102-590000-5, A25, 01 JUN 2002.</p> <p>This propeller is approved for return to service with respect to the work performed.</p> <p><i>Mark W Wiebe</i> Mark W Wiebe AP561868073IA</p>
				<div style="display: flex; justify-content: space-between;"> <div data-bbox="494 1457 622 1510">  </div> <div data-bbox="630 1457 949 1510"> <p>Loyd's AIRCRAFT MAINTENANCE, INC. (661) 393-1588 Fax (661) 393-2502 SO# 20463</p> </div> <div data-bbox="965 1436 1101 1532"> <p>N 6731Z AFTT: 3731.10 Hobbs: 605.90 Prop. TT: 559.80 Prop. S/N ED6342B Date: 7/10/2020</p> </div> </div> <p>Work Accomplished</p> <p>Left Propeller -</p> <p>I certify that a Annual 100 HR Inspection was performed on the above propeller, in accordance with FAR 43, Appendix D, and Textron/ Beechcraft Baron 58P, Annual/100 Inspection Guide 55-590000-13, REV G12, Dated: 18 JUN 2019.</p> <p>This propeller is approved for return to service with respect to the work performed.</p> <p><i>Mark W Wiebe</i> Mark W Wiebe AP561868073IA</p>

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				

 **Loyd's AIRCRAFT MAINTENANCE, INC.**
 (861) 393-1888 Fax (861) 393-2802
 N 6731Z
 AFTT: 3831.20
 Hobbs: 706.00
 Prop. TT: 659.90
 Prop. S/N ED6342B
 Date: 8/18/2021
 SOW# 21160

Work Accomplished
 Left Propeller -

I certify that an Annual inspection was performed on the above propeller, in accordance with FAR 43, appendix D and Textron/ Beechcraft MM, ML-B-68, REV 5, 66-590000-13, REV. G-12, Dated: 22 JUN 2017.

This propeller is approved for return to service with respect to the work performed.

Mark W Wiebe AP561868073IA *Mark W Wiebe*



Loyd's AIRCRAFT MAINTENANCE, INC.

P.O. Box 80958
 Bakersfield, California 93380



Date: 10/03/2022; Aircraft: N6731Z; Type: BEECHCRAFT, 58P; S/N: TJ-255; Hobbs: 818.00; Total Time: 3943.20; Engine 1 Type: TSIO-520-WB, S/N: 508518, Time: 5168.70; Prop 1 Type: PHC-J3YF-2UF/FC7663DRB, S/N: ED6342B, Time: 771.90; Engine 2, Type: TSIO-520-WB, S/N: 518349, Time: 3986.90; Prop 2, Type: PHC-J3YF-2UF/FC7663DRB, S/N: ED6392B, Time: 771.90; Work Done At - Airframe Time: 3943.20., Engine Time: 5168.70., Heater Time: 436.50, Left Propeller

-Discrepancy-
 Annual inspection due.

Completed an Annual inspection this date in accordance with F.A.R. 43 appendix d.

I certify that an annual inspection was performed this date in accordance with F.A.R. 43 appendix d. This propeller is approved for return to service with respect to the work performed.

Mark W Wiebe
 Mark W Wiebe AP561868073IA

Mark L Blackburn
 Mark L Blackburn AP3458706



Loyd's AIRCRAFT MAINTENANCE, INC.

P.O. Box 80958
 Bakersfield, California 93380



Date: 12/01/2023; Aircraft: N6731Z; Type: BEECHCRAFT, 58P; S/N: TJ-255; Hobbs: 919.10; Total Time: 4044.30; Engine 1 Type: TSIO-520-WB, S/N: 508518, Time: 873.00; Prop 1 Type: PHC-J3YF-2UF/FC7663DRB, S/N: ED6342B, Time: 873.00; Engine 2, Type: TSIO-520-WB, S/N: 518349, Time: 873.00; Prop 2, Type: PHC-J3YF-2UF/FC7663DRB, S/N: ED6392B, Time: 873.00; Work Done At - Airframe Time: 4044.30., Engine Time: 873.00., Heater Time: 436.50, Left Propeller

-Discrepancy-
 Annual inspection due.

Completed an Annual Inspection this date in accordance with F.A.R. 43 appendix d.

This propeller is approved for return to service with respect to the work performed.

Sтивен Slager
 Steven Slager AP3247849

I certify that this aircraft has been inspected in accordance with an Annual Inspection and is approved for return to service.
Mark W Wiebe
 Mark W Wiebe AP561868073IA

DATE	



Date: 2/03/2023
 Type: TSIO-520
 Engine 2, Type: 873.50
 Left Propeller
 Discrepancy:
 Annual Inspe
 Completed an

I certify that th
 the work perfo

Aurelio Flores

