

SERVICE BULLETIN

SUBJECT: Machined screws holding the cap to the body could come lose. It has been identified that a limited lot of 1/2 inch, 8-32 screws were found mixed with 5/8 inch x 8-32 screws.

SERVICE RECOMMENDED:

Replace screw(s), if needed. If desired, blue thread lock may be applied. For replacement screws, please contact us at Service@teacherlock.com with your mailing address and the desired number of screws.

For technical support, please email: service@teacherlock.com Or call:
978-286-8855 For spare parts or additional keys, please visit our website at:
www.teacherlock.com

TeacherLock is a product of DefCon Products, LLC. 808 Main Street, Fitchburg MA 01420