



Construction workers are excavating soil near 75 Wainscott NW Road (close to Montauk Highway), the site of a house fire. South Fork Wind did not test soil or groundwater for PFOA contamination before beginning construction.

Photo taken on March 21, 2022



Construction workers are excavating soil near Monitoring Well 4A, where South Fork Wind reported PFOA contamination (82 ppt) that exceeds the 2016 EPA Health Advisory Levels.

Photo taken March 14, 2022