

Elk River's Enterprise: The Turning Point

Presented By: Angela Hauge – GIS/Mapping Technician



Elk River
Municipal Utilities

INTRODUCTION

- ▶ Intro
- ▶ History of Mapping @ ERMU
- ▶ Current Mapping @ ERMU
 - ▶ Enterprise
 - ▶ GPSing – Hardware & Software
 - ▶ Media – Print/Publishing
 - ▶ InfraMap (Water)
- ▶ Build The Foundation
- ▶ Mapping Apps & Extensions
 - ▶ In Use
 - ▶ Future Use
- ▶ Up & Coming
- ▶ Re-Cap

2012-2015

- ▶ Contracted GPSing

- ▶ Water:

- ▶ Hydrants
 - ▶ Valves
 - ▶ Other water features


- ▶ Contracted GIS

- ▶ Electric database constructed
 - ▶ The “A” Team GPSed & gathered data
 - ▶ Lineman & Meter Reader GPSing
 - ▶ Excel Sheets – basic fields, unique numbers, tables brought into GIS
 - ▶ Unique number issues, field checks
 - ▶ No one keeping up with system changes
 - ▶ No workflow practices to catch them



2016-2017

- ▶ GIS/Mapping Position Created
 - ▶ Brush the rust off & learn the latest
 - ▶ 10 years
 - ▶ Tech changes in GIS
 - ▶ Software & Hardware
- ▶ Learn Electric & Dug Into The Database
 - ▶ What's everything, what does it do, how does the map showcase each item
 - ▶ What is pertinent information?
 - ▶ If this, than that...
 - ▶ Communicated with Linemen/Foremen
 - ▶ What was useful for them in the field/office
 - ▶ What did we need/potentially need for data from the field?
 - ▶ Think outside the box
- ▶ Cleaned up the GIS & kept up with CAD
 - ▶ System continually grew through large territory acquisition & new builds
 - ▶ Tremendous learning opportunity



► Enterprise - 2017



ArcGIS for Server enables Web GIS in your infrastructure



► Portal

► Company Connection



ArcGIS Enterprise – Distributed collaboration



Establishes a trusted environment among participants.

...Providing insight, visibility and accessibility to content.

...Extending beyond geographic & organizational boundaries.

...Allowing users to work towards goals, initiatives and projects together.



ERMU's Portal - Website

[Home](#) [Gallery](#) [Map](#) [Scene](#) [Groups](#) [Content](#) [Organization](#)

Angela ▾




ManagerViewOnly

PCBmanager


WaterGpsMap

Publish Services To Portal



Publish a **Features Map** (editable items & a **Background Map** (items not to be edited by end user: GPSSer or viewer), add both published maps to create a Portal Map & configure for the users. Pop-Ups (Labels), organize those fields), hide what they don't need.

Manage Feature Editing



Allow Access

Manager View
Owner: ahaug
Created: Apr 12, 2018 Last Updated: Apr 12, 2018 Viewable by: Organization
Manger View Maps

Transformer PCB's
Owner: ahaug
Created: Mar 21, 2018 Last Updated: Aug 9, 2018 Viewable by: Organization
Transformer PCB Tracking

Water Dept. GPS
Owner: ahaug
Created: Aug 21, 2018 Last Updated: Aug 27, 2018 Viewable by: Organization
Water

Collector – In The Field Editing

Home ▾ WaterGpsMap

New Map ▾ Create Presentation Angela ▾

Details Add Edit Basemap Save Share Print Measure Bookmarks Find address or place

Add Features

- MiscFeature
- TracerWire
- WatermainBreak
- WaterBuildingStructure
- Hydrants
- Valves
- WaterMeter

Hydrants (1 of 2)

Hydrant Number	ERA64
Type	
Project Name	
Project Number	
Year Installed	0
PDF Location	
Asbuilt Plan	
Horizontal Accuracy	
Elevation	816.554
Northing	225372.939
Easting	572764.47
Point ID	856
Asbuilt Image	Meado_93_10
Comments	

New Collector – Enable *Tracking* for certain fields if you want it to be a required data entry, some could be automatic.... Timestamp, Date, User, etc...

▶ GPSing – Hardware & Software

▶ Hardware

- ▶ Cellphone – Hotspot to iPad
- ▶ RI Receiver – Connect to Cell
- ▶ iPad – Operating Work Surface

▶ Software



- ▶ GIS Server - Portal
- ▶ ArcMap
- ▶ Collector App
- ▶ GNSS Status App



ERMU GPS

GPSING POLES







Mobile Data via phone cell company
Or
Hotspot from cellphone service
Wi-Fi to iPad from Cell
Bluetooth to iPad from RI Receiver

GET THE MOST OUT OF YOUR TECHNOLOGY


High-Accuracy GNSS Receiver Support



Trimble released a rugged R1 GNSS Receiver for smartphones and tablets

Receiver Firmware Update - April 6th

The R1 is compatible with **Android, iOS, Windows OS** and enables to achieve up to 50 cm accuracy using various correction sources (via IP or over **satellite**).



RTX

GNSS:68033




WATER – GIS USE


▶ InfraMap infraMAP SOFTWARE

- ▶ Management, fieldworker & mapping interface

- ▶ Data in Geodatabase on Server

- ▶ Communicates by linking data pathways of feature fields in ArcMap from forms that you create in InfraMap





- Elk River Forms
 - Hydrants
 - Water System Valve
 - Wells
 - Water Tower
 - Water Meter
 - Main & Service Breaks/Leaks

Asset Win Form

Form name: Form type: Description:

Asset group: Asset:

Form size: x Form color: Show overview map

Hydrants Hidden Controls | Recondition

Operational Status	Initials	Hydrant Number
<input type="text"/>	<input type="text"/>	<input type="text"/>
Brand	Year	District
<input type="text"/>	<input type="text"/>	<input type="text"/>
Location	Iso. Valve Exercised	Comments
<input type="text"/>	<input type="text"/>	<input type="text"/>
3 Caps/3 Chains	Private	Break Away Depth
<input type="text"/>	<input type="text"/>	<input type="text"/>
Filled With Oil	Nozzles Anti Seized	Exercised
<input type="text"/>	<input type="text"/>	<input type="text"/>
Facing Street	Flagged	Drains
<input type="text"/>	<input type="text"/>	<input type="text"/>
Equipment	Parts	
<input type="text"/>	<input type="text"/>	
Time	<input type="text"/>	
<input type="text"/>	<input type="text"/>	

-
-
-
-
-
-
-

Page

Page name:

Description:

Hidden

Controls

Type:

Field:

Description:















Default value:

Action:

Properties


Activity Codes

Activity Code	Required	Reset	Res...
<input type="checkbox"/> INST	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> UPDT	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> INSP	<input type="checkbox"/>	<input type="checkbox"/>	
<input type="checkbox"/> ...	<input type="checkbox"/>	<input type="checkbox"/>	

 Asset
  Form
  Lookup Data
  Map Tip
  Question
  Find
  Template
  Shutdown Report
  Redline
  WorkTask
  MC
  Cityworks
  User
  Setting


Template:
 Status:


Type	Description	Created Date	Computer Name	Created By	File Path	Template Name
Contains:	Contains:	Equals:	Contains:	Contains:	Contains:	Contains:
New	add line	8/23/2018 1:23:19 PM	ERMU_MOBILE9	kolson	131795221991811436.jpg	WaterDistribution
New	remove valve	8/23/2018 1:22:55 PM	ERMU_MOBILE9	kolson	131795221755815786.jpg	WaterDistribution
New	remove valve	6/21/2018 2:52:50 PM	ERMU_MOBILE9	kolson	131740843704285434.jpg	WaterDistribution
New	remove valve	6/21/2018 1:54:00 PM	ERMU_MOBILE9	kolson	131740808405435902.jpg	WaterDistribution
New	add gate valve	6/21/2018 1:40:44 PM	ERMU_MOBILE9	kolson	131740800442499688.jpg	WaterDistribution
New	remove valve	6/21/2018 11:15:54 AM	ERMU_MOBILE9	kolson	131740713544735622.jpg	WaterDistribution
New	disregard add valve curbston	6/21/2018 11:01:50 AM	ERMU_MOBILE9	kolson	131740705098251058.jpg	WaterDistribution
New	remove valve it is hydrant isolation v...	6/21/2018 10:33:54 AM	ERMU_MOBILE9	kolson	131740688339735374.jpg	WaterDistribution
New	disregard add valve hydrant isolation valve	6/21/2018 10:26:17 AM	ERMU_MOBILE9	kolson	131740683768868333.jpg	WaterDistribution
New	add lines see sheet	6/20/2018 2:00:00 PM	ERMU_MOBILE9	kolson	131739947998416211.jpg	WaterDistribution
New	add lines see sheet	6/20/2018 1:55:43 PM	ERMU_MOBILE9	kolson	131739945434809876.jpg	WaterDistribution
New	add gate valve	6/19/2018 1:47:28 PM	ERMU_MOBILE9	kolson	131739076479951474.jpg	WaterDistribution
New	move line off of yards see sheet	6/19/2018 11:27:47 AM	ERMU_MOBILE9	kolson	131738992675166619.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 11:02:09 AM	ERMU_MOBILE9	kolson	131738977289888688.jpg	WaterDistribution
New	move line off of house see sheet	6/19/2018 10:59:40 AM	ERMU_MOBILE9	kolson	131738975797915086.jpg	WaterDistribution
New	add lines see sheet	6/19/2018 10:57:23 AM	ERMU_MOBILE9	kolson	131738974429338275.jpg	WaterDistribution
New	remove lines see sheet	6/19/2018 10:53:40 AM	ERMU_MOBILE9	kolson	131738972198231935.jpg	WaterDistribution
New	add lines see sheet	6/19/2018 10:53:09 AM	ERMU_MOBILE9	kolson	131738971889489911.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 10:36:28 AM	ERMU_MOBILE9	kolson	131738961882457726.jpg	WaterDistribution
New	add lines see sheet	6/19/2018 10:31:39 AM	ERMU_MOBILE9	kolson	131738958990843152.jpg	WaterDistribution
New	add line see sheet	6/19/2018 10:28:25 AM	ERMU_MOBILE9	kolson	131738957052862691.jpg	WaterDistribution
New	move valve see sheet and measure...	6/19/2018 10:25:31 AM	ERMU_MOBILE9	kolson	131738955312068536.jpg	WaterDistribution
New	add gate valve	6/19/2018 10:24:18 AM	ERMU_MOBILE9	kolson	131738954587212536.jpg	WaterDistribution
New	move line off of garage see sheet	6/19/2018 8:55:23 AM	ERMU_MOBILE9	kolson	131738901236523823.jpg	WaterDistribution
New	add line see sheet	6/19/2018 8:52:53 AM	ERMU_MOBILE9	kolson	131738899729525178.jpg	WaterDistribution
New	add valve see sheet	6/19/2018 8:49:49 AM	ERMU_MOBILE9	kolson	131738897895549959.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:46:44 AM	ERMU_MOBILE9	kolson	131738896046030713.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:45:35 AM	ERMU_MOBILE9	kolson	131738895347481489.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:44:32 AM	ERMU_MOBILE9	kolson	131738894717572385.jpg	WaterDistribution
New	add line see sheet	6/19/2018 8:43:23 AM	ERMU_MOBILE9	kolson	131738894035871190.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:41:57 AM	ERMU_MOBILE9	kolson	131738893169309671.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:39:44 AM	ERMU_MOBILE9	kolson	131738891846815350.jpg	WaterDistribution
New	move line off of yard see sheet	6/19/2018 8:37:59 AM	ERMU_MOBILE9	kolson	131738890792081496.jpg	WaterDistribution
New	Add main	6/18/2018 3:21:18 PM	ERMU_MOBILE5	evolk	131738268782431659.jpg	WaterDistribution
New	add valve	6/15/2018 2:00:29 PM	ERMU_MOBILE5	evolk	131735628293382267.jpg	WaterDistribution



- Hydrant Questions
 - Total Hydrants
 - Hydrants Needing Inspection**
 - Hydrants Inspected This Year
 - Inspected Hydrant Date Range
 - Hydrants Needing Repair
 - Hydrants 30 Years Older
 - Private Hydrant
 - Winterize Hydrant
- Valve Questions
- Wells Questions
- Meter Questions
- Main Leaks/Breaks

Name:	<input type="text" value="Hydrants Needing Inspection"/>
Description:	<input type="text" value="Located Hydrants Needing Inspection"/>
Asset Group:	<input type="text" value="Elk River Assets"/>
Asset:	<input type="text" value="Hydrants"/>
Work Task Table:	<input type="text"/>
Asset Display Color:	<input type="color" value="#FF8C00"/>
Button Image:	<input type="text" value="Warning Icon"/>
Query Type:	<input type="text" value="None"/>
SQL Statement:	<input type="text" value="InspectionDate <= (Current_Date - 365) OR InspectionDate IS NULL"/>
<input type="checkbox"/> Display the total based on a field	<input type="text"/>
Letter Template:	<input type="text"/>
<input type="checkbox"/> SQL Query	





Answers and Reports


Show Current View Counts

Hydrant Questions

Create Report

Create Work Task

- (1,233) Locate All Hydrants
- (847) Located Hydrants Needing...
- (366) Located Inspected Hydrant...
- (0) Located Inspected Hydrants...
- (6) Locate Hydrants Needing Rep...
- (0) Locate Hydrants That Are 30...
- (238) Private Hydrants
- (25) Winterize Hydrant




Pipeline Isolation





This tool will isolate a section of pipeline and display the affected assets.


Tap a section of pipe on the map to begin.


 **Reset Pipeline Trace**



 Valves to Close:

 Hydrants Affected:

 Services Affected:


 Main Affected:

 Lateral Affected:




Data Transfer

Last Synchronized on:
08/29/2018 07:04:52

Start Data Sync 


Settings

- Sync All Data
- Quick Sync (Send only my Work)





► Media – Print/Publishing



Perkin's Booster



175th Booster



ERMU's Water Map Book Page





Map Key

Hydrants
 Private, Winterize
 <all other values>
 Hydrant Needs GIS Data Entered
 Standard Hydrant
 Standard - Winterize Hydrant

Gate Valves
 <all other values>
ValveCategory
 Customer/Stub
 High/Low Valve
 Other
 Standard

Pressure Zones
 High Zone
 Hydrant District
 Low Zone

Tracer Wire & Locator Features
 <all other values>

Type
 GateValveBox
 GateValveSign
 Other
 SnakePit
 WaterMainLocatorSign
 SnakePitInValveBox

Watermains
 6" RAW
 10" - 24" RAW
 Abandoned Line
 Unknown Size
 4" - 8"
 10" - 24"



BUILD THE FOUNDATION

▶ Communication is Key

- ▶ GIS opens the door to so many options
 - ▶ You have to build it that way

▶ Field creation & planning will save so much time!

- ▶ Do the groundwork up front!
- ▶ Think about every potential piece of data on each piece of equipment/material/data calculated in the field
 - ▶ Domain/subtype creation
 - ▶ Write it down
 - ▶ Fields for comments/GIS comments/Mtc or repair comments (Flag Users)
 - ▶ Organize fields in Portal & Collector
 - ▶ ** Keep the order**
 - ▶ You'll need it! Trust me 😊

▶ Damage/Recovery Plan

- ▶ Fail-Safes in place with IT
- ▶ Regular database maintenance
 - ▶ Compress regularly, Copy databases for backup & be alert to database signs of corruption
 - ▶ VERY Slow, issues with snapping, glitchy items of concern
- ▶ Regular Server maintenance/updates
 - ▶ Ours is copied every night automatically – Backup Server
 - ▶ Have a plan in place to not forget things that will save you from issues later

MAPPING APPS & EXTENSIONS

▶ In Use

- ▶ Collector, GNSS App, InfraMap

▶ In The Works

- ▶ Survey123 & StoryMaps

▶ Future Use

- ▶ AppSuite, Sites, ArcGIS Hub, Insights & Dashboard

▶ Beneficial To Industry

- ▶ Workforce (ERMU won't need – NISC)
 - ▶ Assign tasks, locational reference & record maintenance/repair activities

SURVEY 123

1	A	B	C	I	J	K	L
2	Integer	DamageReportNumber_2018	2018 Damage Report - Survey#:	appearance	default	readonly	relevant
3	dateTime	Survey123DateTime	Date & Time Observed:	hide input			
4	select_multiple	EmployEmployee	Inspector(s):	minimal	now()		
5	geopoint	DamageLocation	Location of Damage/Concern (Geo Point)				
6	select_multiple	DamageItem	What is damaged or needs further inspection? (Comment w/specifics)	minimal			
7	image	DamagePhoto1	Photo of Damage:				
8	image	DamagePhoto2	Photo of Damage2:				
9	text	Survey123Comments	Initial Inspection Comments:	multiline			\$(DamagePhoto1)
10							
11	select_multiple	yes_no	OilLeakY1pcb	is there an oil leak? Any visible oil/weeping/discoloration to signify leak? (If so, contact PCB Manager ASAP)			
12	select_one	yes_no	ContactPCBmg	Did you contact the PCB Manager?			\$(OilLeakY1pcb)='Yes'
13							
14	begin group	GroupOilLeakPCB	<center>Oil Leak - PCB Management</center>	compact			\$(OilLeakY1pcb)='Yes'
15	text	AddressOilLeakPCB	Address of Leak (Please be specific - detailed):				
16	select_multiple	OilLeakTransformerType	Oil Leak Source Type (Complete a survey for each leaking item):				
17	select_one	yes_no	LeakProtocolAdherence	Was Oil Leak Clean-up Protocol Followed? (Get instructions from PCB Manager)			
18	text	LeakingItemDescription	Leaking Item Description (Size, Location(s) (ex: U2), weight, gallons, serial#, Manufacturer, Oil PCB Testing Data - PLEASE BE THOROUGH)	multiline			
19	select_one	yes_no	AmountOilLeaked	Did 5 gallons of oil or less leak? (Educated Guess)			
20	image	LeakPhotoPCB	Photo of Leak:				
21	image	LeakPhotoPCB2	Photo of Leak2:				\$(LeakPhotoPCB)
22	image	LeakCleanupPhoto	Photo of Site Cleaned - Final:				
23	image	LeakCleanupPhoto2	2nd Photo of Site Cleaned - Final:				\$(LeakCleanupPhoto)
24	end group						
25							
26							
27	select_multiple	yes_no	CustomerUtilNeedsContact	Does a customer or another entity need to be contacted to resolve an issue to make them of additional information to THIS item's issue?			
28	begin group	GroupCustContact	<center>Customer/Utility/Owner Contact</center>	compact			\$(CustomerUtilNeedsContact)='Yes'
29	text	AddressNameCustomerContact	Address(es) of Customers That Need/Had Contact From Damage of This Damaged Item Location:				
30							
31	select_multiple	Custom	Customers/UtilsToContact	Who Needs/Needed to Be Contacted?			
32	select_multiple	Custom	CustomerContacted	Customer Contacted?			
33	dateTime	CustomerContactedDateTime	When Was Contact Made/Attempted?				
34	text	CustomerOrUtilityContactComm	Customer or Utility Contact Comments (if other contact methods/attempts were made place detail in comments)	multiline			
35	select_one	yes_no	CustomerUtilityFollowUpNeeded	Follow Up or Inspection Needed?			

2018 Damage Report - Survey#:


Date & Time Observed:*

Any comments?

Inspector(s):*

Angela Hauge

- Mark Fuchs
- Tom Geiser
- Mitch Girtz
- Derek Groebner
- Angela Hauge



What is damaged or needs further inspection? (Comment w/specifics)

Photo of Damage:

Photo of Damage2:

Initial Inspection Comments:

Is there an oil leak? Any visible oil/weeping/discoloration to signify leak? (If so, contact PCB Manager ASAP)

 Yes

 No

Storm Damage Test
Overview Design Collaborate Analyze **Data** Settings

7/17/18 - 8/27/18
Filter Report (Beta) Export Open in Map Viewer Show individual response

Form_2 (Features: 1, Selected: 0)

Date & Time Observed:	Inspector(s):	What is damaged or needs further inspection? (Comment w/specifics)	Initial Inspection Comments:	Is there an oil leak? A visible oil/weeping/discoloration to signify leak? (If so, contact PCB Manager ASAP)	Did you contact the PCB Manager?	Address of Leak (Please be specific + detailed):	Oil Leak Source Type (Complete a survey for each leaking item):	Was Oil Leak Clean-up Protocol Followed? (Get instructions from PCB Manager)	Leaking Item Description (Size, LocationID (ex: D2), weight, gallons, serial#, Manufacturer, PCB Testing Data - PLEASE BE THOROUGH)	Did 5 gallons of oil or less leak? (Educated Guess)
Jul 17, 2018	Ahaugc,Mthiry	Other	Test	yes						

INSIGHTS

The screenshot displays the Esri Insights web application interface. The browser address bar shows the URL: <https://erasmus.esri.nl/arcgis/apps/insights/#/31b43f4f58814dcf8560c914aa9f1e40>. The application title is "Potentiele locaties nieuwe biosupermarkten".

The interface includes a left sidebar with "My Data" and "Geographies" sections. The main workspace is divided into several panels:

- Map Panel:** Shows a map of Amsterdam with orange circles representing potential locations. A search bar contains "Euros".
- Spatial Filter Panel:** A dialog box with three steps:
 - Choose layer to filter: "Euros"
 - Choose layer to filter by: "BiologischeSupermarkten - Buffer"
 - Choose type of filter: "Intersects" (selected)A "Run" button is visible.
- Card 3:** A horizontal bar chart titled "Group by" showing the distribution of payment methods. The x-axis is labeled $\bar{x} = 52$. The y-axis categories are Bon, Cash, Credit Card, and PIN.
- Card 7:** A map showing a heatmap of potential locations, with a legend for "TYP_E_PER".
- Donut Chart:** A donut chart titled "Campaign" showing the distribution of campaigns. The total is 207. The categories are Kortingsbon, Direct Mail, and Online.

The bottom of the screen shows the Windows taskbar with the system clock at 09:49 on 04-04-2017.

Palm Springs Map Tour


A story map  

A selection of cool places to discover in this fantastic desert resort.



Welcome to Palm Springs!

Palm Springs, California, is an American Shangri-La in a unique desert environment with endless sun, rediscovered mid-century architecture and a fun, relaxed atmosphere. (Photo: Greater Palm Springs CVB)



1 Indian Canyons



2 Indian Canyons Golf Resort



3 Elrod House



4 Palm Canyon Drive



5 Lula California Bistro



6 Starbucks



7 Palm Springs Art Museum

RE-CAP

- ▶ Intro
- ▶ History of Mapping @ ERMU
- ▶ Current Mapping @ ERMU
 - ▶ Enterprise
 - ▶ GPSing – Hardware & Software
 - ▶ Media – Print/Publishing
 - ▶ InfraMap (Water)
- ▶ Build The Foundation
- ▶ Mapping Apps & Extensions
 - ▶ In Use
 - ▶ Future Use
- ▶ Up & Coming
- ▶ Re-Cap



THANK YOU!!



ANY QUESTIONS?