

Leeson

Model:119417 - 2 Horse Power

There are two red wires that are TSTAT wires.

We do not use these.

Please cap them off individually.

Do not connect them to anything.

Do not connect them to each other.

Please contact us with any questions.



