

# NORTON FLOOR MAINTENANCE PADS FOR THE PROFESSIONAL CLEANING MARKET

## NORTON FLOOR PAD APPLICATION RECOMMENDATION CHART

RPM	MACHINE	CHEMICAL/WET OR DRY	PAD RECOMMENDATION	RESULTS
<b>Stripping</b>				
175+	Electric & Auto Scrub	Strip Solution/Wet	Ultra Blue Stripper High Productivity Black Stripping Black Super Strip	Strips even the most severe floors quickly and effectively. Removes tough finishes and extreme wax build up. Provides uniform finish removal in wet stripping applications.
<b>Scrubbing</b>				
175+	Electric & Auto Scrub	Cleaner/Wet	Green Super Scrub Blue Super Clean	Removes the toughest scuff marks in heavily soiled areas. Scrubs dirt and grime in heavy spray cleaning applications.
<b>Spray Buffing</b>				
175+	Electric	Spray Buff Solution/Wet	Red Buffer	Produces a high gloss finish when dry or spray buffing.
350-1200	Electric	Spray Buff Solution	Grizzly Bear Lite Grizzly	Creates a high luster finish on soft and flexible surfaces. Removes heavy marks and produces a high luster shine on hard finishes.
1200+	Electric	Spray Buff Solution/ Mop On Restorer	Ultra Grizzly Bear	Quickly removes scratches and marks to leave a glistening finish.
<b>Buffing &amp; Polishing</b>				
175+	Electric	Dry or Restoration Process	White Super Gloss	Produces a mirror gloss shine during low speed polishing.
350-1200	Propane	Dry or Restoration Process	Champagne Polish & Burnish Grizzly Bear Lite Aqua Ultra High Speed Burnish	Creates the highest gloss of any pad on the market. Restores a high luster shine quickly and easily. Produces a "wet-look" shine on soft to medium hard finishes.
<b>Burnishing</b>				
1500-3000	Propane	Dry or Restoration Process	Pink "Topshine" Burnish Ultra Grizzly Bear Grizzly Grizzly Bear Lite Aqua Ultra High Speed Burnish	Revives the gloss to dull floors on hard finishes only. Removes marks and scratches on medium to hard finishes. Removes heavy marks and produces a high luster shine on hard finishes. Produces a high luster shine on soft to medium finishes. Produces the "wet-look" shine on soft, medium and metal-free finishes.
1000-2000	Electric & Battery	Dry or Restoration Process	Thermal Burnish	Produce an outstanding shine on soft to medium finishes.
1000-3000	Electric & Battery	Dry or Restoration Process	Pink "Topshine" Burnish Ultra Grizzly Bear Grizzly Grizzly Bear Lite Aqua Ultra High Speed Burnish	Revives the gloss to dull floors on hard finishes only. Removes marks and scratches on medium to hard finishes. Removes heavy marks and produces a high luster shine on hard finishes. Produces a high luster shine on soft to medium finishes. Produces "wet-look" shine on soft to medium and metal-free finishes.
1500-2000	Electric & Battery	Dry or Restoration Process	Champagne Polish & Burnish	Creates the highest gloss of any pad on the market.

## FLOOR PAD PERFORMANCE

### General Purpose Thick Line Pads



### Ultra High Speed Finishing Pads

