

### **Making your Plug Slowly Blink for AP Mode**

1. If your Plug is not blinking, turn your plug on, and hold the power button down for 5 seconds until you hear a click, let go of the power button and then press the button. It should now be blinking (2 blinks per second)
2. Now repeat previous step by holding down the power button again for 5 seconds until you hear the click. Let go of the power button and then press the button.
3. Your plug will now be blinking slowly (1 blink every 3 seconds) and is ready to be paired in AP mode.