

## LIFE SAFETY ISSUE



**Customer**

**Inspection Date / Year, Make, Model:**

November 14, 2023 / 2021 Keystone Montanta High Country 331RL

**VIN Number:**

The following items indicate that the condition is a LIFE SAFETY ISSUE. It is recommended that a qualified RV technician correct the identified issue, and before the unit is occupied.

### 13. Propane Tank, Lines and Connections

#### 13.4 Fire Extinguisher

**Poor**



The current NFPA-1192 standards for recreational vehicles recommends a 1A-10B:C size fire extinguisher for fifth wheels. It is recommended that the fire extinguisher be upgraded to meet the current standard before the RV is occupied.

Streetside Sidewall



Streetside Front to Back




Streetside Back to Front

3.1.C Paint and/or Decals

**Comments:** Acceptable



There is a tear in the decal, about a quarter inch in length, located on the streetside, rear slideout. Located four feet in from the rear of the slide and 6 feet up the bottom of the slide.




Slideout Decal

RV Safe CO/LP




RV Safe CO/LP



RV Safe CO/LP

13.3 Smoke Detector  
Comments: Acceptable

## BRK Smoker Detector



BRK Smoker Detector

## 13.4 Fire Extinguisher

Comments: Poor



The current NFPA-1192 standards for recreational vehicles recommends a 1A-10B:C size fire extinguisher for fifth wheels. It is recommended that the fire extinguisher be upgraded to meet the current standard before the RV is



Knobs / Controls



Knobs / Controls

**14.13 Cooktop - Color of Burner Flame**

**Comments:** Acceptable

Burner Flame



Burner Flame

**14.14 Oven - Condition**

**Comments:** Acceptable

**14.15 Oven - Racks Condition**

**Comments:** Acceptable

**14.16 Oven - Color of Burner Flame**

**Comments:** Acceptable