

Portable /Fixed Appliance

Equipment formal visual and combined inspection and test

Part 1: Details of Installation

Client	Ryan Robinson	Installation	Inspector Name			Zam Mtumwa		
Address		Address	104 Greenfield Avenue NORTHAMPTON	Branch No.	001	Scheme No.	21165	
				Date of Test	12/02/2025	Date of Re-test	12/02/2026	
				Test Equipment	Seaward Prime Test 50			
Postcode		Postcode	NN3 2BB	Signature				

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/Earth Bond Ω	Polarity	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
1	Speaker JBL	12/02/2025	41984	II	3	✓	N/A	✓	>299	0.8	✓	N/A	N/A	N/A	✓	
2	Speaker JBL	12/02/2025	45076	II	3	✓	N/A	✓	>299	1.1	✓	N/A	N/A	N/A	✓	
3	Speaker JBL	12/02/2025	10003	II	3	✓	N/A	✓	>299	0.24	✓	N/A	N/A	N/A	✓	
4	Speaker JBL	12/02/2025	10004	II	3	✓	N/A	✓	>299	0.24	✓	N/A	N/A	N/A	✓	
5	Speaker Vonxy	12/02/2025	17369	I	3	✓	Pass	✓	>299	0.05	✓	N/A	N/A	N/A	✓	
6	Air Blower	12/02/2025	23328	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
7	Air Blower	12/02/2025	15756	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
8	Air Blower	12/02/2025	23365	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
9	Air Blower	12/02/2025	39103	I	5	✓	Pass	✓	>299	0.75	✓	N/A	N/A	N/A	✓	
10	Air Blower	12/02/2025	41268	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	
11	Air Blower	12/02/2025	10011	I	13	✓	Pass	✓	>299	1.8	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

FT/PAT 6242000001968

Equipment formal visual and combined inspection and test

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation M Ω	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
12	Blow Heater Erberur	12/02/2025	08816	I	13	✓	Pass	✓	>299	2.5	✓	N/A	N/A	N/A	✓	
13	Light	12/02/2025	10013	I	13	✓	Pass	✓	>299	2.5	✓	N/A	N/A	N/A	✓	
14	Extension Lead	12/02/2025	38952	I	13	✓	Pass	✓	>299	3.12	✓	N/A	N/A	N/A	✓	
15	Extension Lead	12/02/2025	10015	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
16	Extension Lead	12/02/2025	10015	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
17	Extension Lead	12/02/2025	10016	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
18	Extension Lead	12/02/2025	10018	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
19	Extension Lead	12/02/2025	10019	I	13	✓	Pass	✓	>299	N/A	✓	N/A	✓	N/A	✓	
20	Extension Lead	12/02/2025	10020	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
21	Extension Lead	12/02/2025	10021	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
22	Extension Lead	12/02/2025	10020	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
23	Light	12/02/2025	10023	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
24	Light	12/02/2025	10024	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
25	Light	12/02/2025	10025	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
26	Beamz 1	12/02/2025	62963	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
27	Extension Lead	12/02/2025	10027	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
28	Extension Lead	12/02/2025	10028	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

FT/PAT 6242000001968

Equipment formal visual and combined inspection and test

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/ Earth Bond Ω	Polarity	Insulation M Ω	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
29	Light	12/02/2025	10029	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
30	Light	12/02/2025	10030	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
31	Extension Lead	12/02/2025	10031	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
32	Extension Lead	12/02/2025	10032	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
33	Light	12/02/2025	10033	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
34	Light Qtx	12/02/2025	10034	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
35	Beamz 2	12/02/2025	61285	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
36	Extension Lead	12/02/2025	10036	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
37	Extension Lead	12/02/2025	10037	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
38	Commando Extension Lead	12/02/2025	10038	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
39	Commando Extension Lead	12/02/2025	10039	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
40	Speaker & Light	12/02/2025	29984	II	3	✓	N/A	✓	N/A	0.05	✓	N/A	N/A	N/A	✓	
41	Extension Lead	12/02/2025	10041	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
42	Extension Lead	12/02/2025	10042	I	13	✓	Pass	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
43	Beamz 3	12/02/2025	62948	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
44	Party Light	12/02/2025	10044	II	13	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case

Portable /Fixed Appliance

Equipment formal visual and combined inspection and test

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/Earth Bond Ω	Polarity	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
45	Light	12/02/2025	10045	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	
46	Light	12/02/2025	10046	II	3	✓	N/A	✓	>299	0.02	✓	N/A	N/A	N/A	✓	
47	Light	12/02/2025	10047	II	3	✓	N/A	✓	>299	N/A	✓	N/A	N/A	N/A	✓	

Test Result Totals:

Total Items Tested: 40

Total Failed Items Tested: 0

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case