



MY20-22 Ford F59

PCM Connector P175T Repair Terminals



C175T Repair terminals



- Pins 2, 46, 76, 77
 - Motorcraft
 - WT1001
 - Ford
 - DU2Z14474BA
- All other pins
 - Motorcraft
 - WT1002
 - Ford
 - DU2Z14474CA

Pins 2, 46, 76, 77

Motorcraft WT1001

Ford SPN DU2Z14474BA



Fuel Pump Jumper Harness Kit

Terminal - 0.64mm

Silver Plated Terminals.

Part #: WT1001 (DU2Z14474BA)

Most parts available next business day.



All other pins

Motorcraft WT1002

Ford SPN DU2Z14474CA



Fuel Pump Jumper Harness Kit

Terminal - 0.64mm

Silver Plated Terminals.

Part #: WT1002 (DU2Z14474CA)

Most parts available next business day.