

# MY14 – 19 F59 Horn Pad Installation

- Please note when replacing the horn pad on model year 2014 – 2019 Ford F59 chassis that the horn pad mounting capscrew torque is 44 in-lb( approx. 4 ft-lb).
- Replacement clips are not available and the entire steering wheel needs replaced (Steering wheel: Ford # BU9Z-3600-BA, UPS # 5211307)

