




OBDII connector for Geotab

Access and mounting

Lower the glove compartment.

1. Press the glove compartment stopper inward.
2. Fully lower the glove compartment.



Remove the 5 screws at the bottom of this panel and remove panel



Remove 5 screws and lift out cover. The screws are 6mm hex head



The OBDII connector will be mounted to the Instrument Panel bracket by the manufacturing plant. The customer or upfitter will connect the Geotab unit to the OBDII connector . The Geotab unit can only connect to the connector one way with the white label printed with the serial number pointing up.



This picture shows the Geotab unit mounted in the connector and to the Instrument panel bracket. A piece of double sided adhesive tape can be used applied between the Instrument panel bracket and the Geotab unit if needed for possible rattle issues. The tape is not needed to secure the Geotab unit.



Re install the cover using the 5 screws.
Raise the glove box door back into position