

# UPS Ford F59 Shifter Interlock: Type 1

- Shifter can only be replaced as complete unit.
- Shifter interlock solenoid can not be replaced separately.
- For replacement shifter assembly contact:

National Fleet Service

Detroit, MI

Olena Timek

(313) 923-1799

[otimek@nationalfleetservices.com](mailto:otimek@nationalfleetservices.com)

Shifter Assembly Part #: NFS-PN-0019



Pull pin out from bottom of solenoid to release shift lock

# UPS Ford F59 Shifter Interlock: Type 2

- Shifter can only be replaced as complete unit.
- Shifter interlock solenoid can not be replaced separately.
- For replacement shifter assembly contact:

National Fleet Service

Detroit, MI

Olena Timek

(313) 923-1799

[otimek@nationalfleetservices.com](mailto:otimek@nationalfleetservices.com)

Shifter Assembly Part #: NFS-PN-0019

Use finger to push locking pin in to release shift lock

