

SUBJECT: Active Service Documents Master Indices¹

I. INTRODUCTION

This Service Document Master Index organizes an alphanumeric list of active and recently retired service documents. Service documents not included in this index (with release dates issued earlier than this index) are considered obsolete or inactive. Inactive service documents are no longer eligible for publication or release.

This document is comprised of multiple reorganized indices tailored for your specific point of reference:

Table 1. Service Documents, Indexed by Reference

Section	Index Reference	Description	Page
III	FAA AD	Sorted numerically by FAA AD number and their corresponding service document (if applicable). May contain supplemental or standard practices.	2
IV	RR Document No.	Table reference to Rolls Royce Service Documents effective for Rolls Royce manufactured C90, O200, O240, and O300 engines.	4
V	Recent Changes	A summary of all documents released since the last published Index. New, revised, and retired service documents sorted by most recently released date.	5
VI	Subject Tables	Engine subsystem tables (grouped alphabetically by subject type). Active service documents are sorted by most recently released date.	9
VII	Engine Model	Cross-referenced index (grouped by engine model) with the applicable service document number and release date. Active service documents are sorted by most recently released date.	21

Continental issues service documents to announce product improvements and to address conditions that affect maintenance, preventive maintenance, safety and continued airworthiness. Compliance is required as specified in the **COMPLIANCE** section of each service document.

For the different service document categories released by Continental, refer to the most current version of M-0, “Standard Practice Maintenance Manual” for Continental Aerospace Technologies service documents and SIL640, “New Service Document Format” for Continental Ignition System service documents.

Information contained in service documents will be incorporated into engine parts, maintenance, and overhaul manuals at the next revision or reprinting of the affected manual. Once incorporated into all applicable manuals, the information becomes a part of the engines type design data and is required for continued airworthiness of the engine or components.

1. Published and printed in the U.S.A. by Continental Motors, Inc.® dba Continental Aerospace Technologies™

II. INSTRUCTIONS FOR CONTINUED AIRWORTHINESS

In accordance with Title 14 of the Code of Federal Regulations (14 CFR) part 33.4, Continental issues Instructions for Continued Airworthiness (ICA) for the engines and components for which it holds the Type Certificate or Parts Manufacturing Authorization (PMA) authority. ICAs are primarily published in the form of Maintenance Manuals, Overhaul Manuals, or combined Maintenance and Overhaul Manuals. These manuals may be supplemented by service documents, which may contain updates to an ICA until such time that the updated ICA is incorporated into the appropriate manual. Additionally, service documents may address a specific issue and modify the published ICA for a limited purpose which may not be incorporated into the manual (reference the latest revision of **M-0** for more information).

III. FAA AD

The following is a list of FAA Airworthiness Directives (AD) applicable to Continental engines or corresponding service documents. Document No. column may contain release announcements, follow-on maintenance, supplemental or standard practices.

FAA AD No.	Document No.
46-36-01	M46-6 ¹
47-40-02	M47-9 ¹
49-50-01	M49-4 ¹
50-32-01	M48-14 ¹ , M48-15 ¹
50-20-01	M50-2 ¹
51-26-03	M48-12, M51-2 ¹
53-09-04 ²	N/A to Continental
56-06-01	M56-2 ¹
60-06-04	M57-4 ¹
60-12-01	M56-2 ¹
63-15-01	M60-1 ¹
63-22-03	M63-18 ¹
69-18-05	M69-8 ¹
70-13-03	M70-5 ¹
70-14-07R2	M70-10R1 ¹
71-09-03	M70-17 ¹
72-06-05R2	M73-12
72-15-02	M73-6R1
72-20-02	M73-2
72-24-03	M70-16 ¹
73-13-04 ²	N/A to Continental
74-18-05	M74-18 ³
74-18-07 ²	N/A to Continental
74-18-08	M74-5A
74-22-04	M74-21 ¹

FAA AD No.	Document No.
74-26-09 ²	BENDIX SB No. 556C ³
75-09-13 ²	N/A to Continental
76-02-07	M75-30 ³
76-07-12 ²	BENDIX SB No. 583 ³
76-13-09	M76-14 ¹
77-05-04	M77-6 Sup1 ¹
77-13-22	M90-17 ¹
78-06-01	M78-5 Rev3
78-18-04 ²	BENDIX SB No. 584B, 587, 590A, 600 ³
79-05-09	M79-2 Rev1 ¹
79-12-07 ²	BENDIX SB No. 606B ³
79-18-06 ²	BENDIX SB No. 605A ³
80-01-04 ²	N/A to Continental
80-09-11 ²	N/A to Continental
80-17-04 ²	N/A to Continental
80-22-05	M81-9 (SS M80-20)
80-25-06R1	M80-30 Rev1 ¹
81-07-06	M81-8R1
81-12-06 R1 ²	BENDIX SB No. 618, 619 ³
81-13-10 R1	M81-23 R1
81-16-05	M81-13 R1
81-17-01 ²	BENDIX SB No. 614 ³
81-23-02 ²	N/A to Continental
81-24-06	M80-26 Rev1 ¹
82-09-01	M82-5

FAA AD No.	Document No.
82-11-05 ²	BENDIX SB No. 617B ³
82-13-01 ²	BENDIX SB No. 613 ³
82-20-01 ²	BENDIX SB No. 623A ³
82-27-03	M83-3
84-19-04 ²	N/A to Continental
84-25-05 ²	N/A to Continental
85-08-02	M85-3
86-08-07 ²	N/A to Continental
86-13-04 R2	M86-7 R5 ¹
87-04-05	M87-6
87-14-02 (see 88-17-03)	M87-24 (SS M87-13)
87-26-08	M87-25 / M87-26
88-03-06	M88-4
88-17-03	M89-6 (SS M88-6, M87-3), M87-24 / M88-5 / M88-6
89-14-01	M89-14
89-24-01 R1	M90-6
89-24-03 ²	N/A to Continental
91-19-03	M90-14 ¹
92-04-09	M92-4 R1
93-08-17	M91-10R1
93-10-02	MSB93-12
93-11-03 ²	N/A to Continental
93-16-15	MSB95-6 (SS M93-9R1)
93-19-04 ²	N/A to Continental
93-22-05	CSB93-13
94-05-05 ²	N/A to Continental
94-06-09	CSB94-1
95-03-14	MSB94-9
95-08-10	CSB95-1A
95-21-15	SB03-3 ¹ (SS M84-15)/M88-10
96-12-04 ²	N/A to Continental
96-12-06	MSB94-8D
96-12-22 ²	N/A to Continental
97-21-02	CSB97-10B
97-26-17	CSB96-8/MSB96-10B
98-01-06 ²	N/A to Continental
98-01-08 ²	N/A to Continental
98-17-11 ²	N/A to Continental

FAA AD No.	Document No.
98-19-02 ²	N/A to Continental
99-19-01	MSB99-3C/CSB99-6B
2000-23-21	MSB00-5D
2002-13-04 ²	N/A to Continental
2004-08-10 ²	N/A to Continental
2005-12-06	MSB645
2005-20-04 (superseded)	MSB94-4G
2007-05-15	MSB94-4H
2007-04-19 ²	N/A to Continental
2007-16-10	MSB07-4 ³
2008-08-17	MSB08-5
2009-02-03 ²	N/A to Continental
2009-19-07	MSB09-1B
2010-07-08	MSB10-3
2010-11-04	MSB09-8A
2011-13-03	SB10-8A ³
2011-25-51	MSB11-4B
2011-26-07	MSB00-6D ³
2012-03-06 ²	N/A to Continental
2012-24-09 ²	N/A to Continental
2012-10-13	MSB11-4B
2013-21-02	MSB13-7
2014-05-29 ²	N/A to Continental
2016-16-12 ²	N/A to Continental
2016-21-04	CSB15-2C ⁴
2016-21-04	CSB15-7B ⁴

¹Corresponding Continental Service Documents retired, removed from set, or superseded (SS to current version M-0 for general references, standard practices, torque tables, and maintenance practices). Documents available upon request. Please contact Continental Technical Service.

²No applicable Continental Service Documents are referenced within the specified FAA AD.

³Service Document is a coversheet or reference used for follow-on airworthiness.

⁴Added FAA AD 2016-21-04 1st Qtr., 2017

IV. ROLLS ROYCE SERVICE DOCUMENTS, *for reference only*

The following Rolls Royce Service Documents are effective on Rolls Royce manufactured C90, O200, O240, and O300 engines.

Table 2. General Topics

Rolls Royce Document No.	Subject	Mandatory	Non-mandatory	C90	O200	O240	O300
T-200	Oil Pump Gears	X		X	X		X
T244/1	Valve Guide	X			X		X
T272/2	Cylinder. P/N A50222RR		X	X	X		X
T282	Tech. Pubs		X		X		X
T304	Replacement Piston		X			X	
T398	Engine Installation	X				X	
T406	AC Fuel Pump		X	X	X	X	X
T416	Crankshaft	X				X	

V. SERVICE DOCUMENTS, listed by most recent changes

Table	Subject Title	Page
3	New Service Documents (Apr. 1 thru Jun. 30, 2019)	5
4	Revised Service Documents (Apr. 1 thru Jun. 30, 2019).....	5
5	Retired & Superseded Service Documents (Apr. 1 thru Jun. 30, 2019)	5
6	Archived & Superseded Service Documents, (207 Documents)	6

NOTE: The following tables list the current period’s Service Document activity during Apr. 1 thru Jun. 30, 2019. Each table includes the service Document Number, Release Date, release Status (either **N** = New, **R** = Revised, **X** = Retired, or **S** = Superseded) and Document Title/Description. All Service Documents in this section are sorted by the “Release Date” column.

Table 3. New Service Documents (Apr. 1 thru Jun. 30, 2019)

Document No.	Release Date	Status	Document Title/Description
CSB19-03	2019-05-21	N	Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 078

Table 4. Revised Service Documents (Apr. 1 thru Jun. 30, 2019)

Document No.	Release Date	Status	Document Title/Description
SB19-02A	2019-04-22	R	Champion Aerospace Slick Service Bulletin SB1-19
SIL18-06A	2019-04-10	R	Superseding Magneto and Harness Application

Table 5. Retired & Superseded Service Documents (Apr. 1 thru Jun. 30, 2019)

Document No.	Release Date	Status	Document Title/Description
SB19-02	2019-03-07	S	Champion Aerospace Slick Service Bulletin SB1-19
SIL16-2	2016-04-15	X	Standard Practice Maintenance Manual Release (M-0)
SIL18-06	2018-10-11	S	Superseding Magneto and Harness Application

Table 6. Archived & Superseded Service Documents, (207 Documents)

Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision
631	RETIRED	M85-10	M-0	SB03-7A	RETIRED
CSB04-6	CSB04-6A	M85-14	RETIRED	SB04-11	RETIRED
CSB04-6A	CSB04-6B	M85-9R1	RETIRED	SB04-4A	RETIRED
CSB05-8C	CSB05-8D	M86-4	RETIRED	SB04-7	SB14-2
CSB07-2	CSB07-2A	M87-10	SB11-3	SB05-10	M-18 MANUAL
CSB08-3B	CSB08-3C	M87-13	M87-24	SB05-2	M-0
CSB08-3C	M-0	M87-15	M-0	SB05-7	FI-2
CSB08-9	CSB08-9A	M87-3	M88-6	SB05-8	SB05-8A
CSB09-11	CSB09-11A	M88-10	M-0	SB05-8A	MSB05-8B
CSB10-2	MSB10-3	M88-6	M89-6	SB06-1	SB06-1A
CSB13-1	CSB13-1A	M88-9	M-0	SB06-1A	RETIRED
CSB13-1A	CSB13-1B	M89-5	SB11-3	SB07-8	SB07-8A
CSB14-1	CSB14-1A	M89-7R1	M-0	SB07-8A	CSB09-11
CSB15-2	CSB15-2A	M89-9	M-0	SB07-9	RETIRED
CSB15-2A	CSB15-2B	M90-17	M-0	SB08-13	M-0
CSB15-2B	CSB15-2C	M90-9	RETIRED	SB08-3	SB08-3A
CSB15-7	CSB15-7A	M91-9	SID05-1A	SB08-3A	CSB08-3B
CSB15-7A	CSB15-7B	M92-11	RETIRED	SB08-4	SB08-4A
CSB95-4	CSB95-4A	MSB00-6C	MSB00-6D	SB08-6	SB09-6
CSB97-10A	CSB97-10B	MSB05-8B	CSB05-8C	SB08-8	SB08-8A
CSB98-1B	CSB98-1C	MSB08-2	MSB08-2B	SB08-8A	SB08-8B
CSB99-6A	CSB99-6B	MSB09-1	MSB09-1A	SB09-3	SB09-3A
M67-12	M-0	MSB09-1A	MSB09-1B	SB09-4A	SB09-4B
M70-17	RETIRED	MSB09-8	MSB09-8A	SB09-6	SB09-6A
M71-14	RETIRED	MSB11-4	MSB11-4A	SB10-1	SB10-1A
M72-17R1	M-0	MSB11-4A	MSB11-4B	SB10-8	SB10-8A
M74-16	SB18-03	MSB94-4G	MSB94-4H	SB11-3	M-0
M75-17	RETIRED	MSB94-8B	MSB94-8C	SB12-2	M-2
M76-4	M-0	MSB94-8C	MSB94-8D	SB13-4A	SB13-4B
M76-5R1	SIL15-9	MSB94-8D	M-0	SB13-4B	SB13-4C
M76-8	M-0	MSB96-10	MSB96-10A	SB13-6	SB13-6A
M77-3	M-0	MSB96-10A	MSB96-10B	SB14-5	SB14-5A
M78-11	RETIRED	MSB96-10B	M-0	SB14-8	M-0
M79-11	SB11-3	SB00-2	SB00-2A	SB15-1	RETIRED
M80-18	RETIRED	SB00-2A	SB00-2B	SB15-3	SB15-3A
M80-9R1	RETIRED	SB00-3A	M-0	SB15-4	SB15-4A
M81-25	SB14-8	SB02-10A	RETIRED		
M84-5	RETIRED	SB03-3	M-0		
M84-8	RETIRED	SB03-7	SB03-7A		

...continue on next page.

Table 6. Archived & Superseded Service Documents, *continued*

Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision	Superseded Document	Subsequent Revision
SB15-6	SB15-6A	SID97-3E	SID97-3F	SIL16-1	SIL16-1A
SB15-6A	SB15-6B	SID97-3F	SID97-3G	SIL16-2	RETIRED
SB16-3	M-0 REV 3	SID97-3G	M-0	SIL17-02	RETIRED
SB17-01	SB17-01A	SID97-4C	SID97-4D	SIL17-03	M-0
SB17-01A	M-0	SID97-4D	SID97-4E	SIL93-11A	SIL93-11B
SB18-04	SB18-04A	SID97-4E	SID97-4F	SIL93-11B	M-0
SIL18-06	SIL18-06A	SID97-4F	M-0	SIL93-15	M-0
SB18-08	SB18-08A	SIL00-11B	M-0	SIL95-5	M-0
SB19-02	SB19-02A	SIL00-7A	SIL00-7B	SIL97-14	RETIRED
SB669	SB670	SIL00-9A	M-0	SIL98-3A	SIL98-3B
SB94-8	MSB94-8	SIL02-4	RETIRED	SIL98-5	RETIRED
SB95-2	M-0	SIL02-6A	RETIRED	SIL98-6B	SEE PARTS CATAL
SB95-3B	M-0	SIL03-1	M-0	SIL98-9B	SIL98-9C
SB95-7	SB95-7A	SIL03-2B	SIL03-2C	SIL98-9C	SIL98-9D
SB96-11A	SB96-11B	SIL03-2C	M-0	SIL98-9D	SIL98-9E
SB96-11B	M-0	SIL04-12	SIL04-12A	SIL98-9E	M-0
SB96-12	M-0	SIL04-12A	M-0	SIL99-1	M-0
SB96-3B	SB96-3C	SIL04-1A	RETIRED	SIL99-2B	SIL99-2C
SB96-7B	SB96-7C	SIL04-2	SIL04-2A	SIL99-2C	M-0
SB96-7C	SB96-7D	SIL04-3	RETIRED	SIL671 ¹	SIL671A
SB96-7D	M-0	SIL04-8	SB14-2	SSI06-6	SSI06-6A
SB97-6	SB97-6A	SIL04-9	RETIRED	SSI10-5	M-2
SB97-6A	SB97-6B	SIL05-3	SIL05-3A	SSI10-9A	M-2
SB97-6B	M-0	SIL05-4A	RETIRED		
SB98-2	RETIRED	SIL05-5	RETIRED		
SB99-8	SB99-8A	SIL05-6A	RETIRED		
SB99-8A	SB99-8B	SIL06-4	RETIRED		
SID05-1	SID05-1A	SIL07-7	SIL07-7A		
SID05-1A	SID05-1B	SIL07-7A	RETIRED		
SID07-10	RETIRED	SIL10-6	SIL1-6A		
SID07-3A	RETIRED	SIL13-2	SIL13-2A		
SID97-2B	M-0	SIL13-2A	M-0		
SID97-3B	SID97-3C	SIL13-3	RETIRED		
SID97-3C	SID97-3D	SIL14-4	SIL14-4A		
SID97-3D	SID97-3E	SIL14-4A	SIL14-4B		
		SIL14-6	SIL14-6A		

¹Unreleased document. SIL671A was first released version.

Intentionally Left Blank

VI. SERVICE DOCUMENTS, *listed by subject*

Table	Subject Title	Page
7	Alternators.....	10
8	Bearings	10
9	Camshafts / Lifters.....	10
10	Carburetors.....	11
11	Connecting Rods	11
12	Crankcases	11
13	Crankshafts.....	12
14	Cylinders	13
15	Electronic Systems.....	14
16	Fuel / Fuel Hoses / Fuel Injection	14
17	Gears	15
18	General Topics	15
19	Hoses / Control Cables / Linkages.....	16
20	Ignition / Magnetos	16
21	Induction / Air Intake	17
22	Lubrication / Oils	17
23	Miscellaneous.....	18
24	Pistons	19
25	Starters / Starter Adapters	19
26	Turbocharging / Exhaust Systems.....	19

NOTE: The following subject tables contain the Service Document Number, Release Date, release Status (**N** = New, or **R** = Revised document activity during Apr. 1 thru Jun. 30, 2019), and Document Title/Description. All services documents in each subject table are sorted by most recently released date.

¹*Special Service Instructions (SSI) are issued to address an issue on specific model and/or serial number engines. Continental will distribute SSI notification directly to the owners of the affected engines. SSIs will not be included in the general service document set but will be made available through Continental Customer Service to owners of the affected engines only. For further information on SSIs, refer to the latest revision of M-0 or contact Continental Customer Service at 1 (251) 436-8299.*

Table 7. Alternators

Document No.	Release Date	N/R	Document Title/Description
CSB19-03	2019-05-21	N	Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 078
SIL17-07	2017-11-14		Alternator, 60A, 24V (P/N 646845)
SB16-9	2017-02-03		Hartzell Engine Technologies (HET) Service Bulletin (SB) No. 066
SB14-5A	2016-06-16		Hartzell Engine Technologies (HET) Service Bulletin (SB) No. 059
SIL14-4B	2016-06-16		24 Volt/70 Amp Belt-Driven Alternator Brace Alignment
SIL15-8	2015-11-30		Front Mounted Alternator Bracket Assembly Inspection
SSI06-6A	2014-12-17		Alternator Mount Bracket Assembly Inspection
SB13-8	2014-01-22		Hartzell Engine Technologies Service Information Letter A-137
SB11-1A	2011-03-17		Hartzell Engine Technologies Service Information Letter A-138
SB11-2	2011-01-13		Hartzell Engine Technologies Service Information Letter A-135
SB09-12	2009-10-16		Kelly Aerospace Energy Systems Serv Bull 038A Inspection of Slip Ring End Housing for Cracks ES1024-1, TCM 646802
CSB08-11	2008-07-16		Kelly Aerospace Power Systems Bulletin 033
SB01-3A	2002-12-10		Teledyne Continental Motors P/N 649304A1 and P/N 649305A1 Gear-Driven Alternators
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
M92-12	1992-08-27		New and Rebuilt Alternator Thru-Bolt torque Inspection, P/N 649304, 649305 (with Drive Coupling), 649304R and 649305R (with Drive Coupling)
M81-15R1	1983-06-16		Prestolite 100 Amp Alternator Exchange
M81-12	1981-05-11		Installation Instructions and Rework Instructions for Part Nos. 642266 & 643935 Alternator Brackets
M76-7	1976-03-25		P/N 634021 Alternator Face Drive Gear Lockplates
M75-30	1975-12-19		Prestolite Alternators
M73-6R1	1973-06-11		Prestolite Alternator Cooling Fan Maintenance and Inspection

Table 8. Bearings

Document No.	Release Date	N/R	Document Title/Description
SB97-5	1997-03-31		Installation of Flanged Type Front Main Bearings
M93-5	1993-02-19		Chamfer of Crankcase Main Bearing Oil Feed Holes
M89-14	1989-06-29		Thru Bolt torque Check and Visual Inspection #2 Main Bearings
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications

Table 9. Camshafts / Lifters

Document No.	Release Date	N/R	Document Title/Description
CSB05-8D	2018-08-22		Camshaft Gear (P/N 656818)
SIL18-05	2018-08-22		O-470-U Camshaft Gear Configuration
SID05-1B	2016-06-08		Inspection Guidelines for CMI Camshafts and Hydraulic Lifters
MSB09-8A	2009-12-04		Inspection and Removal of Certain TCM Engine Hydraulic Lifters
SB00-1	2000-01-14		Camshaft Packaging
M86-13R1	1986-10-17		Camshaft Plug Inspection and Overhaul Manual Revision
M86-14	1986-10-01		Camshaft (P/N 629726) Rework

Table 10. Carburetors

Document No.	Release Date	N/R	Document Title/Description
CSB19-01	2019-02-07	N	Fuel (Primer) Diverter Valve Assembly
SB16-4	2016-06-08		Incorrectly Identified Control Levers
SB09-6A	2009-06-22		Volare' Carburetors, LLC SB-5 Rev A Service Bulletin
SB09-5	2009-04-30		Volare Carburetors, LLC SB4 Service Bulletin, Carburetor Bowl to Float Clearance
SB09-3A	2009-04-24		Volare Carburetors, LLC SB2 Service Bulletin, Required Replacement of Foam and Hollow Floats
SB09-2	2009-03-17		Volare Carburetors, LLC SB1 Service Bulletin
SB08-7	2008-06-27		Precision Airmotive, LLC Mandatory Carburetor Service Bulletin MSA-14
SID97-7	1997-05-07		Precision Airmotive Corporation Service Bulletin MSA-10
SID94-12	1994-11-14		Precision Airmotive Corporation Service Bulletin - MSA-7
CSB93-13	1993-08-12		Carburetor Air Intake Housing Assembly Inspection
M92-5	1992-02-28		Precision Airmotive Corporation Mandatory Service Bulletins #MSA-1 Rev. 1 and MSA-2 Rev. 1
M88-15	1988-10-10		Facet Service Bulletin A1-88
M75-15	1975-07-14		New Carburetor Airbox
M73-12	1973-06-08		Marvel-Schebler Carburetor Bulletin A1-73

Table 11. Connecting Rods

Document No.	Release Date	N/R	Document Title/Description
SB17-06	2017-10-20		Connecting Rod Bolt (P/N 655959) Crankcase Clearance Inspection
SB07-1	2007-03-19		Connecting Rod Pistons Pin Bushing Installation
CSB96-13	1996-11-14		IO360, TSIO360 and LTSIO360 Series Engine Connecting Rod Inspection and Replacement

Table 12. Crankcases

Document No.	Release Date	N/R	Document Title/Description
SB18-04A	2018-12-18		Replacement of Flanged Nut (P/N 652541) Identified with Manufacturer's Stamp "ZB"
CSB05-8D	2018-08-22		Camshaft Gear (P/N 656818)
SB17-06	2017-10-20		Connecting Rod Bolt (P/N 655959) Crankcase Clearance Inspection
SIL14-6A	2017-02-03		Sandcast Crankcase Oil Gage Rod Housing/Housing Extension Installations on 470, 520, and 550 Engines
SB09-4B	2016-06-16		Crankcase Inspection for "Permold" Engines Equipped with Air Conditioner Systems Installed From 1998 to Present
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
CSB97-9	1997-05-28		GTSIO-520 Crankcase Inspection
CSB96-2	1996-03-21		Crankcase Oil Passage Inspection
CSB94-15	1994-12-02		Crankcase Stud Inspection
MSB94-9	1994-10-21		Inspection of Engine Mount Bracket, Part Number 630695; Replacement of Engine Mount Brackets, Part Numbers 630694 and 630695
M93-5	1993-02-19		Chamfer of Crankcase Main Bearing Oil Feed Holes
M92-9	1992-05-29		Flanged 500 Thru Bolt Nut, P/N 652541
M92-7	1992-05-26		Crankcase Cylinder Deck Studs
M90-16	1990-08-22		7th Stud Improvement on TCM Crankcases
M89-14	1989-06-29		Thru Bolt torque Check and Visual Inspection #2 Main Bearings

Table 12. Crankcases

Document No.	Release Date	N/R	Document Title/Description
M86-9	1986-03-20		Crankcase Modification
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications
M77-9	1977-03-17		Thru Bolt Change
M70-3	1970-02-03		Crankcase Modification Recommended At Next Engine Major Overhaul

Table 13. Crankshafts

Document No.	Release Date	N/R	Document Title/Description
SB18-07	2018-11-19		Crankshaft Dowel (P/N 536563) Inspection and Replacement Instructions at Maintenance and Overhaul
SB15-3A	2016-08-09		Oil Sump Assembly Inspection
MSB94-4H	2016-07-27		Starter Adapter Shaftgear and Crankshaft Gear Inspection
CSB99-6B	2016-06-16		GTSIO-520 & GIO-550 Crankshaft Inspection
SB96-3C	2016-06-16		Crankshaft Gear Bolt Inspection
MSB96-10B	2015-08-10		Crankshaft Ultrasonic Inspection
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
SB13-6A	2014-04-10		Crankshaft Gear Replacement
CSB12-1	2012-05-11		P/N 641909 Lock Plate Inspection
SB09-14	2009-10-16		Crankshaft Corrosion Treatment
SB08-12	2008-09-09		Crankshaft Gear Supersedure
SSI07-5 ¹	2007-08-22		Replacement of 6th order Crankshaft Counterweights, Pins, Bushings, Plates and Snaprings
SB06-5	2006-05-25		Crankshaft Oil Transfer Tube Inspection and Replacement
SIL06-3	2006-05-01		Crankshaft Gear Retaining Screw
SB03-5	2003-11-06		New Limits for Crankshaft End Clearance
MSB00-5D	2001-10-17		Crankshaft Material Inspection
MSB99-3C	1999-07-27		Crankshaft Inspection
CSB96-8	1996-06-25		Replacement of Airmelt (Non-Var) Crankshafts
SB94-7	1994-09-14		Crankshaft Flange Timing Marks
M93-4	1993-02-12		Crankshaft Counterweights
M87-23	1987-11-24		Crankshaft Counterweight Identification at Overhaul
M78-9	1978-08-23		Crankcase, Crankshaft and Bearing Applications
M78-3	1978-01-11		Governor Oil Transfer Collar Sleeves, Retaining Clips and Clearances

Table 14. Cylinders

Document No.	Release Date	N/R	Document Title/Description
SB18-08A	2019-01-14	R	Inspection and Maintenance Modification of Cylinder Assemblies, (P/Ns 658058, 658472, 658473)
SB15-6B	2018-08-09		NiC3™ Cylinder Assemblies
SB18-03	2018-04-05		Valve Spring Identification
SIL18-01	2018-01-19		Rocker Assembly Valve, Exhaust (P/N 658745)
SIL04-2A	2016-07-27		Cylinder Barrel Ultrasonic Inspection
CSB98-1C	2016-07-27		Intake and Exhaust Valve Inspection
SIL98-3B	2016-07-27		Production Release of New Intake and Exhaust Valve Springs
CSB14-1A	2016-06-16		Cylinder Barrel Fin Inspection
CSB95-4A	2016-06-16		Intake Valve Guide Seal P/N 646678 Inspection
SB00-2B	2016-06-16		IO346 Replacement Cylinder Assembly Kit
SSI13-5 ¹	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
MSB09-1B	2009-08-18		Cylinder Replacement
SB09-7	2009-07-16		Potential Push Rod Seal Leakage
SB08-1	2008-02-18		Rocker Shaft Inspection and Replacement
SID97-4D	2013-08-23		Cylinder Bore and Pistons Fit Specifications
SB02-9	2002-10-25		Cylinder Head to Barrel Seepage P/N 654972 Cylinder Assembly
SIL99-5	1999-05-25		TCM Part Number 629141 Thermo Unit
SB98-8	1998-10-22		Number One and Three Cylinder Intake Tube Modifications
SB97-11	1997-08-10		Installation of Single Piece Rocker Assembly Bushings Part Numbers 652129 and 652963
SIL94-10	1994-11-14		Replacement of Intake Valve Rotocoils
SB94-13	1994-11-14		Pistons Ring Set, Part Number 649226 and Cylinder Kit Part Numbers 653443A3, 653443A3BP, 653443A5, 653443A5BP, 653444A4, 653444A4BP, 653455A2 and 653455A2BP
MSB93-12	1993-05-12		Valve Retainer Key Installation Inspection
M93-8	1993-02-19		Rocker Arm to Rotocoil Clearance
M92-11	1992-08-24		Liquid Cooled Cylinder Assembly, Spark Plug and Spark Plug Heli-Coil
M92-8	1992-05-29		Application of 4-1/6" Diameter Cylinder Assemblies
M92-6	1992-02-28		Shaftgear Retention Improvement for Inclined Valve Cylinder
M92-4R1	1992-02-05		IO and L/TSIO360 Rocker Shaft Stud Inspection
M91-6	1991-03-20		Cylinder Barrel Inspection
M91-7	1991-03-20		Cylinder Barrel Ultrasonic Inspection
M90-15	1990-08-21		Rocker Arm and Push Rod Inspection
M90-13	1990-07-16		Exhaust Valve Stem Corrosion/Erosion
M88-12	1988-09-09		Piper Aircraft Mandatory Service Bulletin No. 892
M87-8	1987-02-26		Exhaust Valve Inspection
M85-10	1985-07-18		Cylinder Hold Down Nuts
M85-3	1985-02-04		Exhaust Valves In P/N 646680 Cylinder Assemblies
M78-16	1978-11-29		Number Two Cylinder Intake Elbow Tube, TCM Part No. 629138
M78-6	1978-03-03		Removal and Re-Installation of Special Rosan Exhaust Port Studs
M77-19	1977-08-12		Intake and Exhaust Rocker Arm Identification and Application
M76-12	1976-05-24		Chrome Plating of Cylinders

Table 14. Cylinders

Document No.	Release Date	N/R	Document Title/Description
M75-17	1975-07-17		Cylinder Head and Rocker Pivot Pin Change
M73-13	1973-07-10		Reaming and Bushing Rocker Shaft Bosses
M73-2	1973-01-17		FAA Airworthiness Directive No. 72-20-2 (470 Cylinder)

Table 15. Electronic Systems

Document No.	Release Date	N/R	Document Title/Description
SSI07-6 ¹	2007-08-31		IOF-240-B Electronic Control Unit (ECU) Replacement

Table 16. Fuel / Fuel Hoses / Fuel Injection

Document No.	Release Date	N/R	Document Title/Description
CSB19-01	2019-02-07	N	Fuel (Primer) Diverter Valve Assembly
SB13-4C	2016-11-07		Aneroid Equipped Fuel Pumps
SB08-4A	2016-07-27		Fuel Injection System Contamination
SB95-7A	2016-06-20		Manifold Valve Cover Inspection
CSB13-1B	2016-06-17		Replacement of Part No. 640560 Set Screws Installed on Part No. 642100-X (X= -1 Through -6 & -8), 646292-1 And 646663-1 And R-642100-3, -4, -5 And -6 Fuel Pressure Regulators
SB99-8B	2016-06-16		Engine Fuel Injection System Preservation
SB16-4	2016-06-08		Incorrectly Identified Control Levers
SIL14-9	2015-01-09		Fuel Pump Mixture Control Lever Configuration
SSI13-5 ¹	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
CSB08-3C	2013-07-17		Throttle and Mixture Control Levers
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SIL08-10	2008-07-16		Precision Airmotive LLC SIL RS-88. RSA5, RSA10 Servo Inspections of Hex Head Plug
MSB08-2B	2008-09-17		Precision Airmotive LLC Fuel Injection Servo RSA-5, RSA-10
SIL01-2B	2001-09-04		Precision Airmotive Corporation SIL RS-59 Revision 2
SIL01-4	2001-09-04		Precision Airmotive Corporation SIL RS-60
CSB01-1	2001-04-25		Fuel Pump Inspection and Seal Leak Test
M81-8R1	2001-02-05		Fuel Pump Screen Restriction
SB00-10	2000-12-19		Fuel Pump Seal P/N 649198
SB00-4A	2000-03-07		Australian AVGAS Contamination
SB99-8	1999-11-18		Engine Fuel Injection System Preservation
SB97-13	1997-10-30		Replacement Fuel Pump for TSIO520BE Engine
MSB95-6	1995-10-19		Fuel Pump Drive Coupling
M90-20	1990-12-20		Lear Romec Corporation, Service Bulletin No.101SB019
M90-19	1990-10-16		Fuel Inlet Tee
M89-19	1989-09-18		Re-Design of Lower Throttle Body Bracket
M87-6	1987-02-16		Romec Service Bulletin No. 101SB015 Fuel Pump P/N RR36090C (TCM P/N 643367)
M83-8R1	1983-07-15		Fuel Pump Replacement
M82-13	1982-10-27		Fuel Control Inlet Fitting

Table 16. Fuel / Fuel Hoses / Fuel Injection

Document No.	Release Date	N/R	Document Title/Description
M82-5	1982-04-26		Fuel Pressure Regulator 642100-5 & 642100-6 on Engines Installed In Cessna 340 and 414 Series Aircraft
M82-3	1982-03-08		Lear Siegler, Inc., Romec Division, Fuel Pump, TCM P/N 643367A1
M81-6R2	1982-01-29		Fuel Hoses
M80-11	1980-04-14		Intake Manifold Tube Drain Bosses
M79-4	1979-02-14		Fuel Injection Adjustment and Flight Testing Procedures of TIARA 6-285 Series Engine
M76-15	1976-06-17		Fuel Pumps
M75-14	1975-06-30		635014 Air Throttle Bracket Assemblies

Table 17. Gears

Document No.	Release Date	N/R	Document Title/Description
CSB05-8D	2018-08-22	N	Camshaft Gear (P/N 656818)
MSB94-4H	2016-07-27		Starter Adapter Shaftgear and Crankshaft Gear Inspection
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
SB13-6A	2014-04-10		Crankshaft Gear Replacement
SB08-12	2008-09-09		Crankshaft Gear Supersedure
SIL06-3	2006-05-01		Crankshaft Gear Retaining Screw
SB01-3A	2002-12-10		Teledyne Continental Motors P/N 649304A1 and P/N 649305A1 Gear-Driven Alternators
SB01-5	2001-10-18		Starter Adapter Bevel Gear Inspection
SID97-8	1997-05-28		Interference of TCM 24 Volt 60 Ampere Gear Driven Alternator and Crankcase Through Bolt
SB96-3B	1996-10-14		Crankshaft Gear Bolt Inspection
CSB96-5	1996-04-12		Oil Pump Drive Gears, P/N 649506 and 649681
SB96-4	1996-04-12		Improved Oil Pump Gears and Suction Screens
CSB96-1	1996-03-01		Starter Gear and Clutch Assembly P/N 653575
M90-6	1990-02-26		Inspection and Replacement of Scavenge Pump Gears P/N 635334 and 639388
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M76-7	1976-03-25		P/N 634021 Alternator Face Drive Gear Lockplates
M72-8	1972-06-21		New Design Splined Drive Scavenge Pump Shaft and Gear Assembly
M70-7	1970-03-17		Increasing Size of Oil Feed Holes to Starter Adapter Shaftgear

Table 18. General Topics

Document No.	Release Date	N/R	Document Title/Description
CSB19-03	2019-05-21		Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 078
SIL18-02	2018-02-15		Applicability of Service Documents
SIL05-3A	2014-04-10		Engine Specification Numbers
SIL06-2	2006-05-01		Unapproved Parts Notification No. 2004-00053
SB05-11	2005-12-08		Piper Service Bulletin 1157A
SIL99-2B	2005-10-20		Current Listing of Sealants, Lubricants & Adhesives Authorized By TCM
SB00-12	2000-12-19		Service Publications for Rolls Royce Manufactured Engines
SIL93-14	1993-08-17		CFC Warning Statement

Table 18. General Topics

Document No.	Release Date	N/R	Document Title/Description
M89-18	1989-08-10		Exhaust Gas Temperature (E.G.T.) Recommendations for Standard Engines (Leaning Lean)
M87-21	1987-10-07		Operation and Service

Table 19. Hoses / Control Cables / Linkages

Document No.	Release Date	N/R	Document Title/Description
CSB19-01	2019-02-07	N	Fuel (Primer) Diverter Valve Assembly
SIL02-5	2002-04-04		Induction Hose Clamp
SB94-3A	1995-05-23		Induction System Hose and Clamp Replacement
M84-3	1984-01-18		Induction Manifold Hose Inspection
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M81-6R2	1982-01-29		Fuel Hoses
M81-18	1981-08-05		Air Reference Hoses

Table 20. Ignition / Magnetos

Document No.	Release Date	N/R	Document Title/Description
SB19-02A	2019-04-22	N	Champion Aerospace Slick Service Bulletin SB1-19
SIL18-06A	2019-04-10	R	Superseding Magneto and Harness Application
SIL671A	2019-03-25		Aircraft Supplemental Type Certificate (STC) Installation Instructions for Shower-of-Sparks Starting Vibrator Booster Systems
SB15-4A	2018-12-18		Champion Aerospace Slick SB1-15A
SB18-08	2018-12-11		Inspection and Maintenance Modification of Cylinder Assemblies, (P/Ns 658058, 658472, 658473)
SB17-05	2017-09-29		Continental Motors Ignition Systems Service Bulletin SB643C
SB17-04	2017-09-29		Continental Motors Ignition Systems Service Bulletin SB670
SB643C	2017-07-21		Maintenance Intervals for Continental Motors (formerly TCM/Bendix) S-20, S-200, and S-1200 series Magnetos and Related Equipment
SB670	2017-07-14		Continental Motors S-20, S-200, and S-1200 Series Magneto Distributor Gear Block Inspection
SB16-6	2016-10-19		Engine Damage Due to Kickback
SB15-5	2015-10-06		Champion Aerospace Slick Service Letter SL No. 4300/6300-74-20-001
SB12-3	2012-10-08		Champion Aerospace Slick SB1-12
MSB00-6D	2010-11-19		Slick Service Bulletin SB1-00C
MSB94-8D	2010-02-17		Magneto to Engine Timing
SB08-8B	2009-04-10		Slick Service Bulletin SB2-08A
CSB08-9A	2008-10-14		Slick Service Bulletin 03-8A
SB05-11	2005-12-08		Piper Service Bulletin 1157A
SB05-9	2005-10-20		Slick Service Bulletin SB1-88B
CSB04-5A	2004-08-30		Teledyne Continental Motors Ignition Systems Critical Service Bulletin CSB665A Aircraft Supplemental Type Certificate (STC) Installation Instructions for Shower-of-Sparks Starting Vibrator Booster Systems
CSB02-8	2002-09-06		Teledyne Continental Motors Ignition System Critical Service Bulletin CSB664
SB02-7	2002-06-28		Teledyne Continental Motors Ignition System Service Bulletin SB663
SB02-3	2002-01-31		Magneto Tachometer Sensors
SB97-15	1997-12-05		TCM Ignition System Service Bulletin SB660
SIL657A	1997-10-09		Supersedure of P/N 10-163136 and 10-361638 Covers and of 10-361637 Cover Kit

Table 20. Ignition / Magnetos

Document No.	Release Date	N/R	Document Title/Description
SID96-6	1996-05-03		TCM Ignition Systems Service Bulletin SB653
CSB94-1	1994-02-01		Teledyne Continental Motors Ignition Systems Critical Service Bulletin 641
M93-10	1993-03-01		TCM Ignition Systems Service Bulletin No. 639
M87-16	1987-08-14		Slick Service Bulletin 1-86A
M84-13	1984-10-27		Slick Service Bulletin 1-84
M83-6	1983-03-07		Slick Service Bulletin 2-82
M83-5	1983-03-07		Slick Service Bulletin 3-82
M81-26	1981-12-04		Pressurization of Magnetos in Mooney M20K Aircraft
M81-13R1	1981-07-18		Slick Service Bulletin 1-81 (Revised)
M78-8	1978-08-25		Ignition System Maintenance
M74-18	1974-09-16		Compliance with Slick Bulletin 1-74
M70-11	1970-06-22		Slick Electro Bulletin 1-70

Table 21. Induction / Air Intake

Document No.	Release Date	N/R	Document Title/Description
SSI13-5 ¹	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SIL02-5	2002-04-04		Induction Hose Clamp
SB98-8	1998-10-22		Number One and Three Cylinder Intake Tube Modifications
SB94-3A	1995-05-23		Induction System Hose and Clamp Replacement
CSB93-13	1993-08-12		Carburetor Air Intake Housing Assembly Inspection
M89-23	1989-09-25		TSIO520CE Lower Throttle Body Support Bracket and Linkage
M88-13	1988-09-26		Induction Tube Cracking
M86-5	1986-02-04		Manifold Pressure Line Adapter Improvement
M84-3	1984-01-18		Induction Manifold Hose Inspection
M80-11	1980-04-14		Intake Manifold Tube Drain Bosses
M78-16	1978-11-29		Number Two Cylinder Intake Elbow Tube, TCM Part No. 629138

Table 22. Lubrication / Oils

Document No.	Release Date	N/R	Document Title/Description
SSI17-09	2017-12-22		Engine Oil Cooler (P/N 654585), Temporary Repair and Inspections Instructions
SIL00-7B	2017-06-19		Oil Gauge Rod Application
SB15-3A	2016-08-09		Oil Sump Assembly Inspection
SIL10-6A	2016-06-16		Oil Cooler and Vernatherm Control Valve for Certain Engines Experiencing Low Oil Temperatures
CSB07-2A	2016-06-16		Turbocharger Wastegate Oil Inlet Fitting Inspection and Replacement
SB16-5	2016-06-08		Oil Suction Tube Fasteners
SB16-3	2016-04-28		Turbocharger Check Valve Inspection and Cleaning
CSB15-7B	2016-04-26		TSIO-550-K Oil Cooler Cross Fitting Replacement
SIL15-9	2015-12-11		Remote Mounted Oil Coolers
CSB15-2C	2015-11-09		Oil Cooler Cross Fitting Replacement

Table 22. Lubrication / Oils

Document No.	Release Date	N/R	Document Title/Description
SSI13-5	2013-10-18		Amplified Operation, Maintenance and Servicing Requirements for Cirrus SR-20 Aircraft operated by CAFUC Only
SB12-2	2012-08-09		Oil Filler Tube Inspection and Support Bracket Installation
SSI10-9A	2011-01-13		Replacement of Oil Gauge Rod PN657474 and 658164 with New Oil Gauge Rod 658252
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SSI10-5	2010-07-02		0200D Oil Sump and Material Inspection
SIL09-15	2009-08-06		Oil Gage Rod 632062-3, 4 and 14
SB03-4	2003-07-21		Inspection of Oil Gauge Rod and Cap Assemblies, P/N 652171-22 and P/N 652171-27
SIL96-9	1996-08-12		Oil Pressure Relief Valve Spring
CSB96-5	1996-04-12		Oil Pump Drive Gears, P/N 649506 and 649681
SB96-4	1996-04-12		Improved Oil Pump Gears and Suction Screens
CSB95-1A	1995-04-05		Inspection and Replacement of Dukes Incorporated Turbocharger Oil Outlet Check Valve Part Number 367-00, (TCM P/N 641068)
SB94-11	1994-11-14		Oil Pump Gasket P/N 643749
SIL94-5	1994-06-14		Mobil AV1 Oil
SB94-2	1994-02-10		Oil Filter Adapter Mounting Stud
M92-14	1992-09-09		New Modine Oil Coolers, P/N 635996, 646685, 649479 and 652759
M91-12	1991-12-11		New Oil Gauge Rod Housing
M91-10R1	1991-11-27		Inspection for Correct Oil Pick-Up Tube Installation
M90-10	1990-04-11		Standby Vacuum Pump Oil Leak Check/Inspection
M88-4	1988-01-15		TCM Pro-Tech Oil Filter
M87-17	1987-08-28		Improved Oil Pump Suction Tube Assembly
M86-20	1986-12-15		Air/Oil Separator Drain Modification
M81-28R1	1982-08-23		Oil Filters
M81-10	1981-03-09		Replace Dipstick P/N 632062-2 with P/N 632062-29
M78-3	1978-01-11		Governor Oil Transfer Collar Sleeves, Retaining Clips and Clearances
M78-2	1978-01-10		Turbocharger Oil Supply Line and Fitting Change: TCM Service Kit EQ6536
M76-20	1976-07-19		Oil Filters
M75-7R1	1975-04-04		Oil Filter Change
M67-5	1967-05-02		Lagging Engine Breather Line on GTSIO520 Engines

Table 23. Miscellaneous

Document No.	Release Date	N/R	Document Title/Description
CSB19-01	2019-02-07	N	Fuel (Primer) Diverter Valve Assembly
SIL18-02	2018-02-15		Applicability of Service Documents
SB16-6	2016-10-19		Engine Damage Due to Kickback
CSB09-11A	2014-11-12		Minimum Cruise RPM
SID10-4	2010-07-21		Engine Maintenance for Volcanic Ash Contamination
SSI06-7A ¹	2007-02-13		IOF-240-B4B Engine Conversion
SIL97-1	1997-01-03		Airworthiness Limitations
M90-4	1990-02-01		Conversion of Rolls Royce Engines
M75-6R1	1975-06-04		Conversion of Engines From one Model to Another

Table 24. Pistons

Document No.	Release Date	N/R	Document Title/Description
CSB97-10B	2016-07-27		Pistons Pin Plug Wear
CSB04-6B	2016-07-27		Inspection of TSIO-550 and TSIOL-550 Engines with P/N 654867 Pistons Installed
SB07-1	2007-03-19		Connecting Rod Pistons Pin Bushing Installation
SB04-10	2004-10-28		Pistons Position Marking
SB94-13	1994-11-14		Pistons Ring Set, Part Number 649226 and Cylinder Kit Part Numbers 653443A3, 653443A3BP, 653443A5, 653443A5BP, 653444A4, 653444A4BP, 653455A2 and 653455A2BP
M91-4	1991-02-11		Pistons Identification and Pistons Ring Application Bulletin
M87-26	1987-12-21		Pistons Pin Replacement and Thru Bolt torque Check
M87-25	1987-12-15		Pistons Pin Replacement and Thru Bolt torque Check

Table 25. Starters / Starter Adapters

Document No.	Release Date	N/R	Document Title/Description
MSB94-4H	2016-07-27		Starter Adapter Shaftgear and Crankshaft Gear Inspection
SIL16-1A	2016-05-29		Optional 24V Starters
SB14-2	2014-09-16		Inspection and Replacement of IO240 Starter and Crankshaft Cluster Gear
MSB11-4B	2012-04-04		Starter Adapter Inspection
CSB02-2C	2002-12-11		Starter Adapter Shaft Seal Inspection
SIL02-4	2002-04-02		Production Release of New Light Weight Starter Motors
SB01-5	2001-10-18		Starter Adapter Bevel Gear Inspection
SIL97-12	1997-10-14		Installation of Starter Adapter Shaft Seal and Associated Parts
CSB96-1	1996-03-01		Starter Gear and Clutch Assembly P/N 653575
M92-10	1992-08-14		Starter Adapter
M89-6	1989-03-10		Compressor Belt Sheave Alignment and Belt Tensioning
M88-5	1988-04-04		Starter Adapter Shafts (Reference Service Bulletin M87-24)
M87-24	1987-12-15		Broken Starter Adapter Shafts
M80-25	1980-10-24		Installation Instructions for Air Conditioning Kits
M80-14	1980-04-28		Freon Compressor Bracket
M79-15	1979-09-04		Freon Compressor Bracket Alignment
M79-12	1979-08-01		Starter Adapter Sheave
M71-20	1971-08-20		Installation Instructions for the Compressor Sheave to the Starter Adapter (637778)
M70-7	1970-03-17		Increasing Size of Oil Feed Holes to Starter Adapter Shaftgear

Table 26. Turbocharging / Exhaust Systems

Document No.	Release Date	N/R	Document Title/Description
CSB17-08	2017-12-13		Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 074
SB16-7	2017-02-03		Hartzell Engine Technologies (HET) Service Bulletin (SB) No. 067
SB16-8	2017-02-03		Turbo Exhaust Transition (P/N 657631)
CSB98-1C	2016-07-27		Intake and Exhaust Valve Inspection
SB10-1A	2016-07-27		Exhaust and Turbocharger System Inspection
SIL98-3B	2016-07-27		Production Release of New Intake and Exhaust Valve Springs
CSB07-2A	2016-06-16		Turbocharger Wastegate Oil Inlet Fitting Inspection and Replacement

Table 26. Turbocharging / Exhaust Systems

Document No.	Release Date	N/R	Document Title/Description
MSB14-3	2014-05-02		Hartzell Engine Technologies (HET) Alert Service Bulletin (ASB) No. 057
MSB13-7	2014-01-15		Hartzell Engine Technologies Alert Service Bulletin (ASB) 048 Rev 1
SB10-8A	2011-01-12		Hartzell Engine Technologies Service Bulletin 040A - Turbocharger CHRA Contamination
MSB10-3	2010-05-18		Kelly Aerospace Service Bulletin 039-A
MSB08-5	2008-06-23		Kelly Aerospace Turbocharger Bulletin 030
MSB07-4	2007-07-26		Kelly Aerospace Power Systems Turbocharger Replacement
SIL99-4	1999-05-19		TSIO520UB Exhaust Tail Pipe
SB98-4	1998-06-12		Exhaust System Inspection
M90-13	1990-07-16		Exhaust Valve Stem Corrosion/Erosion
M90-8	1990-03-22		Exhaust System Inspection
M90-6	1990-02-26		Inspection and Replacement of Scavenge Pump Gears P/N 635334 and 639388
M89-18	1989-08-10		Exhaust Gas Temperature (E.G.T.) Recommendations for Standard Engines (Leaning Lean)
M87-14R1	1987-10-08		Turbocharger Check Valve Clamps
M87-8	1987-02-26		Exhaust Valve Inspection
M85-6	1985-04-25		Garrett Service Letter TP61-0001, Rev. E
M85-3	1985-02-04		Exhaust Valves In P/N 646680 Cylinder Assemblies
M84-7	1984-04-18		643797 Turbo Inlet Check Valve
M81-4R1	1983-04-29		Aid Service Bulletin TP60-0120 - Aid Service Letter TP61-0046
M83-3	1983-02-14		Roto Master (Rajay) Service Letter 27 Revision A dated September 24, 1982 and Addendum Thereto dated February 9, 1983 In Response to FAA AD82-07-03
M82-7	1982-05-13		Tube Assembly (Air Reference Tube)
M81-23R1	1982-02-12		360 Series Oil Pump Drive Gear
M81-19	1981-08-05		Availability of New TCM P/N 646220 and 646019 Flexible Elbows
M81-16	1981-07-27		Turbocharger Center Housings
M81-17	1981-07-27		By-Pass Valve Modification -Airesearch Service Letter TP61-0039
M81-9	1981-03-09		Nose Seal Retainer Plates
M81-10	1981-03-09		Replace Dipstick P/N 632062-2 with P/N 632062-29
M80-24	1980-09-18		Exhaust Tailpipe Modification
M80-10	1980-03-28		Replacement of Some P/N 642232 Flexible Elbows
M78-5R3	1978-10-23		Flexible Elbow TCM Part Number 635930
M78-6	1978-03-03		Removal and Re-Installation of Special Rosan Exhaust Port Studs
M78-2	1978-01-10		Turbocharger Oil Supply Line and Fitting Change: TCM Service Kit EQ6536
M77-19	1977-08-12		Intake and Exhaust Rocker Arm Identification and Application
M76-22	1976-08-30		Compliance with Rajay Bulletin #21A
M72-8	1972-06-21		New Design Splined Drive Scavenge Pump Shaft and Gear Assembly
M71-21	1971-11-22		Procedure for Freeing Turbocharger Turbine Shafts Which Are Dragging or Frozen By Rust Deposits
M64-18	1968-10-07		Field Conversion to Turbocharging of Continental Aircraft Engines

VII. SERVICE DOCUMENTS, *listed by engine model*

Engine Model (released documents)	Page
A65 (40 Documents Released)	22
C75/C85 (44 Documents Released)	22
C90 (45 Documents Released)	23
O200 (58 Documents Released)	23
O240 (24 Documents Released)	24
IO240 (50 Documents Released)	24
IOF240 (24 Documents Released)	24
E185 (43 Documents Released)	25
E225 (42 Documents Released)	25
O300 (53 Documents Released)	26
GO300 (43 Documents Released)	26
IO346 (52 Documents Released)	27
IO360 (79 Documents Released)	27
L&TSIO360 (102 Documents Released)	28
O470 (93 Documents Released)	29
IO470 (89 Documents Released)	30
TSIO470 (69 Documents Released)	31
IO520 (121 Documents Released)	32
GTSIO520 (94 Documents Released)	33
L&TSIO520 (171 Documents Released)	34
IO550 (115 Documents Released)	35
IOF550 (56 Documents Released)	36
TSIO550 (103 Documents Released)	37
TSIOF550 (49 Documents Released)	38
TSIOL550 (78 Documents Released)	38
TIARA (31 Documents Released)	39

NOTE: The following Index tables list the active Service Documents by engine model. The tables reflect the updates (New, Revised, Retired, and Superseded documents) from Apr. 1 thru Jun. 30, 2019 for each engine model. All services documents in each table are sorted by most recently released date.

A65 (40 Documents Released)

Document No.	Release Date
SB18-03	2018-04-05
SIL18-02	2018-02-15
SIL00-7B	2017-06-19
SIL04-2A	2016-07-27
SID05-1B	2016-06-16
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB07-1	2007-03-19
SB05-9	2005-10-20

Document No.	Release Date
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
CSB01-1	2001-04-25
M81-8R1	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
M93-10	1993-03-01

Document No.	Release Date
M92-5	1992-02-28
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M81-13R1	1981-07-18
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07

C75/C85 (44 Documents Released)

Document No.	Release Date
SB18-03	2018-04-05
SIL18-02	2018-02-15
SIL00-7B	2017-06-19
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
SID05-1B	2016-06-16
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB07-1	2007-03-19
SB05-9	2005-10-20

Document No.	Release Date
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB03-5	2003-11-06
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
CSB93-13	1993-08-12
M93-10	1993-03-01

Document No.	Release Date
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M81-13R1	1981-07-18
M77-19	1977-08-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07

C90 (45 Documents Released)

Document No.	Release Date
SB18-03	2018-04-05
SIL18-02	2018-02-15
SIL00-7B	2017-06-19
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
SID05-1B	2016-06-16
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30

Document No.	Release Date
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
CSB93-13	1993-08-12
M93-10	1993-03-01
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11

Document No.	Release Date
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M86-9	1986-03-20
M83-5	1983-03-07
M81-13R1	1981-07-18
M77-19	1977-08-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07

O200 (58 Documents Released)

Document No.	Release Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SB15-4A	2015-12-18
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-1	2008-02-18

Document No.	Release Date
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB03-5	2003-11-06
CSB02-8	2002-09-06
M81-8R1	2001-02-05
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB96-1	1996-03-01
SID94-12	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
CSB93-13	1993-08-12
MSB93-12	1993-05-12
M93-10	1993-03-01

Document No.	Release Date
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M86-9	1986-03-20
M83-5	1983-03-07
M81-13R1	1981-07-18
M77-19	1977-08-12
M76-15	1976-06-17
M75-15	1975-07-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M70-11	1970-06-22
M64-18	1968-10-07

O240 (24 Documents Released)

Document No.	Released Date
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL04-2A	2016-07-27
SIL15-9	2015-12-11
SB15-5	2015-10-06
SIL05-3A	2014-04-10

Document No.	Released Date
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB05-9	2005-10-20

Document No.	Released Date
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL94-5	1994-06-14
M90-13	1990-07-16

IO240 (50 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SB15-4A	2015-12-18
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
CSB97-10B	2016-07-27
CSB98-1C	2016-07-27
SB08-4A	2016-07-27
SIL04-2A	2016-07-27
SB95-7A	2016-06-20
CSB14-1A	2016-06-16
SB99-8B	2016-06-16
CSB95-4A	2016-06-16
SID05-1B	2016-06-16
SIL15-9	2015-12-11

Document No.	Released Date
SB15-5	2015-10-06
SB14-2	2014-09-16
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB07-1	2007-03-19
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB97-15	1997-12-05

Document No.	Released Date
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB96-1	1996-03-01
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M70-11	1970-06-22
M64-18	1968-10-07

IOF240 (24 Documents Released)

Document No.	Released Date
SIL18-02	2018-02-15
SIL04-2A	2016-07-27
SB99-8B	2016-06-16
CSB14-1A	2016-06-16
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SSI06-6A	2014-12-17
SB14-2	2014-09-16

Document No.	Released Date
SIL05-3A	2014-04-10
SB13-8	2014-01-22
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SSI07-6	2007-08-31
SB07-1	2007-03-19

Document No.	Released Date
SSI06-7A	2007-02-13
SB04-10	2004-10-28
SB00-4A	2000-03-07
SIL97-1	1997-01-03
SIL94-5	1994-06-14
M92-7	1992-05-26
M75-6R1	1975-06-04
M64-18	1968-10-07

E185 (43 Documents Released)

Document No.	Released Date
SB15-6B	2018-08-09
SB18-03	2018-04-05
SIL18-02	2018-02-15
SIL00-7B	2017-06-19
CSB97-10B	2016-07-27
SIL98-3B	2016-07-27
SIL04-2A	2016-07-27
CSB98-1C	2016-07-27
SB96-3C	2016-06-16
SID05-1B	2016-06-16
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16

Document No.	Released Date
SB06-5	2006-05-25
SIL06-2	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB02-9	2002-10-25
CSB02-8	2002-09-06
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SB94-13	1994-11-14
SIL94-10	1994-11-14
SIL94-5	1994-06-14

Document No.	Released Date
CSB94-1	1994-02-01
SIL93-14	1993-08-17
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-23	1987-11-24
M87-16	1987-08-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-12	1973-06-08
M64-18	1968-10-07

E225 (42 Documents Released)

Document No.	Released Date
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SIL00-7B	2017-06-19
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
CSB97-10B	2016-07-27
SIL98-3B	2016-07-27
SID05-1B	2016-06-16
SB96-3C	2016-06-16
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB06-5	2006-05-25
SIL06-2	2006-05-01
SB05-9	2005-10-20

Document No.	Released Date
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB02-9	2002-10-25
CSB02-8	2002-09-06
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-10	1994-11-14
SB94-13	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
M93-10	1993-03-01
M93-8	1993-02-19

Document No.	Released Date
M93-4	1993-02-12
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-23	1987-11-24
M87-16	1987-08-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-12	1973-06-08
M64-18	1968-10-07

O300 (53 Documents Released)

Document No.	Released Date
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL04-2A	2016-07-27
CSB98-1C	2016-07-27
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
MSB00-6D	2010-11-19
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-1	2008-02-18
SB07-1	2007-03-19
SB06-5	2006-05-25

Document No.	Released Date
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB96-5	1996-04-12
SB96-4	1996-04-12
CSB96-1	1996-03-01
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M92-10	1992-08-14
M92-8	1992-05-29

Document No.	Released Date
M92-5	1992-02-28
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-23	1987-11-24
M87-16	1987-08-14
M77-19	1977-08-12
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M64-18	1968-10-07

GO300 (43 Documents Released)

Document No.	Released Date
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL04-2A	2016-07-27
CSB98-1C	2016-07-27
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-1	2008-02-18

Document No.	Released Date
SB07-1	2007-03-19
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-5	1994-06-14
CSB94-1	1994-02-01
SIL93-14	1993-08-17
M93-10	1993-03-01
M92-8	1992-05-29
M92-5	1992-02-28
M91-4	1991-02-11

Document No.	Released Date
M90-13	1990-07-16
M89-18	1989-08-10
M87-23	1987-11-24
M87-16	1987-08-14
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-13	1973-07-10
M73-12	1973-06-08
M64-18	1968-10-07

IO346 (52 Documents Released)

Document No.	Released Date
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL04-2A	2016-07-27
CSB98-1C	2016-07-27
SB08-4A	2016-07-27bor
CSB97-10B	2016-07-27
SB95-7A	2016-06-20
SB96-3C	2016-06-16
SB99-8B	2016-06-16
SB00-2B	2016-06-16
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21

Document No.	Released Date
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
MSB95-6	1995-10-19
MSB94-9	1994-10-21
SIL94-5	1994-06-14

Document No.	Released Date
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
M93-10	1993-03-01
M93-8	1993-02-19
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M77-9	1977-03-17
M76-20	1976-07-19
M75-6R1	1975-06-04
M74-18	1974-09-16
M64-18	1968-10-07

IO360 (79 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SIL16-1A	2018-05-29
SIL18-02	2018-02-15
SB17-06	2017-10-20
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB13-4C	2016-11-07
CSB97-10B	2016-07-27
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
SB95-7A	2016-06-20
CSB14-1A	2016-06-16
CSB95-4A	2016-06-16
SID05-1B	2016-06-16
SB99-8B	2016-06-16
SIL15-9	2015-12-11
SIL15-8	2015-11-30
SB15-5	2015-10-06
MSB96-10B	2015-08-10
SIL05-3A	2014-04-10
SSI13-5	2013-10-18
CSB08-3C	2013-07-17
MSB00-6D	2010-11-19
SID10-4	2010-07-21

Document No.	Released Date
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB07-1	2007-03-19
SB06-5	2006-05-25
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
SB02-7	2002-06-28
SB01-5	2001-10-18
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-12	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB98-8	1998-10-22
SB97-15	1997-12-05
SIL97-1	1997-01-03
CSB96-13	1996-11-14
CSB96-8	1996-06-25
SID96-6	1996-05-03
SB96-4	1996-04-12
CSB96-5	1996-04-12
SIL94-5	1994-06-14
SB94-2	1994-02-10

Document No.	Released Date
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-7	1992-05-26
M92-4R1	1992-02-05
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M87-8	1987-02-26
M83-5	1983-03-07
M81-23R1	1982-02-12
M81-13R1	1981-07-18
M77-9	1977-03-17
M75-6R1	1975-06-04
M75-7R1	1975-04-04
M74-18	1974-09-16
M64-18	1968-10-07

L&TSIO360 (102 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
CSB19-01	2019-02-07
SIL16-1A	2018-05-29
CSB17-08	2017-12-13
SB17-06	2017-10-20
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB13-4C	2016-11-07
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
CSB97-10B	2016-07-27
SB95-7A	2016-06-20
CSB14-1A	2016-06-16
SB99-8B	2016-06-16
CSB95-4A	2016-06-16
SID05-1B	2016-06-16
CSB07-2A	2016-06-16
SIL15-9	2015-12-11
SIL15-8	2015-11-30
SB15-5	2015-10-06
MSB96-10B	2015-08-10
SIL05-3A	2014-04-10
MSB13-7	2014-01-15
CSB08-3C	2013-07-17
SB10-8A	2011-01-12
MSB00-6D	2010-11-19
SID10-4	2010-07-21
MSB10-3	2010-05-18
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB08-2B	2008-09-17
SB07-1	2007-03-19

Document No.	Released Date
SB06-5	2006-05-25
SB05-11	2005-12-08
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
SB02-7	2002-06-28
MSB00-5D	2001-10-17
SIL01-4	2001-09-04
SIL01-2B	2001-09-04
CSB01-1	2001-04-25
SB00-12	2000-12-19
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB98-8	1998-10-22
SB98-4	1998-06-12
SB97-15	1997-12-05
SIL97-1	1997-01-03
CSB96-13	1996-11-14
CSB96-8	1996-06-25
SID96-6	1996-05-03
CSB96-5	1996-04-12
SB96-4	1996-04-12
CSB95-1A	1995-04-05
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-7	1992-05-26
M92-4R1	1992-02-05

Document No.	Released Date
M91-4	1991-02-11
M90-13	1990-07-16
M90-4	1990-02-01
M89-18	1989-08-10
M88-13	1988-09-26
M88-4	1988-01-15
M87-23	1987-11-24
M87-14R1	1987-10-08
M87-16	1987-08-14
M87-8	1987-02-26
M83-5	1983-03-07
M83-6	1983-03-07
M83-3	1983-02-14
M82-7	1982-05-13
M81-23R1	1982-02-12
M81-26	1981-12-04
M81-16	1981-07-27
M81-13R1	1981-07-18
M80-24	1980-09-18
M79-15	1979-09-04
M78-8	1978-08-25
M78-2	1978-01-10
M77-9	1977-03-17
M76-22	1976-08-30
M75-6R1	1975-06-04
M75-7R1	1975-04-04
M74-18	1974-09-16
M71-21	1971-11-22
M64-18	1968-10-07

O470 (93 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SB18-04A	2018-12-18
SB18-07	2018-11-19
SIL18-05	2018-08-22
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL14-6A	2017-02-03
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
CSB97-10B	2016-07-27
CSB98-1C	2016-07-27
SIL98-3B	2016-07-27
SB96-3C	2016-06-16
SID05-1B	2016-06-16
SIL15-9	2015-12-11
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB09-6A	2009-06-22
SB09-3A	2009-04-24
SB09-2	2009-03-17
SB08-12	2008-09-09

Document No.	Released Date
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-2	2006-05-01
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB02-9	2002-10-25
CSB02-8	2002-09-06
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SB97-15	1997-12-05
SB97-11	1997-08-10
SID97-7	1997-05-07
SB97-5	1997-03-31
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SB94-11	1994-11-14
SB94-13	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29

Document No.	Released Date
M92-7	1992-05-26
M92-5	1992-02-28
M92-6	1992-02-28
M91-10R1	1991-11-27
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-15	1988-10-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M85-3	1985-02-04
M83-6	1983-03-07
M83-5	1983-03-07
M81-12	1981-05-11
M81-10	1981-03-09
M81-9	1981-03-09
M78-9	1978-08-23
M78-3	1978-01-11
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-6R1	1973-06-11
M73-12	1973-06-08
M70-7	1970-03-17
M64-18	1968-10-07

IO470 (89 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL14-6A	2017-02-03
CSB98-1C	2016-07-27
SIL04-2A	2016-07-27
CSB97-10B	2016-07-27
SIL98-3B	2016-07-27
SB95-7A	2016-06-20
SB99-8B	2016-06-16
SB96-3C	2016-06-16
SID05-1B	2016-06-16
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16

Document No.	Released Date
SB08-12	2008-09-09
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-5	1999-05-25
SB97-15	1997-12-05
SB97-11	1997-08-10
SB97-5	1997-03-31
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB94-15	1994-12-02
SB94-13	1994-11-14
SB94-11	1994-11-14
SIL94-10	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01

Document No.	Released Date
M93-8	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-10R1	1991-11-27
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M85-3	1985-02-04
M83-5	1983-03-07
M83-6	1983-03-07
M81-6R2	1982-01-29
M81-13R1	1981-07-18
M78-9	1978-08-23
M78-3	1978-01-11
M75-14	1975-06-30
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-6R1	1973-06-11
M73-2	1973-01-17
M70-7	1970-03-17
M64-18	1968-10-07

TSIO470 (69 Documents Released)

Document No.	Released Date
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL14-6A	2017-02-03
CSB98-1C	2016-07-27
SIL98-3B	2016-07-27
SIL04-2A	2016-07-27
CSB97-10B	2016-07-27
SB08-4A	2016-07-27
SB95-7A	2016-06-20
SB96-3C	2016-06-16
SID05-1B	2016-06-16
SB99-8B	2016-06-16
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB09-1B	2009-08-18

Document No.	Released Date
SB09-7	2009-07-16
SB08-12	2008-09-09
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SB97-15	1997-12-05
SB97-11	1997-08-10
SIL97-1	1997-01-03
SIL96-9	1996-08-12
SID96-6	1996-05-03
SB94-13	1994-11-14
SIL94-10	1994-11-14
SIL94-5	1994-06-14
CSB94-1	1994-02-01

Document No.	Released Date
SIL93-14	1993-08-17
M93-10	1993-03-01
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M81-6R2	1982-01-29
M81-16	1981-07-27
M78-9	1978-08-23
M78-3	1978-01-11
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-2	1973-01-17
M71-21	1971-11-22
M64-18	1968-10-07

IO520 (121 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SB17-01A	2017-10-20
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL14-6A	2017-02-03
SB16-9	2017-02-03
SB16-6	2016-10-19
SIL04-2A	2016-07-27
SIL98-3B	2016-07-27
SB08-4A	2016-07-27
CSB97-10B	2016-07-27
CSB98-1C	2016-07-27
SB95-7A	2016-06-20
SID05-1B	2016-06-16
SB09-4B	2016-06-16
SB96-3C	2016-06-16
SB14-5A	2016-06-16
SB99-8B	2016-06-16
SB16-5	2016-06-08
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
CSB12-1	2012-05-11
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB08-12	2008-09-09
SB07-1	2007-03-19

Document No.	Released Date
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
SID97-8	1997-05-28
SIL97-1	1997-01-03
CSB96-8	1996-06-25
SID96-6	1996-05-03
MSB95-6	1995-10-19
CSB94-15	1994-12-02
SB94-11	1994-11-14
SIL94-10	1994-11-14
MSB94-9	1994-10-21
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-5	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28

Document No.	Released Date
M91-10R1	1991-11-27
M91-7	1991-03-20
M91-6	1991-03-20
M91-4	1991-02-11
M90-16	1990-08-22
M90-13	1990-07-16
M89-19	1989-09-18
M89-18	1989-08-10
M89-6	1989-03-10
M88-5	1988-04-04
M88-4	1988-01-15
M87-24	1987-12-15
M87-23	1987-11-24
M87-16	1987-08-14
M86-13R1	1986-10-17
M86-14	1986-10-01
M85-10	1985-07-18
M81-15R1	1983-06-16
M83-6	1983-03-07
M83-5	1983-03-07
M81-13R1	1981-07-18
M81-12	1981-05-11
M81-9	1981-03-09
M80-25	1980-10-24
M80-14	1980-04-28
M80-11	1980-04-14
M78-9	1978-08-23
M78-3	1978-01-11
M77-9	1977-03-17
M76-20	1976-07-19
M76-7	1976-03-25
M75-30	1975-12-19
M75-14	1975-06-30
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-6R1	1973-06-11
M70-7	1970-03-17
M64-18	1968-10-07

GTSIO520 (94 Documents Released)

Document No.	Released Date
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SIL18-01	2018-01-19
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB16-9	2017-02-03
SB13-4C	2016-11-07
CSB98-1C	2016-07-27
CSB97-10B	2016-07-27
MSB94-4H	2016-07-27
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
SB95-7A	2016-06-20
CSB13-1B	2016-06-17
SB96-3C	2016-06-16
SID05-1B	2016-06-16
SB99-8B	2016-06-16
CSB99-6B	2016-06-16
MSB96-10B	2015-08-10
MSB14-3	2014-05-02
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
SB10-8A	2011-01-12
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-7	2009-07-16
MSB08-5	2008-06-23

Document No.	Released Date
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB01-3A	2002-12-10
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SB97-11	1997-08-10
SID97-8	1997-05-28
CSB97-9	1997-05-28
SIL97-1	1997-01-03
SID96-6	1996-05-03
CSB96-2	1996-03-21
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14

Document No.	Released Date
M92-9	1992-05-29
M92-7	1992-05-26
M91-6	1991-03-20
M91-7	1991-03-20
M91-4	1991-02-11
M90-20	1990-12-20
M90-16	1990-08-22
M90-15	1990-08-21
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-6	1987-02-16
M85-10	1985-07-18
M81-15R1	1983-06-16
M81-4R1	1983-04-29
M82-3	1982-03-08
M81-6R2	1982-01-29
M81-16	1981-07-27
M78-6	1978-03-03
M77-9	1977-03-17
M76-12	1976-05-24
M76-7	1976-03-25
M75-30	1975-12-19
M75-6R1	1975-06-04
M74-18	1974-09-16
M71-21	1971-11-22
M71-20	1971-08-20
M70-3	1970-02-03
M64-18	1968-10-07
M67-5	1967-05-02

L&TSIO520 (171 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
CSB19-01	2019-02-07
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SIL18-01	2018-01-19
SIL17-07	2017-11-14
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB16-9	2017-02-03
SB16-7	2017-02-03
SIL14-6A	2017-02-03
SB13-4C	2016-11-07
SB16-6	2016-10-19
SB15-3A	2016-08-09
CSB97-10B	2016-07-27
SB08-4A	2016-07-27
SIL98-3B	2016-07-27
CSB98-1C	2016-07-27
SB10-1A	2016-07-27
SIL04-2A	2016-07-27
SB95-7A	2016-06-20
CSB13-1B	2016-06-17
SB96-3C	2016-06-16
SID05-1B	2016-06-16
SB09-4B	2016-06-16
SB14-5A	2016-06-16
SB99-8B	2016-06-16
SB16-5	2016-06-08
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
MSB14-3	2014-05-02
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB10-8A	2011-01-12
SID10-4	2010-07-21
MSB10-3	2010-05-18
MSB94-8D	2010-02-17
SB09-14	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06

Document No.	Released Date
SB09-7	2009-07-16
SB08-12	2008-09-09
MSB08-5	2008-06-23
SSI07-5	2007-08-22
MSB07-4	2007-07-26
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-4	1999-05-19
SB97-15	1997-12-05
SB97-13	1997-10-30
SIL97-12	1997-10-14
SB97-11	1997-08-10
SID97-8	1997-05-28
SIL97-1	1997-01-03
SIL96-9	1996-08-12
CSB96-8	1996-06-25
SID96-6	1996-05-03
MSB95-6	1995-10-19
SB94-3A	1995-05-23
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SB94-11	1994-11-14
SB94-7	1994-09-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26

Document No.	Released Date
M92-6	1992-02-28
M91-12	1991-12-11
M91-10R1	1991-11-27
M91-6	1991-03-20
M91-7	1991-03-20
M91-4	1991-02-11
M90-19	1990-10-16
M90-16	1990-08-22
M90-15	1990-08-21
M90-13	1990-07-16
M90-10	1990-04-11
M90-8	1990-03-22
M90-6	1990-02-26
M89-23	1989-09-25
M89-18	1989-08-10
M89-14	1989-06-29
M89-6	1989-03-10
M88-12	1988-09-09
M88-5	1988-04-04
M88-4	1988-01-15
M87-26	1987-12-21
M87-24	1987-12-15
M87-25	1987-12-15
M87-23	1987-11-24
M87-21	1987-10-07
M87-17	1987-08-28
M87-16	1987-08-14
M86-20	1986-12-15
M86-13R1	1986-10-17
M86-14	1986-10-01
M86-5	1986-02-04
M85-10	1985-07-18
M85-6	1985-04-25
M84-13	1984-10-27
M84-7	1984-04-18
M84-3	1984-01-18
M83-8R1	1983-07-15
M81-15R1	1983-06-16
M81-4R1	1983-04-29
M83-6	1983-03-07
M83-5	1983-03-07
M82-13	1982-10-27
M81-28R1	1982-08-23
M82-5	1982-04-26
M81-6R2	1982-01-29
M81-19	1981-08-05
<i>...continue on next page.</i>	

L&TSIO520 (171 Documents Released), continued

Document No.	Released Date
M81-18	1981-08-05
M81-16	1981-07-27
M81-13R1	1981-07-18
M81-12	1981-05-11
M81-9	1981-03-09
M80-25	1980-10-24
M80-14	1980-04-28
M80-10	1980-03-28
M79-12	1979-08-01

Document No.	Released Date
M78-16	1978-11-29
M78-5R3	1978-10-23
M78-9	1978-08-23
M78-6	1978-03-03
M78-3	1978-01-11
M77-9	1977-03-17
M76-20	1976-07-19
M76-7	1976-03-25
M75-30	1975-12-19

Document No.	Released Date
M75-6R1	1975-06-04
M74-18	1974-09-16
M73-6R1	1973-06-11
M72-8	1972-06-21
M71-21	1971-11-22
M70-7	1970-03-17
M64-18	1968-10-07

IO550 (115 Documents Released)

Document No.	Released Date
CSB19-03	2019-05-21
SB19-02A	2019-04-22
SIL18-06A	2019-04-10
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL16-1A	2018-05-29
SIL18-02	2018-02-15
SIL18-01	2018-01-19
SSI17-09	2017-12-22
SIL17-07	2017-11-14
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SIL14-6A	2017-02-03
SB16-9	2017-02-03
SB13-4C	2016-11-07
SB16-6	2016-10-19
CSB97-10B	2016-07-27
SIL04-2A	2016-07-27
CSB98-1C	2016-07-27
SB95-7A	2016-06-20
SID05-1B	2016-06-16
SB09-4B	2016-06-16
SB99-8B	2016-06-16
SB96-3C	2016-06-16
SIL10-6A	2016-06-16
SIL14-4B	2016-06-16
SB14-5A	2016-06-16
SB16-5	2016-06-08
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
SB13-8	2014-01-22
CSB08-3C	2013-07-17

Document No.	Released Date
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-1A	2011-03-17
SB11-2	2011-01-13
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-12	2009-10-16
MSB09-1B	2009-08-18
SIL09-15	2009-08-06
SB09-7	2009-07-16
SB08-12	2008-09-09
CSB08-11	2008-07-16
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB03-4	2003-07-21
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
CSB02-8	2002-09-06
SIL02-5	2002-04-04
SB02-3	2002-01-31
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
SID97-8	1997-05-28
SIL97-1	1997-01-03
SID96-6	1996-05-03
MSB95-6	1995-10-19

Document No.	Released Date
CSB94-15	1994-12-02
SB94-11	1994-11-14
SIL94-10	1994-11-14
MSB94-9	1994-10-21
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-14	1992-09-09
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-10R1	1991-11-27
M91-6	1991-03-20
M91-7	1991-03-20
M91-4	1991-02-11
M90-16	1990-08-22
M90-13	1990-07-16
M89-19	1989-09-18
M89-18	1989-08-10
M89-6	1989-03-10
M88-5	1988-04-04
M88-4	1988-01-15
M87-24	1987-12-15
M87-23	1987-11-24
M87-16	1987-08-14
M86-13R1	1986-10-17
M85-10	1985-07-18
M75-6R1	1975-06-04
M74-18	1974-09-16
M64-18	1968-10-07

IOF550 (56 Documents Released)

Document No.	Released Date
CSB19-03	2019-05-21
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL16-1A	2018-05-29
SIL18-02	2018-02-15
SIL18-01	2018-01-19
SIL00-7B	2017-06-19
SB08-4A	2016-07-27
SIL04-2A	2016-07-27
SIL14-4B	2016-06-16
SID05-1B	2016-06-16
SB99-8B	2016-06-16
SB14-5A	2016-06-16
SB16-5	2016-06-08
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SB13-6A	2014-04-10

Document No.	Released Date
SIL05-3A	2014-04-10
SB13-8	2014-01-22
CSB08-3C	2013-07-17
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-1A	2011-03-17
SB11-2	2011-01-13
SID10-4	2010-07-21
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-12	2009-10-16
MSB09-1B	2009-08-18
SB09-7	2009-07-16
SB08-12	2008-09-09
CSB08-11	2008-07-16
SB07-1	2007-03-19
SB06-5	2006-05-25
SIL06-3	2006-05-01
SB04-10	2004-10-28
SB03-4	2003-07-21

Document No.	Released Date
SIL02-5	2002-04-04
MSB00-5D	2001-10-17
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL97-1	1997-01-03
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
M93-8	1993-02-19
M93-4	1993-02-12
M92-9	1992-05-29
M92-7	1992-05-26
M89-6	1989-03-10
M87-23	1987-11-24
M85-10	1985-07-18
M75-6R1	1975-06-04
M64-18	1968-10-07

TSIO550 (103 Documents Released)

Document No.	Released Date
SB19-02A	2019-04-22
CSB19-01	2019-02-07
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
CSB05-8D	2018-08-22
SB15-6B	2018-08-09
SIL16-1A	2018-05-29
SIL18-02	2018-02-15
SIL18-01	2018-01-19
CSB17-08	2017-12-13
SIL17-07	2017-11-14
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB16-9	2017-02-03
SB16-8	2017-02-03
SB13-4C	2016-11-07
SB16-6	2016-10-19
SB15-3A	2016-08-09
SB10-1A	2016-07-27
CSB97-10B	2016-07-27
SB08-4A	2016-07-27
CSB04-6B	2016-07-27
SIL98-3B	2016-07-27
CSB98-1C	2016-07-27
SIL98-3B	2016-07-27
SB95-7A	2016-06-20
SB99-8B	2016-06-16
SB14-5A	2016-06-16
SB96-3C	2016-06-16
SIL14-4B	2016-06-16
SIL10-6A	2016-06-16
SB09-4B	2016-06-16
SID05-1B	2016-06-16

Document No.	Released Date
SB16-4	2016-06-08
CSB15-7B	2016-04-26
CSB15-2C	2015-11-09
SB15-5	2015-10-06
MSB96-10B	2015-08-10
SIL14-9	2015-01-09
CSB09-11A	2014-11-12
SB13-6A	2014-04-10
SB13-8	2014-01-22
CSB08-3C	2013-07-17
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-1A	2011-03-17
SB11-2	2011-01-13
SB10-8A	2011-01-12
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-12	2009-10-16
SB09-14	2009-10-16
MSB07-4	2007-07-26
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-2C	2002-12-11
SB01-3A	2002-12-10
CSB02-8	2002-09-06
SB02-3	2002-01-31
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27

Document No.	Released Date
SB97-15	1997-12-05
SIL97-12	1997-10-14
SB97-11	1997-08-10
SID97-8	1997-05-28
SIL97-1	1997-01-03
SIL96-9	1996-08-12
SID96-6	1996-05-03
MSB95-6	1995-10-19
SB94-3A	1995-05-23
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-8	1993-02-19
M93-5	1993-02-19
M93-4	1993-02-12
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M85-10	1985-07-18
M75-6R1	1975-06-04
M74-18	1974-09-16
M71-21	1971-11-22
M64-18	1968-10-07

TSIOF550 (49 Documents Released)

Document No.	Released Date
SB18-08A	2019-01-11
SB18-04A	2018-12-18
SB18-07	2018-11-19
SB15-6B	2018-08-09
SIL16-1A	2018-05-29
CSB17-08	2017-12-13
SIL17-07	2017-11-14
SB17-01A	2017-10-20
SIL17-03	2017-07-27
SB15-3A	2016-08-09
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
SB14-5A	2016-06-16
SB99-8B	2016-06-16
SID05-1B	2016-06-16
SIL14-4B	2016-06-16
SB16-4	2016-06-08

Document No.	Released Date
CSB15-2C	2015-11-09
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SIL05-3A	2014-04-10
SB13-6A	2014-04-10
SB13-8	2014-01-22
CSB08-3C	2013-07-17
CSB12-1	2012-05-11
MSB11-4B	2012-04-04
SB11-1A	2011-03-17
SB11-2	2011-01-13
SB10-8A	2011-01-12
SID10-4	2010-07-21
MSB09-8A	2009-12-04
SB09-14	2009-10-16
SB09-12	2009-10-16
SB07-1	2007-03-19

Document No.	Released Date
SIL06-3	2006-05-01
SB04-10	2004-10-28
SB00-4A	2000-03-07
SB00-1	2000-01-14
SIL97-1	1997-01-03
SIL94-10	1994-11-14
SIL94-5	1994-06-14
SB94-2	1994-02-10
M93-8	1993-02-19
M93-4	1993-02-12
M92-9	1992-05-29
M92-7	1992-05-26
M87-23	1987-11-24
M85-10	1985-07-18
M75-6R1	1975-06-04
M71-21	1971-11-22

TSIOL550 (78 Documents Released)

Document No.	Released Date
SB18-04A	2018-12-18
SB18-07	2018-11-19
SB15-6B	2018-08-09
SIL18-02	2018-02-15
SIL18-01	2018-01-19
SB17-04	2017-09-29
SB17-05	2017-09-29
SIL00-7B	2017-06-19
SB16-9	2017-02-03
SB16-6	2016-10-19
SIL04-2A	2016-07-27
SB08-4A	2016-07-27
SIL98-3B	2016-07-27
CSB98-1C	2016-07-27
CSB97-10B	2016-07-27
CSB04-6B	2016-07-27
SB95-7A	2016-06-20
CSB13-1B	2016-06-17
SB96-3C	2016-06-16
SB14-5A	2016-06-16
SB99-8B	2016-06-16
SID05-1B	2016-06-16
SB15-5	2015-10-06
MSB96-10B	2015-08-10
CSB09-11A	2014-11-12
SB13-6A	2014-04-10
SIL05-3A	2014-04-10
CSB08-3C	2013-07-17

Document No.	Released Date
SID10-4	2010-07-21
MSB94-8D	2010-02-17
MSB09-8A	2009-12-04
SB09-14	2009-10-16
MSB08-5	2008-06-23
SB07-1	2007-03-19
SIL06-3	2006-05-01
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
SB01-3A	2002-12-10
CSB02-8	2002-09-06
MSB00-5D	2001-10-17
CSB01-1	2001-04-25
SB00-10	2000-12-19
SB00-4A	2000-03-07
SB00-1	2000-01-14
MSB99-3C	1999-07-27
SIL99-4	1999-05-19
SB97-15	1997-12-05
SB97-11	1997-08-10
SIL97-1	1997-01-03
SIL96-9	1996-08-12
SID96-6	1996-05-03
MSB95-6	1995-10-19
CSB94-15	1994-12-02
SIL94-10	1994-11-14
SIL94-5	1994-06-14

Document No.	Released Date
SB94-2	1994-02-10
CSB94-1	1994-02-01
SIL93-14	1993-08-17
MSB93-12	1993-05-12
M93-10	1993-03-01
M93-5	1993-02-19
M93-8	1993-02-19
M93-4	1993-02-12
M92-12	1992-08-27
M92-10	1992-08-14
M92-9	1992-05-29
M92-7	1992-05-26
M92-6	1992-02-28
M91-4	1991-02-11
M90-13	1990-07-16
M89-18	1989-08-10
M88-4	1988-01-15
M87-23	1987-11-24
M87-16	1987-08-14
M85-10	1985-07-18
M75-6R1	1975-06-04
M74-18	1974-09-16
M71-21	1971-11-22
M64-18	1968-10-07

TIARA (31 Documents Released)

Document No.	Released Date
SIL00-7B	2017-06-19
SB08-4A	2016-07-27
SIL04-2A	2016-07-27
SID10-4	2010-07-21
MSB94-8D	2010-02-17
SB09-14	2009-10-16
SB07-1	2007-03-19
SB05-9	2005-10-20
SB04-10	2004-10-28
CSB04-5A	2004-08-30
CSB02-8	2002-09-06

Document No.	Released Date
CSB01-1	2001-04-25
SB00-4A	2000-03-07
SB00-1	2000-01-14
SB97-15	1997-12-05
SIL97-1	1997-01-03
SID96-6	1996-05-03
SIL94-5	1994-06-14
SIL93-14	1993-08-17
M93-10	1993-03-01
M92-7	1992-05-26
M91-4	1991-02-11

Document No.	Released Date
M90-13	1990-07-16
M89-18	1989-08-10
M87-16	1987-08-14
M79-4	1979-02-14
M78-6	1978-03-03
M76-20	1976-07-19
M75-6R1	1975-06-04
M74-18	1974-09-16
M64-18	1968-10-07

Intentionally Left Blank