
TC00398, TC00399, TC00400

OEM No: 27105A371D7; 27105A371D8; 27105A371D9



49 52

| Pos | Part number | OEM no | Quantity | Product name | Info |
|------|-------------|-------------|----------|---------------|--------------|
| 'I01 | TC00398 | 27105A371D7 | | OE References | 27107605344, |
| | | | | | 27107609196, |
| | | | | | 27107610586, |
| | | | | | 27107619178, |
| | | | | | 27107627944, |
| | | | | | 27107629405, |
| | | | | | 27107629605, |
| | | | | | 27107635753, |
| | | | | | 27107636480, |
| | | | | | 27107639271, |
| | | | | | 27107643751, |
| | | | | | 27108697972, |
| | | | | | 27105A371D7 |

TC00398, TC00399, TC00400

OEM No: 27105A371D7; 27105A371D8; 27105A371D9

| List of parts | | | | | |
|---------------|-------------|---|----------|--------------------|--|
| Pos | Part number | OEM no | Quantity | Product name | Info |
| '102 | TC00399 | 27105A371D9 | | OE References | 27107609193, 27107610588, 27107619180, 27107619776, 271076392642, 27107639264, 27107643753, 27108697974, 27105A371D9 |
| '103 | TC00400 | 27105A371D8 | | OE References | 27107605345, 27107609197, 27107610587, 27107619179, 27107627945, 27107629406, 27107635754, 27107635754, 27107636481, 27107639272, 27107643752, 27108697973, 27105A371D8 |
| 'K01 | SP01497 | | 1 piece | Bearing Kit | Contains position 05, 12, 24, 33, 41, 53, 55 |
| 'K02 | SP01498 | | 1 piece | Sealing Kit | Contains position 01, 03, 34, 37, 52, 58, 59, 63 |
| 'K05 | SP01501 | 27107595650; 27107645468 | 1 piece | Flange Kit Rear | Contains position 36, 37, 38, K20 Information for ATC35L: Used in 27105A371F3, 27105A371F1 Information for ATC45L: Used in 27105A371E0, 27105A4A0B9, 27105A371E1, 27105A4A0C0, 27105A371E2, 27105A4A0C1, 27105A371E3, 27105A4A0C2 |
| 'K10 | SP01299 | | 1 piece | Sliding Block Kit | Contains position 70, 71 Information for DCS: Used in A2512801300, A2512801400, A2512802700, A2512803100, A2512803200 Information for PL72 T Porsche: Used in 95834102011, 95834102012 Information for PL72 T VW: Used in 0BU341010M, 0BU341011C, 0BU341011K, 0BU341011M |
| 'K11 | SP01097 | | 1 piece | Clutch Kit | Contains position 18, 19, 20, 21 |
| 'K12 | | | 1 piece | Shaft Actuator Kit | Contains position 53, 54, 55, 56, 57 |
| 'K20 | SP00115 | 27107546670 | 1 piece | Shim Set | Contains 13 different Shims with Dimensions from 2.90mm up to 4.10mm |
| 'K25 | OIL0005 | 00004330136; 00004330563; 83220397244; 83222409710; N052515B0; N052515B1 | 1 piece | Transmission Fluid | Shipment in 1 liter bottles. Fillgrade information please see Oil List. |
| 'K32 | SP04545 | | 1 piece | Plastic Parts Kit | Contains position 08, 32,40 |
| 01 | SP00445 | 02C2D27326; 27107609202 | 1 piece | O-Ring | |
| 02 | SP00312 | | 1 piece | Retaining Ring | |

TC00398, TC00399, TC00400

OEM No: 27105A371D7; 27105A371D8; 27105A371D9

| Pos | | List of parts | | | | | |
|----------|-----------------------|---|-----------|--------------------------------|---|--|--|
| | Part number | OEM no | Quantity | Product name | Info | | |
|)3 | SP00165 | 02C2D27145; 27107539262; 473524E000; 673002353 | 1 piece | Radial Sealing | | | |
| 04 | SP00140 | | 1 piece | Retaining Ring | | | |
|)5 | Only available in K01 | | 1 piece | Ball Bearing | | | |
| 06 | Not available | | 1 piece | Housing Front | | | |
|)7 | SP00154 | | 1 piece | Pin | | | |
|)8 | Only available in K32 | | 1 piece | Deflector ASM | | | |
|)9 | SP01933 | | 1 piece | Shim | | | |
| 10 | SP01923 | | 1 piece | Input Shaft | | | |
| 11 | SP01717 | | 1 piece | Chain | | | |
| 2 | Only available in K01 | | 1 piece | Needle Bearing | | | |
| 13 | SP01975 | | 1 piece | - | | | |
| 4 | SP01932 | | 1 piece | Thrust Washer | | | |
| 15 | Not available | | 1 piece | Shim | | | |
| 16 | SP01034 | | 1 piece | Adjusting Ring | | | |
| 17 | SP01096 | | 1 piece | | 1 ST | | |
| 18 | Only available in K11 | | 5 pieces | | | | |
| 19 | Only available in K11 | | | Friction Plate | | | |
| 20 | Only available in K11 | | 6 pieces | | | | |
| 21 | Only available in K11 | | 1 piece | | | | |
| 22 | SP01082 | | 1 piece | | | | |
| 23 | SP01083 | - | 2 pieces | | | | |
| 24 | Only available in K01 | | 2 pieces | | | | |
| 25 | SP01946 | | 1 piece | | | | |
| 26 | SP01085 | | 3 pieces | | | | |
| 27 | SP01945 | | 1 piece | | | | |
| 28 | SP01084 | | 1 piece | | | | |
| 29 | Not available | | 1 piece | • | | | |
| 30 | Not available | | | Housing Rear | | | |
| 31 | SP01042 | | 14 pieces | - | | | |
| 32 | Only available in K32 | | | Deflector ASM | | | |
| | Only available in K01 | | | | | | |
| 33 34 | SP00113 | 27107546667; 673002344; A0159973446 | | Ball Bearing Radial Sealing | | | |
| 35 | SP01499 | 27107597688 | 1 piece | - | Information for ATC35L: Used in 27105A371F3, 27105A371F1 | | |
| 36 | Only available in K05 | | 1 piece | Flange Rear | | | |
| 37 | SP01037 | 27107599326; 6000626079; 673002346 | 1 piece | Seal O-Ring | | | |
| 38 | SP00112 | 27107539525; 331381LA0A; 6000626080; 673002348 | 1 piece | | | | |
| 40 | Only available in K32 | | 1 piece | Tube ASM | | | |
| 1 | SP00152 | | 2 pieces | Ball Bearing | | | |
| 13 | SP00646 | | 1 piece | Sprocket Output | | | |
| 15 | SP00155 | | 2 pieces | Pin | | | |
| 16 | SP01315 | 05143630AA; | 1 piece | Magnet | | | |

TC00398, TC00399, TC00400

OEM No: 27105A371D7; 27105A371D8; 27105A371D9

| List of parts | | | | | |
|---------------|-------------------------------|--|----------|---------------------------------------|--|
| Pos | Part number | OEM no | Quantity | Product name | Info |
| 48 | SP01213 | | 1 piece | Retaining Ring | |
| 49 | SP00102 | 27107539212 | 1 piece | Slinger | |
| 52 | SP00099 | 27107539266 | 1 piece | Radial Sealing | |
| 53 | Only available in K01 & K12 | | 1 piece | Needle Bearing | |
| 54 | Only available in K12 | | 1 piece | Shaft Actuator | |
| 55 | Only available in K01 & K12 | | 1 piece | , , , , , , , , , , , , , , , , , , , | |
| 56 | Only available in K12 | | 1 piece | | |
| 57 | Only available in K12 | | 1 piece | 0 0 | |
| 58 | SP01038 | 27107593452 | 1 piece | - | |
| 59 | SP01040 | 27107593451; 673002350; 95834150100 | 1 piece | Seal O-Ring | |
| 60 60 60 | SP02030 SP02547 SP01045 | 27605A371F5 27605A371F4 27107593450; | 1 piece | Actuator Motor FR | Information for ATC350: Used in 27105A371E5, 27105A371E6 Information for ATC35L: Used in 27105A371F8, 27105A371E9 Information for ATC450: Used in 27107643751, 27107643752, 27108697972, 27108697973 Information for ATC45L: Used in 27105A371E1, 27105A4A0C0, 27105A371E0, 27105A4A0B9 Information for ATC350: Used in 27105A371E7 Information for ATC35L: Used in 27105A371F3, 27105A371F2, 27105A371F0, 27105A371F1 Information for ATC45L: Used in 27105A371F3, 27105A371F2, 27105A371F0, 27105A371F1 Information for ATC450: Used in 27107643753, 27108697974 Information for ATC45L: Used in 27105A371E2, 27105A4A0C1, 27105A371E3, 27105A4A0C2, 27105A371E4, 27105A4A0C3 |
| | | 673002351; 90038507101; 95834150200 | 2 pieces | | |
| 63 | SP00176 | 02C2D27148; 33117525064; 473904E000; 6000626082; 673002349 | 2 pieces | | |
| 70 | Only available in K10 | | 1 piece | 0 | |
| 71 | Only available in K10 | | 2 pieces | | |
| | SP02000 | | 1 piece | Sealant | Sealant SILICON BLACK (1pce = 300ml) |