

OWNER: KING OF THE SKIER LLC
ADDRESS: 4800 NORTH FEDERAL HIGHWAY
 BOCA RATON FL 34431
PHONE: 561-843-6254
FAX:

OPERATOR: KING OF THE SKIER LLC
ADDRESS: 4800 NORTH FEDERAL HIGHWAY
 BOCA RATON FL 34431
PHONE: 561-843-6254
FAX:

ANALYST: CHRISTA-LISA ORIE
EMAIL: CORIE@CAMPSYSTEMS.COM

+1-514-636-2163 (DIRECT)
 514-636-2020 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 50000037/N100WX **MODEL:** EMB-500 - PHENOM 100 **MANUFACTURER:** EMBRAER

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 25-JUL-2009	1140.3 A/C HRS	as of 13-SEP-2019	A/C HRS	as of ___/___/___
	869 AFL	as of 13-SEP-2019	AFL	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-LC0069/3503100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 28-AUG-2009		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	1140.3 ENG. HRS	as of 13-SEP-2019	ENG. HRS	as of ___/___/___
0 ENC		870 ENC	as of 13-SEP-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-LC0070/3503100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 28-APR-2009		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	1140.3 ENG. HRS	as of 13-SEP-2019	ENG. HRS	as of ___/___/___
0 ENC		870 ENC	as of 13-SEP-2019	ENC	as of ___/___/___



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-30-01	600 FH MAINTENANCE PACKAGE								
+									
	PKG 1	MOS					08-NOV-2013		
		HRS/MSC	600	+30/-30			579.4	1179.4	1209.4
	REF: SMR 05-30-01	AFL					438		
05-30-02	600 FH/12 MO MAINTENANCE PACKAGE								
+									
	PKG 2	MOS	12	+30d/-30d			25-JUL-2019	25-JUL-2020	24-AUG-2020
		HRS/MSC	600	+30/-30			1121.6	1721.6	1751.6
	REF: SMR 05-30-02	AFL					860		
05-30-10	1200 FH MAINTENANCE PACKAGE								
+									
	PKG 10	MOS					25-JUL-2009		
		HRS/MSC	1200	+30/-30			0	1200	1230
	REF: SMR 05-30-10	AFL					0		
05-30-12	1200 FH/24 MO MAINTENANCE PACKAGE								
+									
	PKG 12	MOS	24	+30d/-30d			25-JUL-2019	25-JUL-2021	24-AUG-2021
		HRS/MSC	1200	+30/-30			1121.6	2321.6	2351.6
	REF: SMR 05-30-12	AFL					860		
05-30-20	1800 FH MAINTENANCE PACKAGE								
+									
	PKG 20	MOS					25-JUL-2009		
		HRS/MSC	1800	+30/-30			0	1800	1830
	REF: SMR 05-30-20	AFL					0		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-40	3000 FH MAINTENANCE PACKAGE							
+	PKG 40	MOS				25-JUL-2009		
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-40	AFL				0		
05-30-41	3000 FH/48 MO MAINTENANCE PACKAGE							
+	PKG 41	MOS	48	+30d/-30d	-41	19-DEC-2017	08-NOV-2021	08-DEC-2021
		HRS/MSC	3000	+30/-30		954.6	3954.6	3984.6
	REF: SMR 05-30-41	AFL				746		
05-30-42	3000 FH/60 MO MAINTENANCE PACKAGE							
+	PKG 42	MOS	60	+30d/-30d		25-JUL-2019	25-JUL-2024	24-AUG-2024
		HRS/MSC	3000	+30/-30		1121.6	4121.6	4151.6
	REF: SMR 05-30-42	AFL				860		
05-30-45	4800 FH MAINTENANCE PACKAGE							
+	PKG 91	MOS				25-JUL-2009		
		HRS/MSC	4800	+30/-30		0	4800	4830
	REF: SMR 05-30-45	AFL				0		
05-30-50	6000 FH MAINTENANCE PACKAGE							
+	PKG 50	MOS				25-JUL-2009		
		HRS/MSC	6000	+30/-30		0	6000	6030
	REF: SMR 05-30-50	AFL				0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-53	6000 FH/96 MO MAINTENANCE PACKAGE								
+									
	PKG 53	MOS	96				15-JUN-2017	15-JUN-2025	15-JUL-2025
		HRS/MSC	6000	+30d/-30d			839.2	6839.2	6869.2
	REF: SMR 05-30-53	AFL		+30/-30			687		
05-30-60	7800 FH MAINTENANCE PACKAGE								
+									
	PKG 60	MOS					25-JUL-2009		
		HRS/MSC	7800	+30/-30			0	7800	7830
	REF: SMR 05-30-60	AFL					0		
05-30-66	12000 FH/120 MOS MAINTENANCE PACKAGE								
+									
	PKG 66	MOS	120	+30d/-30d			25-JUL-2019	25-JUL-2029	24-AUG-2029
		HRS/MSC	12000	+30/-30			1121.6	13121.6	13151.6
	REF: SMR 05-30-66	AFL					860		
05-30-80	12 MO MAINTENANCE PACKAGE								
+									
	PKG 80	MOS	12	+30d/-30d			25-JUL-2019	25-JUL-2020	24-AUG-2020
		HRS/MSC					1121.6		
	REF: SMR 05-30-80	AFL					860		
05-30-81	24 MO MAINTENANCE PACKAGE								
+									
	PKG 81	MOS	24	+30d/-30d			25-JUL-2019	25-JUL-2021	24-AUG-2021
		HRS/MSC					1121.6		
	REF: SMR 05-30-81	AFL					860		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-82	36 MO MAINTENANCE PACKAGE							
	PKG 82	MOS	36	+30d/-30d	-17	06-DEC-2018	19-NOV-2021	19-DEC-2021
	REF: SMR 05-30-82	HRS/MSC AFL				1071 829		
05-30-83	48 MO MAINTENANCE PACKAGE							
+	PKG 83	MOS	48	+30d/-30d	-41	19-DEC-2017	08-NOV-2021	08-DEC-2021
	REF: SMR 05-30-83	HRS/MSC AFL				954.6 746		
05-30-84	60 MO MAINTENANCE PACKAGE							
+	PKG 84	MOS	60	+30d/-30d		25-JUL-2019	25-JUL-2024	24-AUG-2024
	REF: SMR 05-30-84	HRS/MSC AFL				1121.6 860		
05-30-87	120 MO MAINTENANCE PACKAGE							
+	PKG 87	MOS	120	+30d/-30d		25-JUL-2019	25-JUL-2029	24-AUG-2029
	REF: SMR 05-30-87	HRS/MSC AFL				1121.6 860		
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							
	PKG 90	MOS	60	+30d/-30d		25-JUL-2019	25-JUL-2024	24-AUG-2024
	REF: SMR 05-30-90	HRS/MSC AFL				1121.6 860		

ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070
1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051254	NO. 1 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
+								
	PKG 1	MOS	12			25-JUL-2019	25-JUL-2020	24-AUG-2020
		HRS/MSC	600	+30d		1121.6	(1721.6) 1721.6	1781.6
	REF: LMM 05-20-00	ENC		+10%		860		

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01								
051254	NO. 2 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
+								
	PKG 1	MOS	12			25-JUL-2019	25-JUL-2020	24-AUG-2020
		HRS/MSC	600	+30d		1121.6	(1721.6) 1721.6	1781.6
	REF: LMM 05-20-00	ENC		+10%		860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
EM50-161022	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM50-161022	MOS HRS/MSC - AFL							
EM50-161122	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 46 DATED NOV 22/2016								
REQUIREMENT CHANGE FORMS	REF: RCF EM50-161122	MOS HRS/MSC - AFL							
EM50-161202	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/MAINTENANCE CHECK (CHAPTER-5) ADVANCE REVISION DATED DEC 02/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM50-161202	MOS HRS/MSC - AFL							
EM50-161216	REVIEW EMBRAER PHENOM 100 (EM50) TIME LIMITS/ MAINTENANCE CHECKS/CHAPTER-5 REVISION 47 DATED DEC 16/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM50-161216	MOS HRS/MSC - AFL							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
+ H242-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE						PKG		
	PKG 87	MOS	120	+30d/-30d			25-JUL-2019		
	REF: AMM 05-42-00	HRS/MSC AFL					1121.6		860
+ H340-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PITCH TRIM ACTUATOR ELECTRICAL BONDING						PKG		
	PKG 87	MOS	120	+30d/-30d			25-JUL-2019		
	REF: AMM 05-44-00	HRS/MSC AFL					1121.6		860

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ H430-001	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS PKG 84 REF: AMM 05-46-00	MOS HRS/MSC AFL	60				25-JUL-2019 1121.6 860	25-JUL-2024	
+ H700-001	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ H700-002	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
CHAPTER 21	AIR CONDITIONING								
21-00-00	ELECTROMECHANICAL LINEAR ACTUATOR 100000-77 0005 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
21-01-01	PRESSURIZATION AND AIR CONDITIONING CONTROL PANEL 441-40931-002 0047 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
21-21-01	LEFT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY 1300230-15 354 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:9 TSR:0 TSR:0		26-SEP-2011 253 186		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-21-01	RIGHT REAR FUS FLOW CONTROL SHUT OFF VALVE ASSEMBLY 1300230-27 305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			06-MAR-2019 1087.3 840		
21-21-02	LH AFT INLET AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
21-21-02	RH AFT INLET AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-21-02-001 (s)	OPERATIONAL CHECK LH AFT INLET AIR CHECK VALVE PN PKG 50 SN-UNKNOWN REF: AMM 21-21-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-21-02-001 (s)	OPERATIONAL CHECK RH AFT INLET AIR CHECK VALVE PN PKG 50 SN-UNKNOWN REF: AMM 21-21-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
21-23-03	RAM AIR VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE POSITION PN PKG 50 SN-UNKNOWN REF: AMM 21-23-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PN PKG 1 SN-UNKNOWN REF: AMM 21-23-03	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
21-23-04	LH AFT FUSELAGE RAM AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
21-23-04	LH CENTER FUSELAGE RAM AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
21-23-04	RH AFT FUSELAGE RAM AIR CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 21-23-04-001 (s)	OPERATIONAL CHECK LH AFT FUSELAGE RAM AIR CHECK VALVE PN PKG 50 SN-UNKNOWN REF: AMM 21-23-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-23-04-001 (s)	OPERATIONAL CHECK LH CENTER FUSELAGE RAM AIR CHECK VALVE PN PKG 50 SN-UNKNOWN REF: AMM 21-23-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-23-04-001 (s)	OPERATIONAL CHECK RH AFT FUSELAGE RAM AIR CHECK VALVE PN PKG 50 SN-UNKNOWN REF: AMM 21-23-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-23-05	TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY 1133710-5 259 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-23-05-001 (s)	GENERAL VISUAL INSPECTION TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY 1133710-5 PKG 10 259 REF: AMM 21-23-05	MOS HRS/MSC AFL	1200	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-31-00-002 (s)	OPERATIONAL CHECK AFT BULKHEAD OUTFLOW (OFV) VALVE MANUAL PRESSURIZATION CONTROL MODE 103920-1 PKG 1 103920-00084 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
+ 21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
+ 21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 91 REF: AMM 21-31-00	MOS HRS/MSC AFL	4800	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 91 REF: AMM 21-31-00	MOS HRS/MSC AFL	4800	+30/-30			PKG 25-JUL-2009 0 0		
21-31-01	ELECTRONIC CONTROL AND MONITORING UNIT 2119286-4 2119286-00599 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-SEP-2011 253 186		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) 2119286-4 2119286-00599 REF: AMM 21-31-01	MOS HRS/MSC AFL	6000	+30/-30			25-JUL-2009 0 0	6000	6030
21-31-02	AFT BULKHEAD OUTFLOW (OFV) VALVE 103920-1 103920-00084 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-31-02-001	RESTORATION (REPAIR) OF AFT BULKHEAD OUTFLOW VALVE 103920-1 103920-00084 REF: AMM 21-31-02	MOS HRS/MSC AFL	7200	+30/-30			25-JUL-2009 0 0	7200	7230
21-31-03	NEGATIVE PRESSURE RELIEF VALVE 130664-2 34163-0043 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-31-03-001 (s)	OPERATIONAL CHECK NEGATIVE PRESSURE RELIEF VALVE 130664-2 PKG 50 34163-0043 REF: AMM 21-31-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
21-31-04	AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE 103916-2 103916-00115 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-31-04-001 (s)	FUNCTIONAL CHECK AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE 103916-2 PKG 50 103916-00115 REF: AMM 21-31-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-52-01-001	DETAILED VISUAL INSPECTION VCS COMPRESSOR DRIVE MODULE OF VCS COMPRESSOR MOTOR DRIVE 1133630-10 190 REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C				19-DEC-2017 954.6 746		
+ 21-52-01-002 (s)	DISCARD OF COMPRESSOR DRIVE MODULE BELT PN PKG 20 SN-UNKNOWN REF: AMM 21-52-01	MOS HRS/MSC AFL	1800	+30/-30			PKG 08-NOV-2013 579.4 438		
+ 21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION PN PKG 1 SN-UNKNOWN REF: AMM 21-52-01	MOS HRS/MSC AFL	600	+30/-30			PKG 19-DEC-2017 954.6 746		
+ 21-52-01-004	RESTORATION (OVERHAUL) CDM COMPRESSOR MODULE PN SN-UNKNOWN REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			25-JUL-2009 0 0	2000	2030
21-52-02	HEAT EXCHANGER PACK 1133750-3 144 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 21-52-02-001 (s)	GENERAL VISUAL INSPECTION HEAT EXCHANGER PACK 1133750-3 PKG 10 144 REF: AMM 21-52-02	MOS HRS/MSC AFL	1200	+30/-30			PKG 25-JUL-2009 0 0		
+ 21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES PKG 1 REF: AMM 21-52-03	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-04	FWD FUS VCS SYSTEM FWD EVAPORATOR BLOWER 1133850-104 237 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 2 REF: AMM 12-17-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1 REF: AMM 21-61-00	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
21-61-01	REAR FUS ECS TEMPERATURE CONTROLLER 1300650-10 201 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
21-61-03	COCKPIT DUCT TEMPERATURE SENSOR SWITCH 1300450-10 197 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-OCT-2009 18 12		
21-61-03	LH REAR DUCT TEMPERATURE SENSOR SWITCH 1300450-10 375 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
21-61-03	PAX DUCT TEMPERATURE SENSOR SWITCH 1300450-10 262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-03	RH REAR DUCT TEMPERATURE SENSOR SWITCH 1300450-10 283 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 50 REF: AMM 21-61-06	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
215201-0101	VCS COMPRESSOR DRIVE MODULE 1133630-10 190 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-NOV-2013 579.4 438		
215201-0102	CDM COMPRESSOR MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
215201-0201	COMPRESSOR DRIVE MODULE BELT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-11-02	RH REAR CHECK VALVE 3D3555-01 N090267 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 22	AUTO FLIGHT								
+ 22-11-00-001	FUNCTIONAL CHECK OF AILERON SERVO 011-00878-10 71306250 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020
AIRWORTHINESS									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-11-00-001	FUNCTIONAL CHECK OF ELEVATOR SERVO 011-00878-10 71306251 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020
AIRWORTHINESS									
+ 22-11-00-001	FUNCTIONAL CHECK OF RUDDER SERVO 011-00878-10 71306266 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020
AIRWORTHINESS									
+ 22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS PKG 12 REF: AMM 22-11-00	MOS HRS/MSC AFL	24	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 22-11-00-003 (s)	DETAILED VISUAL INSPECTION OF AUTOPILOT SERVO CABLE PKG 42 REF: AMM 22-11-00	MOS HRS/MSC AFL	60	+1m/-1m +30/-30			PKG 25-JUL-2019 1121.6 860		
22-11-01	GMC 715 GUIDANCE PANEL 011-01430-00 15900205 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR 011-00878-10 71306250 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
22-11-03	AILERON GSM 85A MED TORQUE SERVO MOUNT 011-01436-01 22305164 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-05	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR 011-00878-10 71306251 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
22-11-06	ELEVATOR GSM 85A MED TORQUE SERVO MOUNT 011-01436-01 22305175 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
22-11-08	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR 011-00878-10 71306266 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
22-11-09	RUDDER GSM 85A MED TORQUE SERVO MOUNT 011-01436-01 22305179 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 23	COMMUNICATIONS								
23-12-02	BOTTOM VHF ANTENNA S65-8280-41 322-1851 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-12-02	TOP VHF ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-12-03	VHF 3 RADIO UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-15-01	IRIDIUM TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-15-03	IRIDIUM ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-23-01	GD59 DATALINK MANAGEMENT UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-23-03	WIFI - DATALINK ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
23-51-01	COPILOT GMA 1347D AUDIO PANEL 011-01257-20 17105612 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-51-01	PILOT GMA 1347D AUDIO PANEL 011-01257-20 17105583 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-51-05	LH AUDIO JACK CONTROL PANEL 441-40943-002 0113 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-51-05	RH AUDIO JACK CONTROL PANEL 441-40943-002 0054 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-51-09	LH MODEL HME 25-KA-2 HEADSET 025-250-015 002413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-51-09	RH MODEL HME 25-KA-2 HEADSET 025-250-015 002412 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
23-51-11	COCKPIT ELECTRODYNAMIC MICROPHONE 85-03-12369-04 202529 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 19-DEC-2017 954.6 746		
CHAPTER 24	ELECTRICAL POWER								
24-00-07	RELAY ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-01-01	ELECTRICAL CONTROL PANEL 441-40929-002 0041 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
24-31-01	NO.1 ENGINE STARTER-GENERATOR MG94F-2 1057 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-OCT-2014 620.1 487		
24-31-01	NO.2 ENGINE STARTER-GENERATOR MG94F-2 1058 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-OCT-2014 620.1 487		
+ 24-31-01-001	RESTORATION (OVERHAUL) OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-2 AND 400SG180Q) MG94F-2 1057 REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30			21-OCT-2014 620.1 487	1820.1	1850.1
+ 24-31-01-001	RESTORATION (OVERHAUL) OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-2 AND 400SG180Q) MG94F-2 1058 REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30			21-OCT-2014 620.1 487	1820.1	1850.1
+ 24-31-01-002	DETAILED DIMENSIONAL INSPECTION NO.1 ENGINE STARTER-GENERATOR OF BRUSHES (P/N MG94F-2 AND 400SG180Q) MG94F-2 1057 REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30			21-OCT-2014 620.1 487	1220.1	1250.1
+ 24-31-01-002	DETAILED DIMENSIONAL INSPECTION NO.2 ENGINE STARTER-GENERATOR OF BRUSHES (P/N MG94F-2 AND 400SG180Q) MG94F-2 1058 REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30			21-OCT-2014 620.1 487	1220.1	1250.1

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-31-01-003	RESTORATION (OVERHAUL) OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-1) MG94F-2 1057 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
+ 24-31-01-003	RESTORATION (OVERHAUL) OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-1) MG94F-2 1058 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
+ 24-31-01-004	DETAILED INSPECTION OF NO.1 ENGINE STARTER-GENERATOR (P/N MG94F-1) MG94F-2 1057 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
+ 24-31-01-004	DETAILED INSPECTION OF NO.2 ENGINE STARTER-GENERATOR (P/N MG94F-1) MG94F-2 1058 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
24-31-02	NO.1 GENERATOR - DC, 28V CONTROL UNIT CG301A-12 729 REF: See Workcard	MOS HRS/MSC AFL	O/C				02-MAR-2018		
24-31-02	NO.2 GENERATOR - DC, 28V CONTROL UNIT CG301A-12 412 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2015 697.4 559		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84	MOS	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 24-31-07	HRS/MSC AFL							
24-36-01	NO.1 MAIN BATTERY 7639-30LT G03045570	MOS	O/C	TSN:2 TSN:0 TSN:0			25-JUL-2019 1121.6 860		
	REF: See Workcard	HRS/MSC AFL							
24-36-01	NO.2 MAIN BATTERY 7639-30LT G03045573	MOS	O/C	TSN:2 TSN:0 TSN:0			25-JUL-2019 1121.6 860		
	REF: See Workcard	HRS/MSC AFL							
+ 24-36-01-003	DISCARD NO.1 MAIN BATTERY 7639-30LT G03045570	MOS	24	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2021	24-AUG-2021
	REF: AMM 24-36-01	HRS/MSC AFL	600	+30/-30				1460	1490
+ 24-36-01-003	DISCARD NO.2 MAIN BATTERY 7639-30LT G03045573	MOS	24				25-JUL-2019 1121.6 860	25-JUL-2021	
	REF: AMM 24-36-01	HRS/MSC AFL	600					1460	
+ 24-36-01-004	FUNCTIONAL CHECK NO.1 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014) 7639-30LT G03045570	MOS	N/A						
	REF: AMM 24-36-01	HRS/MSC AFL							
+ 24-36-01-004	FUNCTIONAL CHECK NO.2 MAIN BATTERY OF - (PRE-MOD SB 500-24-0014) 7639-30LT G03045573	MOS	N/A						
	REF: AMM 24-36-01	HRS/MSC AFL							

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-36-01-005	FUNCTIONAL CHECK OF NO.1 MAIN BATTERY - (POST-MOD SB 500-24-0014) 7639-30LT G03045570 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020
+ 24-36-01-005	FUNCTIONAL CHECK OF NO.2 MAIN BATTERY - (POST-MOD SB 500-24-0014) 7639-30LT G03045573 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020
24-36-02	BATTERY CURRENT (HB2) SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 24-36-02-001 (s)	OPERATIONAL CHECK BATTERY CURRENT (HB2) SENSOR PN PKG 50 SN-UNKNOWN REF: AMM 24-36-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0059 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
24-65-00	CABLE W109 LPDU/RPDU FEEDER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
24-65-01	LEFT POWER DISTRIBUTION UNIT ASSEMBLY SX7EG16-1B 0127 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-NOV-2013 579.4 438		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-02	RIGHT POWER DISTRIBUTION UNIT ASSEMBLY SX7EG17-1B 0109 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-NOV-2013 579.4 438		
24-65-03	CENTER POWER DISTRIBUTION UNIT ASSEMBLY SX7EG18-1B 0080 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-NOV-2013 579.4 438		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
25-11-01	COPILOT CITRINE FINISH GOODRICH SEAT 1429-621AG 527-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:101 TSN:954.6 TSN:746		19-DEC-2017 954.6 746		
25-11-01	PILOT CITRINE FINISH GOODRICH SEAT 1429-521AG 519-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:101 TSN:954.6 TSN:746		19-DEC-2017 954.6 746		
+ 25-11-01-001 (s)	DETAILED VISUAL INSPECTION COPILOT CITRINE FINISH GOODRICH SEAT 1429-621AG PKG 40 527-1429 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-11-01-001 (s)	DETAILED VISUAL INSPECTION PILOT CITRINE FINISH GOODRICH SEAT 1429-521AG PKG 40 519-1429 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-11-01-002 (s)	DETAILED VISUAL INSPECTION OF COCKPIT SEAT BELTS PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01	#5 SEAT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
25-21-01	LH AFT PAX SEAT 403176-3AE 47567 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
25-21-01	LH FWD PAX SEAT 403176-1AE 47565 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
25-21-01	RH AFT PAX SEAT 403176-4AE 47568 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
25-21-01	RH FWD PAX SEAT 403176-2AE 47566 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
+ 25-21-01-001 (s)	DETAILED VISUAL INSPECTION LH AFT PAX SEAT 403176-3AE PKG 40 47567 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-21-01-001 (s)	DETAILED VISUAL INSPECTION LH FWD PAX SEAT 403176-1AE PKG 40 47565 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-21-01-001 (s)	DETAILED VISUAL INSPECTION RH AFT PAX SEAT 403176-4AE PKG 40 47568 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-21-01-001 (s)	DETAILED VISUAL INSPECTION RH FWD PAX SEAT 403176-2AE PKG 40 47566 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-21-01-002 (s)	DETAILED VISUAL INSPECTION OF PASSENGER SEAT BELTS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-21-03-001 (s)	DETAILED INSPECTION OF FIFTH SEAT PKG 40 REF: AMM 25-21-03	MOS HRS/MSC AFL	N/A				PKG 25-JUL-2009 0 0		
+ 25-21-03-002 (s)	DETAILED INSPECTION OF THE FIFTH SEAT BELT PKG 40 REF: AMM 25-21-03	MOS HRS/MSC AFL	N/A				PKG 25-JUL-2009 0 0		
+ 25-43-01-001 (s)	DETAILED VISUAL INSPECTION OF BELTED TOILET UNIT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		
+ 25-43-01-002 (s)	DETAILED VISUAL INSPECTION OF BELTED TOILET SEAT BELT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM S1821502-02 LX1100336689 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				25-JUL-2019 1121.6 860	25-JUL-2020	
+ 25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100336689 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				25-JUL-2019 1121.6 860	25-JUL-2020	
25-61-01	EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100336689 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-NOV-2016 766.6 621		
25-61-02	EMERGENCY LOCATOR TRANSMITTER BATTERY PN-UNKNOWN SN-UNKNOWN REF: AMM 25-61-04	MOS HRS/MSC AFL	A/R				11-NOV-2016 766.6 621		
25-61-03	ELT ANTENNA S65-8282-406 401-1173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY PN-UNKNOWN SN-UNKNOWN REF: AMM 25-61-04	MOS HRS/MSC AFL	DUE				11-NOV-2016 766.6 621	01-OCT-2022 M	
+ 25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE PN SN-UNKNOWN REF: AMM 25-61-07	MOS HRS/MSC AFL	N/A						

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-05-01	ELT/NAV INTERFACE - CS144-A MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
25-61-05-02	INTERCONNECTION CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 25-62-01	FIRST AID KIT 019708-0005L SN-UNKNOWN REF: GENERIC NO REF Expiry Date: 01-JUL-2020	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			21-SEP-2018 1020 793	01-JUL-2020 M	
+ 25-62-01-001	VISUAL CHECK FIRST AID KIT 019708-0005L SN-UNKNOWN REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				21-SEP-2018 1020 793	01-JUL-2020 M	
25-62-02	COPILOT CREW LIFE VEST 66601-505 L3949967 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:1 TSN:0 TSN:0			06-DEC-2018 1071 829		
25-62-02	NO.1 PAX LIFE VEST 66601-105 L4173929 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			06-DEC-2018 1071 829		
25-62-02	NO.2 PAX LIFE VEST 66601-105 L4173930 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			06-DEC-2018 1071 829		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	NO.3 PAX LIFE VEST 66601-105 L4173933 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			06-DEC-2018 1071 829		
25-62-02	NO.4 PAX LIFE VEST 66601-105 L4173932 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:8 TSN:0 TSN:0			06-DEC-2018 1071 829		
25-62-02	PILOT CREW LIFE VEST 66601-505 L3949993 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:1 TSN:0 TSN:0			06-DEC-2018 1071 829		
+ 25-62-02-001	RESTORATION (OVERHAUL) OF COPILOT LIFE VEST 66601-505 L3949967 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-NOV-2018	30-NOV-2028	
	OVERHAUL								
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST 66601-105 L4173929 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-APR-2018	30-APR-2028	
	OVERHAUL								
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST 66601-105 L4173930 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-APR-2018	30-APR-2028	
	OVERHAUL								
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST 66601-105 L4173933 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-APR-2018	30-APR-2028	
	OVERHAUL								
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST 66601-105 L4173932 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-APR-2018	30-APR-2028	
	OVERHAUL								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST 66601-505 L3949993 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				30-NOV-2018	30-NOV-2028	
OVERHAUL									
+ 25-62-02-003	DISCARD OF COPILOT CREW LIFE VEST 66601-505 L3949967 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-NOV-2018	01-NOV-2027 M	
+ 25-62-02-003	DISCARD OF NO.1 PAX LIFE VEST 66601-105 L4173929 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-APR-2018		
+ 25-62-02-003	DISCARD OF NO.2 PAX LIFE VEST 66601-105 L4173930 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-APR-2018		
+ 25-62-02-003	DISCARD OF NO.3 PAX LIFE VEST 66601-105 L4173933 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-APR-2018		
+ 25-62-02-003	DISCARD OF NO.4 PAX LIFE VEST 66601-105 L4173932 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-APR-2018		
+ 25-62-02-003	DISCARD OF NO.5 PAX LIFE VEST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A						
+ 25-62-02-003	DISCARD OF PILOT CREW LIFE VEST 66601-505 L3949993 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-NOV-2018	01-NOV-2027 M	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-04	LAV WATER BARRIER PN SN-UNKNOWN REF: AMM 25-62-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION LAV WATER BARRIER PN PKG 81 SN-UNKNOWN REF: AMM 25-62-04	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
CHAPTER 26 FIRE PROTECTION									
26-11-01	LH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M 41270 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
26-11-01	RH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M 41268 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 26-11-01-001 (s)	DETAILED VISUAL INSPECTION LH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M PKG 10 41270 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 25-JUL-2009 0 0		
+ 26-11-01-001 (s)	DETAILED VISUAL INSPECTION RH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M PKG 10 41268 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 25-JUL-2009 0 0		
+ 26-11-01-002	OPERATIONAL CHECK LH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M 41270 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			25-JUL-2009 0 0	1200	1230
AIRWORTHINESS									
+ 26-11-01-002	OPERATIONAL CHECK RH ENGINE FIRE DETECTOR 3951-49-565/211C-3.7M 41268 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			25-JUL-2009 0 0	1200	1230
AIRWORTHINESS									



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-01	FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 26-21-01-001	FUNCTIONAL CHECK FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL FIREX PANEL/SYSTEM PN SN-UNKNOWN REF: AMM 26-21-00	MOS HRS/MSC AFL	2400	+30/-30			25-JUL-2009 0 0	2400	2430
AIRWORTHINESS									
26-21-03	ENGINE FIRE EXTINGUISHING BOTTLE 3300073-4 87031A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			06-DEC-2018 1071 829		
+ 26-21-03-001	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHING BOTTLE 3300073-4 87031A1 REF: AMM 26-21-03	MOS HRS/MSC AFL	120				23-NOV-2018	23-NOV-2028	
AIRWORTHINESS									
+ 26-21-05-001	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) REF: AMM 26-21-05	MOS HRS/MSC AFL	2400	+30/-30			25-JUL-2009 0 0	2400	2430
AIRWORTHINESS									
26-21-07	LEFT ENG FIREX CARTRIDGE 30903962-1 1400WG REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			06-DEC-2018 1071 829		
26-21-07	RIGHT ENG FIREX CARTRIDGE 30903963-1 1738WF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			06-DEC-2018 1071 829		
+ 26-21-07-001	DISCARD LEFT ENG FIREX CARTRIDGE 30903962-1 1400WG REF: AMM 26-21-07	MOS HRS/MSC AFL	120				01-AUG-2018	01-AUG-2028	
LIFE LIMIT									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-21-07-001	DISCARD RIGHT ENG FIREX CARTRIDGE 30903963-1 1738WF REF: AMM 26-21-07	MOS HRS/MSC AFL	120				01-AUG-2018	01-AUG-2028	
LIFE LIMIT									
+ 26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 REF: AMM 26-21-09	MOS HRS/MSC AFL	1800	+30/-30			PKG 25-JUL-2009 0 0		
26-24-01	CABIN PORTABLE EXTINGUISHER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
26-24-01	COCKPIT PORTABLE EXTINGUISHER RT-A1200 S738388 REF: See Workcard	MOS HRS/MSC AFL	A/R		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 26-24-01-001	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				06-DEC-2018		
+ 26-24-01-001	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER RT-A1200 S738388 REF: GENERIC NO REF	MOS HRS/MSC AFL	12				25-JUL-2019	25-JUL-2020	
+ 26-24-01-002	DISCARD CABIN PORTABLE EXTINGUISHER PN SN-UNKNOWN REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-002	DISCARD COCKPIT PORTABLE EXTINGUISHER RT-A1200 S738388 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-SEP-2008	01-SEP-2020	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-24-01-003	DISCARD CABIN PORTABLE EXTINGUISHER PN SN-UNKNOWN REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-003	DISCARD COCKPIT PORTABLE EXTINGUISHER RT-A1200 S738388 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK CABIN PORTABLE EXTINGUISHER PN SN-UNKNOWN REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER RT-A1200 S738388 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
CHAPTER 27 FLIGHT CONTROLS									
+ 27-001	LEFT FLAP ACTUATOR PN-UNKNOWN 0636 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:517.5 TSN:389			07-FEB-2013		20581.9 M
LIFE LIMIT									
+ 27-001	RIGHT FLAP ACTUATOR PN-UNKNOWN 0502 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:517.5 TSN:389			07-FEB-2013		20141.9 M
LIFE LIMIT									
+ 27-002	ROLL TRIM ACTUATOR 452900-1007 0153 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		35000
LIFE LIMIT									
+ 27-003	YAW TRIM ACTUATOR 453000-1007 0063 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		35000
LIFE LIMIT									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-004	LEFT PITCH TRIM ACTUATOR 453100-1009 0328 REF: See Workcard	MOS HRS/MSC AFL	3200	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0	3200	
LIFE LIMIT									
+ 27-004	RIGHT PITCH TRIM ACTUATOR 453100-1009 0334 REF: See Workcard	MOS HRS/MSC AFL	3200	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0	3200	
LIFE LIMIT									
+ 27-005	LH WING GROUND SPOILER ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 27-005	RH WING GROUND SPOILER ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-01-01	LEFT CONTROL YOKE 500-15069-411 0000503088 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-01-01	RIGHT CONTROL YOKE 500-15069-412 0000503853 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-01-02	LH PEDAL ASSEMBLY 500-15010-411 0000293525 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-01-02	RH PEDAL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81 REF: AMM 12-21-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
27-04-01	NO.1 TRIM ACTUATOR CONTROLLER 461600-1007 0192 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
27-04-01	NO.2 TRIM ACTUATOR CONTROLLER 461600-1007 0212 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
+ 27-04-01-001 (s)	FUNCTIONAL CHECK OF TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 27-04-01-002 (s)	FUNCTIONAL CHECK OF TRIM TABS ELECTRICAL STOP PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 27-04-01-003 (s)	OPERATIONAL CHECK OF TRIM TAB JAM MONITORING FUNCTION PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-11-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 25-JUL-2019 1121.6 860		
27-11-01	LH AILERON BALANCED ASSEMBLY 500-14650-407 0000496508 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-11-01	RH AILERON BALANCED ASSEMBLY 500-14651-403 0000495979 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+30d/-30d +30/-30	-30		19-DEC-2017 954.6 746	19-NOV-2022 3954.6	19-DEC-2022 3984.6
+ 27-11-02-002 (s)	DETAILED VISUAL INSPECTION OF AILERON CONTROL CABLES PKG 42 REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 27-14-02-001	FUNCTIONAL CHECK ROLL TRIM ACTUATOR AILERON TRIM BACKLASH/ INTEGRITY 452900-1007 0153 REF: AMM 27-14-03	MOS HRS/MSC AFL	6000	+30/-30			25-JUL-2009 0 0	6000	6030
	AIRWORTHINESS								
27-14-03	LEFT AILERON TRIM TAB 500-14630-403 0000496605 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-21-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 25-JUL-2019 1121.6 860		
27-21-01	RUDDER BALANCED ASSEMBLY 500-10520-411 0000496521 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION REF: AMM 27-21-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30	-30		19-DEC-2017 954.6 746	19-NOV-2022 3954.6	19-DEC-2022 3984.6

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-21-02-002 (s)	DETAILED VISUAL INSPECTION OF RUDDER CONTROL CABLES PKG 42	MOS	60	+1m/-1m			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 27-21-02	HRS/MSC AFL	3000	+30/-30					
+ 27-24-02-001	FUNCTIONAL CHECK YAW TRIM ACTUATOR RUDDER TRIM BACKLASH INTEGRITY 453000-1007 0063	MOS	6000	+30/-30			25-JUL-2009 0 0	6000	6030
AIRWORTHINESS	REF: AMM 27-24-03	HRS/MSC AFL							
27-24-03	TAB RUDDER 500-10420-407 0000493048	MOS	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
	REF: See Workcard	HRS/MSC AFL							
+ 27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42	MOS	60	+1m/-1m			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 27-31-00	HRS/MSC AFL	3000	+30/-30					
27-31-01	LEFT ELEVATOR 500-11085-4001 0000305290	MOS	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
	REF: See Workcard	HRS/MSC AFL							
27-31-01	RIGHT ELEVATOR 500-11085-602 0000490562	MOS	O/C		TSR:0 TSR:0 TSR:0		11-DEC-2012 464.5 353		
	REF: See Workcard	HRS/MSC AFL							
+ 27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION	MOS	60	+30d/-30d		-30	19-DEC-2017 954.6 746	19-NOV-2022 3954.6	19-DEC-2022 3984.6
	REF: AMM 27-31-02	HRS/MSC AFL	3000	+30/-30					
+ 27-31-02-002 (s)	DETAILED VISUAL INSPECTION OF ELEVATOR CONTROL CABLES PKG 42	MOS	60	+1m/-1m			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 27-31-02	HRS/MSC AFL	3000	+30/-30					

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-34-02-001	FUNCTIONAL CHECK OF PITCH TRIM BACKLASH/ INTEGRITY	MOS					25-JUL-2009		
AIRWORTHINESS	REF: AMM 27-34-05	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-34-04	PITCH TRIM INTERCONNECTION ACTUATOR 453110-1001 0172 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
27-34-05	LEFT ELEVATOR TRIM TAB 500-11010-4001 0000289307 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
27-34-05	RIGHT ELEVATOR TRIM TAB 500-11010-4002 0000293356 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
27-36-01	LEFT ANGLE-OF-ATTACK SENSOR C-100117-4 142873-02 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2014 620.1 487		
27-36-01	RIGHT ANGLE-OF-ATTACK SENSOR C-100117-4 419 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2014 620.1 487		
+ 27-36-01-001 (s)	OPERATIONAL CHECK OF ANGLE-OF-ATTACK (AOA) SENSOR PKG 2 REF: AMM 27-36-01	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
27-36-02	STICK PUSHER LINEAR ACTUATOR 260926258-0101 152 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-36-03-001 (s)	OPERATIONAL CHECK OF SPWS CUTOUT SWITCH PKG 12	MOS	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 27-36-03	HRS/MSC AFL	1200	+30/-30					
27-36-04	STALL WARNING AND PROTECTION COMPUTER C-100106-1 141	MOS	O/C				21-OCT-2010 24.1 13		
	REF: See Workcard	HRS/MSC AFL							
+ 27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS PKG 80	MOS	12	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 12-21-00	HRS/MSC AFL							
+ 27-51-01-002 (s)	DETAILED VISUAL INSPECTION LEFT FLAP ACTUATOR PN-UNKNOWN PKG 50 0636	MOS	6000	+30/-30	TSI:517.5		PKG 07-FEB-2013		
	REF: See Workcard	HRS/MSC AFL			TSI:389				
+ 27-51-01-002 (s)	DETAILED VISUAL INSPECTION RIGHT FLAP ACTUATOR PN-UNKNOWN PKG 50 0502	MOS	6000	+30/-30	TSI:517.5		PKG 07-FEB-2013		
	REF: See Workcard	HRS/MSC AFL			TSI:389				
+ 27-51-01-003	RESTORE (OVERHAUL) LEFT FLAP ACTUATOR PN-UNKNOWN 0636	MOS	3600	+30/-30			07-FEB-2013 517.5 389	4117.5	4147.5
	REF: AMM 27-51-01	HRS/MSC AFL							
+ 27-51-01-003	RESTORE (OVERHAUL) RIGHT FLAP ACTUATOR PN-UNKNOWN 0502	MOS	3600	+30/-30			07-FEB-2013 517.5 389	4117.5	4147.5
	REF: AMM 27-51-01	HRS/MSC AFL							
27-51-03	LH WING FLAP 500-14301-403 0000489191	MOS	O/C		TSN:0		25-JUL-2009 0 0		
	REF: See Workcard	HRS/MSC AFL			TSN:0 TSN:0				

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-03	RH WING FLAP 500-14301-404 0000494607 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-53-01	FLAP SELECTOR LEVER 780501-7 1059 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-53-02	FLAP SYSTEM CONTROL UNIT 8025B0001-04 0247 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-SEP-2019 1140.3 869		
27-53-03	LH WING FLAP POSITION SENSOR UNIT 7906A0001-01 KA1156 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
27-53-03	RH WING FLAP POSITION SENSOR UNIT 7906A0001-01 KA1171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 27-60-00-001	OPERATIONAL CHECK OF GROUND SPOILER SYSTEM	MOS HRS/MSC AFL	6000	+30/-30			25-JUL-2009 0 0	6000	6030
AIRWORTHINESS	REF: AMM 27-60-00								
CHAPTER 28 FUEL									
+ 28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICRO-ORGANISMS PKG 80 REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
28-11-05	LH WING WATER DRAIN VALVE L83A13-628 H17229 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			08-NOV-2013 579.4 438		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-11-05	RH WING WATER DRAIN VALVE L83A13-628 D71078 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-11-07	LH WING DUMP VALVE V98A32-001 D61994 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-11-07	RH WING DUMP VALVE V98A32-001 D70607 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 2 REF: AMM 28-12-01	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
28-12-03	LH WING FUEL TANK FLOAT VENT VALVE L87-19-001P2 D69633 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-12-03	RH WING FUEL TANK FLOAT VENT VALVE L87-19-001P2 D69631 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 28-12-03-001 (s)	OPERATIONAL CHECK LH WING FUEL TANK FLOAT VENT VALVE L87-19-001P2 PKG 50 D69633 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 28-12-03-001 (s)	OPERATIONAL CHECK RH WING FUEL TANK FLOAT VENT VALVE L87-19-001P2 PKG 50 D69631 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-12-05	LH WING DRAIN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-12-05	RH WING DRAIN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-00	NO.1 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-00	NO.2 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-00	NO.3 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-00	NO.4 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-03	LH WING DC AUXILIARY CANISTER BOOST PUMP C93R19-601 D73428 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-03	RH WING DC AUXILIARY CANISTER BOOST PUMP C93R19-601 D73429 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-04	LH WING DC AUXILIARY CARTRIDGE BOOST PUMP P99C19-601 D57568 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-04	RH WING DC AUXILIARY CARTRIDGE BOOST PUMP P99C19-601 D79209 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-05	LH WING MAIN EJECTOR PUMP T99A19-601 D67772 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-05	RH WING MAIN EJECTOR PUMP T99A19-601 D67780 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 28-21-07-001	OPERATIONAL CHECK LEFT WING 0.75 IN SHUTOFF VALVE B97-15-601 D71623 REF: AMM 28-21-07	MOS HRS/MSC AFL	1200	+30/-30			25-JUL-2009 0 0	1200	1230
AIRWORTHINESS									
+ 28-21-07-001	OPERATIONAL CHECK RIGHT WING 0.75 IN SHUTOFF VALVE B97-15-601 D71633 REF: AMM 28-21-07	MOS HRS/MSC AFL	1200	+30/-30			25-JUL-2009 0 0	1200	1230
AIRWORTHINESS									
28-21-07-01	LEFT WING 0.75 IN SHUTOFF VALVE B97-15-601 D71623 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-07-01	RIGHT WING 0.75 IN SHUTOFF VALVE B97-15-601 D71633 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-07-02	LH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY D97C00-644P2 C70363 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-07-02	RH WING 28-V DC ENGINE SHUTOFF VALVE ACTUATOR ASSEMBLY D97C00-644P2 C70360 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 28-21-08-001 (s)	OPERATIONAL CHECK OF FUEL TRANSFER VALVE B97-38-603P2 PKG 12 D71139 REF: AMM 28-21-08	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
28-21-08-01	1.5 IN FUEL SYSTEM SHUTOFF VALVE B97-38-603P2 D71139 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-08-02	ENGINE 28-V DC TRANSFER VALVE ACTUATOR ASSEMBLY D97C00-644P2 C70362 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-11	LH WING MOTIVE FLOW 3/8 IN CHECK VALVE L96-09-001P4 D73762 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-11	RH WING MOTIVE FLOW 3/8 IN CHECK VALVE L96-09-001P4 D73761 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-21-13	FUEL CONTROL PANEL 441-42854-002 0026 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 1 LEFT WING FUEL QUANTITY PROBE 765551-1-0 765551IN00147 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 1 RIGHT WING FUEL QUANTITY PROBE 765826-1-0 765826IN00174 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 2 LEFT WING FUEL QUANTITY PROBE 765548-1-0 765548IN00135 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 2 RIGHT WING FUEL QUANTITY PROBE 765827-1-0 765827IN00173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 3 LEFT WING FUEL QUANTITY PROBE 765549-1-0 765549IN00201 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 3 RIGHT WING FUEL QUANTITY PROBE 765549-1-0 765549IN00209 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 4 LEFT WING FUEL QUANTITY PROBE 765550-1-0 765550IN00169 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-41-01	NO. 4 RIGHT WING FUEL QUANTITY PROBE 765550-1-0 765550IN00177 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05	ELECTRONIC FUEL CONTROL UNIT 738667-2-6 738790IN00145 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-43-01	FUEL TEMPERATURE SENSOR 798840-1-0 01744 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 28-43-01-001 (s)	FUNCTIONAL CHECK FUEL TEMPERATURE SENSOR 798840-1-0 PKG 50 01744 REF: AMM 28-43-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
28-45-01	NO.1 FUEL LOW PRESSURE SWITCH D98C07-611 0107 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
28-45-01	NO.2 FUEL LOW PRESSURE SWITCH D98C07-611 0108 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 29 HYDRAULIC POWER									
+ 29-00-00-001 (s)	VISUAL CHECK HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR (DPI) PN PKG 2 SN-UNKNOWN REF: AMM 29-31-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
29-11-01	HYDRAULIC POWERPACK 3032683-002 MX735585 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-SEP-2012 436.8 326		
+ 29-11-01-001	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK 3032683-002 MX735585 REF: AMM 29-11-01	MOS HRS/MSC AFL	1200	+30/-30			25-JUL-2009 0 0	1200	1230

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-11-01-002	RESTORATION (OVERHAUL) OF THE HYDRAULIC POWERPACK 3032683-002 MX735585 REF: AMM 29-11-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
29-11-09	HYDRAULIC POWERPACK TEMPERATURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 29-11-09-001 (s)	FUNCTIONAL CHECK HYDRAULIC POWERPACK TEMPERATURE SWITCH PN PKG 50 SN-UNKNOWN REF: AMM 29-11-09	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
29-15-01	LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
29-15-01	LH WING - GROUND SPOILER ACTUATOR RETURN HOSE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
29-15-01	RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
29-15-01	RH WING - GROUND SPOILER ACTUATOR RETURN HOSE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 29-15-01-001	DISCARD LH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE PN SN-UNKNOWN REF: AMM 29-15-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-15-01-001	DISCARD LH WING - GROUND SPOILER ACTUATOR RETURN HOSE PN SN-UNKNOWN REF: AMM 29-15-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
+ 29-15-01-001	DISCARD RH WING - GROUND SPOILER ACTUATOR PRESSURE HOSE PN SN-UNKNOWN REF: AMM 29-15-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
+ 29-15-01-001	DISCARD RH WING - GROUND SPOILER ACTUATOR RETURN HOSE PN SN-UNKNOWN REF: AMM 29-15-01	MOS HRS/MSC AFL	N/A				25-JUL-2009 0 0		
29-15-03	HYDRAULIC ACCUMULATOR MS28797-3 8423-12215 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
29-20-01	POWERPACK VENTILATION FAN SF9202D00 L00119 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 29-20-01-001 (s)	OPERATIONAL CHECK POWERPACK VENTILATION FAN SF9202D00 PKG 1 L00119 REF: AMM 29-20-01	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
29-31-02	HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 30	ICE AND RAIN PROTECTION								
30-01-01	ICE PROTECTION/HEATING SYSTEM CONTROL PANEL 441-43199-001 0031 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-10-00-001 (s)	OPERATIONAL CHECK OF PNEUMATIC DE-ICING SYSTEM PKG 2	MOS	12	+30d/-30d			PKG		
	REF: AMM 30-10-00	HRS/MSC AFL	600	+30/-30			25-JUL-2019 1121.6 860		
30-11-01	DE-ICING SYSTEM CONTROLLER 4D2037-24 U0073 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
30-11-02	NO.1 REAR FUSELAGE CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
30-11-02	NO.2 REAR FUSELAGE CHECK VALVE 3D3555-01 N085016 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
30-11-03	REAR FUS PRESSURE REGULATOR/RELIEVER VALVE 4D2095-2011 N093586 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-FEB-2011 119.7 68		
+ 30-11-03-001 (s)	CLEANING REAR FUS PRESSURE REGULATOR/RELIEVER VALVE 4D2095-2011 PKG 50 N093586 REF: AMM 30-11-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
30-11-04	WATER SEPARATOR 44E13-5A N132116 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-NOV-2013 579.4 438		
+ 30-11-04-001 (s)	CLEANING WATER SEPARATOR 44E13-5A PKG 50 N132116 REF: AMM 30-11-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 08-NOV-2013 579.4 438		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-05	REAR FUS LOW PRESSURE SWITCH 3D3552-02 0087 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 30-11-05-001 (s)	FUNCTIONAL CHECK REAR FUS LOW PRESSURE SWITCH 3D3552-02 PKG 50 0087 REF: AMM 30-11-05	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
30-13-01	INBOARD WING FLOW CONTROL VALVE 3D2376-07 N084924 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-13-01	OUTBOARD WING FLOW CONTROL VALVE 3D2376-07 N084923 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-13-02	NO.1 L/H WING DE ICE PRESSURE SWITCH 3D3533-04 0181 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-13-02	NO.1 R/H WING DE ICE PRESSURE SWITCH 3D3533-04 0147 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-13-02	NO.2 L/H WING DE ICE PRESSURE SWITCH 3D3533-04 0183 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-13-02	NO.2 R/H WING DE ICE PRESSURE SWITCH 3D3533-04 0171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-13-02-001 (s)	FUNCTIONAL CHECK NO.1 L/H WING DE ICE PRESSURE SWITCH 3D3533-04 PKG 50 0181 REF: AMM 30-13-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 30-13-02-001 (s)	FUNCTIONAL CHECK NO.1 R/H WING DE ICE PRESSURE SWITCH 3D3533-04 PKG 50 0147 REF: AMM 30-13-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 30-13-02-001 (s)	FUNCTIONAL CHECK NO.2 L/H WING DE ICE PRESSURE SWITCH 3D3533-04 PKG 50 0183 REF: AMM 30-13-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 30-13-02-001 (s)	FUNCTIONAL CHECK NO.2 R/H WING DE ICE PRESSURE SWITCH 3D3533-04 PKG 50 0171 REF: AMM 30-13-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
30-13-03	LH WING DE-ICER BOOT PS29S4D5321-19 MBLT130 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
30-13-03	RH WING DE-ICER BOOT PS29S4D5321-20 MBHC550 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 30-13-03-001 (s)	GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT PS29S4D5321-19 PKG 2 MBLT130 REF: AMM 30-13-03	MOS HRS/MSC AFL	12	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 30-13-03-001 (s)	GENERAL VISUAL INSPECTION RH WING DE-ICER BOOT PS29S4D5321-20 PKG 2 MBHC550 REF: AMM 30-13-03	MOS HRS/MSC AFL	12	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-15-01	REAR FUS FLOW CONTROL VALVE 3D2376-07 N084757 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-15-02	REAR FUS DE ICE PRESSURE SWITCH 3D3533-04 0131 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 30-15-02-001 (s)	FUNCTIONAL CHECK REAR FUS DE ICE PRESSURE SWITCH 3D3533-04 PKG 50 0131 REF: See Workcard	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
30-15-03	LH TAIL DE-ICER BOOT PS29S4D5321-21 MBAT280 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
30-15-03	RH TAIL DE-ICER BOOT PS29S4D5321-22 MAZY110 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 30-15-03-001 (s)	GENERAL VISUAL INSPECTION LH TAIL DE-ICER BOOT PS29S4D5321-21 PKG 2 MBAT280 REF: AMM 30-15-03	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 30-15-03-001 (s)	GENERAL VISUAL INSPECTION RH TAIL DE-ICER BOOT PS29S4D5321-22 PKG 2 MAZY110 REF: AMM 30-15-03	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
30-21-01	LEFT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE 5727-00-5 0706A REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:25 TSN:565 TSO:0 TSN:492 TSO:0			21-MAR-2019 1095.9		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-21-01	RIGHT ENGINE ANTI-ICE SYSTEM SHUTOFF VALVE 5727-00-5 0662A REF: See Workcard	MOS HRS/MSC AFL	O/C				06-MAR-2019 1087.3 840		
30-21-02	LH ENG ANTI-ICE PRESSURE TRANSDUCER APTE-473A-1000-50G 7367-6-249 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
30-21-02	RH ENG ANTI-ICE PRESSURE TRANSDUCER APTE-473A-1000-50G 8404-5-420 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		06-MAR-2019 1087.3 840		
+ 30-21-02-001 (s)	FUNCTIONAL CHECK LH ENG ANTI-ICE PRESSURE TRANSDUCER APTE-473A-1000-50G PKG 66 7367-6-249 REF: AMM 30-21-02	MOS HRS/MSC AFL	120	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 30-21-02-001 (s)	FUNCTIONAL CHECK RH ENG ANTI-ICE PRESSURE TRANSDUCER APTE-473A-1000-50G PKG 66 8404-5-420 REF: AMM 30-21-02	MOS HRS/MSC AFL	120	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE PKG 50 REF: AMM 30-21-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 30-21-04-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE ANTI-ICE DUCTS PKG 20 REF: AMM 30-21-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 25-JUL-2009 0 0		
+ 30-31-00-001 (s)	OPERATIONAL CHECK OF PITOT, STATIC, AOA AND P-STATIC HEATING PKG 81 REF: AMM 30-30-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-31-01	AIR DATA PROBES HEATER CURRENT MONITOR- C-100131-1 135 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C				06-DEC-2018 1071 829		
30-41-01-002 (s)	DISCARD OF WINDSHIELD RAIN REPELLENT COATING PKG 80 REF: AMM 30-41-01	MOS HRS/MSC AFL	12	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
30-42-01	LH WINDSHIELD HEATER CONTROL UNIT EMP-112-3 01452 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-SEP-2012 436.8 326		
30-42-01	RH WINDSHIELD HEATER CONTROL UNIT EMP-112-3 01567 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-SEP-2012 436.8 326		
30-81-01	CREW CABIN LIGHT ICING INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
+ 31-31-00-002 (s)	OPERATIONAL CHECK OF COCKPIT VOICE AND DATA RECORDER SYSTEM 2100-3083-50 PKG 80 000574351 REF: AMM 31-31-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-01	CVR - COCKPIT VOICE RECORDER 2100-3083-50 000574351 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-31-03	CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY DK120/90 AT130315 REF: See Workcard	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			29-MAR-2019 1096 846		
+ 31-31-03-001	DISCARD CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY DK120/90 AT130315 REF: AMM 31-31-03	MOS HRS/MSC AFL	DUE				29-MAR-2019 1096 846	01-MAR-2026 M	
31-31-04	IMPACT SWITCH 5930-4-000 4462 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-31-09	CVDR INSC ILLUM PANEL 441-42635-002 0040 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-31-13	CVDR/UNDERWATER LOCATOR BEACON PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-01	GSD 41 DATA CONCENTRATOR UNIT 011-01457-00 16905016 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-03	NO.1 ENGINE/AIRFRAME INTERFACE UNIT 011-00831-00 46709240 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-41-03	NO.2 ENGINE/AIRFRAME INTERFACE UNIT 011-00831-00 46709269 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-03	NO.3 ENGINE/AIRFRAME INTERFACE UNIT 011-00831-00 46709270 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-05	NO.1 GIA63W INTEGRATED AVIONICS UNIT 011-01105-01 15W007568 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-05	NO.2 GIA63W INTEGRATED AVIONICS UNIT 011-01105-01 15W007570 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-06	NO.1 AMLCD (GDU1240A, 12IN) DISPLAY UNIT 011-01440-10 18T000628 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-06	NO.2 AMLCD (GDU1240A, 12IN) DISPLAY UNIT 011-01440-10 18T000627 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
31-41-06	NO.3 AMLCD (GDU1240A, 12IN) DISPLAY UNIT 011-01440-10 18T000618 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 50 REF: AMM 31-42-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-42-01	MAINTENANCE CONTROL PANEL 441-40947-001 0030 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			25-JUL-2009 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			25-JUL-2009 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			25-JUL-2009 0 0		
CHAPTER 32 LANDING GEAR									
+ 32-00-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	600	+30/-30			11-NOV-2016 766.6 621		
32-000	LEFT MAIN GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
32-000	RIGHT MAIN GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
+ 32-001	LEFT MAIN GEAR SHOCK STRUT - MAIN FITTING 2310-2206-501 1258393/001 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-002	RIGHT MAIN GEAR SHOCK STRUT - MAIN FITTING 2310-2206-502 1277849/001 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-005	NO.1 LEFT MAIN GEAR PINTLE PIN 2310-2107-001 1244637/019 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-005	NO.1 RIGHT MAIN GEAR PINTLE PIN 2310-2107-001 1244637/010 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-005	NO.2 LEFT MAIN GEAR PINTLE PIN 2310-2107-001 1244637/014 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-005	NO.2 RIGHT MAIN GEAR PINTLE PIN 2310-2107-001 1244637/016 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-006	LEFT MAIN GEAR UPPER AXLE 2310-2104-001 1244638/019 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-006	RIGHT MAIN GEAR UPPER AXLE 2310-2104-001 1244638/013 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-007	LEFT MAIN GEAR LOWER AXLE 2310-2108-003 1231734-003 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-007	RIGHT MAIN GEAR LOWER AXLE 2310-2108-003 1255998/019 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-008	LEFT MAIN GEAR JACKING PIN 2310-2109-001 1249574/017 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-008	RIGHT MAIN GEAR JACKING PIN 2310-2109-001 1258423/010 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-009	LEFT MAIN GEAR PIN 2310-2103-001 1236980/005 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-009	RIGHT MAIN GEAR PIN 2310-2103-001 1236980/007 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-010	LEFT MAIN GEAR PIN 2310-2113-003 1263728/005 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-010	RIGHT MAIN GEAR PIN 2310-2113-003 1263728/010 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
32-100	LEFT MAIN GEAR TRAILING ARM ASSEMBLY 2310-3000-401 00045 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-100	RIGHT MAIN GEAR TRAILING ARM ASSEMBLY 2310-3000-402 00044 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		
+ 32-101	LEFT MAIN GEAR TRAILING ARM AXLE 2310-2102-001 1232895/014 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-101	RIGHT MAIN GEAR TRAILING ARM AXLE 2310-2102-001 1232895/012 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-102	LEFT MAIN GEAR TRAILING ARM 2310-3002-501 1255981/002 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-103	RIGHT MAIN GEAR TRAILING ARM 2310-3002-502 1247344/004 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-106	LEFT MAIN GEAR TRAILING ARM WHEEL AXLE 2310-3010-001 1252319/008 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-106	RIGHT MAIN GEAR TRAILING ARM WHEEL AXLE 2310-3010-001 1252319/005 REF: See Workcard	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
+ 32-11-00-001 (s)	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-00-001 (s)	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 32-11-00-002	RESTORE (OVERHAUL) LEFT MAIN GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			25-JUL-2019 1121.6 860	25-JUL-2029	24-AUG-2029 12890
OVERHAUL								12860	
+ 32-11-00-002	RESTORE (OVERHAUL) RIGHT MAIN GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			25-JUL-2019 1121.6 860	25-JUL-2029	24-AUG-2029 12890
OVERHAUL								12860	
+ 32-11-00-003 (s)	LUBRICATION LEFT MAIN GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 32-11-00-003 (s)	LUBRICATION RIGHT MAIN GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
32-11-01	LEFT MAIN GEAR SHOCK STRUT 2310-2000-403 00053 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0	25-JUL-2019 1121.6 860	
32-11-01	RIGHT MAIN GEAR SHOCK STRUT 2310-2000-404 00047 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0	25-JUL-2019 1121.6 860	
+ 32-11-03-004 (s)	SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY 2310-4000-407 PKG 2 00187 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-03-004 (s)	SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY 2310-4000-407 PKG 2 00199 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
32-200	LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY 2310-4000-407 00187 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
32-200	RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY 2310-4000-407 00199 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
+ 32-201	LEFT MAIN GEAR SHOCK ABSORBER CYLINDER 2310-4102-001 1578897/003 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:0 TSN:0 TSN:0			25-JUL-2019 1121.6 860	4360	
+ 32-201	RIGHT MAIN GEAR SHOCK ABSORBER CYLINDER 2310-4102-501 1262143/004 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	3500	
+ 32-204	LEFT MAIN GEAR SHOCK ABSORBER SLIDING TUBE 2310-4201-003 1590076/002 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:0 TSN:0 TSN:0			25-JUL-2019 1121.6 860	4360	
+ 32-204	RIGHT MAIN GEAR SHOCK ABSORBER SLIDING TUBE 2310-4201-003 1621991/002 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:0 TSN:0 TSN:0			25-JUL-2019 1121.6 860	4360	
+ 32-206	LEFT MAIN GEAR SHOCK ABSORBER BEARING 2310-4006-007 1275537/017 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	3500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-206	RIGHT MAIN GEAR SHOCK ABSORBER BEARING 2310-4006-007 1278450/004 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-207	LEFT MAIN GEAR SHOCK ABSORBER BEARING CAP 2310-4014-001 1275135/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-207	RIGHT MAIN GEAR SHOCK ABSORBER BEARING CAP 2310-4014-001 1236992/008 REF: GENERIC NO REF	MOS HRS/MSC AFL	3500	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		3500
LIFE LIMIT									
+ 32-21-00-001 (s)	GENERAL VISUAL INSPECTION NOSE LANDING GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 32-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 32-21-00-002	RESTORE (OVERHAUL) NOSE LANDING GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 32-21-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			25-JUL-2019 1121.6 860	25-JUL-2029 12860	24-AUG-2029 12890
OVERHAUL									
+ 32-21-00-003 (s)	LUBRICATION NOSE LANDING GEAR ASSEMBLY PN-UNKNOWN PKG 2 SN-UNKNOWN REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
32-21-01	NOSE LANDING GEAR SHOCK STRUT 2310-1000-403 00047 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
32-21-02	NOSE LANDING GEAR RETRACT ACTUATOR ASSEMBLY 2135-1000-403 00053 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-03	NOSE LANDING GEAR DOWNLOCK RELEASE ACTUATOR ASSEMBLY 2137-1000-401 00053 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 32-21-05-004 (s)	SERVICING NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER 2310-1100-403 PKG 2 00049 REF: AMM 12-14-03	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 32-21-06-005 (s)	VISUAL CHECK NOSE LANDING GEAR SHIMMY DAMPER 2310-1500-403 PKG 2 00054 REF: AMM 12-14-04	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
32-300	LEFT MAIN GEAR LOCKING ACTUATOR ASSEMBLY 2136-1000-405 00873 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			25-JUL-2019 1121.6 860		
32-300	RIGHT MAIN GEAR LOCKING ACTUATOR ASSEMBLY 2136-1000-405 00874 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			25-JUL-2019 1121.6 860		
+ 32-301	LEFT MAIN GEAR LOCKING ACTUATOR CYLINDER 2136-1013-503 1650348/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
+ 32-301	RIGHT MAIN GEAR LOCKING ACTUATOR CYLINDER 2136-1013-503 1644629/003 REF: GENERIC NO REF	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
+ 32-304	LEFT MAIN GEAR LOCKING ACTUATOR PISTON 2136-1035-003 1644477/003 REF: GENERIC NO REF	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-304	RIGHT MAIN GEAR LOCKING ACTUATOR PISTON 2136-1035-003 1644477/005	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-305	LEFT MAIN GEAR LOCKING ACTUATOR FINGER 2136-1052-901 20007	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-305	RIGHT MAIN GEAR LOCKING ACTUATOR FINGER 2136-1052-901 20019	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-306	LEFT MAIN GEAR LOCKING ACTUATOR ROD 2136-1020-001 1653930/001	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-306	RIGHT MAIN GEAR LOCKING ACTUATOR ROD 2136-1020-001 1653930/002	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-307	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON 2136-1046-009 1640882/003	MOS HRS/MSC AFL	19500	TSN:0 TSN:0			25-JUL-2019 1121.6 860		20360
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-307	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING PISTON 2136-1046-009 1640882/001	MOS HRS/MSC AFL	19500	TSN:0 TSN:0			25-JUL-2019 1121.6 860		20360
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-309	LEFT MAIN GEAR LOCKING ACTUATOR PIN 2136-1049-001 1652339/013	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-309	RIGHT MAIN GEAR LOCKING ACTUATOR PIN 2136-1049-001 1652339/007	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
32-31-01	LANDING GEAR CONTROL LEVER PANEL 827101-5 1052	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
REF: See Workcard									
32-31-02	LANDING GEAR HYDRAULIC SYSTEM (MANIFOLD) ASSEMBLY 72375-3 0133	MOS HRS/MSC AFL	O/C				11-NOV-2016 766.6 621		
REF: See Workcard									
+ 32-310	LEFT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE 2136-1036-003 85172	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-310	RIGHT MAIN GEAR LOCKING ACTUATOR LOCKING SLEEVE 2136-1036-003 85175	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-311	LEFT MAIN GEAR LOCKING ACTUATOR CAP BEARING 2136-1005-003 1651786/002	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-311	RIGHT MAIN GEAR LOCKING ACTUATOR CAP BEARING 2136-1005-003 1651786/004	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-312	LEFT MAIN GEAR LOCKING ACTUATOR NUT 2136-1042-003 1622614/016	MOS HRS/MSC AFL	21000	TSN:0 TSN:0			25-JUL-2019 1121.6 860		21860
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-312	RIGHT MAIN GEAR LOCKING ACTUATOR NUT 2136-1042-003 1622614/011	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
LIFE LIMIT	REF: GENERIC NO REF		21000	TSN:0 TSN:0					21860
+ 32-313	LEFT MAIN GEAR LOCKING ACTUATOR STOP 2136-1008-003 1644368/002	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
LIFE LIMIT	REF: GENERIC NO REF		21000	TSN:0 TSN:0					21860
+ 32-313	RIGHT MAIN GEAR LOCKING ACTUATOR STOP 2136-1008-003 1644368/003	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
LIFE LIMIT	REF: GENERIC NO REF		21000	TSN:0 TSN:0					21860
+ 32-314	LEFT MAIN GEAR LOCKING ACTUATOR ROD END MEK12EL 00722	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
LIFE LIMIT	REF: GENERIC NO REF		21000	TSN:0 TSN:0					21860
+ 32-314	RIGHT MAIN GEAR LOCKING ACTUATOR ROD END MEK12EL 00710	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
LIFE LIMIT	REF: GENERIC NO REF		21000	TSN:0 TSN:0					21860
+ 32-35-00-001 (s)	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM PKG 81	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 32-35-00								
+ 32-35-00-002 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 32-35-00								
32-400	NOSE LANDING GEAR ASSEMBLY PN-UNKNOWN SN-UNKNOWN	MOS HRS/MSC AFL					25-JUL-2019 1121.6 860		
	REF: GENERIC NO REF		O/C	TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0					

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-401	LEFT SIDE NLG SIDE PINTLE PIN 2310-1137-003 1247507/002	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-401	RIGHT SIDE NLG SIDE PINTLE PIN 2310-1137-003 1247507/007	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-402	NOSE LANDING GEAR MAIN FITTING 2310-1204-501 1249658-001	MOS HRS/MSC AFL	28200	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		28200
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-404 (1)	NOSE LANDING GEAR TORQUE LINK 2310-1124-501 1257043/016	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: See Workcard								
+ 32-404 (2)	NOSE LANDING GEAR TORQUE LINK 2310-1124-501 1262137/012	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: See Workcard								
+ 32-406	NOSE LANDING GEAR SHOCK STRUT PIN 2310-1407-001 1256014/009	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: See Workcard								
+ 32-407	NOSE LANDING GEAR AXLE 2310-1165-001 1263620/007	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT	REF: GENERIC NO REF								
+ 32-408	NOSE LANDING GEAR STEERING BELLCRANK 2310-1131-001 1247178/003	MOS HRS/MSC AFL	10800	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		10800
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-409	NOSE LANDING GEAR SHIMMY DAMPER 2310-1500-403 00054 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
+ 32-41-00	BRAKE SYSTEM ACCUMULATOR 0860231003 60231-2102 REF: See Workcard	MOS HRS/MSC AFL	700	TSN:0			26-SEP-2011 253 186	886	
LIFE LIMIT									
32-41-01	DIGITAL BRAKE CONTROL UNIT 90005034-7 FEB11-1262 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2019 1121.6 860		
32-41-02	LH BRAKE PEDAL TRANSDUCER Q3008 823242 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-41-02	RH BRAKE PEDAL TRANSDUCER Q3008 823241 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER Q3008 PKG 53 823242 REF: AMM 32-41-02	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 15-JUN-2017 839.2 687		
+ 32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER Q3008 PKG 53 823241 REF: AMM 32-41-02	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 15-JUN-2017 839.2 687		
+ 32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER Q3008 PKG 2 823242 REF: AMM 32-41-02	MOS HRS/MSC AFL	N/A				PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER Q3008 PKG 2 823241 REF: AMM 32-41-02	MOS HRS/MSC AFL	N/A				PKG 25-JUL-2019 1121.6 860		
32-41-03	MAIN BRAKE SHUT-OFF VALVE 90005027 NOV08-0077 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-41-04	LH BRAKE CONTROL VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				26-SEP-2011 253 186		
32-41-04	RH BRAKE CONTROL VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				26-SEP-2011 253 186		
32-41-05	LH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER 90005191-1 AUG08-0098 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-41-05	RH MAIN BRAKE SYSTEM PRESSURE TRANSDUCER 90005191-1 AUG08-0103 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-41-06	LEFT MAIN GEAR WHEEL SPEED TRANSDUCER 90005036 OCT08-0112 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-41-06	RIGHT MAIN GEAR WHEEL SPEED TRANSDUCER 90005036 OCT08-0116 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-41-11-001 (s)	FUNCTIONAL CHECK OF BRAKE HYDRAULIC ACCUMULATOR PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 19-FEB-2014		
	REF: AMM 32-41-11								
+ 32-410	NOSE LANDING GEAR WHEEL AXLE 2317-5101-001 1257061/010	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-411	NOSE LANDING GEAR LOCK PIN 57675-1 00091	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-412	NOSE LANDING GEAR AXLE BOLT 2310-1144-005 1263779/010	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-413	NOSE LANDING GEAR BOLT 2310-1172-003 1249612/010	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-414	NOSE LANDING GEAR PIN 2310-1173-001 1237005/007	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-415	NOSE LANDING GEAR BOLT 2310-1183-001 1242098/011	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
	REF: GENERIC NO REF								
+ 32-43-00-001	FUNCTIONAL CHECK OF EMERGENCY/PARKING BRAKE SYSTEM	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30	-30		19-DEC-2017 954.6 746	19-NOV-2019 2154.6	19-DEC-2019 2184.6
	REF: See Workcard								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM PKG 12 REF: AMM 32-43-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
32-43-02	EMERGENCY/PARKING BRAKE VALVE 11056-5 0345 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			08-NOV-2013 579.4 438		
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR 0860231003 60231-2173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:24 TSO:0 TSO:0			08-NOV-2013 579.4 438		
32-43-05	EMERGENCY/PARKING BRAKE PRESSURE SWITCH 15H0126PH 0045 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-43-06	EMERGENCY/PARKING BRAKE PRESSURE- TRANSDUCER APT-218A-1000-3000A 7428-4-121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-43-11	EMERGENCY/PARKING BRAKE SHUT OFF VALVE 2216-0001-401 00031 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 32-43-11-001	OPERATIONAL CHECK EMERGENCY/PARKING BRAKE SHUT OFF VALVE 2216-0001-401 00031 AIRWORTHINESS REF: AMM 32-43-11	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			25-JUL-2019 1121.6 860	25-JUL-2020 1721.6	24-AUG-2020 1751.6
32-45-01	LH MLG 21X6.5-10 12PR TIRE 215K26-2 80282191 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-DEC-2018 1071 829		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-01	RH MLG 21X6.5-10 12PR TIRE 215K26-2 80222182 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-DEC-2018 1071 829		
32-45-01-001	RESTORATION (OVERHAUL) OF LH MLG WHEEL ASSEMBLY 500-19026-605 FEB09-0187 REF: See Workcard	MOS HRS/MSC AFL	T/C 1500				06-DEC-2018 1071 829	2329	
32-45-01-001	RESTORATION (OVERHAUL) OF RH MLG WHEEL ASSEMBLY 500-19026-605 JUN09-0311 REF: See Workcard	MOS HRS/MSC AFL	T/C 1500				06-DEC-2018 1071 829	2329	
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LH MLG WHEEL ASSEMBLY 500-19026-605 FEB09-0187 REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				06-DEC-2018 1071 829		
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RH MLG WHEEL ASSEMBLY 500-19026-605 JUN09-0311 REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				06-DEC-2018 1071 829		
32-45-02	LH MLG 21X6.5-10, AL WHEEL 90005024 FEB09-0187 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			06-DEC-2018 1071 829		
32-45-02	RH MLG 21X6.5-10, AL WHEEL 90005024 JUN09-0311 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			06-DEC-2018 1071 829		
32-45-03	LH MLG WHEEL ASSEMBLY 500-19026-605 FEB09-0187 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			06-DEC-2018 1071 829		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-03	RH MLG WHEEL ASSEMBLY 500-19026-605 JUN09-0311 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			06-DEC-2018 1071 829		
32-45-10	NLG 15X6.0-6 10PR TIRE PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				11-NOV-2016 766.6 621		
32-45-11	NLG WHEEL ASSEMBLY 500-19001-601 DEC10-0398 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			11-NOV-2016 766.6 621		
32-45-11-001	RESTORATION (OVERHAUL) OF NLG WHEEL ASSEMBLY 500-19001-601 DEC10-0398 REF: See Workcard	MOS HRS/MSC AFL	T/C 1500				11-NOV-2016 766.6 621	2121	
32-45-11-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NLG WHEEL ASSEMBLY 500-19001-601 DEC10-0398 REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				11-NOV-2016 766.6 621		
32-45-12	NLG 15X6.0-6, AL WHEEL 90005023-1 DEC10-0398 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			11-NOV-2016 766.6 621		
32-45-21	LH MLG STEEL BRAKE ASSEMBLY 90005025 JUN09-0285 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			06-DEC-2018 1071 829		
32-45-21	RH MLG STEEL BRAKE ASSEMBLY 90005025-3 AUG08-0062 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:7 TSO:0 TSO:0			08-NOV-2013 579.4 438		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-21-20	LH MLG SHUTTLE VALVE 90005154-1 1040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
32-45-21-20	RH MLG SHUTTLE VALVE 90005154-1 1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-OCT-2010 24.1 13		
32-500	NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER 2310-1100-403 00049 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		
+ 32-501	NOSE LANDING GEAR SHOCK ABSORBER PISTON TUBE 2310-1225-003 1262116/002 REF: GENERIC NO REF	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
+ 32-502	NOSE LANDING GEAR SHOCK ABSORBER BEARING 2310-1221-009 1220063/007 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
+ 32-504	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER 2310-1241-501 1257482/002 REF: GENERIC NO REF	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
+ 32-506	NOSE LANDING GEAR SHOCK ABSORBER FORK 2310-1308-501 1264870/002 REF: GENERIC NO REF	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
32-600	NLG DRAG BRACE ASSEMBLY 2310-1400-403 00005 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-601	NOSE LANDING GEAR UPPER DRAG BRACE 2310-1421-001 1148290/001 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
+ 32-603	NOSE LANDING GEAR LOWER DRAG BRACE 2310-1451-005 1215492/003 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
+ 32-605	LEFT SIDE NLG DRAG BRACE PINTLE PIN 2310-1415-003 1228789/003 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
+ 32-605	RIGHT SIDE NLG DRAG BRACE PINTLE PIN 2310-1415-003 1228789/005 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
+ 32-606	NOSE LANDING GEAR DRAG BRACE PIN 2310-1407-001 1128680/003 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860	35000	
LIFE LIMIT									
32-61-01	LH MLG PROXIMITY SWITCH 80-057-01 19652 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 18906 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-61-01	NO. 2 NLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	RH MLG PROXIMITY SWITCH 80-057-01 19655 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-61-02	LH MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-61-02	RH MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
32-700	NLG LOCKING STAY ASSEMBLY 2310-1700-403 00044 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:120 TSO:0 TSN:1121.6 TSO:0 TSN:860 TSO:0			25-JUL-2019 1121.6 860		
+ 32-701	LOWER NLG LOCKING STAY 2310-1712-501 1251113/005 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
+ 32-703	UPPER NLG LOCKING STAY 2310-1722-501 1277895/008 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			25-JUL-2019 1121.6 860		35860
LIFE LIMIT									
+ 32-706	LOWER NLG LOCKING STAY BOLT 2310-1734-001 1257060/017 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									
+ 32-706	UPPER NLG LOCKING STAY BOLT 2310-1734-001 1257060/018 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:120 TSN:1121.6 TSN:860			25-JUL-2019 1121.6 860		35000
LIFE LIMIT									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 84	MOS	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-47-00	HRS/MSC AFL							
CHAPTER 33	LIGHTS								
33-01-01	UPPER COCKPIT LIGHTING SYSTEM CONTROL PANEL 441-40941-002	MOS		TSN:0			25-JUL-2009		
	0042	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
33-12-01	FORWARD FUSELAGE BOTTOM DIMMER 81-01760-002	MOS		TSN:0			25-JUL-2009		
	0064	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
33-12-02	MAIN TEST ANUNCIATOR/FIRE PANEL ASSEMBLY 441-43213-001	MOS		TSN:0			25-JUL-2009		
	0061	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
33-21-05	PASSENGER-CABIN LED LIGHT DIMMER AS-33-0038-001	MOS		TSN:0			25-JUL-2009		
	0059	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
33-31-02	W001 ELECTRICAL NOSE HARNESS PN	MOS		TSN:0			25-JUL-2009		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
33-41-01	LEFT LANDING/TAXI LIGHT 81012-3	MOS		TSN:0			25-JUL-2009		
	000100	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
33-41-01	RIGHT LANDING/TAXI LIGHT 81012-4	MOS		TSN:0			25-JUL-2009		
	000120	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		

Status Report

EMB-500 - PHENOM 100 S/N 5000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-43-01	LH WING NAVIGATION/STROBE LIGHTS 84016-1 000037 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
33-43-01	RH WING NAVIGATION/STROBE LIGHTS 84016-2 000038 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 33-43-01-001 (s)	DISCARD LH WING NAVIGATION/STROBE LIGHTS 84016-1 PKG 60 000037 REF: AMM 33-43-01	MOS HRS/MSC AFL	7800	+30/-30			PKG 25-JUL-2009 0 0		
+ 33-43-01-001 (s)	DISCARD RH WING NAVIGATION/STROBE LIGHTS 84016-2 PKG 60 000038 REF: AMM 33-43-01	MOS HRS/MSC AFL	7800	+30/-30			PKG 25-JUL-2009 0 0		
+ 33-43-01-002 (s)	GENERAL VISUAL INSPECTION OF LH WING NAVIGATION/STROBE LIGHTS 84016-1 PKG 20 000037 REF: AMM 33-43-01	MOS HRS/MSC AFL	1800	+30/-30			PKG 25-JUL-2009 0 0		
+ 33-43-01-002 (s)	GENERAL VISUAL INSPECTION OF RH WING NAVIGATION/STROBE LIGHTS 84016-2 PKG 20 000038 REF: AMM 33-43-01	MOS HRS/MSC AFL	1800	+30/-30			PKG 25-JUL-2009 0 0		
332503-7101	L/H REAR FACING PAX SEAT READ/TABLE (PCU) PASSENGER CONTROL UNIT AS-33-0072-001 1236 REF:	MOS HRS/MSC AFL	O/C				11-NOV-2016 766.6 621		
CHAPTER 34 NAVIGATION									
+ 34-11-00-001	FUNCTIONAL CHECK INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT C16221ANA01 C16221017153 REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2021	24-AUG-2021

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-01	INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT C16221ANA01 C16221017153 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-OCT-2015 697.4 559		
34-11-02	PITOT-STATIC PROBE 101469-4-003 875452 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:2 TSN:0 TSN:0		26-SEP-2011 253 186		
+ 34-11-02-001	RESTORATION PITOT-STATIC PROBE (CLEANING) 101469-4-003 875452 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2021	24-AUG-2021
+ 34-15-00-001	FUNCTIONAL CHECK (CALIBRATION) OF AIR DATA SYSTEM REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+1m/-1m			25-JUL-2019 1121.6 860	25-JUL-2021	25-AUG-2021
+ 34-15-00-002 (s)	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 34-15-00-003	SPECIAL DETAILED INSPECTION OF STATIC PORT SURROUNDING PLATE FOR FLUSHNESS PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+1m/-1m			25-JUL-2019 1121.6 860	25-JUL-2021	25-AUG-2021
34-15-01	NO. 1 GDC 74B AIR DATA COMPUTER UNIT 011-01110-00 43805107 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-OCT-2015 697.4 559		
34-15-01	NO. 2 GDC 74B AIR DATA COMPUTER UNIT 011-01110-00 43805222 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-OCT-2015 697.4 559		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-15-03	LH FWD PITOT TUBE 0851LW 312262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:22 TSN:0 TSN:0			19-DEC-2017 954.6 746		
34-15-03	RH FWD PITOT TUBE 0851LW 311992 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			19-DEC-2017 954.6 746		
+ 34-15-03-001 (s)	RESTORATION OF PITOT PROBE (CLEANING) PKG 81 REF: AMM 34-15-03	MOS HRS/MSC AFL	24	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
34-15-05	LH FWD DUAL STATIC PORT 100442-106 803303 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			26-SEP-2011 253 186		
34-15-05	RH FWD DUAL STATIC PORT 100442-107 818991 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			26-SEP-2011 253 186		
34-21-01	LH ATTITUDE AND HEADING REFERENCE UNIT 011-00868-10 42010478 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-21-01	RH ATTITUDE AND HEADING REFERENCE UNIT 011-00868-10 42010493 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-21-02	LH WING MAGNETOMETER 011-00870-00 47512287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-02	RH WING MAGNETOMETER 011-00870-00 47512292 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 34-23-00-001	FUNCTIONAL CHECK MAGNETIC COMPASS KCA0120W BB6120908 REF: AMM 34-23-00	MOS HRS/MSC AFL	24	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2021	24-AUG-2021
34-23-01	MAGNETIC COMPASS KCA0120W BB6120908 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-31-01	KRA RADAR ALTIMETER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-31-02	NO. 1 RADIO ALTIMETER ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-31-02	NO. 2 RADIO ALTIMETER ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-32-01	TAIL PHASING COUPLER SSPD-113-10 5289 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-32-03	LEFT VOR/LOC 2&3 ANTENNA BLADE S65-247170 8481 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-32-03	RIGHT VOR/LOC 2&3 ANTENNA BLADE S65-247170 8673 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-32-04	LW FWR MARKER BEACON ANTENNA S35-1000-2 102-7768 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-42-01	WEATHER RADAR ANTENNA 011-00883-20 47203097 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-SEP-2012 436.8 326		
34-43-00	BAGGAGE COMPARTMENT GTS 850 TRAFFIC PROCESSOR UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-43-02	TRC899 TRANSMITTER RECEIVER COMPUTER 805-11900-001 83034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-FEB-2011 119.7 68		
34-43-05	LOWER DIRECTIONAL ANTENNA 805-10003-001-001 82555 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-FEB-2011 119.7 68		
34-43-05	UPPER DIRECTIONAL ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-43-08	LOW NOISE (TCAS) POWER AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-51-01	NO.1 CENTER DISTANCE MEASURING EQUIP UNIT 066-01070-0001 32814 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-51-01	NO.2 CENTER DISTANCE MEASURING EQUIP UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-81658 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-51-02	NO. 2 DME L BAND ANTENNA S65-5366-7L 261-81662 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 34-52-00-001	FUNCTIONAL CHECK LH TRANSPONDER MODULE TRANSPONDER SYSTEM 011-00779-30 89107648 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				16-JUL-2019 1121.6 860	16-JUL-2021	
+ 34-52-00-001	FUNCTIONAL CHECK RH TRANSPONDER MODULE TRANSPONDER SYSTEM 011-00779-21 84805393 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				16-JUL-2019 1121.6 860	16-JUL-2021	
34-52-01	LH TRANSPONDER MODULE 011-00779-30 89107648 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-DEC-2018 1071 829		
34-52-01	RH TRANSPONDER MODULE 011-00779-21 84805393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-DEC-2018 1071 829		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-02	BOTTOM TRANSPONDOR 1 L BAND ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-52-02	TOP TRANSPONDOR 2 L BAND ANTENNA S65-5366-7L 261-81694 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-52-04	COAXIAL SWITCH D2-729B005 552079 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-53-01-01	UMT 12 ADF MOUNTING TRAY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-53-01-02	RADIO PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-53-02	ANT-462A ADF ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-56-02	LH TOP CENTER GPS WAAS - GA 36 ANTENNA 013-00244-00 6189 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-56-02	RH TOP CENTER WAAS & SATELLITE WEATHER AND RADAR ANTENNA 013-00245-00 6226 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-57-01	SATELLITE WEATHER AND RADIO RECIEVER 011-00987-00 47760932 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
34-61-01	FLIGHT MANAGEMENT SYSTEM PANEL 011-01054-10 21805479 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:25 TSR:0 TSR:0			15-DEC-2018 1079 834		
CHAPTER 35 OXYGEN									
+ 35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30		-17	06-DEC-2018 1071 829	19-NOV-2021 2871	19-DEC-2021 2901
AIRWORTHINESS	REF: AMM 35-00-00								
+ 35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION PKG 84 REF: AMM 35-01-02	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
35-01-02	OXYGEN CYLINDER PRESSURE AND TEMPERATURE TRANSDUCER 4441125-000 7467-4-371 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-01-05	OXYGEN SYSTEM LOW PRESSURE SWITCH 4421134-000 0091 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-01-06	LH CSL OXYGEN SYSTEM CONTROL PANEL 441-40945-002 0047 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-01-07	OXYGEN SYSTEM CABIN ALTITUDE SWITCH 4421133-000 0834052 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-09	CENTER FUSELAGE ALTITUDE COMPENSATING REGULATOR 4421135-000 00046 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-01-10	OXYGEN LOW PRESSURE 3 POSITION VALVE 4421132-109 00032 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-02-01	50 CU.FT OXYGEN CYLINDER 4441122-050 471012803 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:15 TSR:0 TSR:0			21-SEP-2018 1020 793		
+ 35-02-01-001	FUNCTIONAL CHECK (HYDROSTATIC TEST) 50 CU.FT OXYGEN CYLINDER 4441122-050 471012803 REF: AMM 35-02-01	MOS HRS/MSC AFL	60				29-JUN-2017	29-JUN-2022	
+ 35-02-01-003	DISCARD 50 CU.FT OXYGEN CYLINDER 4441122-050 471012803 REF: AMM 35-02-01	MOS HRS/MSC AFL	180				01-OCT-2011	01-OCT-2026	
35-02-05	OXYGEN PRESSURE REGULATOR PN-UNKNOWN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-NOV-2013 579.4 438		
+ 35-11-00-001	OPERATIONAL CHECK OF LH CREW OXYGEN MASK AND STOWAGE BOX REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			06-DEC-2018 1071 829	06-DEC-2021 2871	05-JAN-2022 2901
35-11-00-001	OPERATIONAL CHECK OF RH CREW OXYGEN MASK AND STOWAGE BOX REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-17		06-DEC-2018 1071 829	19-NOV-2021 2871	19-DEC-2021 2901

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-01	LH CREW OXYGEN-MASK STOWAGE BOX 1186F6-23 00086 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-11-01	RH CREW OXYGEN-MASK STOWAGE BOX 1186F6-23 00106 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-11-02	LH CREW OXYGEN MASK 174232-93 34553 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:4 TSN:2381 TSR:0 TSN:1524 TSR:0			18-OCT-2017 917 735		
35-11-02	RH CREW OXYGEN MASK 174232-93 26776 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			19-NOV-2015 697.4 559		
+ 35-11-02-001	DETAILED VISUAL INSPECTION OF LH CREW OXYGEN MASK 174232-93 34553 REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			06-DEC-2018 1071 829	06-DEC-2021 2871	05-JAN-2022 2901
+ 35-11-02-001	DETAILED VISUAL INSPECTION OF RH CREW OXYGEN MASK 174232-93 26776 REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-17		06-DEC-2018 1071 829	19-NOV-2021 2871	19-DEC-2021 2901
+ 35-11-02-002	RESTORATION (OVERHAUL) OF LH CREW OXYGEN MASK 174232-93 34553 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			16-JUN-2017 839.2	16-JUN-2023 4439.2	16-JUL-2023 4469.2
+ 35-11-02-002	RESTORATION (OVERHAUL) OF RH CREW OXYGEN MASK 174232-93 26776 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			20-OCT-2015 697.4 559	20-OCT-2021 4297.4	19-NOV-2021 4327.4

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-11-04-001 (s)	DETAILED VISUAL INSPECTION OF CREW GOGGLES PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	36	+30d/-30d			PKG 06-DEC-2018 1071 829		
+ 35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-17		06-DEC-2018 1071 829	19-NOV-2021 2871	19-DEC-2021 2901
AIRWORTHINESS									
+ 35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30	-17		06-DEC-2018 1071 829	19-NOV-2021 2871	19-DEC-2021 2901
AIRWORTHINESS									
35-21-01	PAX 1 OXYGEN MASK 4411072-111 44110072-111-00001 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-NOV-2015 697.4 559		
35-21-01	PAX 2 OXYGEN MASK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
35-21-01	PAX 3 OXYGEN MASK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
35-21-01	PAX 4 OXYGEN MASK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
+ 35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN-MASKS ASSEMBLY PKG 82 REF: AMM 35-21-01	MOS HRS/MSC AFL	36	+30d/-30d			PKG 06-DEC-2018 1071 829		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-02	CABIN OXYGEN THREE MASK DEPLOYMENT CONTAINER 4411073-001 4411073-001-00096 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-21-02	LH OXYGEN TWO MASK DEPLOYMENT CONTAINER 4411072-001 4411072-001-00050 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-SEP-2012 436.8 326		
35-21-02	OXYGEN ONE MASK DEPLOYMENT CONTAINER 441073-111 441073-111-00093 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			19-NOV-2015 697.4 559		
35-21-02	RH OXYGEN TWO MASK DEPLOYMENT CONTAINER 4411072-001 4411072-001-00134 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
35-31-01	PROTECTIVE BREATHING EQUIPMENT (PBE) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 35-31-01-001	DISCARD PROTECTIVE BREATHING EQUIPMENT (PBE) PN SN-UNKNOWN REF: AMM 35-31-01	MOS HRS/MSC AFL	N/A						
CHAPTER 36 PNEUMATIC									
+ 36-11-00-001 (s)	OPERATIONAL CHECK LH PYLON PRESSURE REGULATING SHUTOFF VALVE 1330310-5 PKG 1 0614 REF: AMM 36-11-00	MOS HRS/MSC AFL	600	+30/-30			PKG 13-SEP-2019 1140.3 869		
+ 36-11-00-001 (s)	OPERATIONAL CHECK RH PYLON PRESSURE REGULATING SHUTOFF VALVE 1330310-3 PKG 1 0419 REF: AMM 36-11-00	MOS HRS/MSC AFL	600	+30/-30			PKG 21-OCT-2014 620.1 487		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-01	LH PYLON PRESSURE REGULATING SHUTOFF VALVE 1330310-5 0614 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			13-SEP-2019 1140.3 869		
36-11-01	RH PYLON PRESSURE REGULATING SHUTOFF VALVE 1330310-3 0419 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-OCT-2014 620.1 487		
+ 36-11-02-001 (s)	DETAILED INSPECT OF BLEED LINE WATER DRAINS PKG 12 REF: AMM 36-11-02	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
+ 36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS REF: AMM 36-21-01	MOS HRS/MSC AFL	6000	+30/-30			25-JUL-2009 0 0	6000	6030
AIRWORTHINESS									
CHAPTER 38 WATER/WASTE									
383312-7101	TOILET ELECTRIC FLUSH PUMP ASSEMBLY RCP5160-00 03130467 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-NOV-2016 766.6 621		
CHAPTER 44 CABIN SYSTEMS									
24-21-03	DC CONVERTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
44-21-09	IFE, ASSY INSC ILLUM PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
CHAPTER 52 DOORS									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-00	OPTIONAL DOOR EQUIPPED STEP ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 52-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN PAX DOOR ASSEMBLY STRUCTURE PN PKG 84 SN-UNKNOWN REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 52-10-01-002	INTERNAL GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY STRUCTURE PN PKG 90 SN-UNKNOWN REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 52-10-01-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE UPPER EXTERNAL FRAME, UPPER HORIZONTAL STRINGER, EXTERNAL VERTICAL FRAME, AND LOWER HORIZONTAL FRAME. REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500						17500
+ 52-10-01-01-902	EXTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER. REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500						17500
+ 52-10-02-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR LATCH MECHANISM LATCH PINS. REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500						17500
+ 52-10-20-001 (s)	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY RUBBER SEAL PN PKG 12 SN-UNKNOWN REF: AMM 52-10-20	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 25-JUL-2019 1121.6 860		
52-11-00	MAIN PAX DOOR ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-11-00-001 (s)	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY LOCKING AND ACTUATING MECHANISM PN PKG 41 SN-UNKNOWN REF: AMM 52-11-00	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			PKG 19-DEC-2017 954.6 746		
+ 52-11-00-002 (s)	LUBRICATION OF MAIN DOOR LATCH PINS PKG 80 REF: AMM 52-11-21	MOS HRS/MSC AFL	12	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
52-11-01	DOOR KEY LOCK KIT 500-38850-901 100072-10072 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
52-13-00	MAIN DOOR BALANCE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 52-13-21-001 (s)	DISCARD MAIN DOOR BALANCE ASSEMBLY GEAR SECTOR PN PKG 50 SN-UNKNOWN REF: AMM 52-13-21	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 52-13-22-002 (s)	DISCARD MAIN DOOR BALANCE ASSEMBLY MECHANISM CABLE PN PKG 1 SN-UNKNOWN REF: AMM 52-13-22	MOS HRS/MSC AFL	600	+30/-30			PKG 08-NOV-2013 579.4 438		
+ 52-13-23-001 (s)	DISCARD MAIN DOOR BALANCE ASSEMBLY PINION SHAFT PN PKG 50 SN-UNKNOWN REF: AMM 52-13-23	MOS HRS/MSC AFL	6000	+30/-30			PKG 25-JUL-2009 0 0		
+ 52-20-01-01-901	INTERNAL DETAILED VISUAL INSPECTION EMERGENCY DOOR STRUCTURE SPAR AND FRAMES. REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-20-01-01-902	EXTERNAL - DETAILED INSPECTION EMERGENCY DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.								
AIRWORTHINESS	REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL							17500
			17500						
+ 52-20-20-001 (s)	GENERAL VISUAL INSPECTION CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY LOCKING AND ACTUATING MECHANISM						PKG		
	500-09700-417 PKG 41 0000495581 REF: AMM 52-20-20	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			19-DEC-2017 954.6 746		
52-20-21	CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY								
	500-09700-417 0000495581 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 52-20-21-001 (s)	GENERAL VISUAL INSPECTION CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY RUBBER SEAL						PKG		
	500-09700-417 PKG 12 0000495581 REF: AMM 52-20-21	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			25-JUL-2019 1121.6 860		
+ 52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM						PKG		
	PKG 41 REF: AMM 52-31-20	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			19-DEC-2017 954.6 746		
+ 52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM						PKG		
	PKG 41 REF: AMM 52-32-20	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			19-DEC-2017 954.6 746		
52-71-20	LOWER DOOR MICRO SWITCH								
	500-38876-401 0000283088 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
52-71-20	UPPER DOOR MICRO SWITCH								
	500-38876-401 0000283090 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 53 FUSELAGE									
+ 53-00-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS						PKG		
	PKG 1	MOS					11-NOV-2016		
	REF: AMM 53-00-20	HRS/MSC	600	+30/-30			766.6		
		AFL					621		
+ 53-05-00-001 (s)	DETAILED VISUAL INSPECTION OF FUSELAGE DRAINS						PKG		
	PKG 84	MOS	60	+30d/-30d			25-JUL-2019		
	REF: AMM 53-05-00	HRS/MSC					1121.6		
		AFL					860		
+ 53-10-00-001	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE LOWER SKIN PANEL AND COCKPIT FLOOR STRUCTURES								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-10-00	HRS/MSC					1121.6		
		AFL					860		
+ 53-10-00-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS, SKIN SPLICES AND WINDSHIELD CUTOUT STRUCTURE								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-10-00	HRS/MSC					1121.6		
		AFL					860		
53-10-01	REAR PRESSURE BULKHEAD ASSY								
	PN	MOS					25-JUL-2009		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
+ 53-10-01-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)								
		MOS							
	REF: NDT PART 5 53-10-00	HRS/MSC							
AIRWORTHINESS		AFL	6300						6300
+ 53-10-01-01-902	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)								
		MOS							
	REF: NDT PART 5 53-10-00	HRS/MSC	N/A						
		AFL							

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-01-01-903	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE SKIN PANEL AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-02-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS FRAMES AND SPLICES.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-02-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-FRAMES AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-02-02-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS STRINGERS.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-02-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-STRINGERS AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-03-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL FRAMES AND STRINGERS.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	
+ 53-10-03-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL SKIN-TO-FRAME/STRINGERS AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-04-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500						17500
+ 53-10-04-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES - SKIN-TO-LONGITUDINAL SPLICE AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500						17500
+ 53-10-04-02-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES CIRCUMFERENTIAL SPLICE.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500						17500
+ 53-10-04-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES SKIN-TO-CIRCUMFERENTIAL-SPLICE AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500						17500
+ 53-10-05-001	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
+ 53-10-05-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE PRESSURE BULKHEAD PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
+ 53-10-05-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE PRESSURE BULKHEAD.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-06-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE FORWARD SKIN PANELS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-10-00								
+ 53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL METALLIC STRUCTURE PKG 81	MOS HRS/MSC AFL	24	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 53-10-00								
+ 53-10-07-01-901	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE (EDDY CURRENT) TRUNION.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 6 53-10-00								
+ 53-10-07-02-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 5 53-10-00								
+ 53-10-07-02-902	EXTERNAL SPECIAL DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE (EDDY CURRENT) DRAG LOCKING STRUTS.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 6 53-10-00								
+ 53-10-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL COMPOSITE STRUCTURE PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 53-10-00								
+ 53-10-08-01-901	EXTERNAL - DETAILED INSPECTION NOSE LANDING GEAR WHEEL COMPOSITE STRUCTURE UPPER PANEL AND SIDE SKIN.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 5 53-10-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-14-00	NOSE RADOME 5190-102-1 025 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 53-20-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 53-20-00-002	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS, SKIN SPLICES, AND FLOOR STRUCTURE PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 53-20-00-003	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TO-WING LATERAL AND CENTER LINKS PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 53-20-01-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) FRAMES. REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-01-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) SKIN TO FRAMES AREA. REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-01-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) STRINGERS. REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-01-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-02-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) FRAMES.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-02-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) SKIN TO FRAMES AREA.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-02-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) STRINGERS.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-02-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-03-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) CUT-OUT REINFORCEMENT (SKIN DOUBLER).	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	
+ 53-20-03-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO CUT-OUT AREA.	MOS							
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-03-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) FRAMES AND STRINGERS.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-03-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO FRAMES AND STRINGERS AREA.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-04-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-30-00		17500					17500	
+ 53-20-04-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-04-02-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE CIRCUMFERENTIAL SKIN SPLICE.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-04-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE SKIN AT CIRCUMFERENTIAL SKIN SPLICE AREA.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-05-002	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 53-20-00								
+ 53-20-05-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS SKIN (FROM STRINGER 12L TO 12R).	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-05-01-902	EXTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS (EDDY CURRENT) SPLICE (1ST AND 3RD ROWS) (FROM STRINGER 01R TO 01L, FROM STINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 6 53-20-00		17500					17500	
+ 53-20-05-01-903	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS SKIN (FROM STRINGER 01R TO 01L, FROM STRINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-05-01-904	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES END FITTINGS	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500					17500	
+ 53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 53-20-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-06-002	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 53-20-06-01-901	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE DOUBLER 1 AT CORNERS OF MAIN DOOR CUTOUT STRUCTURE. REF: NDT PART 6 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-06-01-902	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE SKIN AT CORNERS OF THE MAIN DOOR CUTOUT STRUCTURE. REF: NDT PART 6 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-06-01-903	EXTERNAL - DETAILED INSPECTION THE MAIN DOOR CUTOUT STRUCTURE SKIN TO DOOR CUTOUT STRUCTURE. REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-06-01-904	INTERNAL GENERAL VISUAL INSPECTION THE MAIN DOOR CUT-OUT STRUCTURE. REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-06-01-905	INTERNAL DETAILED INSPECTION MAIN DOOR CUTOUT STRUCTURE MACHINED FRAME AT LATCH PIN BOX AREA . REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS									
+ 53-20-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR CUTOUT STRUCTURE PKG 84 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
+ 53-20-07-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-07-01-901	INTERNAL GENERAL VISUAL INSPECTION EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-07-01-902	EXTERNAL - DETAILED INSPECTION THE SKIN TO EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUT-OUT STRUCTURE PKG 90	MOS HRS/MSC AFL	60	+1m/-1m			PKG 25-JUL-2019 1121.6 860		
REF: NDT PART 5 53-20-00									
+ 53-20-08-01-901	INTERNAL GENERAL VISUAL INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER WINDOW FRAME (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18)	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-08-01-902	EXTERNAL - DETAILED INSPECTION PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18) SKIN AT WINDOW AREA.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-10-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKS.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-10-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING LATERAL LINKS MACHINED FRAME (FRAME 14 AND FRAME 18) AND FASTENERS	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-11-01-901	INTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK (EDDY CURRENT) CONNECTION LINK FITTING (LUG AND INNER CAP).	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 6 53-20-00		17500						17500
+ 53-20-11-01-902	INTERNAL DETAILED INSPECTION CENTER FUSELAGE-TO-WING CONNECTION LINK FITTING.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-20-12-01-901	INTERNAL DETAILED INSPECTION AFT PRESSURE BULKHEAD.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-20-00		17500						17500
+ 53-30-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKINS AND ATTACHMENTS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
REF: NDT PART 5 53-30-00									
+ 53-30-00-002	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER SKIN, JUNCTIONS AND ATTACHMENTS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
REF: NDT PART 5 53-30-00									
+ 53-30-00-003	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN, CUTOUTS AND ATTACHMENTS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
REF: NDT PART 5 53-30-00									
+ 53-30-01-01-901	INTERNAL DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL BEDPLATE AND ITS ATTACHMENTS, BEDPLATES TO STRINGER ATTACHMENTS AND SKIN TO BEDPLATE AREA.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-30-00		17500						17500
+ 53-30-01-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL SKIN TO BEDPLATE AREA.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 53-30-00		17500						17500

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-02-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL FORWARD MACHINED FRAME (FRAME 22 AND FRAME 23)								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-02-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL SKIN TO FRAME AREA								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-02-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL AFT MACHINED FRAME (FRAME 25 AND FR25A)								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-02-02-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL - SKIN TO FRAME AREA								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-04-01-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES AFT FUSELAGE SKIN TO LONGITUDINAL SPLICE.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-04-01-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	
+ 53-30-04-02-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES TO CIRCUMFERENTIAL SPLICE.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-04-02-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES TO CIRCUMFERENTIAL SPLICE.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500
+ 53-30-05-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
REF: NDT PART 5 53-30-00									
+ 53-30-05-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500
+ 53-30-05-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE AFT FUSELAGE THE SKIN TO BAGGAGE DOOR CUTOUT STRUCTURE.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500
+ 53-30-06-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE CUTOUT STRUCTURES - INTERNAL FRAMES, STRINGER, REINFORCEMENT, AND DOUBLER OF AFT FUSELAGE CUTOUT STRUCTURES.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500
+ 53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER FRAMES 29 TO 32 PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
REF: NDT PART 5 53-30-00									
+ 53-30-07-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) MACHINED FRAMES.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-07-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) SKIN TO FRAME AREA.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL		17500					17500
+ 53-30-07-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) BEDPLATES AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL		17500					17500
+ 53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE MACHINED FRAME 32						PKG		
	PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 53-30-00								
+ Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION						PKG		
	PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: See Workcard								
+ Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION						PKG		
	PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: See Workcard								
+ Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION						PKG		
	PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: AMM 05-41-00								
+ Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION						PKG		
	PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: AMM 05-41-00								
+ Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION						PKG		
	PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: AMM 05-42-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: See Workcard								
+ Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-42-00								
+ Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-42-00								
+ Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-43-00								
+ Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-43-00								
+ Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-43-00								
+ Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-43-00								
CHAPTER 54 NACELLES/PYLONS									
+ 54-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600	+30/-30			PKG 11-NOV-2016 766.6 621		
	REF: AMM 54-51-20								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-00-001	INTERNAL DETAILED VISUAL INSPECTION OF PYLON MAIN BOX PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 54-50-00-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD BEAM PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 54-50-01-01-901	INTERNAL DETAILED INSPECTION PYLON FORWARD BEAM PYLON SPARS 1 AND 2, UPPER AND LOWER SKIN AND FASTENERS. AIRWORTHINESS	MOS HRS/MSC AFL	17500					17500	
+ 54-50-02-01-901	INTERNAL DETAILED INSPECTION PYLON AFT BEAM PYLON SPARS 3 AND 4 AND FASTENERS. AIRWORTHINESS	MOS HRS/MSC AFL	17500					17500	
+ 54-50-03-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF PYLON MAIN BOX PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 54-50-03-01-901	EXTERNAL GENERAL VISUAL INSPECTION OF PYLON MAIN BOX MAIN BOX SKIN AND FASTENERS. AIRWORTHINESS	MOS HRS/MSC AFL	17500					17500	
+ 54-50-04-01-901	INTERNAL DETAILED INSPECTION PYLON-TO-FUSELAGE CONNECTIONS OF BOLTS. AIRWORTHINESS	MOS HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 54-50-00								
+ 54-50-05-01-901	INTERNAL DETAILED INSPECTION PYLON YOKES LUG HOLES AT YOKES, YOKES, GUSSETS AND SHIELD.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 54-50-00								
+ 54-50-06-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT MOUNT FITTINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 54-50-00								
+ 54-50-06-01-901	INTERNAL DETAILED INSPECTION PYLON AFT FITTING AFT MOUNT FITTING AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 54-50-00								
+ Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: See Workcard								
+ Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-46-00								
+ Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-46-00								
+ Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: AMM 05-46-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 55 STABILIZERS									
+ 55-00-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF STABILIZER POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600	+30/-30			PKG 11-NOV-2016 766.6 621		
	REF: AMM 55-00-20								
55-10-00	HORIZONTAL STABILIZER 500-10700-405 0000493210 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 55-10-00-001 (s)	EXTERNAL - DETAILED INSPECTION OF HORIZONTAL-STABILIZER SPARS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-10-00								
+ 55-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER MAIN BOX PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-10-00								
+ 55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL-TO-HORIZONTAL STABILIZER ATTACHMENTS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-10-00								
+ 55-10-01-01-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR (BORESCOPIIC) FRONT SPAR AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-02-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR FRONT SPAR AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR (BORESCOPIC) REAR SPAR.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-03-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR FASTENERS.	MOS HRS/MSC AFL	17500			REAR SPAR AND			17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN (BORESCOPIC) STRINGERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-04-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN UPPER SKIN AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-05-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN - LOWER SKIN.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-05-01-902	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN SKIN AT FIN TO HORIZONTAL STABILIZER LINK AREA AND STRINGERS, INCLUDING FASTENERS.	MOS HRS/MSC AFL	17500			LOWER			17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-06-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER COMPOSITE RIBS AND FASTENERS.						(BORESCOPIC)		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-07-001	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER TIP RIBS								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
+ 55-10-07-01-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER METALLIC RIBS, INCLUDING FASTENERS.						ROOT AND TIP METALLIC		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-08-001	EXTERNAL - DETAILED INSPECTION ON HORIZONTAL STABILIZER ROOT RIBS								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
+ 55-10-08-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE (BORESCOPIC) HORIZONTAL STABILIZER LEADING EDGE SKIN AND SPAR.								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-08-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER LEADING EDGE STABILIZER LEADING EDGE SKIN AND FASTENERS.						HORIZONTAL		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-09-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL STABILIZER LEADING EDGE						PKG		
	PKG 87	MOS	120	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-09-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING FASTENERS.						HINGE FITTINGS, AND		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-09-02-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING (EDDY CURRENT) LUGS.								
AIRWORTHINESS	REF: NDT PART 6 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-09-03-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER ELEVATOR FITTING TORQUE BOX AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL-STABILIZER HINGE FITTINGS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-10-01-901	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TRIM TAB SUPPORTING FITTING AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-10-02-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS TRIM TAB LINK SUPPORT FITTING AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500						17500
+ 55-10-11-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF TRIM-TAB SUPPORT FITTINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
AIRWORTHINESS	REF: NDT PART 5 55-10-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20-00-001 (s)	EXTERNAL - DETAILED INSPECTION OF ELEVATOR FITTINGS AND TORQUE-TUBE ATTACHMENTS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-20-00								
+ 55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-20-00								
+ 55-20-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) (BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00								
+ 55-20-01-01-902	EXTERNAL - DETAILED INSPECTION ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE AND HORN.	MOS HRS/MSC AFL	17500			SKIN AND			17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00								
+ 55-20-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS (DYE PENETRANT) ELEVATOR HINGE PINS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 8 55-20-00								
+ 55-20-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS (EDDY CURRENT) ELEVATOR HINGE FITTINGS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 6 55-20-00								
+ 55-20-02-02-902	INTERNAL DETAILED INSPECTION ELEVATOR HINGE FITTINGS ELEVATOR HINGE FITTINGS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 55-20-00								



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (EDDY CURRENT) ELEVATOR TORQUE TUBE FLANGE.								
AIRWORTHINESS	REF: NDT PART 6 55-20-00	MOS HRS/MSC AFL	17500						17500
+ 55-20-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION ELEVATOR TORQUE TUBE ASSY (DYE PENETRANT) ELEVATOR TORQUE TUBE.								
AIRWORTHINESS	REF: NDT PART 8 55-20-00	MOS HRS/MSC AFL	17500						17500
+ 55-22-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TAB PIANO HINGE PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 55-22-02-001	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR TAB BOX PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 55-30-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER TO AFT FUSELAGE CONNECTIONS AT VERTICAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-REAR FUSELAGE CONNECTIONS AT VERTICAL STABILIZER PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 55-30-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER (BORESCOPIC) FITTING, PINS AND SPARS ATTACHMENTS (UPPER PART OF CONNECTIONS).								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-01-01-902	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER FITTING, PINS AND SPAR ATTACHMENTS (LOWER PART OF CONNECTIONS), NUT, SEAL AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-01-02-901	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER L SHAPE, RIB AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-02-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			25-JUL-2019		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					1121.6 860		
+ 55-30-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) DOUBLER AND TIP RIB.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-02-01-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (EDDY CURRENT) DOUBLER AND TIP RIB AT FRONT AND REAR FITTING AREA.								
AIRWORTHINESS	REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-02-02-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER L SHAPE AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-02-02-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) L SHAPE AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-02-03-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER FITTINGS AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-02-04-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER COMPOSITE PLATES AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-03-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL STABILIZER MAIN BOX PKG 87						PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	120	+30d/-30d					
+ 55-30-03-01-901	EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) SKIN AND SPAR.								
AIRWORTHINESS	REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-03-01-902	INTERNAL SPECIAL DETAILED INSPECTION VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) (BORESCOPIK) SPAR.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER FITTING PKG 84						PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d					
+ 55-30-05-01-901	EXTERNAL - DETAILED INSPECTION RUDDER HINGE FITTINGS HINGE FITTING 1 AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-05-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (EDDY CURRENT) HINGE FITTING 2 FLANGES.								
AIRWORTHINESS	REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-05-03-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS (EDDY CURRENT) RUDDER LUG HINGE FITTINGS 1 AND 2.								
AIRWORTHINESS	REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500						17500
+ 55-30-06-001	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB ACTUATOR FITTING AND SUPPORT FITTINGS PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					860		
+ 55-30-06-01-901	EXTERNAL - DETAILED INSPECTION VERTICAL STABILIZER TAB ACTUATOR AND SUPPORT FITTINGS FITTINGS, LUGS AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500						17500
55-33-00	VERTICAL STABILIZER 500-10100-411 0000493217 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-JUL-2009 0 0		
+ 55-40-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF RUDDER ASSEMBLY PKG 87	MOS	120	+30d/-30d			25-JUL-2019 1121.6		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					860		
+ 55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER ASSEMBLY PKG 87	MOS	120	+30d/-30d			25-JUL-2019 1121.6		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-40-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER MAIN BOX FASTENERS.			(BORESCOPIC) SKIN, SPARS, RIBS AND					
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-01-01-902	EXTERNAL - DETAILED INSPECTION RUDDER MAIN BOX SKINS, INCLUDING FASTENERS.			MAIN BOX, TRAILING EDGE AND LEADING EDGE					
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-02-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF RUDDER HINGE FITTINGS PKG 87						PKG		
	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
+ 55-40-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS FITTINGS PINS.			(DYE PENETRANT) RUDDER HINGE					
AIRWORTHINESS	REF: NDT PART 8 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER HINGE FITTINGS FITTINGS.			(EDDY CURRENT) RUDDER HINGE					
AIRWORTHINESS	REF: NDT PART 6 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-02-02-902	INTERNAL DETAILED INSPECTION RUDDER HINGE FITTINGS			RUDDER HINGE FITTINGS.					
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE-TUBE ASSEMBLY PKG 87						PKG		
	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-40-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY RUDDER TORQUE TUBE FLANGE.						(EDDY CURRENT)		
AIRWORTHINESS	REF: NDT PART 6 55-40-00	MOS HRS/MSC AFL	17500						17500
+ 55-40-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION RUDDER TORQUE TUBE ASSEMBLY RUDDER TORQUE TUBE.						(DYE PENETRANT)		
AIRWORTHINESS	REF: NDT PART 8 55-40-00	MOS HRS/MSC AFL	17500						17500
55-41-00	RUDDER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 55-42-01-001	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TAB PIANO HINGE PKG 90 REF: NDT PART 5 55-42-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 84 REF: AMM 05-44-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
+ Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		
+ Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84 REF: AMM 05-44-00	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
+ Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 56 WINDOWS									
+ 56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF COCKPIT SIDE-WINDOWS						PKG		
	PKG 84	MOS	60	+30d/-30d			25-JUL-2019		
		HRS/MSC					1121.6		
	REF: NDT PART 5 56-10-00	AFL					860		
+ 56-10-01-002	FUNCTIONALLY CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS								
		MOS					19-NOV-2015		
		HRS/MSC	1200	+30/-30			697.4	1897.4	1927.4
	REF: AMM 56-10-00	AFL					559		
+ 56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WINDSHIELD AND COCKPIT SIDE WINDOW FRAMES AND FASTENERS						PKG		
	PKG 81	MOS	24	+30d/-30d			25-JUL-2019		
		HRS/MSC					1121.6		
	REF: NDT PART 5 56-10-00	AFL					860		
+ 56-10-03-01-901	EXTERNAL SPECIAL DETAILED INSPECTION WINDSHIELD FRAME AND FASTENERS FRAMES AND FASTENERS.					(EDDY CURRENT)			
		MOS							
		HRS/MSC							
AIRWORTHINESS	REF: NDT PART 6 56-10-00	AFL	17500					17500	
56-11-00	COPILOT RH HEATED GLASS WINDSHIELD ASSY, (LH)								
	NP-195301-6	MOS			TSN:3		06-DEC-2018		
	18250H8067	HRS/MSC	O/C		TSN:0		1071		
	REF: See Workcard	AFL			TSN:0		829		
56-11-00	PILOT LH HEATED GLASS WINDSHIELD ASSY, (LH)								
	NP-195301-1	MOS			TSN:0		25-JUL-2009		
	08217H5793	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
56-12-00	COPILOT RH ACRYLIC SIDE WINDOW								
	NP-195302-4	MOS			TSN:0		25-JUL-2009		
	08301H7076	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
56-12-00	PILOT LH ACRYLIC SIDE WINDOW								
	NP-195302-3	MOS			TSN:0		25-JUL-2009		
	09026H7861	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	LEFT NO.1 WINDOW TRANSPARENCY 14024 00527 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	LEFT NO.2 WINDOW TRANSPARENCY 14024 194094 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-NOV-2016 766.6 621		
56-20-00	LEFT NO.3 WINDOW TRANSPARENCY 14024 00548 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	LEFT NO.4 WINDOW TRANSPARENCY 14024 00578 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	RIGHT NO. 1 WINDOW TRANSPARENCY 14024 00589 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	RIGHT NO. 2 WINDOW TRANSPARENCY 14024 00599 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	RIGHT NO. 3 WINDOW TRANSPARENCY 14024 00604 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
56-20-00	RIGHT NO. 4 WINDOW TRANSPARENCY 14024 00607 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF PASSENGER CABIN WINDOWS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 56-20-00								
CHAPTER 57 WINGS									
+ 57-00-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF WING POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600	+30/-30			PKG 11-NOV-2016 766.6 621		
	REF: AMM 57-30-20								
+ 57-10-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-FUSELAGE LINKS PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-10-00								
+ 57-10-00-002	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-10-00								
+ 57-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MIDDLE AND REAR SPARS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-10-00								
+ 57-10-01-01-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE BOLT, NUT AND SEAL.	MOS HRS/MSC AFL	17500			FRONT FITTING,			
AIRWORTHINESS	REF: NDT PART 5 57-10-00								17500
+ 57-10-01-02-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE BOLT, NUT AND SEAL.	MOS HRS/MSC AFL	17500			REAR FITTING,			
AIRWORTHINESS	REF: NDT PART 5 57-10-00								17500



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CURRENT) WING CENTER FITTING AND LUG.						(EDDY		
AIRWORTHINESS	REF: NDT PART 6 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-02-01-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE FITTING.						WING CENTER		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE CURRENT) CENTER LINK LUGS.						(EDDY		
AIRWORTHINESS	REF: NDT PART 6 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-02-02-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE FITTING, BOLT, NUT AND SEAL.						CENTER LINK		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-02-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE (MAGNETIC PARTICLE) HORIZONTAL LINK BOLTS.								
AIRWORTHINESS	REF: NDT PART 7 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-03-01-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS.						FRONT SPAR LOWER CAP BETWEEN RIB 1 AND 3		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-03-02-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS.						FRONT SPAR LOWER CAP BETWEEN RIB 3 AND 6		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-03-03-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR FASTENER.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-03-04-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-03-05-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR INCLUDING FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-04-01-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR INCLUDING FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-04-02-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR INCLUDING FASTENERS .								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-04-03-901	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR 9, INCLUDING SPAR-STRINGER-SPLICE AND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-04-04-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR (LUG, SURFACE AND RADIUS).								
AIRWORTHINESS	REF: NDT PART 6 57-10-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-04-04-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR			MLG FRONT TRUNNION AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-04-05-901	INTERNAL SPECIAL DETAILED INSPECTION WING MIDDLE SPAR (SURFACE AND RADIUS).			(EDDY CURRENT) MLG ACTUATOR FITTING					
AIRWORTHINESS	REF: NDT PART 6 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-04-05-902	INTERNAL DETAILED INSPECTION WING MIDDLE SPAR			MLG ACTUATOR FITTING AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-05-01-901	INTERNAL DETAILED INSPECTION WING REAR SPAR AND WINDOW ACCESS FRAME.			REAR SPAR LOWER CAP BETWEEN RIB 1 AND 3					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-05-02-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR INCLUDING FASTENERS.			REAR SPAR LOWER CAP BETWEEN RIB 3 AND 7,					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-05-03-901	INTERNAL DETAILED INSPECTION WING REAR SPAR INCLUDING FASTENERS.			REAR SPAR LOWER CAP BETWEEN RIB 7 AND 10,					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	
+ 57-10-05-04-901	EXTERNAL - DETAILED INSPECTION WING REAR SPAR FASTENERS.			LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-05-05-901	EXTERNAL SPECIAL DETAILED INSPECTION WING REAR SPAR (LUG, SURFACE AND MACHINED RADIUS).			(EDDY CURRENT) MLG REAR TRUNNION					
AIRWORTHINESS	REF: NDT PART 6 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-05-05-902	EXTERNAL - DETAILED INSPECTION WING REAR SPAR			MLG REAR TRUNNION AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87	MOS	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84	MOS	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-07-002	INTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-07-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL CLIPS OF STRINGER 5 AND SHEAR CLIPS FASTENERS.			STRINGER 2 AND 3 BETWEEN RIB 1 AND 3 AND SHEAR					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-07-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL AT RIB 8 AND WINDOW ACCESS PANEL 9 FRAMES.			STRINGER 2 RUN-OUT, STRINGER SHEAR CLIPS					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-07-03-901	EXTERNAL - DETAILED INSPECTION WING LOWER PANEL 2 AND RIB 10, INCLUDING DOU-BLER AND ITS FASTENERS.			LOWER PANEL AND FASTENERS BETWEEN RIB					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-08-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL 6R, RIB 7R, RIB 8R).			MACHINED RIBS (RIB 1, RIB 3, RIB 3A, RIB 5R, RIB					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-08-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL 6F, RIB 7F, RIB 8F, RIB 9, RIB 10, RIB11, RIB 12, RIB 13, RIB 14, RIB 15 AND RIB 16).			WING FORMED RIBS (RIB 2, RIB 4F, RIB 5F, RIB					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-08-03-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL			DRY BAY WALLS AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-10-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 57-10-10-002	INTERNAL GENERAL VISUAL INSPECTION OF WING CENTER SPLICE PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 57-10-10-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTRAL SPLICE PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-10-01-901	EXTERNAL - DETAILED INSPECTION WING CENTRAL SPLICES REAR SPAR SPLICES, INCLUDING FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-10-01-902	INTERNAL DETAILED INSPECTION WING CENTRAL SPLICES BETWEEN RIB1 AND RIB 2, FRONT , REAR AND MIDDLE SPAR ON SPLICE AREA AND MIDDLE SPAR SPLICE, INCLUDING FASTENERS.								
AIRWORTHINESS	REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500						17500
+ 57-10-11-001	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON TAB ACTUATOR SUPPORT FITTINGS AND TAB HINGE FITTINGS								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-50-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE INBOARD AND OUTBOARD TORQUE BOXES						PKG		
	PKG 84	MOS	60	+30d/-30d			25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-50-00	HRS/MSC AFL							
+ 57-50-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS (EDDY CURRENT) WING ROOT TRACK.								
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-01-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS WING ROOT TRACK.								
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-01-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS (DYE PENETRANT) WING ROOT ROLLER.								
AIRWORTHINESS	REF: NDT PART 8 57-50-00	MOS HRS/MSC AFL	8875						8875

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-01-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS			(EDDY CURRENT) RIB 1.					
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-01-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS			RIB 1 AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS			(EDDY CURRENT) WING CENTER TRACK.					
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-02-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS			WING CENTER TRACK.					
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS			(EDDY CURRENT) WING CENTER TRACK SUPPORT.					
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-02-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS			WING CENTER TRACK SUPPORT.					
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500					17500	
+ 57-50-02-03-901	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS			FITTINGS (LUG, ATTACHMENTS, PIN AND FASTENERS).					
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500					17500	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) WING TIP TRACK.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 6 57-50-00		17500						17500
+ 57-50-03-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS WING TIP TRACK.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 57-50-00		17500						17500
+ 57-50-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (DYE PENETRANT) WING TIP ROLLER.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 8 57-50-00		8875						8875
+ 57-50-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) RIBS 13 AND 13A WEB AND FLANGE.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 6 57-50-00		17500						17500
+ 57-50-03-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS RIBS 13 AND 13A.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 57-50-00		17500						17500
+ 57-50-03-04-901	EXTERNAL - DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS TORQUE BOX SKIN AND FASTENERS.	MOS HRS/MSC AFL							
AIRWORTHINESS	REF: NDT PART 5 57-50-00		17500						17500
+ 57-50-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE AILERON HINGE FITTING PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-50-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 01.							
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-04-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 02 .							
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-04-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	AILERON HINGE FITTING 02.							
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-04-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 03.							
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-50-04-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	AILERON HINGE FITTING 03.							
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS HRS/MSC AFL	17500						17500
+ 57-51-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP ASSEMBLY								
	PKG 90	MOS	60	+30d/-30d			25-JUL-2019	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-51-00	HRS/MSC AFL					1121.6 860		
+ 57-51-01-01-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS								
AIRWORTHINESS	REF: NDT PART 5 57-51-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-51-02-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE FLAP MAIN BOX PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
	REF: NDT PART 5 57-51-00								
+ 57-51-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS (BORESCOPIC) FLAP FRONT SPAR BETWEEN RIB 5A AND RIB 5B.	MOS HRS/MSC AFL	7049					7049	
AIRWORTHINESS	REF: NDT PART 5 57-51-00								
+ 57-51-02-03-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS FLAP LOWER SKIN FROM RIB 1 TO RIB 5A AND FROM RIB 5B TO RIB 10.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 5 57-51-00								
+ 57-51-02-04-901	EXTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS (EDDY CURRENT) FLAP LOWER SKIN FROM RIB 4 TO RIB 5A AND FROM RIB 5B TO RIB 6 AT FRONT SPAR AREA.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 6 57-51-00								
+ 57-51-02-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS (BORESCOPIC) AROUND FASTENERS THAT CONNECT CENTER ROLLERS FITTING TO RIB 5A AND RIB 5B	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 5 57-51-00								
+ 57-51-02-06-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS (EDDY CURRENT) FRONT SPAR FROM RIB 5A TO RIB 5B.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 6 57-51-00								
+ 57-51-02-07-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS (EDDY CURRENT) RIB 1 AND RIB 10.	MOS HRS/MSC AFL	17500					17500	
AIRWORTHINESS	REF: NDT PART 6 57-51-00								



Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-51-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP TRACK FITTINGS AND ACTUATOR FITTING PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
	REF: NDT PART 5 57-51-00								
+ 57-51-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP ROOT TRACK.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 6 57-51-00								
+ 57-51-03-01-902	INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP ROOT TRACK.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 57-51-00								
+ 57-51-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP TIP TRACK.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 6 57-51-00								
+ 57-51-03-02-902	INTERNAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS FLAP TIP TRACK.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 5 57-51-00								
+ 57-51-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) FLAP ROOT AND TIP ROLLERS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 8 57-51-00								
+ 57-51-03-04-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) CENTER ROLLERS EXTERNAL PINS.	MOS HRS/MSC AFL	17500						17500
AIRWORTHINESS	REF: NDT PART 8 57-51-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-51-03-05-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) CENTER ROLLERS FITTING AROUND FASTENERS.								
AIRWORTHINESS	REF: NDT PART 6 57-51-00	MOS HRS/MSC AFL	17500						17500
+ 57-51-04-01-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING SUPPORT PIN.					FLAP ACTUATOR			
AIRWORTHINESS	REF: NDT PART 5 57-51-00	MOS HRS/MSC AFL	17500						17500
+ 57-51-04-02-901	INTERNAL DETAILED INSPECTION FLAP ACTUATOR SUPPORT FITTING SUPPORT FITTING AND FASTENERS.					FLAP ACTUATOR			
AIRWORTHINESS	REF: NDT PART 5 57-51-00	MOS HRS/MSC AFL	17500						17500
57-60-00	LH AILERON ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
57-60-00	RH AILERON ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 57-60-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON ASSEMBLY AND AILERON TAB BOX PKG 87 REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		
+ 57-60-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON MAIN BOX PKG 87 REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON MAIN BOX FASTENERS.			(BORESCOPIC) SKIN, SPARS, RIBS AND					
AIRWORTHINESS	REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-01-01-902	EXTERNAL - DETAILED INSPECTION AILERON MAIN BOX			SKIN, SPARS, RIBS AND FASTENERS.					
AIRWORTHINESS	REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS FITTINGS PINS.			(DYE PENETRANT) AILERON HINGE					
AIRWORTHINESS	REF: NDT PART 8 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS FITTINGS (LUGS, STIFFENERS RADIUS).			(EDDY CURRENT) AILERON HINGE					
AIRWORTHINESS	REF: NDT PART 6 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-02-02-902	INTERNAL DETAILED INSPECTION AILERON HINGE FITTINGS			AILERON HINGE FITTINGS.					
AIRWORTHINESS	REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-03-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AILERON ACTUATOR FITTING, HINGE FITTINGS AND PINS						PKG		
	PKG 84	MOS	60	+30d/-30d			25-JUL-2019		
	REF: NDT PART 5 57-60-00	HRS/MSC AFL					1121.6		
							860		
+ 57-60-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN PENETRANT) AILERON ACTUATOR HINGE FITTINGS PINS.						(DYE		
AIRWORTHINESS	REF: NDT PART 8 57-60-00	MOS HRS/MSC AFL	17500						17500

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN CURRENT) AILERON ACTUATOR HINGE FITTINGS (LUGS, STIFFEN-ERS RADIUS).					(EDDY			
AIRWORTHINESS	REF: NDT PART 6 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-60-03-02-902	INTERNAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS.								
AIRWORTHINESS	REF: NDT PART 5 57-60-00	MOS HRS/MSC AFL	17500						17500
+ 57-63-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF OF AILERON TAB ASSEMBLY PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860	25-JUL-2024	24-AUG-2024
+ 57-63-00-001	REF: NDT PART 5 57-63-00								
+ Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
+ Z500-001 (s)	REF: AMM 05-45-00								
+ Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			25-JUL-2019 1121.6 860		
+ Z500-002 (s)	REF: AMM 05-45-00								
CHAPTER 71	POWER PLANT								
+ 71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL PKG 50	MOS HRS/MSC AFL	6000	+30/-30			25-JUL-2009 0 0		
+ 71-11-00-001 (s)	REF: AMM 71-11-00								
+ 71-20-00-001	DISCARD LEFT ENGINE AFT MOUNT ISOLATOR LM-474-SA2 LK0200	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-OCT-2008 0	01-OCT-2028 4800	31-OCT-2028 4830
+ 71-20-00-001	REF: AMM 71-20-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-20-00-001	DISCARD LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0172 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-AUG-2008 0	01-AUG-2028 4800	31-AUG-2028 4830
+ 71-20-00-001	DISCARD LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0200 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-AUG-2008 0	01-AUG-2028 4800	31-AUG-2028 4830
+ 71-20-00-001	DISCARD RIGHT ENGINE AFT MOUNT ISOLATOR LM-474-SA2 LK0254 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-OCT-2008 0	01-OCT-2028 4800	31-OCT-2028 4830
+ 71-20-00-001	DISCARD RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0175 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-AUG-2008 0	01-AUG-2028 4800	31-AUG-2028 4830
+ 71-20-00-001	DISCARD RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0181 REF: AMM 71-20-00	MOS HRS/MSC AFL	240 4800	+30d/-30d +30/-30			01-AUG-2008 0	01-AUG-2028 4800	31-AUG-2028 4830
71-21-01	LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0172 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	25-JUL-2009 0 0	
71-21-01	LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0200 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	25-JUL-2009 0 0	
71-21-01	RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0175 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 TSN:0 TSN:0	25-JUL-2009 0 0	

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-21-01	RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR LM-474-SA11 LK0181 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 71-21-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.	MOS HRS/MSC AFL	5000						5000
AIRWORTHINESS	REF: NDT PART 8 71-21-00								
+ 71-21-01-01-902	INTERNAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY ENGINE BOLT AND SLEEVE BOLT.	MOS HRS/MSC AFL	5000						5000
AIRWORTHINESS	REF: NDT PART 5 71-21-00								
71-22-01	LEFT ENGINE AFT MOUNT ISOLATOR LM-474-SA2 LK0200 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
71-22-01	RIGHT ENGINE AFT MOUNT ISOLATOR LM-474-SA2 LK0254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
+ 71-22-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.	MOS HRS/MSC AFL	5000						5000
AIRWORTHINESS	REF: NDT PART 8 71-22-00								
+ 71-22-01-01-902	INTERNAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY PYLON BOLTS, ENGINE BOLTS AND SLEEVE BOLTS.	MOS HRS/MSC AFL	1500						1500
AIRWORTHINESS	REF: NDT PART 5 71-22-00								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-31-00-001 (s)	DETAILED VISUAL INSPECTION OF PYLON FIREWALL SEAL PKG 20	MOS					PKG		
	REF: AMM 71-31-00	HRS/MSC AFL	1800	+30/-30			25-JUL-2009 0 0		
71-50-00	LH ENG W403 HARNESS PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
71-50-00	RH ENG W404 HARNESS PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
71-60-01	LH ENG NACELLE AIR INLET ASSEMBLY 500-36000-407 00020 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
71-60-01	RH ENG NACELLE AIR INLET ASSEMBLY 500-36000-407 00025 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
71EN1	NO. 1 ENGINE 3503100-01 PCE-LC0069 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71EN2	NO. 2 ENGINE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01									
+ 710010	NO. 1 ENGINE - COMPRESSOR WASH	MOS					25-JUL-2019		
	REF: See Workcard	HRS/MSC ENC	A/R				1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710011	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH								
		MOS					18-OCT-2017		
		HRS/MSC	A/R				917		
	REF: LMM 71-00-00	ENC					735		
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01									
+ 710010	NO. 2 ENGINE - COMPRESSOR WASH								
		MOS					25-JUL-2019		
		HRS/MSC	A/R				1121.6		
	REF: See Workcard	ENC					860		
+ 710011	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH								
		MOS					18-OCT-2017		
		HRS/MSC	A/R				917		
	REF: LMM 71-00-00	ENC					735		
CHAPTER 72 ENGINE									
+ 72-00-00-001 (s)	VISUAL CHECK OF ENGINE MAINTENANCE PAGE FOR ENGINE DISPATCH AND EXCEEDANCE INFORMATION						PKG		
	PKG 2	MOS	12	+30d/-30d			25-JUL-2019		
		HRS/MSC	600	+30/-30			1121.6		
	REF: AMM 72-00-00	AFL					860		
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01									
+ 72-00-00-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
		HRS/MSC	600	+10%			1121.6		
	REF: LMM 72-00-00	ENC					860		
+ 72-00-00-212-802 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
		HRS/MSC	600	+10%			1121.6		
	REF: LMM 72-00-00	ENC					860		
+ 72-00-00-212-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
		HRS/MSC	600	+10%			1121.6		
	REF: LMM 72-00-00	ENC					860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-212-804 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
	REF: LMM 72-00-00								
+ 72-00-00-212-805 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
	REF: LMM 72-00-00								
+ 72-00-00-212-806 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
	REF: LMM 72-00-00								
+ 72-00-00-215-801 (s)	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA PKG 1	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
	REF: LMM 72-00-00								
+ 72-00-00-215-802	NO. 1 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY PKG 2	MOS HRS/MSC ENC	600	+10%			08-NOV-2013 579.4 438	(1179.4) 1179.4	1239.4
	REF: LMM 72-00-00								
+ 72-00-00-215-803	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA PKG 2	MOS HRS/MSC ENC	600	+10%			08-NOV-2013 579.4 438	(1179.4) 1179.4	1239.4
	REF: LMM 72-00-00								
+ 72-00-00-280-802	NO. 1 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				06-DEC-2018 1071 829		
+ 72-00-00-290-815	NO. 1 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY REF: LMM 72-00-00	MOS HRS/MSC ENC	1750	+50			28-APR-2009 0 0	(1750) 1750	1800

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-640-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
		HRS/MSC	600	+10%			1121.6		
	REF: LMM 72-00-00	ENC					860		
72-00-02-810-801	NO. 1 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM								
		MOS					28-APR-2009		
		HRS/MSC	O/C				0		
	REF: LMM 72-00-02	ENC					0		
+ 72-30-04-000-803	NO. 1 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL								
	PN	MOS			TSN:0		28-APR-2009		
	SN-UNKNOWN	HRS/MSC	1750	+50	TSN:0		0	(1750) 1750	1800
	LIFE LIMIT	ENC			TSN:0		0		
	REF: See Workcard								
+ 72-30-04-000-804	NO. 1 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL								
	PN	MOS			TSN:0		28-APR-2009		
	SN-UNKNOWN	HRS/MSC	1750	+50	TSN:0		0	(1750) 1750	1800
	LIFE LIMIT	ENC			TSN:0		0		
	REF: See Workcard								
+ 72-60-01-000-805	NO. 1 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER								
	PN	MOS			TSN:0		28-APR-2009		
	SN-UNKNOWN	HRS/MSC	1750	+50	TSN:0		0	(1750) 1750	1800
	DISCARD	ENC			TSN:0		0		
	REF: See Workcard								
+ 720000	NO. 1 ENGINE - PERFORM ENGINE OVERHAUL								
		MOS					28-APR-2009		
		HRS/MSC	3500	+100			0	(3500) 3500	3600
	OVERHAUL	ENC					0		
	REF: GENERIC NO REF								
+ 720001	NO. 1 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION								
		MOS					28-APR-2009		
		HRS/MSC	1750	+50			0	(1750) 1750	1800
	REF: See Workcard	ENC					0		
+ 720003	NO. 1 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)								
		MOS	144	+1m			28-APR-2009	28-APR-2021	28-MAY-2021
		HRS/MSC					0		
	REF: GENERIC NO REF	ENC					0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720010	NO. 1 ENGINE - FAN ROTOR 35C3881-01 AATPWACE023 REF: GENERIC NO REF	MOS HRS/MSC ENC					28-APR-2009 0 0		(10500) 10499
LIFE LIMIT			10500	TSN:0 TSN:0 TSN:0					
+ 720030 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF EXTERIOR SURFACES OF THE NACELLE FOR EVIDENCE OF OIL LEAKS PKG 1 REF: GENERIC NO REF	MOS HRS/MSC ENC	12 600	+30d +10%			25-JUL-2019 1121.6 860		
+ 721010	NO. 1 ENGINE - HP TURBINE DISK 35C3091-01 A002H9B1 REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A				28-APR-2009 0 0		
721015	NO. 1 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-APR-2009 0 0		
+ 721020	NO. 1 ENGINE - LP TURBINE DISK 35C5392-01 A002FNR6 REF: GENERIC NO REF	MOS HRS/MSC ENC	N/A				28-APR-2009 0 0		
721025	NO. 1 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-APR-2009 0 0		
723002 (1)	NO. 1 ENGINE - FAN CASE 35C5323-01 NYAB00004217 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-APR-2009 0 0		
723002 (2)	NO. 1 ENGINE - ASSEMBLY OF FAN CASE 35C5324-01 NYAB00004217 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723003	NO. 1 ENGINE - FLANGED BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
+ 723010	NO. 1 ENGINE - IMPELLER AND SHAFT ASSEMBLY 35C4716-01 AAPPIACG2041 REF: GENERIC NO REF	MOS HRS/MSC ENC	10500	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0	(10500) 10499	
+ 723015	NO. 1 ENGINE - LP COMPRESSOR SHAFT 35C4620-01 KWA4841003 REF: GENERIC NO REF	MOS HRS/MSC ENC	10500	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0	(10500) 10499	
723020	NO. 1 ENGINE - TOWERSHAFT BALL ANNULAR BEARING 35C2168-01 FCN201073 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723025	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 35C4832-01 FCN285010 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723030	NO. 1 ENGINE - LP SHAFT BALL ANNULAR BEARING 35C5051-01 FCN231237 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723035	NO. 1 ENGINE - LP SHAFT BALL FLANGED BEARING 35C4831-01 FCN292191 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723040	NO. 1 ENGINE - TOWERSHAFT ROLLER BEARING 3107496-01 FCN283070 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723045	NO. 1 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING 35C4534-01 FCN289474 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY 35C5325-01 NYAB00004217 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723055	NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY 35C4935-01 RWA27C078 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723060	NO. 1 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY 35C4860-01 RWA27C120 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723065	NO. 1 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 35C5334-01 PKAAA239950 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723070	NO. 1 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 35C3627-01 PKAAA243213 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723075	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR 35C3628-01 PKAAA243033 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723080	NO. 1 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY 35C4714-01 AAPPIACG2041 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723085	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 35C5326-01 EYA16780 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723090	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 35C4623-01 EYA17143 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723095	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLY 35C5330-01 PKAAA247395 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
723110	NO. 1 ENGINE - HOUSING IMPELLER ASSEMBLY 35C5211-01 RWA27C430 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
724010	NO. 1 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY 35C5050-01 A002KE4C REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
724015	NO. 1 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY 35C5053-01 A002KH7E REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725006	NO. 1 ENGINE - ANNULAR ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725008	NO. 1 ENGINE - NO.5 BEARING CARBON SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725010	NO. 1 ENGINE - HP COMPRESSOR ROTOR 35C4781-01 AATPWACG030 REF: GENERIC NO REF	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		(10500) 10499
LIFE LIMIT			10500						
725015	NO. 1 ENGINE - BALL ROLLER ANNULAR BEARING 35C0590-02 FCN286585 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725020	NO. 1 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY 35C4726-01 RWA22C514 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725025	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 35C4755-01 DYA327157 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725030	NO. 1 ENGINE - NO. 5 SEAL BEARING RUNNER 35C4886-01 EYA17090 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725035	NO. 1 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT 35C5549-01 UNA020791 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE VANE-RING 35C4971CL01 PDANE473 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725045	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE-RING 35C4622CL01 HLA062AA160 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8963 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH9002 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH9005 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0420 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0422 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0425 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0427 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0429 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0431 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0437 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8974 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0438 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0439 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0441 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0442 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0447 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0449 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0453 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0454 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0456 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8982 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0457 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0463 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0467 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0468 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0469 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0738 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0739 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0742 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0751 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0752 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8988 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1834 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1850 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1857 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1864 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1865 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1881 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3167 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3173 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3190 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8989 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBP5319 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8993 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH8996 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 1 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH9000 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
725050	NO. 1 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBH9001 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
726010	NO. 1 ENGINE - FLANGED ROLLER BEARING 3107449-01 FCN219389 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
726015	NO. 1 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING 35C3615-01 FCN281887 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
726020	NO. 1 ENGINE - ACCESSORY DRIVE GEAR SHAFT 35C5333-01 PKAAA205749 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
726025	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY 35C5141-01 RWA27C073 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		
727010	NO. 1 ENGINE - BYPASS DUCT ASSEMBLY 35C5332-01 FDA5199041 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2009 0 0		

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01

+ 72-00-00-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
		HRS/MSC	600	+10%			1121.6		
	REF: LMM 72-00-00	ENC					860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-212-802 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-212-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-212-804 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-212-805 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-212-806 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-215-801 (s)	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 72-00-00	HRS/MSC ENC	600	+10%			1121.6 860		
+ 72-00-00-215-802	NO. 2 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY PKG 2	MOS	600	+10%			08-NOV-2013 579.4 438	(1179.4) 1179.4	1239.4
	REF: LMM 72-00-00	HRS/MSC ENC							
+ 72-00-00-215-803	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA PKG 2	MOS	600	+10%			08-NOV-2013 579.4 438	(1179.4) 1179.4	1239.4
	REF: LMM 72-00-00	HRS/MSC ENC							

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-280-802	NO. 2 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS	MOS					06-DEC-2018		
	REF: LMM 72-00-00	HRS/MSC A/R ENC					1071 829		
+ 72-00-00-290-815	NO. 2 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	MOS					28-APR-2016		
	REF: LMM 72-00-00	HRS/MSC 1750 ENC	+50				0 0	(1750) 1750	1800
+ 72-00-00-640-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					PKG		
	PKG 1	HRS/MSC 12 ENC	+30d +10%				25-JUL-2019 1121.6 860		
	REF: LMM 72-00-00								
72-00-02-810-801	NO. 2 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM	MOS					28-APR-2016		
	REF: LMM 72-00-02	HRS/MSC O/C ENC					0 0		
+ 72-30-04-000-803	NO. 2 ENGINE - REPLACE FRONT NO. 4 BEARING CARBON SEAL	MOS					28-APR-2016		
	PN SN-UNKNOWN	HRS/MSC 1750 ENC	+50	TSN:0 TSN:0			0 0	(1750) 1750	1800
	LIFE LIMIT REF: See Workcard								
+ 72-30-04-000-804	NO. 2 ENGINE - REPLACE REAR NO. 4 BEARING CARBON SEAL	MOS					28-APR-2016		
	PN SN-UNKNOWN	HRS/MSC 1750 ENC	+50	TSN:0 TSN:0			0 0	(1750) 1750	1800
	LIFE LIMIT REF: See Workcard								
+ 72-60-01-000-805	NO. 2 ENGINE - DISCARD THE STARTER GENERATOR GEAR-SHAFT SPLINE ADAPTER	MOS					28-APR-2016		
	PN SN-UNKNOWN	HRS/MSC 1750 ENC	+50	TSN:0 TSN:0			0 0	(1750) 1750	1800
	DISCARD REF: See Workcard								
+ 720000	NO. 2 ENGINE - PERFORM ENGINE OVERHAUL	MOS					28-APR-2016		
	REF: GENERIC NO REF	HRS/MSC 3500 ENC	+100				0 0	(3500) 3500	3600

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720001	NO. 2 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION	MOS					28-APR-2016		
	REF: See Workcard	HRS/MSC	1750	+50			0	(1750) 1750	1800
		ENC					0		
+ 720003	NO. 2 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)	MOS	144	+1m			28-APR-2016	28-APR-2028	28-MAY-2028
	REF: GENERIC NO REF	HRS/MSC					0		
		ENC					0		
+ 720010	NO. 2 ENGINE - FAN ROTOR	MOS					28-APR-2016		
	35C3881-01	HRS/MSC			TSN:0		0		
	AATTWABO040	ENC			TSN:0		0		
LIFE LIMIT	REF: GENERIC NO REF		10500		TSN:0		0	(10500) 10499	
+ 720030 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF EXTERIOR SURFACES OF THE NACELLE FOR EVIDENCE OF OIL LEAKS	MOS	12	+30d			25-JUL-2019		
	PKG 1	HRS/MSC	600	+10%			1121.6		
	REF: GENERIC NO REF	ENC					860		
+ 721010	NO. 2 ENGINE - HP TURBINE DISK	MOS					28-APR-2016		
	35C3091-01	HRS/MSC	N/A		TSN:0		0		
	CRAZADLZ032	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		
721015	NO. 2 ENGINE - HP TURBINE DISK BALANCING ASSEMBLY	MOS					28-APR-2016		
	PN	HRS/MSC	O/C		TSN:0		0		
	SN-UNKNOWN	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		
+ 721020	NO. 2 ENGINE - LP TURBINE DISK	MOS					28-APR-2016		
	35C5392-01	HRS/MSC	N/A		TSN:0		0		
	A002FMP8	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		
721025	NO. 2 ENGINE - LP TURBINE DISK BALANCING ASSEMBLY	MOS					28-APR-2016		
	PN	HRS/MSC	O/C		TSN:0		0		
	SN-UNKNOWN	ENC			TSN:0		0		
	REF: GENERIC NO REF				TSN:0		0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723002 (1)	NO. 2 ENGINE - FAN CASE 35C5323-01 NYAB00004122 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723002 (2)	NO. 2 ENGINE - ASSEMBLY OF FAN CASE 35C5324-01 NYAB00004122 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723003	NO. 2 ENGINE - FLANGED BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
+ 723010	NO. 2 ENGINE - IMPELLER AND SHAFT ASSEMBLY 35C4716-01 AAPPIACG2030 REF: GENERIC NO REF	MOS HRS/MSC ENC	10500	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		(10500) 10499
+ 723015	NO. 2 ENGINE - LP COMPRESSOR SHAFT 35C4620-01 KWA4841010 REF: GENERIC NO REF	MOS HRS/MSC ENC	10500	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		(10500) 10499
723020	NO. 2 ENGINE - TOWERSHAFT BALL ANNULAR BEARING 35C2168-01 FCN200055 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723025	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 35C4832-01 FCN285015 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723030	NO. 2 ENGINE - LP SHAFT BALL ANNULAR BEARING 35C5051-01 FCN288209 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723035	NO. 2 ENGINE - LP SHAFT BALL FLANGED BEARING 35C4831-01 FCN292195 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723040	NO. 2 ENGINE - TOWERSHAFT ROLLER BEARING 3107496-01 FCN196268 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723045	NO. 2 ENGINE - HIGH COMPRESSOR ROTOR ROLLER BEARING 35C4534-01 FCN289477 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY 35C5325-01 NYAB00004122 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723055	NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY 35C4935-01 RWA25C517 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723060	NO. 2 ENGINE - HIGH PRESSURE DIFFUSER CASE ASSEMBLY 35C4860-01 RWA25C570 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723065	NO. 2 ENGINE - LOWER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 35C5334-01 PKAAA239944 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723070	NO. 2 ENGINE - UPPER SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 35C3627-01 PKAAA243199 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723075	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR 35C3628-01 PKAAA243042 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723080	NO. 2 ENGINE - IMPELLER CENTRIFUGAL ASSEMBLY 35C4714-01 AAPPIACG2030 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723085	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 35C5326-01 EYA16702 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723090	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 35C4623-01 EYA17127 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723095	NO. 2 ENGINE - COMPRESSOR STATOR ASSEMBLY 35C5330-01 PKAAA255215 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
723110	NO. 2 ENGINE - HOUSING IMPELLER ASSEMBLY 35C5211-01 RWA27C429 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
724010	NO. 2 ENGINE - INNER COMBUSTOR CHAMBER LINER ASSEMBLY 35C5050-01 A002KE4B REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
724015	NO. 2 ENGINE - OUTER COMBUSTOR CHAMBER LINER ASSEMBLY 35C5053-01 A002KH7D REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725006	NO. 2 ENGINE - ANNULAR ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725008	NO. 2 ENGINE - NO.5 BEARING CARBON SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
+ 725010	NO. 2 ENGINE - HP COMPRESSOR ROTOR 35C4781-01 AATPWACG058 REF: GENERIC NO REF	MOS HRS/MSC ENC	10500	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0	(10500) 10499	
725015	NO. 2 ENGINE - BALL ROLLER ANNULAR BEARING 35C0590-02 FCN286580 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725020	NO. 2 ENGINE - HIGH PRESSURE TURBINE CASE ASSEMBLY 35C4726-01 RWA09C434 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725025	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 35C4755-01 DYA326855 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725030	NO. 2 ENGINE - NO. 5 SEAL BEARING RUNNER 35C4886-01 EYA16616 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725035	NO. 2 ENGINE - HIGH PRESSURE TURBINE TIE SHAFT 35C5549-01 UNA020799 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE VANE-RING 35C4971CL01 PDANE538 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725045	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE-RING 35C4622CL01 HLA062AA219 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.1 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0294 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.10 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0303 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.11 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0305 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.12 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0307 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.13 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0308 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.14 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0309 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.15 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0310 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.16 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0313 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.17 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0314 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.18 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0315 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.19 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1814 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.2 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0295 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.20 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1824 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.21 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1825 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.22 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1830 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.23 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1833 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.24 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1837 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.25 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1843 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.26 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1866 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.27 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1874 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.28 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1877 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.29 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1880 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.3 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0296 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.30 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.31 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1888 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.32 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1889 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.33 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1893 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.34 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK1903 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.35 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3169 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.36 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3172 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.37 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3183 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.38 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3193 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.39 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3195 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.4 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0297 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.40 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3197 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.41 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3200 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.42 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3201 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.43 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK3211 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.44 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBP5293 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.45 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBP5298 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.46 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBP8603 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.47 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBT9640 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.48 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBT9641 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.49 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBT9645 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.5 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0298 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.50 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBW0485 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725050	NO. 2 ENGINE - NO.6 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0299 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.7 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0300 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.8 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0301 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
725050	NO. 2 ENGINE - NO.9 HIGH PRESSURE TURBINE BLADE 35C4901-01 HWBK0302 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
726010	NO. 2 ENGINE - FLANGED ROLLER BEARING 3107449-01 FCN219394 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
726015	NO. 2 ENGINE - STARTER GEARSHAFT BALL FLANGED BEARING 35C3615-01 FCN281882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
726020	NO. 2 ENGINE - ACCESSORY DRIVE GEAR SHAFT 35C5333-01 PKAAA205014 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
726025	NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY 35C5141-01 RWA27C063 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727010	NO. 2 ENGINE - BYPASS DUCT ASSEMBLY 35C5332-01 FDA5091562 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
73-21-01	LH ENG FULL AUTHORITY DIGITAL FADEC 35C4812-02 2008100004 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
73-21-01	RH ENG FULL AUTHORITY DIGITAL FADEC 35C4812-02 2008100016 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2009 0 0		
73-21-02	NO.1 W205 FADEC CH B FUS CTRL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-02	NO.2 W205 FADEC CH B FUS CTRL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-03	NO.1 W203 FADEC CH A FUS CTRL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-03	NO.2 W203 FADEC CH A FUS CTRL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-09	NO.1 W307 FADEC CH B HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-21-09	NO.2 W307 FADEC CH B HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-10	NO.1 W305 FADEC CH A HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-21-10	NO.2 W305 FADEC CH A HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-33-01	LH ENG FUEL FLOW METER 8TJ300AAF2 20730 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
73-33-01	RH ENG FUEL FLOW METER 8TJ300AAF2 20718 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-JUL-2009 0 0		
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01									
+ 73-10-04-000-801	NO. 1 ENGINE - FUEL MANIFOLD 35C4916-01 DE1BCH1242 REF: GENERIC NO REF	MOS HRS/MSC ENC	1750	+50	TSN:0 TSN:0 TSN:0		28-APR-2009 0 0	(1750) 1750	1800
+ 73-10-05-000-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+10%			06-DEC-2018 1071 830	(1671) 1671	1731
+ 73-10-05-220-801	NO. 1 ENGINE - DETAILED INSPECTION 2 FUEL FILTER REF: LMM 73-10-05	MOS HRS/MSC ENC	12	+30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-07-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: LMM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: LMM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-30-02-212-801 (s)	NO. 1 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON PKG 1 REF: LMM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-30-02-215-801 (s)	NO. 1 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR PKG 1 REF: LMM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
731002 OVERHAUL	NO. 1 ENGINE - FUEL TO OIL HEAT EXCHANGER 35C4540-01 WA35325 REF: See Workcard	MOS HRS/MSC ENC	3500	+100	TSN:0 TSN:0 TSN:0		28-APR-2009 0 0	(3500) 3500	3600
732101 OVERHAUL	NO. 1 ENGINE - FUEL METERING UNIT 1009000-4 F70537 REF: See Workcard	MOS HRS/MSC ENC	3500	+100	TSN:0 TSR:0 TSN:0 TSR:0 TSN:0 TSR:0		26-SEP-2011 253 186	(3753) 3753	3853
732108	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2009 0 0		
732110	NO. 1 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILED INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+100			(EBT) 	(3500) 3500	3600

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732244	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL 1009211-2-005 2011270050 REF: See Workcard	MOS HRS/MSC ENC	O/C				21-JUL-2014 608.4 462		
733002	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR 35C5593-01 WDA114397 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:1 TSN:0 TSN:0		26-SEP-2011 253 186		
733010	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2009 0 0		
733020	NO. 1 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
733030	NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01									
+ 73-10-04-000-801	NO. 2 ENGINE - FUEL MANIFOLD 35C4916-01 DE1BCK0850 REF: GENERIC NO REF	MOS HRS/MSC ENC	1750	+50			28-APR-2016 0 0	(1750) 1750	1800
+ 73-10-05-000-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+10%			21-OCT-2014 620.1 487	(1220.1) 1220.1	1280.1
+ 73-10-05-220-801	NO. 2 ENGINE - DETAILED INSPECTION 2 FUEL FILTER REF: LMM 73-10-05	MOS HRS/MSC ENC	12	+30d			25-JUL-2019 1121.6 860	25-JUL-2020	24-AUG-2020

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-07-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: LMM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: LMM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-30-02-212-801 (s)	NO. 2 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON PKG 1 REF: LMM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 73-30-02-215-801 (s)	NO. 2 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR PKG 1 REF: LMM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
731002	NO. 2 ENGINE - FUEL TO OIL HEAT EXCHANGER 35C4540-01 WA34931 REF: See Workcard	MOS HRS/MSC ENC	3500	+100	TSN:0 TSN:0 TSN:0		28-APR-2016 0 0	(3500) 3500	3600
732101	NO. 2 ENGINE - FUEL METERING UNIT 1009000-4 F82085 REF: See Workcard	MOS HRS/MSC ENC	3500	+100	TSO:0 TSN:690.3 TSO:0 TSN:600 TSO:0		15-DEC-2018 1079 834	(4579) 4579	4679
732108	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2016 0 0		
732110	NO. 2 ENGINE - ENGINE ELECTRICAL WIRING HARNESS - DO A SPECIAL DETAILED INSPECTION REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+100			(EBT) 	(3500) 3500	3600

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732244	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL 1009211-2-005 2011050016 REF: See Workcard	MOS HRS/MSC ENC	O/C				21-JUL-2014 608.4 462		
733002	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR 35C5593-01 WDA114262 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			26-SEP-2011 253 186		
733010	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
733020	NO. 2 ENGINE - FUEL FILTER IMPENDING BYPASS INDICATOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
733030	NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR (POP-UP) - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01

+ 74-00-01-720-801 (s)	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM PKG 1 REF: LMM 74-00-01	MOS HRS/MSC ENC	12	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 74-10-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER PKG 1 REF: LMM 74-10-01	MOS HRS/MSC ENC	12	+30d +10%			PKG 25-JUL-2019 1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-20-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 74-20-01	HRS/MSC ENC	600	+10%			1121.6 860		
74-20-02-220-801 (s)	NO. 1 ENGINE - INSPECT THE IGNITION IGNITERS PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: See Workcard	HRS/MSC ENC	600	+10%			1121.6 860		
741001	NO. 1 ENGINE - IGNITION EXCITER 35C5472-01 WDA108033	MOS					28-APR-2009		
	REF: See Workcard	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
741002	NO. 1 ENGINE - LEFT IGNITER CABLE PN	MOS					28-APR-2009		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	REF: See Workcard	ENC							
741003	NO. 1 ENGINE - RIGHT IGNITER CABLE PN	MOS					28-APR-2009		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
	REF: See Workcard	ENC							
+ 741004	NO. 1 ENGINE - INBOARD SPARK IGNITER 35C2353-01	MOS					08-NOV-2013		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:2 TSN:0 TSN:0		579.4 438		
	REF: LMM 74-20-02	ENC							
+ 741005	NO. 1 ENGINE - OUTBOARD SPARK IGNITER 35C2353-01	MOS					08-NOV-2013		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:2 TSN:0 TSN:0		579.4 438		
	REF: LMM 74-20-02	ENC							
741010	NO. 1 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION	MOS					(EBT)		
	REF: LMM 74-10-01	HRS/MSC ENC	3500	+100				(3500) 3500	3600

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741020	NO. 1 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST	MOS					(EBT)		
	REF: See Workcard	HRS/MSC ENC	3500	+100				(3500) 3500	3600
741030	NO. 1 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST	MOS					(EBT)		
	REF: See Workcard	HRS/MSC ENC	3500	+100				(3500) 3500	3600
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01									
+ 74-00-01-720-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF THE IGNITION SYSTEM						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
	REF: LMM 74-00-01	HRS/MSC ENC	600	+10%			1121.6		860
+ 74-10-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
	REF: LMM 74-10-01	HRS/MSC ENC	600	+10%			1121.6		860
+ 74-20-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
	REF: LMM 74-20-01	HRS/MSC ENC	600	+10%			1121.6		860
74-20-02-220-801 (s)	NO. 2 ENGINE - INSPECT THE IGNITION IGNITERS						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
	REF: See Workcard	HRS/MSC ENC	600	+10%			1121.6		860
741001	NO. 2 ENGINE - IGNITION EXCITER								
	35C5472-01	MOS				TSN:0	28-APR-2016		
	WDA108105	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	ENC				TSN:0	0		
741002	NO. 2 ENGINE - LEFT IGNITER CABLE								
	PN	MOS				TSN:0	28-APR-2016		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	ENC				TSN:0	0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741003	NO. 2 ENGINE - RIGHT IGNITER CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
+ 741004	NO. 2 ENGINE - INBOARD SPARK IGNITER 35C2353-01 SN-UNKNOWN REF: LMM 74-20-02	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			08-NOV-2013 579.4 438		
+ 741005	NO. 2 ENGINE - OUTBOARD SPARK IGNITER 35C2353-01 SN-UNKNOWN REF: LMM 74-20-02	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			08-NOV-2013 579.4 438		
741010	NO. 2 ENGINE - IGNITION EXCITER - DO A GENERAL VISUAL INSPECTION REF: LMM 74-10-01	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
741020	NO. 2 ENGINE - LEFT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
741030	NO. 2 ENGINE - RIGHT IGNITER CABLE - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	

CHAPTER 75

AIR

ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01

+ 75-30-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA PKG 1 REF: LMM 75-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
------------------------	---	-----------------------	-----------	--------------	--	--	-------------------------------------	--	--

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
751003	NO. 1 ENGINE - BLEED VALVE ACTUATOR								
	35C2851-02	MOS		TSN:0			28-APR-2009		
	16446671	HRS/MSC	3500 +100	TSN:0			0	(3500) 3500	3600
OVERHAUL	REF: See Workcard	ENC		TSN:0			0		
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01									
+ 75-30-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA						PKG		
	PKG 1	MOS	12 +30d				25-JUL-2019		
		HRS/MSC	600 +10%				1121.6		
	REF: LMM 75-30-01	ENC					860		
751003	NO. 2 ENGINE - BLEED VALVE ACTUATOR								
	35C2851-02	MOS		TSN:0			28-APR-2016		
	16445114	HRS/MSC	3500 +100	TSN:0			0	(3500) 3500	3600
OVERHAUL	REF: See Workcard	ENC		TSN:0			0		
CHAPTER 76 ENGINE CONTROLS									
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY								
	6990010-11	MOS		TSN:0			25-JUL-2009		
	1046	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
CHAPTER 77 ENGINE INDICATING									
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01									
+ 77-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM						PKG		
	PKG 1	MOS	12 +30d				25-JUL-2019		
		HRS/MSC	600 +10%				1121.6		
	REF: LMM 77-20-02	ENC					860		
+ 77-20-02-710-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM								
		MOS	36 +30d				06-DEC-2018	06-DEC-2021	05-JAN-2022
		HRS/MSC	1750 +50				1071	(2821) 2821	2871
	REF: LMM 77-20-02	ENC					829		
772002	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY								
	PN	MOS		TSN:0			28-APR-2009		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	ENC		TSN:0			0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772010	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT)	(3500) 3500	3600
772103	NO. 1 ENGINE - DATA COLLECTION UNIT 35C5571-01 DP09-1133 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2009 0 0		
772110	NO. 1 ENGINE - DO A DCU INTEGRITY VERIFACTION REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT)	(3500) 3500	3600
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01									
+ 77-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: LMM 77-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 25-JUL-2019 1121.6 860		
+ 77-20-02-710-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM REF: LMM 77-20-02	MOS HRS/MSC ENC	36 1750	+30d +50			06-DEC-2018 1071 829	06-DEC-2021 (2821) 2821	05-JAN-2022 2871
772002	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2016 0 0		
772010	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS ASSEMBLY - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT)	(3500) 3500	3600
772103	NO. 2 ENGINE - DATA COLLECTION UNIT 35C5571-01 DP09-1120 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-APR-2016 0 0		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
772110	NO. 2 ENGINE - DO A DCU INTEGRITY VERIFACTION	MOS					(EBT)		
	REF: See Workcard	HRS/MSC ENC	3500	+100				(3500) 3500	3600
CHAPTER 79 OIL									
79-31-01	LH ENG OIL TEMPERATURE PRESSURE SENSOR								
	PT9903-275-40012	MOS					25-JUL-2009		
	D808-2189	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
79-31-01	RH ENG OIL TEMPERATURE PRESSURE SENSOR								
	PT9903-275-40012	MOS					25-JUL-2009		
	D808-2186	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0069 Part # 3503100-01									
+ 79-00-00-640-803	NO. 1 ENGINE - OIL CHANGE INTERVAL								
		MOS					28-APR-2009		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 79-20-01-000-801	NO. 1 ENGINE - DISCARD OIL FILTER								
	PKG 2	MOS					21-OCT-2014		
	REF: See Workcard	HRS/MSC ENC	600	+10%			620.1 487	(1220.1) 1220.1	1280.1
+ 79-20-03-000-805-A	NO. 1 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE								
	PN	MOS					28-APR-2009		
	SN-UNKNOWN	HRS/MSC	1750	+50			0	(1750) 1750	1800
	REF: LMM 79-20-03	ENC					0		
	LIFE LIMIT								
+ 79-30-01-720-801 (s)	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR						PKG		
	PKG 1	MOS	12	+30d			25-JUL-2019		
	REF: GENERIC NO REF	HRS/MSC ENC	600	+10%			1121.6 860		

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#1: S/N PCE-LC0069

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-30-02-210-802 (s)	NO. 1 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 79-30-02	HRS/MSC ENC	600	+10%			1121.6 860		
+ 79-30-02-215-801 (s)	NO. 1 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR PKG 1	MOS	12	+30d			PKG 25-JUL-2019		
	REF: LMM 79-30-02	HRS/MSC ENC	600	+10%			1121.6 860		
792007	NO. 1 ENGINE - AIR COOLED OIL COOLER 35C2495-05 WA35407	MOS					28-APR-2009		
OVERHAUL	REF: See Workcard	HRS/MSC ENC	3500	+100	TSN:0 TSN:0 TSN:0		0 0 0	(3500) 3500	3600
792010	NO. 1 ENGINE - P3 AIR COOLER ASSEMBLY 35C5545-01 TYAB0545	MOS					28-APR-2009		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
793001	NO. 1 ENGINE - CHIP DETECTOR PN SN-UNKNOWN	MOS					28-APR-2009		
	REF: See Workcard	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
793002	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN	MOS					28-APR-2009		
	REF: See Workcard	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
793010	NO. 1 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST	MOS					(EBT)		
	REF: See Workcard	HRS/MSC ENC	3500	+100				(3500) 3500	3600
793020	NO. 1 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST	MOS					(EBT)		
	REF: See Workcard	HRS/MSC ENC	3500	+100				(3500) 3500	3600

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0070 Part # 3503100-01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-00-00-640-803	NO. 2 ENGINE - OIL CHANGE INTERVAL	MOS					28-APR-2016		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 79-20-01-000-801	NO. 2 ENGINE - DISCARD OIL FILTER	MOS					21-OCT-2014		
	PKG 2	HRS/MSC ENC	600	+10%			620.1 487	(1220.1) 1220.1	1280.1
	REF: See Workcard								
+ 79-20-03-000-805-A	NO. 2 ENGINE - DISCARD THE NO. 4 BEARING OIL-PRESSURE TUBE	MOS					28-APR-2016		
	PN	HRS/MSC ENC	1750	+50	TSN:0 TSN:0		0 0	(1750) 1750	1800
	SN-UNKNOWN								
	REF: LMM 79-20-03								
	LIFE LIMIT								
+ 79-30-01-720-801 (s)	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR	MOS					PKG		
	PKG 1	HRS/MSC ENC	12	+30d +10%			25-JUL-2019 1121.6 860		
	REF: GENERIC NO REF								
+ 79-30-02-210-802 (s)	NO. 2 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON	MOS					PKG		
	PKG 1	HRS/MSC ENC	12	+30d +10%			25-JUL-2019 1121.6 860		
	REF: LMM 79-30-02								
+ 79-30-02-215-801 (s)	NO. 2 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR	MOS					PKG		
	PKG 1	HRS/MSC ENC	12	+30d +10%			25-JUL-2019 1121.6 860		
	REF: LMM 79-30-02								
792007	NO. 2 ENGINE - AIR COOLED OIL COOLER	MOS					28-APR-2016		
	35C2495-05	HRS/MSC ENC	3500	+100	TSN:0 TSN:0		0 0	(3500) 3500	3600
	WA35398								
	REF: See Workcard								
	OVERHAUL								
792010	NO. 2 ENGINE - P3 AIR COOLER ASSEMBLY	MOS					28-APR-2016		
	35C5545-01	HRS/MSC ENC	O/C		TSN:0 TSN:0		0 0		
	TYAB0548								
	REF: GENERIC NO REF								

Status Report

EMB-500 - PHENOM 100 S/N 50000037 (N100WX): 1140.3 HRS, 869 AFL as of 13-Sep-2019

ENGINE#2: S/N PCE-LC0070

1140.3 HRS, 870 ENC

Owner/Operator: KING OF THE SKIER LLC

Report Date: 26-OCT-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793001	NO. 2 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
793002	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-APR-2016 0 0		
793010	NO. 2 ENGINE - CHIP DETECTOR - DO A VISUAL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	
793020	NO. 2 ENGINE - OIL FILTER IMPENDING BYPASS INDICATOR (POP-UP) - DO A DETAIL INSPECTION AND FUNCTIONAL TEST REF: See Workcard	MOS HRS/MSC ENC	3500	+100			(EBT) (3500) 3500	3600	