

South Seas Club – Update 10/31

Due to work being done in the units, HGV had limited access. Progress is underway :

- Moisture mapping is completed
- Dry wall is marked and being removed
- Furniture, kitchen, and bathrooms are bagged with dehumidifiers to remove all moisture
- Harborview garage has been utilized as drying station for all furniture.
- No replacement LVT flooring at South Seas Club is needed

South Seas Club Photos – 10/29

























