

**RIM VILLAGE HOMEOWNERS ASSOCIATION  
P.O. Box 1583, Moab, Utah 84532**



**October 17<sup>th</sup>, 2019**

**Dear Rim Village Homeowner,**

**It has come to our attention that during the building of Rim Village staples were used near the gas lines to the fireplaces. There have been three incidences where staples have pierced the gas line causing a pin hole leak. If you smell gas please report it to the gas company, Dominion Energy. 800 767 1689**

**Thank You.**

**Rim Village Board of Directors  
Sharon Butler      Mel Taylor  
Jay Beauregard    Bob Ward**