

#### **Insurable Value / Replacement Cost Appraisal**

#### **LOCATED AT:**

633 Edgewater Drive et al Deerfield Beach, FL 33442

#### FOR:

The Lakes of Deer Creek Condominium Association, Inc. 3303 W Commercial Blvd, # 170
Ft. Lauderdale, FL 33309

#### AS OF:

May 16th, 2019

#### BY:

Paul R Cassidy, Cert Gen RZ3176 All Florida Appraisal Group, Inc. 500 S Cypress Road, # 3 Pompano Beach, FL 33060 954/240-8911 (phone); 954/653-0637 (fax) pcassidy02@aol.com A

# RESTRICTED USE Insurable Value / Replacement Cost APPRAISAL REPORT OF:

# 16 Buildings Located at:

# The Lakes of Deer Creek Condominium Deerfield Beach, Florida 33442

Date of Inspection:

May 16<sup>th</sup>, 2019

File Number: 0519-P13222

FOR:

# The Lakes of Deer Creek Condominium Association, Inc.

BY:

Paul R. Cassidy State Certified General REA #RZ3176 Certified Marshall & Swift Estimator # 1055763

ALL FLORIDA APPRAISAL GROUP 500 S Cypress Road, # 3 Pompano Beach, Florida 33060 954/240-8911 (phone); 954/653-0637 (fax) pcassidy02@aol.com Paul R. Cassidy State Certified General R.E. Appraiser #RZ3176 All Florida Appraisal Group 500 S Cypress Road, # 3 Pompano Beach, FL 33060

P (954) 240-8911 F (954) 653-0637 pcassidy02@aol.com

The Lakes of Deer Creek Condominium Association, Inc. c/o TMG Property Management 3303 W Commercial Blvd, # 170 Ft. Lauderdale, FL 33309

May 17<sup>th</sup>, 2019

Reference/Address: The Lakes of Deer Creek Condominium

16 Buildings, 91 Units + Common Areas

Deerfield Beach, Florida 33442

#### Board of Directors:

In accordance with your request, we have appraised the above referenced residential condominium buildings and common area improvements. The report of that appraisal is attached. The sole objective and purpose of this report is to establish an estimate of insurable value (replacement cost) for insurance purposes as of May 16<sup>th</sup>, 2019. This appraisal report is intended for sole use by the Client / Named Insured in obtaining adequate hazard insurance.

This report is based on a physical analysis of the site and improvements. The report was developed, and the report was prepared in accordance with the Uniform Standards of Professional Appraisal Practice. This report is a real estate consulting service and is not a market value appraisal. The following report was prepared in conformity with Standards 4 and 5 of the Uniform Standards of Professional Appraisal Practice (USPAP). Standard 4 addresses the performance of consulting services by an appraiser. Standard 5 addresses the reporting requirements of consulting services by an appraiser. This report is appropriate for the needs of our client and should not be used for any other purpose or submitted to any other person/party. It is also important that the reader does not confuse the value conclusion reported herein with an estimate of market value.

The Lakes of Deer Creek Condominium May 17<sup>th</sup>, 2019 Page Two

Based upon our analysis, it was concluded that the Estimated Insurable Value / Construction Cost for the buildings as of May  $16^{th}$ , 2019 (building and site improvements only - not including land value) to be:

Hazard Value: \$15,654,982.00

Parcif

[Including Site Improvements; See next page for detail]

Respectfully submitted,

Paul R. Cassidy

State Certified General Real Estate Appraiser # RZ3176

Certified Marshall & Swift Estimator # 1055763

# SUMMARY OF VALUES

Bldg	Association Name	#	Total RCV	Below Ground	Hazard Value (including HVAC)
#	Building Street Address / Identification	Units	(above & below ground)	Exclusions	(excluding interiors St. 718)
	The Lakes of Deer Creek COA				
_	3000 - 3010 Lake Shore Dr	9	\$946,604.00	\$64,361.00	\$882,243.00
2	3016 - 3026 Lake Shore Dr	9	\$946,604.00	\$64,361.00	\$882,243.00
3	3032 - 3042 Lake Shore Dr	9	\$946,604.00	\$64,361.00	\$882,243.00
4	3048 - 3058 Lake Shore Dr	9	\$946,604.00	\$64,361.00	\$882,243.00
2	3064 - 3074 Lake Shore Dr	9	\$946,604.00	\$64,361.00	\$882,243.00
27	3109 - 3119 Lake Shore Dr	9	\$1,065,435.00	\$53,655.00	\$1,011,780.00
28	3067 - 3073 Lake Shore Dr	4	\$797,451.00	\$42,289.00	\$755,162.00
29	3035 - 3041 Lake Shore Dr	4	\$739,931.00	\$39,752.00	\$700,179.00
30	3017 - 3027 Lake Shore Dr	9	\$1,065,435.00	\$53,655.00	\$1,011,780.00
31	3001 - 3011 Lake Shore Dr	9	\$1,065,435.00	\$53,655.00	\$1,011,780.00
32	606 - 636 Lake Point N Ln	9	\$1,129,002.00	\$56,178.00	\$1,072,824.00
33	642 - 654; 645 - 657 Lake Point N Ln	9	\$1,111,196.00	\$55,503.00	\$1,055,693.00
34	609 - 639 Lake Point N Ln	9	\$1,156,671.00	\$57,337.00	\$1,099,334.00
35	608 - 628 Edgewater Dr	9	\$988,280.00	\$50,285.00	\$937,995.00
36	632 - 652 Edgewater Dr	9	\$1,016,642.00	\$51,477.00	\$965,165.00
37	656 - 672 Edgewater Dr	2	\$936,187.00	\$48,218.00	\$887,969.00
∢	633 Edgewater Dr (Club)	0	\$487,911.00	\$29,917.00	\$457,994.00
В	Storage Building	0	\$9,422.00	\$365.00	\$9,057.00
	Building Totals	91	\$16,302,018.00	\$914,091.00	\$15,387,927.00

Additional Improvements		Cost New		Cost New
Swimming Pool		\$120,000.00		\$120,000.00
Pool Patio / Deck		\$28,000.00		\$28,000.00
Spa		\$18,500.00		\$18,500.00
Patio Walls / Fencing		\$24,150.00		\$24,150.00
Pool/Spa Equipment		\$28,400.00		\$28,400.00
Pool/Spa Heaters (3)		\$14,775.00		\$14,775.00
Identification Signs (3)		\$11,500.00		\$11,500.00
Mailbox Shelters (4)		\$6,000.00		\$6,000.00
Mailbox Clusters (12)		\$15,730.00		\$15,730.00
Total Additional Improvements		\$267,055.00		\$267,055.00
Grand Totals	91	\$16,569,073.00	\$914,091.00	\$15,654,982.00
Effective Date: 05/16/2019				

# SUMMARY OF SALIENT FACTS

**Valuation Date:** May 16<sup>th</sup>, 2019

**Appraisal Type:** Insurable Value/ Replacement Cost Estimate

**Property Rights** 

Fee Simple for Improvements only – Insurable / Replacement

**Appraised:** Cost (Construction Cost) value

**Location / Address:** 633 Edgewater Dr et al, Deerfield Beach, Florida 33442

**County:** Broward

**Property Owner(s):** Ninety-one (91) residential condominium units

Name Insured: The Lakes of Deer Creek Condominium Association, Inc.

**Zoning:** RM-15 (Residential Multi-Family)

Year Built: 1982

**Site Information:** Seventeen irregular shaped parcels totaling 1,851,300 +/- square

feet and/or 42.51 acres.

**Census Tract:** The buildings are located in Census Tract 0103.08.

(Source: US Census Bureau)

#### Flood Data:

The buildings are not located within a flood zone area per the National Flood Insurance Program; Map Number 12011C0159H dated 08/18/2014. The subject is located in Flood Zone "X". See Flood Certificate or Survey for confirmation and which, if different, will supersede the information in this section.

#### **Folio Numbers:**

Condominium ownership beginning with 47-42-34-AC-0010 through 47-42-34-AC-0500

**Distance to Fire Hydrant:** Less than 1,000 feet

**Distance to Tidal Water:** 4.71 miles east

#### **Building Improvements:**

The Lakes of Deer Creek consists of sixteen (16) detached one and two-story villa & townhouse style residential condominium owned buildings. The buildings have 4, 5 or 6 individual units each and the complex as a whole has 91 privately owned condominium units. Each unit includes an entry / rear terrace area and/or courtyard area. Please note that some of these areas may have been modified by the individual owners. The association is not responsible for any of these alterations and the values shown in this report are for the replacement cost of the original structure items. The buildings frame structures are composed of reinforced concrete block (CBS) wall construction with poured concrete columns and beams. Exterior finishes are stucco and paint. The elevated floors are estimated to be concrete decks. The buildings foundations are poured, steel reinforced concrete slabs over pilings. Finished interior construction includes drywall partitions with steel & wood stud framing. The buildings have pitched, wood truss, gable & hip style roofs built up with a plywood deck and finished with concrete tiles. The plumbing includes connections for a single kitchen and bathrooms per each unit. The HVAC is provided via individual split systems with only the air handlers and thermostats located within each residence. Each unit includes owner-maintained smoke detectors and interior stairwells provide egress from the upper floor.

#### See attached surveys, floor plans and photograph addendums.

**Overall Condition:** The buildings have received adequate routine continual maintenance and are considered to be in overall good condition.

**ISO Construction Class 2 (Joisted Masonry):** The buildings were visited and on-site measurements performed and compared to those of architectural plans provided as well as the Broward County tax rolls for accuracy.

#### Additional Structures & Improvements (as requested by the client):

- 1) Swimming Pool, Spa & Patio Area: Reinforced concrete and gunite in-ground swimming pool, separate spa with an extended brick paver patio / deck. Approximate 3.5' masonry walls topped with metal fencing and self-closing gates surrounds the patio area. Pool/Spa equipment located in fiberglass shelter; pool/spa heaters located on slab on ground.
- 2) Storage Building: Wood frame wall construction, concrete slab and a pitched, wood truss roof finished with concrete tiles. 192 square feet. ISO Construction Class 1 (Frame).

- 3) Identification / Monument Walls (3): Metal frame finished with foam, stucco, paint and raised lettering. End columns and concrete slab.
- 4) Mailbox Shelters: Wood post, pitched wood truss roof finished with shingles; standard, metal pedestal mailboxes.
- 5) Clubhouse Building: CBS, masonry and fixed glass wall construction, wood frame mansard style roof built-up; concrete slab. 3,962 square feet. ISO Construction Class 2 (Joisted Masonry).

Bldg #, Street Address / Identification; # of Units / Floors; Gross Building Area:

Bldg	Building Street	#	#	Enclosed Floor	Terr/Porch	Total Gross
#	Address / Identification	Units	Floors	Area (sqft)	Area (sqft)	Area (sqft)
1	3000 - 3010 Lake Shore Dr	6	1	8,725	880	9,605
2	3016 - 3026 Lake Shore Dr	6	1	8,725	880	9,605
3	3032 - 3042 Lake Shore Dr	6	1	8,725	880	9,605
4	3048 - 3058 Lake Shore Dr	6	1	8,725	880	9,605
5	3064 - 3074 Lake Shore Dr	6	1	8,725	880	9,605
27	3109 - 3119 Lake Shore Dr	6	2	9,773	905	10,678
28	3067 - 3073 Lake Shore Dr	4	2	7,041	599	7,641
29	3035 - 3041 Lake Shore Dr	4	2	6,449	571	7,020
30	3017 - 3027 Lake Shore Dr	6	2	9,773	905	10,678
31	3001 - 3011 Lake Shore Dr	6	2	9,773	905	10,678
32	606 - 636 Lake Point N Ln	6	2	10,464	943	11,407
33	642 - 654; 645 - 657 Lake Point N Ln	6	2	10,266	932	11,198
34	609 - 639 Lake Point N Ln	6	2	10,760	948	11,708
35	608 - 628 Edgewater Dr	6	2	8,983	851	9,834
36	632 - 652 Edgewater Dr	6	2	9,279	874	10,152
37	656 - 672 Edgewater Dr	5	2	8,407	842	9,249
Α	633 Edgewater Dr (Club)	0	1	3,281	681	3,962
В	Storage Building	0	1	192	0	192
	Totals	91		148,067	14,356	162,423

# **VALUATION ANALYSIS**

#### DIRECT SALES COMPARISON APPROACH TO VALUE

Not requested and not considered.

#### INCOME APPROACH TO VALUE

Not requested and not considered.

#### COST APPROACH TO VALUE

In the case of valuation for INSURANCE PURPOSES, there is NO IMPUTED DEPRECIATION, as the Improvements IF DESTROYED must be replaced in whole.

#### **DEFINITION OF INSURABLE VALUE:**

The following definition is used by the Appraisal Institute and others in the valuation industry.

- 1. The portion of the value of an asset or asset group that is acknowledged or recognized under the provisions of an applicable loss insurance policy.
- 2. Value used by insurance companies as the basis for insurance. Often considered to be replacement or reproduction cost less deterioration of non-insurable items. Sometimes cash value or market value, but often entirely a cost concept.

Cost estimates derived from Marshall & Swift / Boeckh BVS [now CoreLogic parent company] software with the most recent costs updates as of December 2018. Administrative and entrepreneurial profit included in price per square foot estimate. The buildings are condominium ownership and subject to the exclusions provided under Florida Statute 718.111. These exclusions are inputted in the building valuations shown in this report.

Porch / Terrace areas for the buildings were included under "Building Additions" and therefore not included in the gross floor area of the BVS reports.

See attached 12/2018 Marshall & Swift / Boeckh BVS report below.

Hazard Value

Policy: Lakes of	Deer Creek		5/17/2019
INSURED	Lakes of Deer Creek Condo Assc	Effective Date:	5/16/2019
	3303 W Commercial Blvd, # 170	Expiration Date:	
	Fort Lauderdale, FL 33309	Cost as of:	12/2018
BUILDING 1	Bldgs 1,2,3,4,5		
	see report		
	Deerfield Beach, FL 33442		
SECTION 1	CTURE		
CCI EROTRO	O I OILE		

100% Condominium, w/o Interior Finishes

100% Joisted Masonry (ISO 2)

Story Height: 9 ft.

Number of Stories:

Irregular Adjustment: Irregular

\$64,361

Вұ⋦-С

Gross Floor Area: 8,725 sq. ft.
Construction Quality: 2 - Average

Occupancy:

**TOTAL RC BUILDING1** 

Standard

Construction Type:

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,911	
Foundations	48,826	44,271	
Foundation Walls, Interior Foundations, Slab	On Ground		
Exterior	332,523		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	193,893		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	208,194	18,179	
Heating, Cooling, Fire Protection, Plumbing, E	Electrical, Elevators		
Built-ins	73,302		
SUBSTRUCTURE			
SUBTOTAL RC	\$856,738	\$64,361	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	25,505		
TOTAL RC SECTION 1	\$882,243	\$64,361	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldgs 1,2,3,4,5

\$882,243

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

BUILDING 2 Bldgs 27,30,31

see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

OURANA DV OF OCCTO

**TOTAL RC BUILDING2** 

Standard

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft. Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 9,773 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,070	
Foundations	27,345	32,249	
Foundation Walls, Interior Foundations, Slab O	n Ground		
Exterior	421,359		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	221,734		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	233,005	20,336	
Heating, Cooling, Fire Protection, Plumbing, Ele	ectrical, Elevators		
Built-ins	82,107		
SUBSTRUCTURE			
SUBTOTAL RC	\$985,550	\$53,655	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	26,230		
TOTAL RC SECTION 1	\$1,011,780	\$53,655	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldgs 27,30,31

\$1,011,780

\$53,655

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

BUILDING 3 Bldg 28

see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

**TOTAL RC BUILDING3** 

Standard

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 7,041 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		771	
Foundations	19,701	27,036	
Foundation Walls, Interior Foundations, Slab C	On Ground		
Exterior	330,359		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	161,960		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	166,627	14,482	
Heating, Cooling, Fire Protection, Plumbing, E	lectrical, Elevators		
Built-ins	59,154		
SUBSTRUCTURE			
SUBTOTAL RC	\$737,802	\$42,289	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	17,360		
TOTAL RC SECTION 1	\$755,162	\$42,289	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldg 28

\$755,162

\$42,289

Вұ⋦-С

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 4** 

Bldg 29

see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

**TOTAL RC BUILDING4** 

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft. Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 6,449 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		706	
Foundations	18,045	25,797	
Foundation Walls, Interior Foundations, Slab On	Ground		
Exterior	309,868		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	149,028		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	152,508	13,249	
Heating, Cooling, Fire Protection, Plumbing, Elec	trical, Elevators		
Built-ins	54,180		
SUBSTRUCTURE			
SUBTOTAL RC	\$683,629	\$39,752	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	16,550		
TOTAL RC SECTION 1	\$700,179	\$39,752	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldg 29

\$700,179

\$39,752

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 5** 

Bldg 32 see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

**TOTAL RC BUILDING5** 

Standard

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 10,464 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,146	
Foundations	29,279	33,464	
Foundation Walls, Interior Foundations, Slab C	n Ground		
Exterior	443,645		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	236,683		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	247,974	21,568	
Heating, Cooling, Fire Protection, Plumbing, El	ectrical, Elevators		
Built-ins	87,912		
SUBSTRUCTURE			
SUBTOTAL RC	\$1,045,494	\$56,178	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	27,330		
TOTAL RC SECTION 1	\$1,072,824	\$56,178	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldg 32

\$1,072,824

\$56,178

BYS-C

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 6** 

Bldg 33 see report

Deerfield Beach, FL 33442

**SECTION 1** 

Standard

**SUPERSTRUCTURE** 

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 10,266 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,124	
Foundations	28,725	33,119	
Foundation Walls, Interior Foundations, Slab O	n Ground		
Exterior	437,284		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	232,411		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	244,015	21,260	
Heating, Cooling, Fire Protection, Plumbing, Ele	ectrical, Elevators		
Built-ins	86,248		
SUBSTRUCTURE			
SUBTOTAL RC	\$1,028,683	\$55,503	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	27,010		
TOTAL RC SECTION 1	\$1,055,693	\$55,503	

TOTAL RC BUILDING6	Bldg 33	\$1,055,693	\$55,503	

BY&S-C

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 7** 

Bldg 34 see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

**TOTAL RC BUILDING7** 

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft. Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 10,760 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,178	
Foundations	30,107	33,974	
Foundation Walls, Interior Foundations, Slab On G	round		
Exterior	453,119		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	243,202		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	255,033	22,185	
Heating, Cooling, Fire Protection, Plumbing, Electr	ical, Elevators		
Built-ins	90,399		
SUBSTRUCTURE			
SUBTOTAL RC	\$1,071,859	\$57,337	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	27,475		
TOTAL RC SECTION 1	\$1,099,334	\$57,337	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldg 34

\$1,099,334

\$57,337

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

BUILDING 8 Bldg 35

see report

Deerfield Beach, FL 33442

**SECTION 1** 

Standard

**SUPERSTRUCTURE** 

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 8,983 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		984	
Foundations	25,135	30,814	
Foundation Walls, Interior Foundations, Slab On G	Ground		
Exterior	395,557		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	204,501		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	212,668	18,487	
Heating, Cooling, Fire Protection, Plumbing, Elect	rical, Elevators		
Built-ins	75,469		
SUBSTRUCTURE			
SUBTOTAL RC	\$913,330	\$50,285	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	24,665		
TOTAL RC SECTION 1	\$937,995	\$50,285	
TOTAL RC BUILDING8 Bldg 35	\$937,995	\$50,285	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 9** 

Bldg 36

see report

Deerfield Beach, FL 33442

#### **SECTION 1**

Standard

#### **SUPERSTRUCTURE**

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 9,279 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,016	
Foundations	25,963	31,358	
Foundation Walls, Interior Foundations, Slab 0	On Ground		
Exterior	405,267		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	210,921		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	219,727	19,103	
Heating, Cooling, Fire Protection, Plumbing, E	lectrical, Elevators		
Built-ins	77,956		
SUBSTRUCTURE			
SUBTOTAL RC	\$939,835	\$51,477	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	25,330		
TOTAL RC SECTION 1	\$965,165	\$51,477	

TOTAL RC BUILDING9	Bldg 36	\$965,165	\$51,477	

BYS-C

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 10** 

Bldg 37

see report

Deerfield Beach, FL 33442

**SECTION 1** 

**SUPERSTRUCTURE** 

**TOTAL RC BUILDING10** 

Standard

Occupancy: 100% Condominium, w/o Interior Finishes Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 2

Gross Floor Area: 8,407 sq. ft. Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		921	
Foundations	23,523	29,734	
Foundation Walls, Interior Foundations, Slab C	n Ground		
Exterior	376,503		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	191,962		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	200,946	17,563	
Heating, Cooling, Fire Protection, Plumbing, E	lectrical, Elevators		
Built-ins	70,630		
SUBSTRUCTURE			
SUBTOTAL RC	\$863,564	\$48,218	
ADDITIONS			
Misc. Additional Features:			
Terrace/Porch/W'way	24,405		
TOTAL RC SECTION 1	\$887,969	\$48,218	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bldg 37

\$887,969

\$48,218

Bys-C

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 11** 

Clubhouse

see report

Deerfield Beach, FL 33442

**SECTION 1** 

Standard

**SUPERSTRUCTURE** 

OURANA DV OF OCCTO

Occupancy: 100% Clubhouse/Recreation Building

Story Height: 12 ft.

Construction Type: 100% Joisted Masonry (ISO 2)

Number of Stories: 1

Gross Floor Area: 3,281 sq. ft.

Irregular Adjustment: Irregular

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		701	
Foundations	17,904	17,876	
Foundation Walls, Interior Foundations, Slab Or	n Ground		
Exterior	182,398		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	63,395		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	166,500	11,340	
Heating, Cooling, Fire Protection, Plumbing, Ele	ctrical, Elevators		
Built-ins	8,057		
SUBSTRUCTURE			
SUBTOTAL RC	\$438,254	\$29,917	
ADDITIONS			
Misc. Additional Features:			
Porch	19,740		
TOTAL RC SECTION 1	\$457,994	\$29,917	

TOTAL RC BUILDING11	Clubhouse	\$457,994	\$29,917	

Hazard Value

Policy: Lakes of Deer Creek 5/17/2019

**BUILDING 12** 

Storage Garage

n/a

Deerfield Beach, FL 33442

**SECTION 1** 

SUBSTRUCTURE
TOTAL RC SECTION 1

Standard

**TOTAL RC BUILDING12** 

**SUPERSTRUCTURE** 

Occupancy: 100% Utility Building, Storage Story Height: 9 ft.

Construction Type: 100% Frame (ISO 1) Number of Stories: 1

Gross Floor Area: 192 sq. ft. Irregular Adjustment: None

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		35	
Foundations	905	330	
Foundation Walls, Interior Foundations, Slab On Gro	ound		
Exterior	8,003		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	149		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals			
Heating, Cooling, Fire Protection, Plumbing, Electric	al, Elevators		
Built-ins	0		

**Storage Garage** 

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

\$9,057

\$9,057

\$365

\$365

Hazard Value

Policy: Lakes o	f Deer Creek		5/17/2019
INSURED	Lakes of Deer Creek Condo Assc	Effective Date:	5/16/2019
	3303 W Commercial Blvd, # 170	Expiration Date:	
	Fort Lauderdale, FL 33309	Cost as of:	12/2018
Equipment: BU	ILDING ITEM, AND SITE IMPROVEMENT BREAK	KDOWN	
BUILDING 1SE	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		25,505
<b>BUILDING 2SEC</b>	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		26,230
BUILDING 3SE	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		17,360
BUILDING 4SE	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		16,550
BUILDING 5SEC	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		27,330
BUILDING 6SEC	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		27,010
<b>BUILDING 7SEC</b>	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		27,475
<b>BUILDING 8SEC</b>	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		24,665
<b>BUILDING 9SEC</b>	CTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		25,330
<b>BUILDING 10SE</b>	ECTION 1		
Misc. Additional	Features		
Terr	ace/Porch/W'way		24,405
BUILDING 11SE	ECTION 1		

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Lakes of Deer Creek	5/17/2019
Misc. Additional Features	
Porch	19,740
Valuation	
Misc. Additional Features	
Spa	18,500
Swimming Pool	120,000
TOTAL:	\$400,100

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Borrower	N/A				
Property Address	633 Edgewater Drive et al				
City	Deerfield Beach	County Broward	State FL	Zip Code 33442	
Lender/Client	The Lakes of Deer Creek Co.	ndominium Association Inc			





representative building view

representative building view





representative building view

representative building view





representative building view

representative building view

Borrower	N/A				
Property Address	633 Edgewater Drive et al				
City	Deerfield Beach	County Broward	State FL	Zip Code 33442	
Lender/Client	The Lakes of Deer Creek Co	ndominium Association Inc			





representative building view

representative building view





representative building view

representative building view





representative building view

representative building view

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co	ndominium Association. Inc.		



representative building view



representative building view



representative building view



clubhouse building



clubhouse building storage building Form PIC6\_LT — "WinT0TAL" appraisal software by a la mode, inc. — 1-800-ALAMODE



Borrower	N/A				
Property Address	633 Edgewater Drive et al				
City	Deerfield Beach	County Broward	State FL	Zip Code 33442	
Lender/Client	The Lakes of Deer Creek Cor	ndominium Association, Inc.			



pool/spa equipment & heater



patio walls / fencing



pool / patio



patio fencing



28

spa pool equipment Form PIC6\_LT — "WinT0TAL" appraisal software by a la mode, inc. — 1-800-ALAMODE

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Cor	ndominium Association, Inc.		



clubhouse interior








identification wall / sign

building view


# Site Map & Building Surveys (1 of 3)

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co	ndominium Association, Inc.		




# Site Map & Building Surveys (2 of 3)

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co	ndominium Association, Inc.		




## Site Map & Building Surveys (3 of 3)

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co	ndominium Association, Inc.		




# **Representative Building Layout / Survey**

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co	ndominium Association, Inc.		



# **Representative Building Layout / Survey**

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek Co.	ndominium Association, Inc.		




# **Aerial Map**

Borrower	N/A			
Property Address	633 Edgewater Drive et al			
City	Deerfield Beach	County Broward	State FL	Zip Code 33442
Lender/Client	The Lakes of Deer Creek C	ondominium Association. Inc.		



#### **Location Map**

Borrower	N/A				
Property Address	633 Edgewater Drive et al				
City	Deerfield Beach	County Broward	State FL	Zip Code 33442	
Lender/Client	The Lakes of Deer Creek Co	ondominium Association, Inc.			



#### **ASSUMPTIONS AND LIMITING CONDITIONS**

The value conclusions and the certification within this report are made expressly subject to the following assumptions and limiting conditions in this report, which are incorporated herein by reference.

- 1. No responsibility is accepted for matters legal in nature; titles is presumed to be good and assumed to be held in fee simple. All existing liens and encumbrances, if any, have been disregarded (unless otherwise stipulated within the report) and the property is appraised as though free and clear, under competent ownership and management.
- 2. The legal description and site drawings furnished (if provided) are assumed to be correct.
- 3. The maps and sketches are included to assist the reader (if provided). Unless a survey of the property has been provided, no responsibility, whatsoever, in connection with such matters will be recognized. Accordingly, the appraiser makes the extraordinary assumption that the square footage indicated herein is correct and is utilizing the departure provision in stating the indicated square footage is found to be different from that as indicted in the property tax rolls, the appraiser accepts no responsibility for same.
- 4. It is assumed that the project herein set forth is an allowable use under the zoning, and is further considered its highest and best use.
- 5. The land and soil of the area under the appraisement appears firm and solid. The analyst was not supplied with an engineering survey and under this condition this appraisal does not warrant this condition.
- 6. Existing buildings involved in this appraisal report have been inspected and damage, if any, by termites, dry rot, wet rot, or other infestations have been reported if discovered as a matter of information but no guarantee of the amount or degree of damage is intended.
- 7. In this appraisal of existing improvements, the physical condition of the improvements was based on a cursory visual inspection. No liability is assumed for the soundness of structural members since no engineering tests were made.
- 8. All furnishings and equipment, except those specifically indicated and typically considered as part or real estate, have been disregarded. Only the real estate has been considered.
- 9. Information furnished by others including comparable sales data is believed to be reliable, but the appraiser assumes no responsibility for its accuracy.
- 10. The fees received for preparation of this report were not contingent upon the final value estimate.

#### **ASSUMPTIONS AND LIMITING CONDITIONS (Continued)**

- 11. The appraiser is not required to give testimony or attendance in court by reason of this appraisal with reference to the property in question, unless arrangements have been made previously thereto.
- 12. No consideration has been given to labor bonuses, material premiums, and additional costs to conform property replaced to future building codes, ordinances or other legal restrictions.
- 13. Possession of the reports or copies thereof, does not carry with it the right to publications nor may be used for any purpose by any but the applicant, without the written consent of the appraiser and then with the proper qualifications.
- 14. The valuations may not be used in conjunction with any other appraisal. The conclusions are based upon the program of utilization described herein and have not been separated into parts.
- 15. This appraisal has been made in accordance with the rules of professional ethics of the Appraisal Institute Inc.
- 16. Neither all nor any part of the contents of this report shall be conveyed to the public through advertising, public relations, news, sales, or other media, without the written consent and approval of the author, particularly as to the valuation conclusions, the identity of the appraiser or firms with which they are connected or any reference to the Appraisal Institute Inc., and /or the M.A.I. or S.R.A. designations.
- 17. The estimate of Replacement Cost applies only to the date specified in the report. Replacement Cost of Real Estate is affected by many related and unrelated economic conditions, local and national, which might necessarily affect the future market of the subject property. We, therefore, assume no liability for an unforeseen precipitous change in the economy, the project, region, or property.
- 18. Unless otherwise stated in this report, the existence of hazardous substances, including without limitation asbestos, polychlorinated biphenyls, petroleum leakage, agricultural chemicals, urea formaldehyde foam insulation, toxic waste, other contents of environmental conditions, which may or may not be present on the property has not been considered, they were not called to the attention of the Appraiser, not did the appraiser become aware of such during the Appraiser's inspection. The Appraiser has no knowledge of the existence of such materials on or in the property unless otherwise stated. The appraiser, however, is not qualified to test such substances or conditions. The value estimated is predicated on the assumption that there is no such condition on or in the property or in such proximity thereto that it would cause a loss in value. No responsibility is assumed for any such conditions, or for any expertise or engineering knowledge required to discover them. An expert in this field should be retained by the property owner if deemed appropriate.

#### **ASSUMPTIONS AND LIMITING CONDITIONS (Continued)**

- 19. No environmental impact study has been ordered or made. The appraised property is assumed to be in compliance with all applicable regulations unless otherwise noted in the report.
- 20. The date of inspection represents the effective date of the Replacement Cost New opinion and is only considered valid for one year from the effective date. Given the recent price fluctuations for building materials (there is currently an over-supply and limited demand for building labor and materials), the client is strongly advised to annually update the replacement cost new estimate to prevent a situation of either "over/under insuring" the structure. It should be noted that the Replacement Cost New opinion does not consider the following: the cost of replacing pilings or foundation; the loss of use during any reconstruction; real estate taxes during construction; financing costs and/or interest on a construction loan.
- 21. The appraiser is valuing the property for a Replacement Cost Estimate for insurance purposes only. This is to replace the existing improvements in the event of total destruction including removal of existing improvements.

#### 22. Natural Disaster Disclaimer:

Recover and reconstruction from widespread natural disasters such as hurricane or flood will create abnormal shortages of labor and materials, which, in turn will cause above average price increases as much as 50-75% above normal costs prior to the event. These increases, while temporary, may last for a year or more before returning to normal market conditions.

The values as reported herein are estimated based on current (normal) market conditions and are considered appropriate for various purposes including insurance coverage. Some or all of the estimated values as reported herein may be inadequate for reconstruction or repair in periods after a widespread natural disaster.

- 23. In the event of a partial loss, the amount of loss may be based upon the individual repair cost, which is usually proportionately higher than the replacement cost new for the entire property as defined and included in this report.
- 24. The component costs utilized in this report are derived solely from the cost data developed by the Marshall & Swift / Boeckh BVS software. As of July 2011 this is the preferred method, and in certain instances (i.e. Citizen Insurance Company), the only acceptable method of valuation. Information, data and opinions presented in this report are believed to be accurate, however, the author of this report accepts no responsibility for the accuracy of data that was developed by third parties. If Citizens Property Insurance Corporation of Florida (Citizens) is the end user of this report, the appraiser has restrictions on the options allowed via the Marshall & Swift BVS program and may not be fully USPAP compliant. The appraiser cites the Jurisdictional Exception Rule as reasoning to conform with said directives. The rule states: "If any part of USPAP is contrary to the law or public policy of any jurisdiction, only that part shall be void and of no force or effect in that jurisdiction".

- 25. It is agreed that the liability of consultants to the client is limited to the amount of fee paid therefore as liquidated damages.
- 26. Acceptance of, and/or use of, this appraisal report constitutes acceptance of the above conditions.